



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-3960

NOV 9 1971

R. T. Carlson, Sr. Reactor Inspector
Division of Compliance, Region I

RC

CO INSPECTION REPORT NO. 50-219/71-03
JERSEY CENTRAL POWER & LIGHT COMPANY
OYSTER CREEK 1 - BWR

The inspection conducted on October 7 and 8, 1971, which was limited to reviewing control of personnel exposures, and radiation and contamination control during the current extended outage, showed no significant deficiencies in their program. Exposure control was maintained on a daily basis with a central control mechanism. Radiation levels in the major work areas were generally low. High radiation areas were well delineated and spoken to in the RWP's covering those areas. All work was controlled by RWP's covering those areas. All work was controlled by RWP's in which work conditions and requirements were well defined. Contamination control appeared adequate.

The radiation protection staff had been increased by six additional technicians provided by contract from General Electric and Eberline. The coverage appeared to be adequate to cope with outage problems, however it may have been spread a little thin during the early stages of the outage.

Two air balance problems noted by the inspector during the inspection apparently had not generated any problems; however, they did provide a potential for contamination spreads or high air concentrations outside of radiation zones. Corrective actions to prevent recurrence were initiated.

The licensee currently has no capability to monitor air concentrations on a continuous basis. Licensee has recognized this and is currently investigating their needs. They do sample continuously with the results not being indicative of any problems to date; however the potential for exposure to excessive air concentrations does exist. Licensee agreed to investigate the needs for a bioassay program. It appears that the current outage has provided experience that will be applied to future outages.

R. T. Carlson - R
R. J. Meyer
Radiation Specialist

U. S. ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I

Field Notes for:

CO Inspection Report No. 50-219/71-03

Subject: Jersey Central Power & Light Company

Oyster Creek 1

License No. DPR-16

Location: Forked River, N. J.

Priority

Category C

Type of Licensee: BWR

Type of Inspection: Special, Announced

Dates of Inspection: October 7, 1971

Dates of Previous Inspection: June 22-25 & July 2, 1971

Principal Inspector: T. Young, Jr.

Date

Accompanying Inspectors:

Date

Date

Other Accompanying Personnel:

Date

Reviewed By: R. T. Carlson

11/8/71
Date

Proprietary Information:

OC1

A. Persons Contacted

1. ~~T.~~ T. McCluskey Station Superintendent.
2. D. Ross Technical Supervisor
3. D. Reeves Technical Engineer
4. E. Riggle Maintenance Supervisor
5. J. Sullivan Asst. Technical Engineer
6. J. P. Zilinskas GE Manager
7. W. L. Swanson GE Shift Supervisor

B. Operations

1. Sipping complete (12 ^{bundles} not sipped)
44 leakers detected
24 New fuel bundles at the site -
and will be placed around
the periphery in the core.
20 of the leakers to be
reconstituted and placed in
the high flux area of the
core.
11 fuel bundles have been inspected
to date.
2. 8 LPM Chambers are being
replaced.

3. Procedures reviewed

- Ⓐ General Information
Fuel Rod Inspection & Bundle
Reconstitution, JCP&L Co.
OC Power Station

Prepared by:

Nuclear Fuel Dept.

GE Co. San Jose Calif.

J. P. Zilinskas, Jul 23, 1971

- Ⓐ Proprietary Information

- Ⓑ Fuel Reconstitution Procedure
JCP&L Co, OC Power Station

Prepared by:

Nuclear Fuel Dept.

GE Co, San Jose Calif

JP Zilinskas, Jul. 23, 1971

- Ⓐ Proprietary Information

- Ⓐ Both procedures were reviewed
and approved by JCP&L Co. on
9/29/71.

① ~~②~~ Reactor fuel examination & reconstruction

Prepared by:

J. S. Atkinson Specialist - Field Service
W. L. Swanson " " "
J. P. Zilinskas " " "

Approved by:

K. W. Hess, Manager - Field Services

Aug 71
② Proprietary Information

C. Observation of operations

1. All ruffling was done by ~~GE~~ A Personnel.
2. Inspection is done by GE Personnel with a GE and a ~~GE~~ Checker to check the rod's position out and placement into the bundles.
 - a) When the rod is taken out of the bundle it is first run through a brush cleaner and then run through the inspection station.
 - b) While in the inspection station the rod is checked over 100% of its length with ultrasonics & eddy currents.

The ultrasonic test is for water inside the fuel rod and the eddy current test is for flaws in the cladding.

3. All fuel bundle handling is done by ~~OC~~ personnel.

- a) Fuel movement from core to spent fuel pit (SFP)
- b) Fuel bundle movement from SFP to fuel preparation racks.
- c) Removal, storage and replacement of channels and storage of channel hardware.
- d) Fuel movement from fuel preparation racks to SFP. and,
- e) Fuel movements from SFP to the reactor core.

4. All of the fuel rod cleaning, inspection and reconstitution is done by GE personnel in the fuel preparation racks.

5. Independent records are ~~kept~~ kept by the ~~OC~~ and the GE. Checkpoints of the fuel rod removal and the fuel rod placement back into the bundle.

6. When the dechanneled fuel assembly is placed into the fuel preparation machine, the GE supervisor and the ~~OC~~ checker verified the assembly identification and orientation in the rack so that fuel rods were readily identifiable upon removal and replacement. This information was recorded on the check sheets.

7. The ~~OC~~ personnel were in constant communication (via intercom) with the control room from the fuel handling crane platform. (3 Men) The fuel handler supervisor, who was also the tool operator was a licensed senior operator. In the inspector's opinion very alert and aware of what was going ~~on~~.

(*) There was a check sheet taped to the bridge telling the operator of which fuel bundle to move next and where to place it. The checker on the bridge recorded this information on his check sheet.
All direction for fuel ^{bundle} movement

Came from the control room and logged in the console log. The fuel handler's check sheet was only to insure that the information relayed from the control room was correct.

An up to date record board was kept in both the control room and in the Reactor Building fuel room area, depicting all fuel bundles by identification numbers and their placement, whether in the core, in the SFF or in the preparation racks.

8. The weak point in the crew all operation were the lack of nuclear experience of the four GE rod handlers. (The GE SS and the manager, have well grounded backgrounds) They are technicians (non nuclear trained) from a GE service shop. They were given one week of training ^{on the way} the tools using a dummy fuel bundle and ~~some~~ some training on the hazards.

of radiations. This was a controlled operation with the GE shift supervisor looking over the fuel handlers shoulders most of the time. However on one occasion the inspector witnessed that one of the GE fuel handlers, hung four (4) ~~fuel~~ fuel handling tools on one hook. This was too much weight for the hook and it partially straighten out allowing two (2) of the tools to fall into the SFP. The tools landed in a spent fuel rack. Fortunately no fuel was in the rack. This was pointed out ~~to the~~ to Mr McCluskey at the exit interview.

D. Exit Interview

An exit interview was held with Mr McCluskey and concern was expressed with the lack of nuclear experience of the GE fuel handlers and their backgrounds. The incident of the fuel handling tools was

pointed out as an example which may have resulted in a very serious problem if fuel had been stored ⁱⁿ those particular racks. Mr McCloskey stated that this was also a concern of Oyster Creek management and that their ~~OC~~ (OC) checker was an experienced licensed operator with orders to report any ~~unsafe~~ unsafe operations to management.

A. Persons Contacted

T. McCluskey, Station Superintendent
D. Ross, Technical Supervisor
D. Kaulback, Radiation Protection Supervisor
R. Standnour, Radiation Protection Supervisor
A. Grimes, General Superintendent

B. Administration & Organization

Ross stated that no significant changes have occurred in the area of radiation protection responsibility and that he has continued to work with that responsibility. He reported that Mr. McCluskey, Sta. Supt. D. Kaulback, Radiation Protection Supervisor, reports to the Station Superintendent.

As outlined by Ross, additional personnel were added to the Radiation Protection staff for the outage. Robert Standnour (waste management systems) was moved in to provide additional support. Six additional Rad. Techn. have been added to the staff for the outage, by contract with Electric. Responsibility for the outage work has been split between Kaulback and

standnow, for purposes of greater exposure coverage.

C. Operations

Reactor down for extended outage 9/27

D. through 0

Not applicable - Inspection limited to
reactor down for extended outage

E. Personnel

1. Personnel - External

A review of the exposure records and
exposure histories were documented on Form 9
and 6 equivalent. JCP&H provides a
and packet dosimeters and maintains a
record of exposures as determined by the
packet dosimeters. Film badges remain on a
monthly exchange program.

Pass started that all external dosimeters

control during exposure to 1.25, with particular emphasis on the control. One individual has been assigned to control the level of exposure that is available to a supervisor to ensure that it is proper.

Records reviewed for the third week were the records for the first week of the month. The records for the first week of the month were reviewed for the first week of the month. The maximum recorded exposure for that week during 1-7-51 was .932 or 93.2% of the limit. JCP&I and contractor were responsible. Pass stated that the high exposure people were being exposed to during the work.

The inspector notes that records were clear, exposures well documented and that control was on a daily basis.

Records Control - Internal
The records were reviewed by the inspector and found to be

are taken on a continuous basis
and on a grab basis in other samples
potential. Continuous samples are taken in the
department, operating from below at the
transmission line reader and at the
Air is being in the purifier, and
and more gases. Gas sampling is done
grab basis at least twice a shift
occasions when air bubbles are noted
in the water.

Respiratory protection that during the
time of the work, and at other times
the use of respirators is permitted
independent of the use of
protection was used and
Respiratory protection
and described by procedure 003.12.
by means of an concentration
those concentrations allowed for the
respiratory equipment.

In general concentrations were below
the limits of A.P.E. concentrations
of the air in the building and
activity was not observed.

creasing over the course of the day. It remains to be seen how well it remains low and do not present any problems presenting much, part of the airborne...

Rose stated that in light of the air quality conditions to date they had not established a mass assay program. He stated that previous environmental events had occurred in the past at a major nature... time period... they would take... them... individuals would be... exposed to...

Currently license has no capabilities in continuously monitoring air... depend on continuous sampling with... fact determination. Rose stated that... budget has money for continuous air... equipment... the... needs.

3. Review of Contaminated...

As evidenced by records, statements and observations by the inspector, radiation and contamination levels appeared to be well controlled. Contamination areas were well defined, posted and controlled by barriers, doors, attending personnel, and access log sheets. Routine surveys were being conducted and results recorded. High radiation areas were clearly marked and access was restricted to appropriate personnel only. All work in the area, as well as the maintenance of the area, was being carried out in a safe manner.

The results of the radiation measurements, taken at various locations, in general, are in accordance with good control practices. It was noted that equipment contamination levels were low and it would contribute to exposure problems or airborne problems are less serious under controlled conditions and supervision of H.P. personnel. In general, contamination levels in the work locations were noted to be as determined by smear surveys. According to statements and records kept, it was noted that control had been infrequent, and control to be an immediate answer to the control

areas. Losses of control were attributed to
careless removal and control of protective equip-
ing and generally poor step off pad side
Eberline. Red. Technicians stated that their
thought was emphasis given in training of the
during the training given to contractors people
but that was generally getting them in
to good practices. Rees stated that some train-
ing would be given in the future.

1. Air Flow

Spent air from the Tower at the
tower was for observation purposes and
as noted in the air flow report to be
at the drywell area. This was verified during
a visit. Kauland stated that this
should be into the drywell report and made
to Rees. The ventilation system was checked
and the air flow problem was identified
cause. Rees stated that during the visit
removal some air flow adjustments had been
made to ensure that an adequate ^{air} flow could
be maintained down and across the tower and
near the working personnel. He stated that it
apparently had not been changed since
the last time in the area. (Date: 1/17/77)

The inspector further noted that the route
was up from the control valve area to
turbine floor area in the turbine house.
was unable to immediately correct the
but were continuing to investigate corrective
actions. The observer has indicated
that he was unable to correct the
the results were as follows: the observer
has agreed that the
action to be taken.

This state that the requirements of the
procedures (LAP) is stated that there are two
types of PUP's, one for a general area and
other for specific areas within the
area. One cover the general area and the
area was valid for, engineering, electric
work, observers, etc. and provide general
and the other type was valid for

is used for a specific job that was abnormal
or of an unusual nature. RWP's are prepared
by the Rad. Tech (E) or only, or the Rad. Tech
Proto. supervisor and signed. A copy is maintained
counter signed by the Over Shift Foreman. The
RWP's define the requirements for, monitoring
clothing, dosimeters, and respiratory protective
Description of work allowed is defined in these
instructions as to hazards, areas to avoid, and
SOS rates are given. Instructions should be
written to work under a specific RWP.

It is noted that copies of the RWP's are placed
that are all copies RWP's are well
detailed, appropriate signatures in
defined with proper maintenance and
location and in the Rad. Proto. of
noted that upon job completion RWP's are
and removed from service, and files

6. Notes

Instructions were reviewed and
approved to the needs.

Instructions were reviewed and
approved to the needs.

Friskets, portable G.M.'s, and hand operated detectors for personal surveys were in good supply.

It was noted that a Rad. Tech was in attendance or available to the major work areas.

OCT 26 1971

J. G. Keppler, Chief, Reactor Testing & Operations Br.
Division of Compliance, HQ

OO INQUIRY REPORT NO. 50-219/71-07
JERSEY CENTRAL POWER & LIGHT COMPANY
OYSTER CREEK - BWR
CONSTRUCTION UNIONS PICKETING TO PROTEST THE
USE OF GE EMPLOYEES FOR MAINTENANCE WORK

The subject inquiry report is forwarded for information.

The plant was shut down for removal of poison curtains, fuel replacement/reconstitution, and a turbine warranty inspection at the time. No safety problems were identified with respect to this event.

No further action is planned by Region I.

R. T. Carlson
Senior Reactor Inspector

Enclosure:
Subject Inquiry Report

cc: E. G. Case, DRS (3)
R. S. Boyd, DRL (2)
R. C. DaYeung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRS (2)
A. Giambusso, CO
L. Kornblith, CO
R. H. Engelken, CO
Regional Directors, CO
DR Central Files

~~8344-210170 (10)~~ B1406

| | | | | | |
|-----------|---------------|-----------|--|--|--|
| OFFICE ▶ | CO <i>33c</i> | <i>RC</i> | | | |
| SURNAME ▶ | Cantrell:smg | Carlson | | | |
| DATE ▶ | 10/26/71 | | | | |

OCT 7 1971

J. G. Keppler, Chief, Reactor Testing & Operations Br.
Division of Compliance, HQ

CO INQUIRY REPORT NO. 50-219/71-06
JERSEY CENTRAL POWER & LIGHT CO. (OYSTER CREEK - BWR)
CO INSPECTOR REVIEW OF RESULTS OF FUEL SIPPING -
LICENSEE REFUELING PLANS

The attached inquiry report is forwarded for information in advance
of a detailed inspection report.

Preliminary results of our inspection indicate that the licensee's
refueling activities are proceeding according to plans with no
major difficulties having been encountered to date.

We intend to continue following closely the current outage and
will keep you informed as is appropriate.

R. T. Carlson
Senior Reactor Inspector

Enclosure:
Inquiry Rpt 50-219/71-06

- cc: E. G. Case, DRS (3)
- R. S. Boyd, DRL (2)
- R. C. DeYoung, DRL (2)
- D. J. Skovholt, DRL (3)
- H. R. Denton, DRS (2)
- A. Giambusso, CO
- L. Kornblith, CO
- R. Engelken, CO
- Regional Directors, CO
- DR Central Files

~~8304210180~~

B/407

| | | | | | | |
|-----------|--------------|-----------|--|--|--|--|
| OFFICE ▶ | <i>smg</i> | <i>RC</i> | | | | |
| SURNAME ▶ | Cantrell:smg | Carlson | | | | |
| DATE ▶ | 10/7/71 | | | | | |

SEP 10 1971

J. G. Keppler, Chief, Reactor Testing and Operations
Branch, Division of Compliance, HQ

EVALUATION MEMORANDUM
CO INQUIRY REPORT NO. 50-219/71-05
JERSEY CENTRAL POWER & LIGHT CO. (OYSTER CREEK - BWR)
ISOLATION CONDENSER RELAY FAILURE

The attached Inquiry Report relating to the failure of time delay relays associated with the isolation condenser is forwarded for information. The action taken by the licensee appears to be adequate.

It is recommended that a survey of other BWR licensees be conducted to determine their experience with this type relay. From the amount of trouble JC has experienced, it would appear that this relay is not reliable for this type service. We plan to review this subject with Nine Mile Point and Millstone. We will keep you informed as appropriate.

R. T. Carlson
Senior Reactor Inspector

Enclosure:
CO Inquiry Rpt. No. 50-219/71-05

- cc: E. G. Case, DRS (3)
- R. S. Boyd, DRL (2)
- R. C. DeYoung, DRL (2)
- D. J. Skovholt, DRL (3)
- H. R. Denton, DRS (2)
- A. Giambusso, CO
- L. Kornblith, CO
- R. H. Engelken, CO
- Regional Directors, CO
- DR Central Files

~~8344216494~~ (p)

B/408

| | | | | | |
|-----------|--------------|---------|--|--|--|
| OFFICE ▶ | CO | | | | |
| SURNAME ▶ | Cantrell:smg | Carlson | | | |
| DATE ▶ | 9/10/71 | | | | |

6. Mr. Carroll stated that JC is reviewing their instrumentation to see if the GE relay is used in other services at the plant.
7. Mr. McCluskey stated that JC would submit a written report of the most recent failure to DRL in accordance with the requirements of the license.