To:

James P. O'Reilly Directorate of Regulatory Operations Region î 631 Park Avenue King of Prossia, Pennsylvania 19406

From:

Jersey Central Power 5 Light Company Oyster Creek Nuclear Concrating Station Docket #50-219 Porked River, New Jersey 08731

Subject:

Abnormal Occurrence Report No. 50-219/74/ 13

The following is a proliminary report being submitted in compliance with the Technical Specifications paragraph 5.5.2.

Preliminary Approval:

J. T. Carroll, Jr. Date

cc: Mr. A. Giambusso

cleanup isolation signal should have been present at this time due to a high pressure condition on pressure switch \$20\forall . This switch, set to actuate at 140 psig, is located upstream of the pressure relief valve. Ordinarily isolation valves V-16-1 and V-16-14 would have gone closed under these circumstances. However, since the breaker to V-16-1 was open, closure was impossible. Valve V-16-14 failed to close automatically and an unsuccessful attempt was made to close it by placing the valve position selector switch to the close position.

Approximately five minutes after returning the selector switch for V-16-14 to the open (automatic closure) position, the valve closed. The breaker for V-16-1 was reclosed and valve closure was achieved when the selector switch was placed in the close position.

APPARENT CAUSE OF OCCURRENCE: Design
Manufacture
Installation/
Construction
Operator

Procedure
Unusual Service Condition
Inc. Environmental
Component Failure
Other (Specify)

The cause of Valve V-16-1 failing to isolate is attributable to the inadvertent opening of its associated breaker. The cause for V-16-14 failing to isolate is presently under investigation.

2/19/74

Time of Occurrence:

1120

OYSTER CREEK NUCLEAR GENERATING STATION PORKED RIVER, NEW JERSEY 08731

> Abnormal Occurrence Report No. 50-219/74/13

IDENTIFICATION OF OCCURRENCE:

Violation of the Technical Specifications, paragraph 3.5.A.1, when the cleanup system AC isolation valve V-16-1 became inoperable with the reactor critical and the coolant temperature above 212°P. In addition, violation of the Technical Specification Table 3.1.1-F.2, when the cleanup system DC isolation valve V-16-14 failed to close when called upon to do so.

This event is considered to be an abnormal occurrence as defined in the Technical Specifications, paragraphs 1.15B & D.

CONDITIONS PRIOR TO OCCURRENCE:

X	Steady State Power
	Hot Standby
C (19. 100)	"Cold Shutdown
	Refueling Shutdown
COLUMN CONTRACT	Routine Startup
	Operation

Routine Shutdown
Operation
Load Changes During
Routine Power Operation
Other (Specify)

Power: Reactor, 1895 MWt. Elsc., 671 MWc

Flow: Recirc., 57.6 x 10⁶ lb/hr Feed., 7.08 x 10⁶ lb/hr

Stack Cas: 29,329 uCi/sec

DESCRIPTION

On Monday, February 18, 1974, at 1120, the breaker for the

cleanup system automatic isolation valve V-16-1 was accidently tripped which consequently caused the cleanup recycle pump NDO2A to trip. As pressure increased in the system piping, due in part to pressure reducing valve ND-11 failing to control pressure, the pressure downstream of ND-11 increased above the cleanup to torus relief valve setpoint of 150 psig. An automatic

ANALYSIS OF OCCURRENCE: Since both cleanup system isolation valves were inoperable or malfunctioned during this event had a loss of coolant accident occurred generating a Lo-Lo reactor water level condition, the cleanup system would not have isolated. This is only significant if there is also a leak in the cleanup system loop in which case a non-isolable leak of reactor coolant into the secondary containment would have been created. It should be noted that after reclosing the breaker for V-16-1 isolation would have occurred.

CORRECTIVE ACTION:

The breaker for Valve V-16-1 was recnergized, thereby recnabling its isolating capabilities. No corrective action was taken for V-16-14 as it appeared to be functioning normally.

FAILURE DATA:

Not applicable.

Propered by Cotton H Fore Date: 2/19/29