

ATOMIC ENERGY COMMISSION

WASHINGTON, D.C. 20545

March 30, 1972

D. J. Skovholt, Assistant Director for Reactor Operations, DRL(3)

JERSEY CENTRAL POWER AND LIGHT COMPANY (OYSTER CREEK) - COMPLIANCE REPORT NO. 50-219/72-01

The enclosed report of a special inspection of the subject facility on February 7, 1972, is forwarded for information. The purpose of this inspection was to review the details relating to the January 28, 1972 fish kill incident at Oyster Creek. No items of noncompliance with Regulatory requirements were identified during the inspection.

Based on the investigations conducted by the licensee and by the State of New Jersey, it appears that the reactor shutdown contributed significantly to the localized fish kills (negative thermal pollution). We understand that this and other environmental matters will be considered further by DRL and DREP in the review of the full term license application, submitted by Jersey Central on March 6, 1972.

Preliminary information concerning this incident was contained in my February 16, 1972 memorandum to you forwarding CO Inquiry Report No. 50-219/72-03, and my March 10, 1972 note to A. Giambusso. We plan no further action with regard to this matter; however, if you desire additional information, please let us know.

R. H. Engelken, Assistant Director for Inspection and Enforcement Division of Compliance

Enclosure: CO Report No. 50-219/72-01

cc: E. G. Case, DRS (3)

R. S. Boyd, DRL (2)

R. C. DeYoung, DRL(2)

H. R. Denton, DRL

L. Rogers, REP

A. Giambusso, REP

D. R. Muller, REP

S. Levine, DEA

R. Schemel, DRL

L. Kornblith, Jr., CO, w/o encl.

Regional Directors

DR Central Files

J. G. Keppler, Chief, Reactor Testing & Operations Br. Division of Compliance, HQ

CO INQUIRY REPORT NO. 50-219/72-05 JERSEY CENTRAL POWER & LIGHT COMPANY OYSTER CREEK - BWR OTHER - INCREASE IN STACK RELEASE RATE

The subject inquiry report is forwarded for your information.

This increase in release rate near the end of the fuel cycle was expected considering the known condition of the fuel in the reactor. A refueling outage is scheduled for April 21, 1972. Mr. McCluskey stated that the increase noted on March 15, 1972 was unusual and may have indicated an additional failure.

In reply to questions about Jersey Central's plans, Mr. McCluskey would not commit Jersey Central to any action to minimize release rates other than to remain below Technical Specification limits.

We plan to contact the Health and Safety Laboratory to see what their schedule is for retrieving radiation data from the vicinity of Oyster Creek. We will keep you informed of their findings and any new developments as is appropriate. The matter of stack release rates has been and will continue to be followed closely during our inspection program at this facility.

R. T. Carlson Sr. Reactor Inspector

Enclosure:

Subject Inquiry Report

cc: E. G. Case, DRS (3)

R. S. Boyd, DRL (2)

R. C. DeYoung, DRL (2)

D. J. Skovholt, DRL (3)

H. R. Denton, DRL (2)

L. Kornblith, CO

R. H. Engelben, CO

Regional Directors, CO

0/387

OFFICE DR Central Files CO

SURNAME .

Cantrell:smg Carlson

Form AEC-318 (Rev. 9-53)

PASS

U.S. GOVERNMENT PRINTING OFFICE 1869- O 364-598

8304180718 1p.

CO Inquiry Report No. 50-219/72-05

Subject: Jersey Central Power & Light Company	
License No.: DPR-16	
Facility: Oyster Creek - BWR	
Title: Other - Increase in Stack Release Rate	
Prepared by:	*****
F. S. Cantrell, Reactor Inspector	Date

A. Date & Manney AEC was Informed:

By telephone call from Mr. T. McCluskey, Station Superintendent, on March 16, 1972.

B. Description of Particular Event or Circumstance:

Several hours after pulling control rods to maintain reactivity on March 15, 1972, the stack release rate suddenly increased from about 85,000 uCi/second to an indicated 100,000 uCi/second. By 9:00 am on March 16, 1972, the release rate had decreased to approximately 90,000 uCi/second.

The steady state release rate has been creeping up gradually since late February. Following the removal of control rods to compensate for fuel burn up, a marked increase in stack release rate occurs. Several hours later, the release rate decreases to an equilibrium value higher than the release rate prior to pulling control rods. The stack release rate on February 23, 1972 was 55,400 uCi/second. On March 11, the release rate was 75,000 uCi/second. (Records of stack release rates following the return to power from a 50% power reduction on January 23, 1972 showed a release rate of 142,800 uCi/second for about one hour with a gradual decrease. Reference CO Report 219/72-02.)

C. Action by Licensee:

Mr. McCluskey stated that the release rate would be maintained below the Technical Specification limit and agreed to notify Compliance (Newark) by telephone if the steady state release rate increases above 100,000 uCi/second.

J. G. Keppler, Chief, Reactor Testing & Operations Br. Division of Compliance, HQ

CO INQUIRY REPORT NO. 50-219/72-04

JERSEY CENTRAL POWER & LIGHT COMPANY

OYSTER CREEK - BWR

EQUIPMENT FAILURE - FAILURE OF SCRAM DUMP VOLUME LEVEL SWITCH

The subject inquiry report is forwarded for your information.

We consider the action by the licensee to be appropriate.

We do not plan any further action with regard to this specific problem. The licensee stated that a written report would be submitted to DRL within 30 days.

R. T. Carlson Sr. Reactor Inspector

Enclosure: Subject Inquiry Report

cc: E. G. Case, DRS (3) R. S. Boyd, DRL (2)

R. C. DeYoung, DRL (2)

D. J. Skovholt, DRL (3)

H. R. Denton, DRL (2)

L. Kornblith, CO

R. H. Engelken, CO

Regional Directors, CO

CO Files

DR Central Files

3/288

OFFICE S	CO			
OFFICE	733,	7031 Fr		
SURNAME .				
	3/6/72		damentari ya mwaka esistanya pandana akaza wa masaka aka Tanan mata	
DATE				

Form AEC-318 (Rev. 9-53)

A Tables

CO Inquiry Report No. 50-219/72-04

icense No.: DPR-16			-/
acility: Oyster Creek - BWR			
itle: Equipment Failure - Failure of Scram Dump	Volume	Leve1	Switch

A. Date & Manner AEC was Informed:

By telephone call from Mr. T. McCluskey, Station Superintendent, on March 2, 1972.

B. Description of Particular Event or Circumstance:

During a routine surveillance test on March 1, 1972, one of the four scram dump volume 10 all switches failed to respond to a simulated high level signal. The cause of the failure was determined to be an improper tilt of the switch arm assembly. The mercury could not make proper contact to initiate a high level signal. (An abnormally high level in this tank could cause an increase in the control rod scram time.) This condition was corrected.

C. Action by Licensee:

bran La

Replacement switches were ordered and will be installed when received.

The failure will be investigated by the Plant Operations Review Committee.

The licensee will submit a written report on this occurrence to DRL within 30 days.



Sen St

UNITED STATES ATOMIC ENERGY COMMISSION

WASHINGTON, D.C. 20545

February 23, 1972

Note to File () / Chief, Reactor Testing and Operations
Branch, CO

OYSTER CREEK - CO INQUIRY REPORT NO. 50-219/72-02 9

The subject inquiry report that was forwarded to Headquarters for action contains a recommendation relating to a possible restriction on the main condenser differential temperature at all power reactors. A specific recommendation regarding the Oyster Creek facility was forwarded to DRL in the Headquarters' transmittal memorandum for the subject inquiry report. No further action is planned at this time for the other power reactors because DREP is considering the effect of temperature change on biota during the environmental review of each facility.

F. J. Nolan, Senior Reactor Inspection Specialist Division of Compliance

cc: J. P. O'Reilly, CO:I R. T. Carlson, CO:I P. S. Cantrell, CO:I

3/389

J. G. Keppler, Chief, Reactor Testing & Operations Br. Division of Compliance, HQ

CO INQUIRY REPORT NO. 50-219/72-03 JERSEY CENTRAL POWER & LIGHT COMPANY OYSTER CREEK 1 - BWR FISHKILL FROM SUDDEN DROP IN COOLING WATER TEMPERATURE

The subject inquiry report is forwarded for action. The effects of the 25°F delta temperature across the condenser appears to be a contributing factor to the fishkill. Checks of comparable plants show that the condenser delta temperatures range from 150 to 320F. Consideration to restricting the condenser delta temperatures at all power reactors may be appropriate.

Our inspector reviewed records of plant releases and inlet and outlet circulating temperature charts. The data appears to show a "cause and effect" relationship between cooling water temperature and the dead fish. The temperature recorder on the condenser indicated that the inlet cooling water temperature dropped drastically during the two days prior to the shutdown. Mr. McCluskey stated that at this time, the inlet water temperature was near the threshold where the warm water fish can not survive. Paul Hamer, Marine Biologist for the State of New Jersey, was reported in the Trenton Sunday Times Advertiser to have stated that 99.9% of the dead fish were menhaden. In that article, he estimated there were 200,000 dead fish. To our knowledge, this is the highest fishkill estimate.

Discussion with New Jersey State officials revealed that a laboratory snalysis of samples of dead fish is in progress. They have agreed to supply the results of this analysis to Region I Compliance.

A licensee report to DRL on this matter is anticipated; even though it is not a specific Regulatory requirement.

3)390 CO OFFICE . Cantrell: smg SURNAME . DATE U.S. GOVERNMENT PRINTING OFFICE, 1969 - O. 364-598

Form AEC-318 (Rev. 9-53)

Ampth.

Upon receipt of the New Jersey State Laboratory results and the Jersey Central report, a decision will be made relative to the need for additional action.

An inspection report relating to this subject is being prepared on a priority basis.

F. S. Cantrell Acting Sr. Reactor Inspector

Enclosure: Subject Inquiry Report (18 cys)

cc: L. Kornblith, CO R. H. Engelken, CO CO Files

CO Inquiry Report No. 50-219/72-03

Subject: J			er a Lift	it corpar	2	
icense No.	: DPR-16				-	
acility:	Oyster Cr	eek 1 - 1	TVR			
itle: Fis	hkill fro	m Sudden	Drop in	Cooling	Vater	Temperature
repared by						-
	F. S. C	antrell,	Reactor	Inspecto	or	Date

Date & Manner AUC was Informed:

By telephone calls from Mr. T. McCluskey, Station Superintendent, to Mr. C. Madsen on February 1, 1972. Additional information was obtained by telephone calls to Mr. McCluskey and Mr. D. Ross, Technical Supervisor, on February 4, 1972. Other details were obtained in a special inspection at the site on February 7, 1972.

Description of Particular Event or Circumstance:

A feature article in the Ashury Park Sunday Press on January 30, 1972 discussed a "big fish kill found near nuclear plant" (Oyster Creck). Accompanying pictures showed dead fish in coves off barnegat Day between the discharge canal and the inlet canal. Similar articles appeared in other daily area newspapers. During the following week, the cause of the fish kill was attributed to the sudden cooling of the water in the discharge canal when Oyster Creek was shut down for maintenance worl .

Plant records show that a power reduction started at 10:30 pm on January 27, 1972 and the plant was taken off line at approximately 4:30 am on January 28, 1972. The generator was put back on line at 4:28 am on January 31, 1972. Temperature charts at the plant show that the condenser inlet temperature (which is representative of the hay temperature) dropped from 470r to 360t between 4:00 pm January 25 and 4:30 am January 27, 1972. At full power, the delta T across the condenser was 250r, siving an outlet temperature of 610r on January 27, 1972. Then the plant was taken off line, the outlet temperature dropped an additional 250r to approximately 360F. Three condenser circulating purps and a dilution pump were operating prior to and

during most of the outage period with a total flow of approximately 600,000 gpm. This flow, which mixes in the discharge canal with a creek named Oyster Creek, caused the discharge canal temperature to drop rapidly at the point the discharge canal leaves Jersey Central property. During the plant shutdown, the recorded temperature at this point in the canal was in the range of 32 to 40°F. (Spikes as high as 60°F were seen on the temperature chart; however, they appeared to be a malfuncation of the recorder.)

Records show that liquid radioactive waste was discharged on both January 28 and 29; however, the records show that the releases were analyzed and were within established limits. Flant records show that no chemical releases from the plant for calendar years 1971 and 1972. However, 10,000 gallons of chromated water were transferred to a tank truck for disposal by Sumco, Inc. of Caldwell, New Jersey in calendar year 1971.

C. Action by Licensee:

A meeting was held with local officials from Ocean and Lacey
Township on February 1, 1972 to discuss the cause of the "fish
kill". According to minutes of the meeting, the local officials
were satisfied with Jersey Central's explanation of what happened
and that Jersey Central was doing all that was possible to protect the environment. Jersey Central has retained a consulting
biologist, Dr. Charles Murtz, to aid in their investigation.
According to Mr. McCluskey, Dr. Murtz discussed the problem with
Mr. F. G. Farvelis, Chief Riologist, Invironmental Protection
Agency, during a tour of the area where the dead fish were found.
Mr. Marvelis did not contact the plant directly. The "fish
kill" was investigated for the State of New Jersey by Paul Hammer,
Marine Biologist, and Bruce Young, Conservation Officer, of the
Fish and Wildlife Service from the nearby Nacote Creek Fishery.

* 4	PRM AEC 166 (Fall) Pr 130018		STATISTICAL DATA						
-	A. DOCKET NUMBER B. REPORT NUMBER	C. PRIORITY	ING HISPECTION INVESTIGATIO	54.53	THE R. P. LEWIS CO., LANSING MICH. 49 LANSING MICH.	F. REGION			
A .	05000219 7201	CATEGORY	0 02/07/72		10	AGTIVITY .			
	LICENSCENENDOA	1	FACILITY			LICENSE NUMBER			
	Jersey Central Power & Lig	ht Company	Oyster Creek			DPR-16			
G	ACTIVITY CONDUCTED	INVESTIGATION	4 VENDER	SNAGE MENT	A NON LICENSEE				
846	1 1 191 1 1 AEGIONAL OFFICE LETTER 1 REFERRED TO HOS FOR ACTION								
,	INSPECTION INVESTIGATION FINDINGS XX CLEAR 1 SAFETY ITEN 1 NONCOMPLIANCE . NONCONFORMANCE								
K.	FIELD ACTION AS A RESULT OF INQUIRY CONDUCT INVESTIGATION INVESTIGATION INVESTIGATION		A REFER TO NOME	EG. A	AUTH.	D NO FURTHER ACTION			
	REASON INSP. FINDINGS REFERRED TO HEADQUARTERS FOR ACTION	SUBJECT OF INQUI	BJECT OF INQUIRY OR INVESTIGATION:			ION ON INSPECTION			
	k l	M OID TYPE	A INT OVEREXPOSURE	N	T				
	01 MEACTH AND SAFETY	-	And a second sec			N REQUIRED			
	COMPLEXITEM INVOLVING	03 TYPE A RELEASE 04 TYPE A LOSS OF FACILITY			02 LETTER-CLEAR				
	92 NONCOMPLIANCE NONCOMPORMANCE								
	03 D LICENSING PROBLEM	OS TYPE	A PROPERTY DAMAGE	1	11 Cl . 67700	AUTO MAN I ANGE			
	04 POLICY MATTER		1	03 LETTER-NONCOMPLIANCE					
	05 INTERPRETATION 01 TYPE B EXT. OVEREXPOSURE			04 CETTER-SAFETY ITEM					
				1	TELLEN-				
	OA SAFETY ITEM	08 TYPE B RELEASE			OS [] PARTZ NOTICE				
	07 MANAGEMENT DEFICIENCY								
	08 D INADEQ REPLY TO LETTER	PROPERTY DAMAGE	1	OTICE AS RESULT OF IP TO REGIONAL					
	69 AS REPLY TO LETTER	10 CFR	18.405	OFFICE L					
	IN NO CORRECTIVE ACTION PLANNED		ERNAL OVEREXPOSURE	-	OI ORDER				
H	11 LI ACTION PLANTED	12 O EXT	ERNAL OVEREXPOSURE	-					
	17 D HOS LETTER DEQUIRED	ford securion	ESSIVE RADIATION LEVELS	OF THE REPERTO DEL FOR RESOL		OPL FOR RESOLUTION			
*	13 Has REVIEW PEQUIRED	14 D 500	XCESSIVE ONCENTRATION LEVELS						
	1. DUNREVIEWED SAFETY MATTER	15 CRITIC	ALITY	04 D REFER TO		DRL FOR INFORMATION			
	IS DESIGN CHANGE	14 D LOSS C	R THEFT						
	I OTHER	11 CONTA	MINATION	1	10 D REFER TO	ONL FOR RESOLUTION			
	110	10 UNSAF	E OPERATION	1	-				
	" []	IND FIRE,	EXPLOSION	-	II AEFERTO	ONL FOR INFORMATION			
		10 HUMA	N (OPERATOR) ERROR	1					
2	REGIONAL DIFFICE ACTION DATES	210 COMPL	A:NT	1	12 REFERTO	RESION TO CLOSE OUT			
	REPORT SENT TO HEADQUARTERS	22 0 908010	INTEREST	1					
-	17.17.72	PID LEAK	NO BOURGE		11 O OTHER				
	141 NETTER 1850ED	ZA TRANS	PORTATION		DATE LETTER, N	OTICE, ORDER ISSUED			
-	X RESLY NOT REQUIRED	EXPOS	ED LICENSE URE REPORTED DUND INVALID	7	120				
-	LICENSEE REPLY RECEIVED	P4		1	DATE LICENSEE	REPLY RECEIVED			
1		5	RUCTION/EQUIP DEFICIENCY	-					
1	REPLYINADEQUATE	Management of the State of the	OLICATION SEED BED'S	1					
			TURE FROM FSAR/TS'S	-	REPLY NO	REQUIRED			
		10 OEPAR	The state of the s	- v	annual and	0/			