м	29	Sara	n 366	BI III
ш	0.0	90111	1 3000	

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO 3150-0104 EXPIRES 8/31/85

LICENSEE EVENT REPORT (LER)

						-				_							To	2015	NUMBE	D (2)				PA	GE (3)				
ACILITY						733								~							10				T -				
TITLE (4)	Susq	uena	inna	St	eam	EI	ect	cric	Sta	itl	on	- 01	nit	2			10	15	1010	10	3	8	8	1 01	FO 12				
ITLE (4)	ESF	Acti	ati	on	- RV	NCU	Is	solat	ior	v	al	ves (Clo	sed															
EVE	NT DATE	(5)	T		LER	NUMB	ER (6)			REF	PORT DA	TE (7			01	THER F	FACILITIES INVOLVED (8)											
MONTH	INTH DAY YEAR YEAR SEQUENTIAL REVISION NUMBER NUMBER						MO	NTH	DAY	Tye	AR	FACILITY NAMES						DOCKET NUMBER(S)											
			1			Owig	-		MBCH									0 5 0 0 0 1											
0 1	1 4	8 5	8	15	- 0	0 0	14	-	00	0	2	1 2	8	5						0	15	0	0	01	1.1				
0.00			THI	S REPO	RT IS	SUBM	ITTE	D PURSI	JANT	O TI	HE RI	EQUIRE	MENTS	OF 1	O CFR &: /C	heck one or	more of	the fo	(lowing)	(11)	-		-						
	RATING DE (9)	1		20.40	2(b)		-		T	20	405(c)			x	50.73(a)(2)	l(iv)			T	73	71(6)							
POWER				20.405(a)(1)(i)					50.36(c)(1)					50.73(a)(2)(v)					73.71(e)										
LEVEL (10)	1	1010		20.40	5(e)(1)	(ii)				50	.36(c)	(2)				50.73(a)(2)(vii)					OTHER (Specify in Abstract								
				20.40	B(a)(1)	(iii)				50	.73(a)	(2)(i)				50.73(e)(2)	(viii)(A)					6A)	nd in	Text, NA	IC Form				
				20.40	5(a)(1)	(iv)				50	.73(e)	(2)(n)				50.73(a)(2)	(viii)(B)			1									
				20.40	6(a)(1)	(v)				50	73(e)	(2)(iii)				50.73(a)(2)	(x)												
									i.	ICEN	SEE	CONTAC	T FOR	R THIS	LER (12)														
NAME																					EPHO	NE N	UMB	R					
	L.A.	Kuc	zyr	ski	- 1	Nuc	lea	ar P	lant	S	pe	cial:	ist	, L	evel I	II		ARI	EA COD	E									
																		7	1117	5	14	121	-1	317	15 19				
					С	OMPL	ETE	ONE LIN	E FOR	EAC	H CO	MPONE	NT FA	LURE	DESCRIBE	D IN THIS R	EPORT	(13)				-	_						
CAUSE	SYSTEM	CON	PONE	NT		UFAC RER		TO N						CAUSE	SYSTEM	COMPONE	ENT		NUFAC										
В	KIM	FIS	51		BIO	17	14	1	1							1.1		1											
		1	1		1	F	1									1.1		1											
		-		-		SUPPI	LEME	NTAL R	EPORT	EXP	ECTE	D (14)					-	-		-		MON	HTH	DAY	YEAR				
											T								SUBMIS	SION			1						
YES	Silt yes, c	omplete	EXPE	TED S	BMISS	ION I	DATE	1			1	NO							DATE	(15)		1		1	1				
BSTRAC	T (Limit	to 1400	speces		roxima	eatu fi	frage	tingle sou	ice type	Write	wn lin	ect (16)		-		7.00		-	-	-		-	-	_					

The Reactor Water Cleanup System (RWCU) had been experiencing isolations due to non-regenerative heat exhanger high outlet temperature. On January 14, 1985, in an effort to prevent another RWCU isolation, Operations personnel throttled opened the RWCU filter demineralizer bypass valve. This resulted in closure of the RWCU inboard and outboard isolation valves on a high system flow signal. These valves are part of the Primary Containment Isolation System, which is an Engineered Safety Feature. The RWCU isolations had been occurring as part of a sequence of events triggered by the trip of the Reactor Building Chilled Water (RBCW) system. The RBCW trips were traced to a loose connection in an RBCW flow switch. The connection was tightened. There have been no recurrences. No further action is required.

8502220267 850212 PDR ADOCK 05000388 PDR 19/1

NRC Ferm 366A (9-83)	LICENSEE EVENT REPO	SEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED EXPIRES: 8										
FACILITY NAME (1)		DOCKET NUMBER (2)		LE	R NUMBER (6)		· P	AGE (3	3)		
Susquehanna Stea	m Electric Station		YEAR		SEQUENTIAL NUMBER		REVISION NUMBER		П	-		
Unit 2		0 15 10 10 10 13 18 18	815	_	01014	_	010	012	OF	0 12		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On January 14, 1985, in response to a Reactor Building Closed Cooling Water (RBCCW) isolation to the Reactor Water Cleanup (RWCU) non-regenerative heat exchangers (NRHX), Operations personnel (licensed, utility) attempted to avert an imminent RWCU isolation by throttling open the RWCU filter/demineralizer bypass valve. The bypass valve was opened somewhat too quickly, and caused a high system flow signal which resulted in the closure of the RWCU inlet inboard and outboard isolation valves. These valves are part of the Primary Containment Isolation System, which is an Engineered Safety Feature. The RWCU system was quickly restored to service.

Beginning on January 4, 1985, problems were experienced with the Reactor Building Chilled Water (RBCW) system. An RBCW low flow switch would send a false low flow signal to the Reactor Building Closed Cooling Water (RBCCW) system. This would cause RBCCW to shed its normal loads (which includes the RWCU NRHX) to pick up the RBCW load of the drywell coolers. This led to several RWCU isolations on RWCU NRHX high outlet temperature. This is a non-safety related system isolation, designed to protect the resin in the RWCU filter/demineralizers. Investigation by Instrumentation and Controls personnel found a loose connection in the terminal box for the RBCW low flow switch. The connection was tightened and the system was monitored for eight days with no recurrences. No further action is required.



Pennsylvania Power & Light Company

Two North Ninth Street . Allentown, PA 18101 . 215 / 770-5151

February 12, 1985

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 85-004-00 ER 100450 FILE 841-23 PLAS-039

Docket No. 50-388 License No. NPF-22

Attached is Licensee Event Report 85-004-00. This event was determined reportable per 10CFR50.73(a)(2)(iv), in that the Unit experienced an unanticipated actuation of an Engineered Safety Feature when the Reactor Water Cleanup System inlet inboard and outboard isolation valves closed on a high flow signal.

H.W. Keiser

Superintendent of Plant-Susquehanna

Ceires

LAK/pjg

cc: Dr. Thomas E. Murley
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Mr. R.H. Jacobs Senior Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 52 Shickshinny, PA 13655

IEZZ