LICENSEE EVENT REPORT (LER)													U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 31500104 EXPIRES: 8/31/85							
FACILITY	FACILITY NAME (1)														MBER	(2)		PAGE (3)		
Bru	nswic	k St	0 5 0 0					10	1 31 2 15	1	OF 0	1								
TITLE (4																				
Aut	omati	c In	it	atio	ons of (Cont	rol	Build	ling	Emerge	ency A	ir Filtr	atio	on S	Sys	tem	Train	s 2/	and	
C. AND THE REAL PROPERTY.	NT DATE		T		LER NUMBER			The same of the same of	PORT DA				R FACI					21		
MONTH	QAY	YEAR	YE	AR	SEQUENTIA		REVISION		NTH DAY	YEAR	Brunswick Unit 2				DOCKET NUMBERIS					
						1										0	151010	0 0 13 12 1		4
0 1	1 5	8 5	8	5	old	, -	do	0 2	1 4	8 5						0	151010	10		
OPE	RATING		THI	S REPOR	T IS SUBMITT	ED PU	RSUANT	TO THE R	EQUIREN	ENTS OF	0 CFR 5: 10	Check one or more	e of the	follow	ing) (1	1)				
MODE (9)				20.402(ь)				20.406(e)			X	50.73(e)(2)(iv)				73.71(b)				
POWE				20.406(a)(1)(i)				60.36(c)(1)			50,73(a)(2)(v)				73.71(c)					
(10) 0 81				20.405(a)(1)(ii)				50.36(e)(2)			50,73(a)(2)(vii)				OTHER (Specify in Abstract					
				20.406	(a)(1)(iii)		_	60.73(a	1(2)(i)			50.73(e)(2)(viii)					366A)			
			_	20.405(a)(1)(iv)			-	50.73(a)(2)(ii)			50,73(e)(2)(viii)(B)									
				20.406	(a)(1)(v)			50.73(a				50.73(a)(2)(x)				L_				
NAME		_						ICENSEE	CONTAC	FOR THE	S LER (12)			-	-	TELE	EPHONE NUM	IRER		_
													7	REAC	CODE	T	S HOITE HON			-
M.	J. P	astv	a .	Jr.	Regula	ator	v Te	chnic	ian				0	9 1 1	119	4	5 7 -	12	3 11 1	5
			,							T FAILUR	DESCRIBE	D IN THIS REPO		-	112	17	131,1	12	21.1	_
						1	ORTABLE									T				
CAUSE	SYSTEM					NPROS			CAUSE	SYSTEM	COMPONENT		MANUFAC- TURER		TO NPROS		*			
					District Co.	1										T				
- 1		1	1		111							111			1					
Sur I						1														
			1		1 1 1	1		000000000000000000000000000000000000000		000		1 1 1		1 1	- 1	-				*33

common Control Building Emergency Air Filtration (CBEAF) System trains 2A and 2B occurred with a cumulative total of five initiations. Two initiations resulted from increased sensitivity of a Control Room area fire detector due to accumulation of dirt and particulate in the detector chamber. Two initiations resulted from spray painting fumes in the Control Room area. One initiation resulted from actuation of a fire detector in the Unit 2 battery room due to overheated strip elements in a temporary heater for the room. The Control Operators of both units became aware of these events through appropriate Control Room alarm annunciations and indications. At the time of each initiation, the corresponding redundant train was in standby. Both units were at power operation. Following the paint fume initiations, the affected CBEAF System train was utilized to remove the paint fumes. The charcoal was replaced and the train was returned to standby. Charcoal samples of the train were removed and are being analyzed to determine the impact of the paint

On January 15, 16, and 22, 1985, automatic initiations of the Units 1 and 2

The subject fire detector was cleaned and returned to service. Control Building fire detectors, susceptible to spurious actuations, are being cleaned. Plant guidelines are in place regarding spray painting in the Control Room to help prevent inadvertent CBEAF System actuations. Initiation of a CBEAF System train places the train into its most conservative mode of operation.

fumes. After each of the other initiations, the affected trains were returned

to standby following verification that fire conditions did not exist.

8502220270 850214 PDR ADOCK 05000325

SUPPLEMENTAL REPORT EXPECTED (14)

YES III yes, complete EXPECTED SUBMISSION DATE!

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

NRC Form 366

150

MONTH

EXPECTED

DAY

YEAR

Carolina Power & Light Company

Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461-0429

February 14, 1985

FILE: B09-13510C SERIAL: BSEP/85-0246

NRC Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
LICENSEF EVENT REPORT 1-85-007

Gentlemen:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-1022, September 1983.

Very truly yours,

2:25

C. R. Dietz, General Manager Brunswick Steam Electric Plant

MJP/vt/LETDR1

Enclosure

cc: Dr. J. N. Grace

IE22