

Georgia Power Company  
40 Inverness Center Parkway  
Post Office Box 1295  
Birmingham, Alabama 35201  
Telephone 205 877-7279

J. T. Beckham, Jr.  
Vice President - Nuclear  
Hatch Project



April 15, 1996

Docket No. 50-321

HL-5139

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Edwin I. Hatch Nuclear Plant - Unit 1  
Licensee Event Report  
Inadequate Procedure Results in Reactor  
Pressure Increase and Automatic Reactor Shutdown

Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv), Georgia Power Company is submitting the enclosed Licensee Event Report (LER) concerning the inadequate procedure which resulted in a reactor pressure increase and automatic reactor shutdown.

Sincerely,

J. T. Beckham, Jr.

IFL/eb

Enclosure: LER 50-321/1996-004

cc: Georgia Power Company

Mr. H. L. Sumner, General Manager - Nuclear Plant  
NORMS

U.S. Nuclear Regulatory Commission, Washington, D.C.  
Mr. K. Jabbour, Licensing Project Manager - Hatch

U.S. Nuclear Regulatory Commission, Region II  
Mr. S. D. Ebnetter, Regional Administrator  
Mr. B. L. Holbrook, Senior Resident Inspector - Hatch

220069

9604220331 960422  
PDR ADOCK 05000321  
S PDR

IE22  
11

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

Edwin I. Hatch Nuclear Plant - Unit 1

DOCKET NUMBER (2)

0 5 | 0 0 | 0 3 | 2 1

PAGE (3)

1 OF 5

TITLE (4)

Inadequate Procedure Results in Reactor Pressure Increase and Automatic Reactor Shutdown

| EVENT DATE (5) |     |      | LER NUMBER (6) |                   |                 | REPORT DATE (7) |     |      | OTHER FACILITIES INVOLVED (8) |                  |  |
|----------------|-----|------|----------------|-------------------|-----------------|-----------------|-----|------|-------------------------------|------------------|--|
| MONTH          | DAY | YEAR | YEAR           | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH           | DAY | YEAR | FACILITY NAME                 | DOCKET NUMBER(S) |  |
| 0 3            | 2 3 | 9 6  | 9 6            | 0 0 4             | 0 0             | 0 4             | 2 2 | 9 6  |                               | 0 5   0 0   0 0  |  |
|                |     |      |                |                   |                 |                 |     |      | FACILITY NAME                 | 0 5   0 0   0 0  |  |

| OPERATING MODE (9)         | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR ? : (Check one or more of the following) (11) |                  |                                     |                      |  |
|----------------------------|---|------------------|-------------------------------------|----------------------|--|
| 1                          | 20.402(b)   | 20.405(c)        | <input checked="" type="checkbox"/> | 50.73(a)(2)(iv)      | 73.71(b)   |
| POWER LEVEL (10) 0   1   7 | 20.405(a)(1)(i)   | 50.36(c)(1)      |                                     | 50.73(a)(2)(v)       | 73.71(c)   |
|                            | 20.405(a)(1)(ii)  | 50.36(c)(2)      |                                     | 50.73(a)(2)(vii)     |  |
|                            | 20.405(a)(1)(iii)   | 50.73(a)(2)(i)   |                                     | 50.73(a)(2)(viii)(A) | OTHER (Specify in Abstract below and in Text, NRC Form 366A) |
|                            | 20.405(a)(1)(iv)  | 50.73(a)(2)(ii)  |                                     | 50.73(a)(2)(viii)(B) |  |
|                            | 20.405(a)(1)(v)   | 50.73(a)(2)(iii) |                                     | 50.73(a)(2)(x)       |  |

LICENSEE CONTACT FOR THIS LER (12)

| NAME  | TELEPHONE NUMBER (include area code) |
|---|--------------------------------------|
| Steven B. Tipps, Nuclear Safety and Compliance Manager, Hatch | 9 1   2 3   6 7   - 1 7   8 5   1    |

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPRDS | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPRDS |
|-------|--------|-----------|--------------|---------------------|-------|--------|-----------|--------------|---------------------|
|       |        |           |              |                     |       |        |           |              |                     |
|       |        |           |              |                     |       |        |           |              |                     |

SUPPLEMENTAL REPORT EXPECTED (14)

| YES (If yes, complete EXPECTED SUBMISSION DATE) | NO                       | EXPECTED SUBMISSION DATE (15) | MONTH | DAY | YEAR |
|---|--------------------------|-------------------------------|-------|-----|------|
| <input checked="" type="checkbox"/>             | <input type="checkbox"/> |                               |       |     |      |

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-space typewritten lines) (16)

On 3/23/96 at 0135 EST, Unit 1 was in the Run mode at a power level of 424 CMWT (17.4% rated thermal power). At that time, personnel manually shut down the turbine. When the turbine was shut down as part of a planned activity for the purpose of beginning a refueling outage, reactor pressure increased to approximately 1045 psig and the reactor automatically shut down on high pressure. Water level decreased due to void collapse from the rapid reduction in power. However, the transient did not result in level decreasing to the automatic reactor shutdown and Primary Containment Isolation System setpoint; therefore, no additional automatic actions occurred. Level decreased to 12 inches above instrument zero (170 inches above the top of the active fuel) before being restored by the reactor feedwater pump. No Emergency Core Cooling Systems actuated nor were any required to actuate. Pressure reached its maximum value of 1045 psig at the time of the automatic shutdown and was reduced and controlled by steam loads and the turbine bypass valves. No safety/relief valves lifted nor were any required to lift.

This event was caused by an inadequate procedure. When the turbine is manually shut down, an immediate pressure increase occurs. Procedure 34SO-N30-001-1S, "Main Turbine Operation," did not require pressure to be decreased in order to provide sufficient margin to the high pressure automatic shutdown setpoint prior to manual shutdown of the turbine. Procedures 34SO-N30-001-1S and 34SO-N30-001-2S, "Main Turbine Operation," have been revised.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB87714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

| YEAR | SEQUENTIAL YEAR | REVISION NUMBER | PAGE (3) |    |   |
|------|-----------------|-----------------|----------|----|---|
| 96   | -004            | -00             | 2        | OF | 5 |

Edwin I. Hatch Nuclear Plant - Unit 1

05000321

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor

Energy Industry Identification System codes appear in the text as (EIS Code XX).

DESCRIPTION OF EVENT

On 3/23/96 at 0135 EST, Unit 1 was in the Run mode at a power level of 424 CMWT (17.4% rated thermal power) with reactor pressure at approximately 995 psig. At that time, Operations personnel manually shut down the main turbine (EIS Code TA) per system operating procedure 34SO-N30-001-1S, "Main Turbine Operation," as part of routine, scheduled activities to begin the 16<sup>th</sup> refueling outage. When the turbine was shut down, reactor pressure immediately increased by about 50 psig, which is normal when the main turbine is shut down manually, to approximately 1045 psig. This exceeded the automatic high reactor pressure shutdown setpoint of 1042 psig and the reactor automatically shut down on high pressure per design.

Reactor water level decreased due to void collapse from the rapid reduction in power. However, because the reactor was at low power at the time of the automatic shutdown, the transient did not result in water level decreasing to the automatic reactor shutdown and Group 2 Primary Containment Isolation System (EIS Code JM) setpoint of three inches above instrument zero. Therefore, no additional automatic actions occurred. Reactor water level decreased to its minimum value of 12 inches above instrument zero (170 inches above the top of the active fuel) before being restored automatically by the operating reactor feedwater pump (EIS Code SJ). No Emergency Core Cooling Systems actuated nor were any required to actuate to restore or maintain water level.

Reactor pressure reached its maximum value of about 1045 psig at the time of the automatic reactor shutdown. Pressure was reduced and controlled thereafter by the main turbine bypass valves (EIS Code SO) and other steam loads, such as the reactor feedwater pump turbine (EIS Code SJ), the steam sealing system (EIS Code TC), and the steam jet air ejector (EIS Code SH). No safety/relief valves lifted nor were any required to lift to reduce or control reactor pressure.

CAUSE OF EVENT

This event was caused by an inadequate procedure. System operating procedure 34SO-N30-001-1S, "Main Turbine Operation," did not require reactor pressure to be decreased in order to provide sufficient margin between actual pressure and the automatic high reactor pressure shutdown setpoint prior to manual shut down of the main turbine. Consequently, reactor pressure was not decreased

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

| YEAR | SEQUENTIAL YEAR | REVISION NUMBER |
|------|-----------------|-----------------|
| 96   | 004             | 00              |

Edwin I. Hatch Nuclear Plant - Unit 1

05000321

96 - 004 - 00

3 OF 5

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

from 995 psig prior to shutdown of the main turbine, resulting in reactor pressure exceeding the high reactor pressure automatic shutdown setpoint of 1042 psig when the turbine was shut down manually.

When the main turbine is manually shut down, an immediate reactor pressure increase of approximately 50 psig occurs before the bypass valves can reduce and control pressure. This increase is usual and, normally, not of concern. Reactor pressure decreases approximately linearly with decreasing power: decreasing reactor power from 100% to less than 30% (where the main turbine is manually shut down) decreases reactor pressure by about 70 psig. This decrease provides sufficient margin to the automatic high reactor pressure shutdown setpoint such that an automatic reactor shut down on high pressure does not occur when the main turbine is shut down manually.

Reactor power was reduced to about 1400 CMWT (57% rated thermal power) several days prior to the beginning of the refueling outage in order to remove a circulating water pump from service for maintenance. This was necessary to ensure the maintenance could be completed and the pump returned to service by the scheduled end of the refueling outage. Normally, the unit is shut down for a refueling outage by continuously decreasing reactor power from near 100% to less than 30%, at which point the main turbine is shut down manually. Reactor pressure is not maintained at or near its normal value during the shutdown. Instead, it is allowed to decrease linearly with power. However, reactor pressure was returned to 998 psig, near its normal full-power value, to maximize electrical generation at the reduced power level during the several days prior to the start of the refueling outage. This is allowed by plant procedure 34GO-OPS-005-1S, "Power Changes."

The reduction from about 57% power to 17% power did result in a reactor pressure decrease. However, with the unit at a reduced power level, the pressure decrease was not as large as would be expected if the unit shutdown had begun at a higher power level. Since the shutdown was started at a lower power level, with pressure near its normal full-power value, the resulting pressure decrease was not enough to provide adequate margin to the automatic high reactor pressure shutdown setpoint to avoid an automatic reactor shutdown when the turbine was shut down. Procedure 34SO-N30-001-1S did not require reactor pressure to be reduced, as needed, to provide the necessary margin.

REPORTABILITY ANALYSIS AND SAFETY ASSESSMENT

This report is required by 10 CFR 50.73 (a)(2)(iv) because of the unplanned actuation of Engineered Safety Feature systems. The Reactor Protection System (EIS Code JC), an Engineered Safety



**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

|  |  |                |                                  |                              |          |      |
|--|--|----------------|----------------------------------|------------------------------|----------|------|
| FACILITY NAME (1)<br><br>Edwin I. Hatch Nuclear Plant - Unit 1 | DOCKET NUMBER (2)<br><br>0   5   0   0   0   3   2   1 | LER NUMBER (6) |                                  |                              | PAGE (3) |      |
|  |  | YEAR<br>9   6  | SEQUENTIAL YEAR<br>-   0   0   4 | REVISION NUMBER<br>-   0   0 | 4        | OF 5 |

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

Feature system, actuated on high reactor pressure per design when pressure increased to approximately 1045 psig following manual shut down of the main turbine.

An increase in reactor pressure during reactor operation compresses the steam voids and results in a positive reactivity insertion. This causes the neutron flux and thermal power transferred to the reactor coolant to increase which could challenge the integrity of the fuel cladding and the reactor coolant pressure boundary. Therefore, the reactor is shut down automatically on high reactor steam dome pressure to limit the neutron flux and thermal power increase. The automatic reactor shutdown on high pressure, along with the safety/relief valves, limits the peak reactor pressure to less than the American Society of Mechanical Engineers Section III Code limits.

In this event, the main turbine control valves (EISS Code TA) and stop valves (EISS Code TA) closed rapidly when the turbine was shut down manually. Their rapid closure resulted in a normal reactor pressure increase of about 50 psig. The bypass valves opened to limit the pressure increase, to reduce pressure to the desired value, and to control pressure at that desired value per their design. However, there was insufficient margin to the automatic high reactor pressure shutdown setpoint because the unit was operating at a pressure higher than normal for the given power level. When pressure reached approximately 1042 psig, the reactor automatically shut down per design. No safety/relief valves opened nor were any required to open to limit or reduce pressure.

Reactor water level decreased due to void collapse from the rapid decrease in reactor power. The operating reactor feedwater pump automatically restored water level; the minimum water level reached was 170 inches above the top of the active fuel and was only about 25 inches below normal. No Emergency Core Cooling Systems actuated nor were any required to actuate to recover or maintain water level during or following this event. All automatic functions operated per design in response to the pressure increase and the automatic reactor shutdown.

Based upon the preceding discussion, it is concluded that this event had no adverse impact on nuclear safety. This analysis is applicable to all power levels.

CORRECTIVE ACTIONS

Procedures 34SO-N30-001-1S and 34SO-N30-001-2S, "Main Turbine Operation," have been revised to require reactor pressure to be decreased to provide an adequate margin between reactor pressure and the automatic high pressure shutdown setpoint prior to a planned manual shut down of the main turbine.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

|  |  |                |                                  |                              |          |      |
|--|--|----------------|----------------------------------|------------------------------|----------|------|
| FACILITY NAME (1)<br><br>Edwin I. Hatch Nuclear Plant - Unit 1 | DOCKET NUMBER (2)<br><br>0   5   0   0   0   3   2   1 | LER NUMBER (6) |                                  |                              | PAGE (3) |      |
|  |  | YEAR<br>9   6  | SEQUENTIAL YEAR<br>-   0   0   4 | REVISION NUMBER<br>-   0   0 | 5        | OF 5 |

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

ADDITIONAL INFORMATION

No systems other than those already mentioned in this report were affected by this event.

No failed components caused or resulted from this event.

A previous similar event in which an unplanned automatic reactor shutdown on high pressure occurred was reported in Licensee Event Report 50-321/1996-001, dated 1/26/96. In the previous event, the high reactor pressure resulted when the main turbine control valves drifted closed while the unit was operating at greater than 30% rated thermal power. The valves drifted closed due to material blocking their servovalve strainers; this material prevented hydraulic fluid from reaching the control valve positioning devices (i.e., the servovalve spools). Upon loss of hydraulic fluid, the control valves closed per their fail-safe design.

As the control valves drifted closed, the bypass valves opened to control reactor pressure. However, the bypass valves could not pass all the steam generated at the high reactor power level. Therefore, when the control valves closed, the excessive steam generated caused reactor pressure to increase and the reactor automatically shutdown.

In this event, the main turbine control valves and stop valves closed rapidly when the turbine was shut down manually. Their rapid closure resulted in a normal reactor pressure increase of about 50 psig. The bypass valves opened to limit the pressure increase, to reduce pressure to the desired value, and to control pressure at that desired value per their design. Because the unit was operating at a pressure higher than normal for the given power level, there was insufficient margin to the automatic high reactor pressure shutdown setpoint. When pressure reached approximately 1042 psig, the reactor automatically shut down per design.

Since the causes of the two events were different, the corrective actions for the previous event could not have prevented this event.