U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO 3150-0104 EXPIRES 8/31/85 LICENSEE EVENT REPORT (LER) DOCKET NUMBER (2) 0 | 5 | 0 | 0 | 0 | 3 | 8 | 8 OF 01 Susquehanna Steam Electric Station - Unit 2 TITLE (4) Unit 2 Reactor Scram Due to High Turbine Vibration. OTHER FACILITIES INVOLVED (8) EVENT DATE (5) LER NUMBER (6) REPORT DATE (7) DOCKET NUMBERIS FACILITY NAMES MONTH DAY YEAR YEAR 0 | 5 | 0 | 0 | 0 | 000219 0 1 1 9 8 5 8 5 0 0 3 0 | 5 | 0 | 0 | 0 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR \$ (Check one or more of the following) (11) OPERATING MODE (9) 1 73 71(b) 50.73(a)(2)(iv) 73.71(c) 20 405(4)(1)(() 50 35(e)(1) 50.73(a)(2)(v) OTHER (Specify in Abstract below and in Text, NRC Form LEVEL (10) 01919 20.405(a)(1)(ii) 50 36(e)(2) 50.73(a)(2)(vii) 20.406(a)(1)(iii) 50.73(a)(2)(viii)(A) 50.73(a)(2)(i) 20.405(a)(1)(iv) 80.73(a)(2)(ii) 50 73(a)(2)(viii)(8) 20.406(a)(1)(v) 50 73(a)(2)(iii) 50.73(a)(2)(x) LICENSEE CONTACT FOR THIS LER (12) TELEPHONE NUMBER NAME AREA CODE R.W. Stanley 71117 5 | 4 | 2 | - | 3 | 9 | 3 | 0

ABSTRACT (Limit to 1400 spaces | e. approximately fifteen single-space typewritten lines) (16)

MANUFAC TURER

On January 19, 1985, at 1655, the Unit 2 Reactor scrammed on Turbine Control Valve Fast Closure which was a result of a Main Turbine Trip on High Vibration. No Emergency Core Cooling System actuations or Primary Containment Isolation occurred, and none were required. Throughout the transient all safety systems performed as designed, and the Unit responsed as predicted.

X NO

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE SYSTEM

COMPONENT

REPORTABLE TO NPROS

EXPECTED

YEAR

Surveillance SO-293-001, Weekly Turbine Overspeed Protection System Valve Cycling Test, was being performed in conjunction with Hot Functional Test HF-293-068, which required Turbine Control Valve Testing to be done at 100% power. During the performance of the test the #1 Control Valve was closed. Approximately 20 seconds after the valve closed, the Main Turbine tripped.

The Unit was restarted at 0523 on January 20, 1985.

SUPPLEMENTAL REPORT EXPECTED (14)

*Not Applicable.

8502260473 850219 PDR ADDCK 05000388 PDR

CAUSE

*

SYSTEM

COMPONENT

YES III yes complete EXPECTED SUBMISSION DATE

NRC Form 366A (9-83)	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION					U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85					
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBER (6)					PAGE (3)			
The second second second second second	Steam Electric Station		YEAR		SEQUENTIAL NUMBER		REVISION				
Unit 2		0 5 0 0 0 3 8 8	815	_	01013	_	010	012	OF	0 2	

TEXT Iff more space is required use additional NRC form 366A's [117]

and the unit responded as predicted.

Susquehanna Steam Electric Station Unit 2 scrammed on Control Valve Fast Closure, which as the result of a Main Turbine Trip on High Vibration. The unit had been operating at 99% power. Additional automatic actions after the turbine trip were turbine stop valve closure, reactor recirculation pump trips, and main generator trips. The turbine bypass valves and the safety relief valves cycled to control reactor pressure. No emergency core cooling system actuations or primary containment isolations occurred and none were required. Throughout the transient all safety systems performed as designed

SO-293-001, Weekly Turbine Overspeed Protection System Valve Cycling Test, was being performed in conjunction with HF-293-068, Maximum Power Level for Turbine Valve Surveillance Determination. This test is a portion of the Power Ascension Testing and requires the turbine control valve testing be done at 100% power. The valve testing consisted of cycling each individual main stop valve, combined intermediate valve and control valve closed one at a time, and checking plant instrumentation for proper response.

The testing of the main stop valves and the combined intermediate valves was completed satisfactorily. The #4 control valve was also cycled without incident and the testing of the #1 control valve was in progress. The #1 valve was closed and, in accordance with the procedure, the plant control operator was waiting 15 to 25 seconds before reopening the valve to allow the main turbine to stabilize. Approximately 20 seconds after the valve closed, the main turbine tripped.

The reactor scram was the direct result of the main turbine tripping on high vibration during turbine control valve testing. Examination of process computer historical data shows that during the test of the #4 control valve, bearing vibration did not increase. However, during the test of the #1 valve, vibration on the #1 and #2 bearings increased significantly. The #1 bearing vibration peaked at 9.9 mils., just before the turbine trip. The calibration of the #1 turbine bearing trip setpoints was checked and found to be within tolerance.

The combination of reduced overall turbine vibration after the rebalancing and the procedure cotrols of SO-293-001 should reduce the risk of subsequent turbine trips.

The Unit was restarted at 0523 on January 20, 1985.



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

February 19, 1985

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 85-003-00 ER 100450 FILE 841-23 PLAS-041

Docket No. 50-388 License No. NPF-22

Attached is Licensee Event Report 85-003-00. This event was determined reportable per 10CFR50.73(a)(2)(iv), in that automatic actuation of the Engineered Safety Feature (ESF) occurred due to Main Turbine High Vibration.

H.W. Keiser

Superintendent of Plant-Susquehanna

RWS/pjg

cc: Dr. Thomas E. Murley
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Mr. R.H. Jacobs Senior Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 52 Shickshinny, PA 18655

IEZZ