

REVIEW OF WATERFORD III BASEMAT ANALYSIS

Structural Analysis Division
Department of Nuclear Energy
Brookhaven National Laboratory
Upton, NY 11973

April 16, 1984

8502270238 840820
PDR FOIA
GARDE84-455 PDR

TABLE OF CONTENTS

	Page No.
INTRODUCTION	1
GENERAL COMMENTS	2
STRUCTURAL ANALYSIS TOPIC REVIEWED	3
1. Dead Loads	3
2. Buoyancy Forces	5
3. Variable Springs Used For the Foundation Modulus	6
4. Vertical Earthquake Effects	6
5. Side Soil Pressure	7
6. Boundary Constraints	7
7. Finite Element Mesh and Its Effect	8
CONCLUSIONS AND RECOMMENDATIONS	8
APPENDIX A LIST OF CONTRIBUTORS	A-1

INTRODUCTION

At the request of SGEB/NRR, the Structural Analysis Division of the Department of Nuclear Energy at BNL undertook a review and evaluation of the HEA Waterford III mat analysis documented in Harstead Engineering Associates (HEA) Reports, Nos. 8304-1 and 8304-2. Both reports are entitled, "Analysis of Cracks and Water Seepage in Foundation Mat". Report 8304-1 is dated September 19, 1983, while Report 8304-2 is dated October 12, 1983. Major topics addressed in the first report are:

- (1) Engineering criteria used in the design, site preparation and construction of the Nuclear Power Island Structure basemat.
- (2) Discussion of cracking and leakage in the basemat.
- (3) Laboratory tests on basemat water and leakage samples.
- (4) Stability calculations for the containment structure.

The second report concentrates on the finite element analysis and its results. Specifically, it describes:

- (1) The geometric criteria and finite element idealization.
- (2) The magnitude and distribution of the loads.
- (3) The final computer results in terms of moments and shear versus the resistance capacity of the mat structure.

Supplemental information to these reports were obtained at meetings held in Bethesda, MD, on March 21 and 26, 1984, at the Waterford Plant site in Louisiana on March 27, 1984, and at Ebasco headquarters in New York City on April 4, 1984. At the close of the EBASCO meeting, a complete listing of the HEA computer run was made available to BNL.

Because of the very short time interval assigned for the review and preparation of this report (i.e., April 4-13, 1984), it was decided to concentrate the BNL efforts on the review of the results presented in report no. 8302-2 and on the supplemental information contained in the computer run given to us by HEA. This run contains 9 load cases and their various combinations. The input/output printout alone consists of roughly two thousand pages of information and thus only selected portions could be reviewed with some detail. The other sections were however reviewed from an engineering judgement view point. Comments regarding the reviewed work are given in the sections that follow.

GENERAL COMMENTS

Basically, the HEA report concludes that large primary moments will produce tension on the bottom surface of the mat. For this condition, it is shown that the design is conservative. Furthermore, the shear capacity vs. the shear produced by load combinations are concluded to be adequate although a few elements were found to be close to the design capacity. Accordingly, the cracking of the top surface is attributed to "benign" causes such as shrinkage, differential soil settlement, and temperature changes.

BNL says
it. Why
not SGEB

Based on the discussions held with EBASCO and HEA, and on the review of data given to BNL, it is our judgement that the bottom reinforcement as well as the mat shear capacity is adequate. The statement that the cracking of the top surface is attributable to "benign" causes however has not been analytically demonstrated by HEA. In the BNL review of the reports and data, an attempt was made to ascertain the reasons for the existing crack patterns that appear around the outside of the reactor shield building as depicted in Figure D-1 Appendix D of the HEA Report 8304-2. Other effects influencing the structural behavior and safety were also investigated. Specifically, the structural analysis topics reviewed in more detail include:

SSE
not in
here ?

- (1) Dead loads and their effects.
- (2) Buoyancy forces and their effects.
- (3) Variable springs used for the foundation modulus.
- (4) Vertical earthquake effects.
- (5) The side soil pressures.
- (6) The boundary constraint conditions used for the mat.
- (7) Finite element mesh size and its effects.

STRUCTURAL ANALYSIS TOPICS REVIEWED

1. Dead Loads

As mentioned, EBASCO in their discussion and HEA in their reports have not shown analytically, the cause of the top surface cracks. In reviewing the HEA computer outputs, it was found that element moments and shears for individual loadings are explicitly given. Thus, for the case involving dead loads only, a number of elements in the cracked regions exhibit moments that can produce tension and thus create cracking on the top surface. This situation is shown in Table 1 which gives moment data for elements in some of the cracked regions. From the HEA report (page C-2-1-9) it seems that the top reinforcement, which is #11 @6" in each direction* is the minimum requirement for temperature steel according to the American Concrete Institute Building Code

*In a subsequent phone conversation, P.C. Liu of EBASCO stated that some additional reinforcement was added on the top surface in one direction. Even if this is the case the statement that follows is true for the unstrengthened direction and perhaps even for the strengthened direction.

TABLE 1

ELEMENT	Mx		My		Mxy		Normal Pressure Side Pressure			
	D	B	D	B	D	B	Mx	Mx	Mxy	
Area T2-R-12M-7FH	437	-242	173	-574	197	116	- 31	-294	-196	93
	212	+644	+595	+207	+ 91	106	- 25	-663	-392	79
	211	-605	205	-412	217	-296	48	-219	-416	- 76
	207	+ 64	99	-136	136	- 81	15	-319	-193	50
	441	-105	168	+172	-170	39	- 12	-347	-489	66
	436	-719	269	-1193	357	+531	-130	-274	-258	117
	438	269	142	-159	158	- 60	26	-730	-347	27
	447	665	59	210	88	248	- 55	-653	-339	-127
	204	193	87	569	72	-143	28	-361	-420	24
	208	350	32	898	- 24	-241	75	-354	-771	- 49
	203	-676	260	-995	236	39	- 21	-574	-247	30
	426	-542	157	-705	310	332	- 65	-171	-486	61
Area R-P-2M-1A	259	62	148	-133	81	+154	- 36			
	253	5	71	531	+ 75	0	18			
	255	30	58	670	5	41	10			
	252	86	24	611	- 55	87	8			
	254	50	26	412	- 41	69	9			
	251	37	5	162	- 23	44	12			
	257	320	- 38	57	15	- 81	- 15			
	248	255	- 26	29	16	- 29	- 6			
	267	-236	80	87	118	- 64	28			
269	-173	59	434	10	- 82	32				
Area R-PI-12A-9M	419	-314	137	-635	313	- 30	12			
	410	-371	71	-642	238	270	- 29			
	400	-315	108	-774	275	- 44	41			
	401	-180	42	-201	102	+108	- 23			
	414	-304	118	-130	178	+ 44	- 19			
	417	-200	93	440	41	- 17	- 15			
	404	- 64	17	428	- 32	98	- 18			

NOTE: D - Dead Load

B - Bouyancy

Specification (i.e., $A_s = .0018 \times 12 \times 144 = 3.11 \text{ in}^2/\text{ft}$). The resisting moment capacity based on working stress design is about $M = A_s f_s j d = 3.12 \times 24 \times 131/12 = 817 \text{ ft-kips/ft}$. The steel reinforcement strain for this moment is equal to

$$\epsilon_s (= \epsilon_c) = \frac{f_s}{E_s} = \frac{24}{29,000} = 0.00083 \text{ in/in}$$

while, the corresponding concrete stress is,

$$f_c = \epsilon_c E_{s/n} = 0.00083 \left(\frac{29,000}{8} \right) = 3 \text{ ksi}$$

In checking the data in Table 1, it can be seen that element 208 has exceeded the working load capacity under the dead load condition and, thus the local area could have exhibited a crack when this load acted alone. Similarly, concrete cracking could occur under this load condition in elements 447, 212, 204, 253, 255, 269, 257, 417, and 404. Thus, the cracks on the upper surface outside of the shield wall could have been initiated after construction of the superstructure, before placement of the backfill. It should be noted that since no analysis is available for dead load without the superstructure, the reason for the basemat cracks inside of the shielded wall cannot be explained by this reasoning.

what does this mean to safety of basemat

2. Buoyancy Forces

The moment results from this analysis show that these forces when acting alone would mostly cause tensile stress on the upper surfaces. The moments causing these stresses are tabulated in Table 1 for groups of elements in the cracked regions. As can be seen, these moments are not as severe as those due to dead weight. By superposition they could in some cases contribute to higher tensile stresses and thus result in further cracking in some of the upper surface areas.

3. Variable Springs Used for the Foundation Modulus

Moments and shears developed in the basemat were computed using the concept of the Winkler Foundation; namely the soil is represented as a series of relatively uniform independent springs. The stiffness of the springs is obtained from relatively crude analyses which are based on some generalized analytic solutions available for rigid mats on the surface of elastic soils. The actual design of the mat was based on a series of interactive computer runs in which the soil stiffness was varied until the computed contact pressures under the mat were fairly uniform and equal to the overburden stress at the elevation of the foundation mat. This approach appears to be reasonable in that the long term consolidation effects can be anticipated to cause effective redistribution of loads and cause the mat to behave in a flexible manner.

4. Vertical Earthquake Effects

- awaiting info from BNL? No. 4-7

Vertical earthquake effect was not discussed in the HEA reports. However, from the finite element analysis print out and the conversation with HEA engineers, it was told that this effect was included in the load combination cases by specifying an additional factor of 0.067, which was then applied to the dead and equipment load case. From the discussions and the review BNL is not clear whether an amplification factor due to vertical mat frequency was used or not. A quick check by the reviewers indicates that this factor could have some influence on the results.

Horizontal earthquake effects were input into the HEA finite element analysis as an equivalent bending moment and in plane (fx_2) shear acting on the pertinent nodes of the foundation mat. The reviewers however, are not certain whether the dynamic interaction effects between the superstructure and the mat were accounted for in the analysis, nor are they certain about its importance in effecting the results.

5. Side Soil Pressure

According to the STARDYNE computer results obtained from HEA, the normal side soil pressures produce large moments that are opposite to those caused by the dead loads. As shown in Table 1 where moments of elements located in one of the cracked regions outside of the shield building are compared. The total

moments in some cases (i.e. element 447 or 208) become quite small. In other regions there is infact a reversal in the total bending moment which causes tension on the bottom surface and compression on the top. This compression would tend to close the cracks on the upper surface. Thus, it appears that this pressure is a very important load case for the mat.

For the static or normal operating condition the lateral pressures are based on the at-rest stress condition and are uniform around the periphery of the structure. For the seismic problems the pressures are computed to approximately account for relative movements between the structure and the soil. On one side the structure will move away from soil (active side) and reduce the pressures while the opposite will occur on the other side (passive side). The actual computations made use of triaxial test data from site soils to arrive at the soil pressures rather than use the standard Rankine analyses. However, no dynamic effects on either the lateral soil or pore pressures was included. The sensitivity of the calculated responses to these effects are currently unknown. Since the lateral pressures have a major impact on the computation stresses in the mat the dynamic effects can significantly influence the stresses computed in load combination studies.

6. Boundary Constraints

For equilibrium calculations no special consideration need be made for vertical case since the soil springs prevent unbounded structural motion. However, the same cannot be said for the horizontal case since soil springs are not used to represent the soil reactions. Rather the lateral soil forces are directly input to the modal. To prevent unbounded rigid body motion artificial lateral constraints must be imposed on the model. From the output presented in the EBASCO and HEA reports, it is not possible to evaluate the impact of these assumptions. The stresses caused by the artificial boundaries must be calculated and compared with those presented.

7. Finite Element Mesh and its Effects

In general finite element models for plate structures require at least four elements between supports to obtain reasonable results on stress computations. The models used by both EBASCO and HEA violate this condition in the vicinity of the shield wall. The significance of this effect is demonstrated in Figure D-3 which presents a plot of moment taken through the center of the slab. The computed moments in adjacent elements 193, 194 and 455 are -3800, -2500 and +400K. The elements used in the EBASCO analysis are constant curvature elements so that the computed moments will be constant within each element. The steep moment gradient in the elements listed indicates that a finer mesh would be required to obtain a better representation of element stresses. A similar effect was also noted when investigating the elements forming the junction between the lateral earth retaining walls and the base mat. In general, it is felt that the finite element grid used for the structural modeling is too coarse.

CONCLUSIONS AND RECOMMENDATIONS

- (a) The Waterford plant is primarily a box-like concrete structure supported on a 12 foot thick continuous concrete mat which houses all Class 1 structures. The plant island is supported by relatively soft over consolidated soils. To minimize long term settlement effects, the foundation mat was designed on the floating foundation principle. The average contact pressure developed by the weight of the structure is made approximately equal to the existing intergranular stresses developed by the weight of the soil overburden at the level of the bottom of the foundation mat. Thus, net changes in soil stresses due to construction and corresponding settlements can be anticipated to be relatively small.

- (b) In reviewing the information reports and computer outputs supplied to BNL by EBASCO, HEA, and LPL, it is concluded that normal engineering practice and procedures used for nuclear power plant structures were employed.
- (c) Accepting the information pertaining to loadings, geometries of the structures, material properties and finite element idealization as correct, it is the judgement of the reviewers:
 - (i) that the bottom reinforcement as well as the shear capacity of the base mat are adequate for the loads considered.
 - (ii) that computed dead weight output data can be used to explain some of the mat cracks that appear on the top surface. The cracks that appear, would have occurred after the construction of the superstructure but before the placement of the backfill. Their growth would be constrained by subsequent backfill soil pressure.
- (d) Due to the existence of the cracks, it is recommended that a surveillance program be instituted to monitor cracks on a regular basis. Furthermore, an alert limit (in terms of amount of cracks, and or crack width, etc) should be specified. If this limit is exceeded, specific structural repairs should be mandated.
- (e) It is also recommended that a program be set up to monitor the water leakage and its chemical content.
- (f) The validity of the BNL conclusions depend mainly on the information supplied by EBASCO, HEA and LPL, either verbally, in reports or in computer outputs. While some checks for accuracy and engineering approach were made pertaining to the supplied information some open questions still remain, especially those mentioned in the text under topics 4 thru 7 under the heading, "Structural Analysis Topics Reviewed". It is recommended that the particular issues raised under these items be resolved.

Since the Waterford plant is located in a low seismicity zone, there is a low likelihood of occurrence of an SSE and its associated effects. Thus, although the inherent safety margins in the design of the basemat are as yet unquantified (due to cracking effects and the other items mentioned above), they seem to be sufficiently adequate to permit the performance of a confirmatory evaluation for their resolution in the near future.