To:

James P. O'Reilly
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Prom:

Jersey Central Power & Light Company Oyster Creek Nuclear Generating Station, Docket #50-219 Forked River, New Jersey 08731

Subject:

Abnormal Occurrence Report No. 50-219/74/33

The following is a preliminary report being submitted in compliance with the Technical Specifications paragraph 6.6.2.

Preliminary Approval:

J. T. Carroll, Jr. Date

cc: Mr. A. Giambusso

BK35

	0		
Initial Tolephone Report Date:	5/22/74	Date of Occurrence:	5/21/74
Initial Written Report Date:	5/22/74	Time of Occurrence:	1530
		CLEAR GENERATING STATER, NEW JERSEY 08731	TION
		mal Occurrence o. 50-219/74/ 33	
IDENTIFICATION OF OCCURRENCE:	Violation of the Technical Specifications, paragraph 3.4.B.4, when it was observed that both auto-depressurization system initiation timers, 16M232A and 16M232B, failed to complete their timing sycle in less than two minutes.  This event is considered to be an abnormal occurrence as defined in the Technical Specifications, paragraph 1.15B & D.		
CONDITIONS PRIOR TO OCCURRENCE:	Steady State Hot Standby Cold Shutdon X Refueling State Routine State Operation	vn Lo nutdown Ro	utine Shutdown eration ad Changes During utine Power Operation her (Specify)
	The reactor mode switch was in REFUEL with the cavity		
	flooded.		

DESCRIPTION

OF OCCURRENCE:

Mhile performing the annual automatic initial test of the autodepressurization system, it was observed that both system
initiation timers, 16M232A and 16M232B, completed their cycle
in 169 seconds and 127 seconds, respectively, which is greater
than the maximum allowable of 120 seconds. The timers act to
delay the opening of the valves and the subsequent depressurization of the reactor vessel for a time riod of 120 seconds after

8102190760 38

receiving coincident triple low reactor water level, high drywell pressure, and 230 psig at the discharge of one core spray
booster pump signals. The timers may be manually recycled by the
operation of a keylock reset switch located on Panel 1P/2F in
the control room in the event of spurious initiation. It should
be noted that system initiation will occur as soon as any one
timer completes its cycle.

APPARENT CAUSE OF OCCURRENCE:

Design
Namufacture
Installation/
Construction
Operator

Procedure
Unusual Service Condition
Inc. Environmental
Component Failure
Other (Specify)

The cause of the occurrence is presently under investigation.

ANALYSIS OF OCCURRENCE: The auto-depressurization system is required to depressurize the reactor vessel to less than 285 psig in the event of a small break design bases LOCA. In this event, it is possible for the reactor pressure to remain above the core spray permissive level with a continued loss of reactor coolant inventory until such time as the auto-depressurization system initiates. System initiation would have been delayed by approximately seven seconds had it been required to function as part of the ECCS.

The significance of this delay is under investigation.

CORRECTIVE ACTION:

1 destantitues

The timers were reset and were observed to time out in less than two minutes. The results of which were: 160232A, 117 seconds; 16N232B, 120 seconds.

. . . .

FAILURE DATA:

Type: GE CR120 KT Delay Unit

Model: 02241AA

Range: 0-5 minute adjustable

Proposed by: athur & Rome

635A

Date:

9.0

5/22/74