RC Form +831	386									LIC	ENSE	EEVE	ENT	RE	PORT	LER)			U.S.	APP	ROV	REGULA ED OMB 5 8/31/85	NO 3		
	NAME IT		+ 1	Ini	+ 3		-											1			ER 12		2, 5,	7		0
ITLE IAI		om		лц														0	5	0	0	01		4	1 OF	1 1
Eng	gineer	ed	Sal	let	y Fe	atu	res	A	ctu	ation	- Rea	actor	T	rip/1	Furbin	e Tri	ip wi	th F	ov	ver	Ab	ove	e P-7			
EVE	NT DATE	(5)	T	-	L	ER N	MBE	R (6	1)	-	REP	ORTDA	TE (7	1 1			OTHE	RFAC	ILIT	IES IN	VOLV	ED (8)			
MONTH DAY YEAR YEAR SEA				SEGU	MBE	AL		REVISION NUMBER	MONTH DAY Y		Y	EAR			AMES			DOCKET NUMBER(S)								
			-												N/A			1				0 5 0 0 0 1				11
0 1	1 9	8	5	8	5 -	0	0	3	-	qo	0 2	1 9	8	5	N/A	1						0 1	5101	0	01	1.1
OPE	RATING	1		THIS	REPORT	15 5	BMI	TTEC	PUR	SUANT	TO THE RE	QUIREN	AENT	S OF 10	CFR \$: 10	theck on	e or mor	e af th	e foi	lowing	/ (11)					
MODE INI N POWER LEVEL (10) 0 1 0			0		20.402(b) 20.405(a)(1)(i) 20.405(a)(⁴)(ii) 20.405(a)(³)(iii) 20.405(a)(1)(iv) 20.405(a)(1)(v)					20.405(c) 50.36(c)(1) 50.36(c)(2) 50.73(a)(2)(i) 50.73(a)(2)(ii) 50.73(a)(2)(iii)				50.73(a)(2)(iv) 50.73(a)(2)(v) 50.73(a)(2)(vi) 50.73(a)(2)(vii) 50.73(a)(2)(viii)(A) 50.73(a)(2)(viii)(B) 50.73(a)(2)(viii)(B) 50.73(a)(2)(viii)(B)					73,71(b) 73,71(c) OTHER (Specify in Abstract below and in Taxt, NRC Form 366A)							
				_	10.400		-				ICENSEE		TFO	R THIS	LER (12)				-							
R. L. Teuteberg, Regulation and Compl					olianc	e En	gin	eer					ARE 3		DE	ELEP 2	4 5	IMBE	R 2, 9	14						
				-			_								DESCRIBE	D IN TH	IS REPO	DRT (1	3)	-	-	-		-		<u> </u>
CAUSE	SYSTEM COMP		MPO	NEN	, ,	MANUFAC TURER			REPORTABLE TO NPRDS					CAUSE	SYSTEM	COMPONENT		MANUFAC				ORTABL	E			
	1	1	1			i.	1								1		11		1	i	1					
			-	-		s	UPPLI	EME	NTAL	REPORT	EXPECTE	D (14)						+	+	+	+	-	MON	TH	DAY	YEAR
YES III yes, complete EXPECTED SUBMISSION DATE!							XI NO				EXPECTED SUBMISSIO DATE (15					+										

On January 19, 1985, at 5:25 a.m., with Unit 3 at 10% power descending from full power to hot shutdown per OP 0205.1, Unit Shutdown - Full Load to Hot Shutdown Condition, due to a suspected condenser tube leak, Permissive P-7 disarmed at 6:46:06 when power was reduced below 10% but rearmed at 6:46:10 due to a slight power increase. Not realizing that P-7 had rearmed, the turbine was manually tripped to prevent Tave from decreasing enough to cause a safety injection signal. The reactor tripped due to a turbine trip with power above P-7. Off-normal operating procedure 0208.1, Shutdown Resulting from a Reactor Trip or Turbine Trip, was initiated and a post-trip review performed. All equipment functioned as designed on initiation of the Engineered Safety Feature Actuation Signal. The USNRC was notified of a Significant Event pursuant to 10CFR50.72(B)(2)(ii) via ENS at 8:44 a.m. The health and safety of the public were not affected. Similar occurrences: LER 250-84-008.

Cause of Event:

The reactor trip was caused by personnel oversight by tripping the turbine with power above Permissive P-7.

Corrective Actions:

Reactor operators will be instructed on this event in requalification class and instructed to pay close attention to permissive P-7 when manually tripping the turbine during power reduction. E22

	the second s	850219 05000250 PDR
0		FDR



FEB 1 @ 1985

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gentlemen:

:

Re: Reportable Event 85-03 Turkey Point Unit 3 Date of Event: January 19, 1985 Engineered Safety Features Actuation -Reactor Trip/Turbine Trip with Power Above P-7

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR to provide notification of the subject event.

Very truly yours,

ulicius }

J. W. Williams, Jr. Group Vice President Nuclear Energy

JWW/SAV/js

Attachment

cc: Dr. J. Nelson Grace, Region II, USMRC Harold F. Reis, Esquire File 933.1 PNS-LI-85-070-1

IEZZ II