

TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant  
Post Office Box 2000  
Soddy Daisy, Tennessee 37379

October 26, 1984

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555


Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET NO.  
50-328 - FACILITY OPERATING LICENSE DPR-79 - SPECIAL REPORT 84-05

The enclosed special report provides information concerning a penetration fire barrier being nonfunctional for a period in excess of seven days. This report is reported in accordance with Sequoyah Unit 2 Technical Specifications 3.7.12 and 6.9.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



P. R. Wallace  
Plant Manager

Enclosure  
cc (Enclosure):

James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30323

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

NRC Inspector, NUC PR, Sequoyah

8411090351 841026  
PDR ADOCK 05000328  
S PDR

IE22  
/1

SPECIAL REPORT 84-05

SEQUOYAH NUCLEAR PLANT

UNIT 2

Event Description and Probable Cause

The biological shield blocks have been removed from unit 2 reactor building equipment hatch for the unit 2 refueling outage. This condition has been identified as a breach of a fire barrier penetration and will remain nonfunctional for the duration of the refueling outage.

Corrective Actions

Proper procedures for breaching fire barrier penetrations are being followed which include verification of fire detector operability and establishment of an hourly fire watch as required by the action statement of LCO 3.7.12.

The fire barrier will be restored at the completion of the refueling outage which is presently scheduled to be completed in late 1984.