



LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-313/82-005/03X-1

Occurrence Date: 2/27/82

Cause Description and Corrective Actions (Continued)

from inadequate turbocharger lubrication during certain repeat start conditions following a hot shutdown from a previous engine run. Under these conditions, turbocharger lubrication oil systems could have lost sufficient "prime" oil supply leading to delayed pressure buildup. The cumulative wear, which would have been minimized with continual oil supply, led to the components failure. Final corrective action was completed on 4/8/84, with the completion of a design change to the engine lubrication systems. With this design change, lubricating oil is continuously supplied to engine components necessary to support an emergency start under initial and repeat start conditions.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

October 31, 1984

1CAN108411


U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 1  
Docket No. 50-313  
License No. DPR-51  
Licensee Event Report  
No. 82-005/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2.(b), attached is the subject report concerning the failure of diesel generator No. 2 to start during its monthly surveillance test. This is an update to a previous submittal dated March 23, 1982.

Very truly yours,

  
J. Ted Enos  
Manager, Licensing

JTE:RJS:ac

Attachment

cc: Mr. Richard C. DeYoung  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Norman M. Haller, Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

IE22  
1/1