LICENSEE EVENT REPORT

EXHIBIT A

NRC Form 366 (9-83)

U.S. Nuclear Regulatory Commission Approved OMB No. 3150-0104

Expires: 8/31/85

LICENSEE EVENT REPORT (LER)

| TITLE (4) | | nsas Nuclear O | | | | | 101510 | T NUMBER (2) 0000 3 1 3 3 | 1 0F 0 |
|---|----------------------------------|-----------------------------|---|-----------------------|--------------------------------|--|--------------------|--|---------|
| | Reactor Tri | p Caused by Los | ss of 6.9 KV | Bus | | | | | |
| EVENT DATE | (5) | (6) | REPORT DAT | E (7) T | OTHER FACILITIES INVOLVED (8) | | | | |
| Month Day | Year Year | | | Month Day | Year | | ty Names | Docket Num | |
| UPERATING | 81 41 81 4 1THIS REPO | 0 0 5 RT IS SUBMITTE | | 1 0 2 6 | 8 4 8 4 | | | 10151010101 | |
| MODE (9) POWERI | N (Check _ 20.402(t | one or more of | the following 20.405(c) | ng) (11) | | | | 2 21/-5 | |
| LEVEL (10) 0 8 5 | 20.405(a 20.405(a 20.405(a | a)(1)(i) | 50.36(c)(50.36(c)(50.73(a)(50.73(a)(50.73(a)(| 2) 2)(i) 2)(ii) | 50. 50. 50. 50. | 73(a)(2)(iv 73(a)(2)(v) 73(a)(2)(vi 73(a)(2)(vi 73(a)(2)(vi 73(a)(2)(x) | ii)(A) ii)(B) | 73.71(b) 73.71(c) Other (Specif Abstract belo in Text, NRC 366A) | w and |
| Name | | | LICENSEE CON | | HIS LER | (12) | | | |
| Patrick Ro | gers, Plant | Licensing Engi | neer | NENT EATTIN | DE NECON | TOPO THE PLAN | | Telephone N Area Code 5 0 1 9 6 4 - | |
| ause Syste | | Manufacturer | Reportable | | | | | Reportable rer to NPRDS | |
| | LIL | 1.11 | | | | 1.1.1 | 1 1 1 1 | | |
| | | SUPPLEMENT REP | ORT EXPLCTED | (14) | | 111 | I L I I I EXPECTED |) Month! Day | IVA |
| I Yes (If yes, complete Expected Submission Date) $ \vec{x} $ No ABSTRACT (Limit to 1400 spaces, i.e., approximatel, fifteen single-space typewri | | | | | | | SUBMISSIO |)N | / Year |

On 10/5/84, at 0924 hours while at 85% full power (FP), an automatic reactor trip occurred as a result of loss of power to two Reactor Coolant Pumps (RCPs). A contractor janitor accidentally bumped the handswitch on the feeder breaker from the unit auxiliary transformer to 6.9 KV bus Hl. When the breaker opened, power was lost for RCPs P-32A and P-32C. This caused a "power-to-pumps" reactor trip to be generated by the Reactor Protective System (RPS) since reactor power level was greater than that permissible for two RCP operation. Forced flow was maintained by RCP's P-32B and P-32D powered by bus H2. RCP's P-32C and P-32A were restarted at 1118 hours and 1158 hours, respectively. Emergency Feedwater (EFW) pump P-7A started automatically during post-trip recovery. Manual control of EFW was taken to maintain steam generator level until auxiliary feedwater was placed in performed satisfactorily during trip recovery. Additional access control for the area where the affected switchgear is located is being applied.

8411130185 841026 PDR ADDCK 05000313 S PDR

TEN



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000 October 26, 1984

1CAN1Ø84Ø9

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 1

Docket No. 50-313 License No. DPR-51 Licensee Event Report

No. 84-005-00

Gentlemen:

In accordance with 10CFR50.73(a)(2)(iv), attached is the subject report concerning an automatic reactor trip which occurred as a result of loss of power to two reactor coolant pumps.

Very truly yours,

A. Ted Enos

Manager, Licensing

JTE: RJS: ac

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Norman M. Haller, Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, DC 20555

IEZZ