



LICENSEE EVENT REPORT

EXHIBIT A

ATTACHMENT

LER NO. 50-368/79-047/04X-1

Cause Description and Corrective Actions (Continued)

2RE-0645 was satisfactorily tested after modification. The system was returned to service on 03/11/82. No detector failures due to moisture have been observed since the completion of the modification.



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000  
February 25, 1985

2CANØ28518

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report  
No. 79-047/04X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Environmental Technical Specification 5.6.2.b, attached is the subject report concerning the failure of condenser vacuum pump radiation monitors 2RE0645 and 2RE0646. This is an update to a previous submittal dated July 27, 1979.

Very truly yours,

J. Ted Enos  
Manager, Licensing

JTE:RJS:ds

Attachment

cc: Mr. Richard C. DeYoung  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Norman M. Haller, Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

IE23  
1/1