

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) <b>EDWIN I. HATCH, UNIT II</b>	DOCKET NUMBER (2) <b>0 5 0 0 0 3 6 6</b>	PAGE (3) <b>1 OF 0 2</b>
---	---	-----------------------------

TITLE (4)  
**Inoperable RHR Service Water Pumps**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
1	0	6	8	4	0	1	1	0			0 5 0 0 0
1	0	6	8	4	0	1	1	0			0 5 0 0 0

OPERATING MODE (9) <b>1</b>	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)									
POWER LEVEL (10) <b>Q 7 5</b>	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
	<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)						
	<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
	<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)								

LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER	
NAME	AREA CODE	NUMBER	
<b>T. L. Elton, Acting Superintendent of Regulatory Compliance</b>	<b>9 1 2</b>	<b>3 6 7 1 7 8 5 1 1</b>	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS
A	B I P		J I I O	5 N					
A	B I P		J I I O	5 N					

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 10/06/84, during an attempt to perform preventive maintenance for Unit One's RHR Service Water pumps (1E11-C001B and 1E11-C001D), plant personnel mistakenly disconnected the motor leads for Unit Two's RHR Service Water pumps (2E11-C001B and 2E11-C001D). Plant personnel had disconnected 2 of 3 motor leads for RHR Service Water pump 2E11-C001B when they discovered this event. An LCO and an equipment clearance were then initiated for the pumps and plant personnel immediately began to reconnect the pumps' motor leads.

This event is the result of personnel error. The involved personnel were counseled by supervision.

The motor leads for 2E11-C001B and 2E11-C001D were reconnected and Hipotted. 2E11-C001B and 2E11-C001D were then returned to service on 10/06/84 (approximately 6 1/2 hours after the event occurred).

8411160001 841105  
PDR ADOCK 05000366  
S PDR

IE22  
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  EDWIN I. HATCH, UNIT II	DOCKET NUMBER (2)  0 5 0 0 0 3 6 6 8 4	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 4	0 2 2	0 0 0	2	OF 2

TEXT (If more space is required, use additional NRC Form 365A's) (17)

This 30 day LER is required by 10CFR50.73 (a)(2)(v).

On 10/06/84, with the reactor mode switch in the run position, during an attempt to perform preventive maintenance on Unit One's RHR Service Water Pumps (1E11-C001B and 1E11-C001D), plant personnel mistakenly disconnected the motor leads for Unit Two's RHR Service Water Pumps (2E11-C001B and 2E11-C001D). Plant personnel had disconnected 2 of 3 motor leads for RHR Service Water pump 2E11-C001B when they discovered this event. An LCO and an equipment clearance were initiated immediately and plant personnel reconnected the pumps' motor leads.


The redundant "A" loop of RHR Service Water remained operable during this event. No actual or potential safety consequences or implications resulted from this event.

This event had no impact on any other Unit 2 system or on Unit 1. The health and safety of the public were not affected by this non-repetitive event.

This event is the result of personnel error. The involved personnel were counseled by supervision.

The motor leads for 2E11-C001B and 2E11-C001D were reconnected and then Hipotted per the "HI POTENTIAL TESTING OF PLANT EQUIPMENT" procedure (HNP-6920). 2E11-C001B and 2E11-C001D were returned to service on 10/06/84 (approximately 6 1/2 hours after the event occurred).

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444




Edwin I. Hatch Nuclear Plant

November 5, 1984  
GM-84-981

PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-366

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-366/1984-022. This report is required by 10CFR 50.73(a)(2)(v).

  
H. C. Nix  
General Manager

HCN/TLE/vlz

xc: R. J. Kelly  
R. E. Conway  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
Superintendent of Regulatory Compliance  
R. D. Baker  
Control Room  
Document Control

IE 22  
1/1