

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Fort St. Vrain, Unit No. 1 DOCKET NUMBER (2) 050002671 OF 12 PAGE (3) 1

TITLE (4) High Reactor Pressure Scram & Ensuing Control Rod Automatic Insertion Failures

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER(S)		
06	23	84	84	008	01	10	03	84	N/A	05000		

OPERATING MODE (9) N

POWER LEVEL (10) 0.23

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50.73 (Check one or more of the following) (11)

<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input checked="" type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 50.73(a)(2)(vi)	<input type="checkbox"/>
<input type="checkbox"/> 50.73(a)(2)(vii)(A)	<input type="checkbox"/>
<input type="checkbox"/> 50.73(a)(2)(vii)(B)	<input type="checkbox"/>
<input type="checkbox"/> 50.73(a)(2)(viii)	<input type="checkbox"/>

OTHER (Specify in Abstract below end in Text, NRC Form 300A)

LICENSEE CONTACT FOR THIS LER (12)

NAME: Jim Eggebrotten, Technical Services Engineering Supervisor

TELEPHONE NUMBER: 303 785-2224

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS
X	A	A	J C G	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15) 011 215 815

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 0029 on June 23, 1984, with reactor power at 23%, the Plant Protective System (PPS) initiated an automatic scram upon exceeding the floating high pressure trip point in the Prestressed Concrete Reactor Vessel (PCRV). Prior to the high pressure trip, an orderly shutdown from 40% power was in progress due to high primary coolant moisture levels following an automatic trip action on "A" helium circulator.

As the orderly shutdown and corresponding vessel depressurization were in progress, the normal depressurization flowpath became blocked causing the eventual high pressure trip. The automatic actuation of the PPS scram circuitry is being reported under Section 50.73(a)(2)(iv).

The reactor went subcritical immediately following the automatic scram action, but it was noted that 6 of the 37 control rod pairs had failed to automatically insert. The six rod pairs were driven into the core within 20 minutes following the event. The reactor remained subcritical throughout the event and the independently redundant reserve shutdown system was available as designed. The conditions of this event are under investigation to determine the potential impact on the automatic safe shutdown function of the control rod system. Therefore, this event is also being reported under Section 50.73(a)(2)(v) for its potential impact in preventing an automatic safe shutdown.

8411160029 841030
PDR ADOCK 05000267
PDR
S

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Fort St. Vrain, Unit No. 1	DOCKET NUMBER (2) 0500026784	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0	10	8	0	12 OF 12

TEXT (If more space is required, use additional NRC Form 368A's) (17)

BACKGROUND: (Fort St. Vrain FSAR Section 3.8)

The control rod drives (CRD) are essentially electrically powered winches, which raise and lower the control rods by means of flexible steel cables. Gravitational force acts to propel the control rods into the core during a scram, the free-fall speed being controlled by a velocity limiting system (Figure 1). All control rod drives are of identical design and have the same operating characteristics.

The control rod drive mechanism operates in a helium environment within the PCRV at reactor pressure (Figure 2). Ambient temperature is nominally maintained at approximately 150 degrees Fahrenheit by the refueling penetration cooling system and a thermal barrier between the drive and the reactor core. Shielding, interposed between the drive and the reactor core, limits the radiation level at the control rod drive to approximately 1 rad per hour. A helium purge flow of about 5.5 pounds per hour floods the drive assembly and reduces the ingress of contaminated reactor helium coolant (Figure 3).

The principal components of the control rod mechanism are the drive motor, motor brake, reduction gearing, rod position potentiometer, limit switches, limit switch cams, slack cable indication device, duplex cable drum, control rod guide tubes, and 1/4 inch diameter suspension cables.

The control rod drive raises and lowers the two control rods simultaneously by winding and unwinding the control rod suspension cables from a common drum having two winding grooves. This drum is made up of three plates which are bolted together. The two joints formed by the three plates are machined to form two deep spiral grooves. Each of the two cables is attached to its respective drum groove by an anchor swaged to the cable. The anchor rides in bushings pressed into the drum plates and is therefore able to rotate as required. The spiral grooves are machined such that each successive wrap of cable lies properly on the previous wrap. From their anchor point on the cable drum, the cables pass through a guide pulley assembly consisting of three pulleys mounted approximately 18 inches below the centerline of the drum. The guide pulleys maintain the cables at the current center distance, where they enter the radiation shield below the drive mechanism.

The control rods are electrically controlled by the shim motor and brake assembly. The shim motor and brake assembly is assembled as a unit having a single shaft and can be easily disconnected from the gear train by removing two screws. The shim motor is a 3-phase, 4-pole induction motor operating at 60 cycles, 105 volts, and approximately 1750 rpm. Attached to the motor shaft is an electromagnetic friction disc brake. The brake is spring-released when de-energized. Thus, the brake, when energized and applied, retains the control rods in a withdrawn position. When a scram is initiated, the brake is de-energized and released, allowing the rods to fall into the core under gravitational force.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Fort St. Vrain, Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 6 7 8 4 - 0 1 0 8 - 0 1 1 0 1 3 OF 1 2	LER NUMBER (5)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

A 3-phase capacitor array is permanently connected to the motor circuit; thus, when the motor is rotated under the influence of the falling rods, it functions as an induction generator supplying a capacitive-resistive load, the characteristic frequency of which determines the limiting speed of the motor and, consequently, the control rod insertion velocity. The rod velocity during a scram, in this case, is controlled at a value approximately 15% in excess of the shim speed (i.e., scram speed is about 1.25 inches per second). The initial excitation of the motor for operation as an induction generator is provided by residual magnetism built into the motor.

Rod-out and rod-in position indication is provided by cam-actuated switches. The cams are mounted on a drum which is gear-driven by the rod position potentiometer drive shaft. This shaft is directly coupled to the cable drum through a gear train and rotates as required for the full rod travel.

All bearings and gears in the drive assembly are treated with a thoroughly tested dry film lubrication technique which is essentially unaffected by the existing radiation and temperature levels. Bearings and gears are fabricated of materials proved by extensive testing to be suitable for dry film lubrication in a purified helium environment. The bearings are of a special construction compatible with such duty. Motor winding insulation is a high grade material, found by test to be necessary in a low-dielectric-strength gaseous environment; the stator windings are entirely encapsulated as an additional precaution against shorting to the frame and laminations.

With the rods in the inserted position, rod movement is initiated by applying electric power to the drive motor and simultaneously de-energizing the motor brake. The cables then begin to wind onto the drums and withdraw the rods. The limit switch cams release the rod-in switch, causing the "rod in" light on the console to be extinguished. Rod position is transmitted to the console by a potentiometer coupled directly to the drum gearing. As a precaution against loss of rod position indication, both the rod-in and rod-out limit switches and the rod position potentiometer transmitters are duplicated. Also, there are two slack cable sensing switches.

Failure or removal of both AC and DC power from any one drive will allow the rods controlled by that drive to drop into the core under the dynamic braking control of the motor and capacitor system. If the AC motor power fails and DC brake power is maintained (no scram signal), the control rods will retain their position. If DC brake power fails (no scram signal), the rods will drop into the core under dynamic braking control. The DC brake power must be maintained if the rods are to be held steady at any position other than fully inserted.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Fort St. Vrain, Unit No. 1	DOCKET NUMBER (2) 0500026784	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		08	08	01	04	OF 12

TEXT (If more space is required, use additional NRC Form 366A's) (17)

EVENT DESCRIPTION:

The sequence of events leading up to the high pressure scram began at 1404 hours on June 22, 1984, with the reactor at about 50% power. A rapid rise pressure relay on auxiliary transformer 1 tripped, resulting in a temporary loss of 480V Essential Bus 1 (until the Bus-tie breaker closed). The temporary loss of Bus 1 power resulted in a loss of normal bearing water supply to both helium circulators (A and B) in Loop 1, initiating backup bearing water (BUBW) to be supplied. The surge of BUBW caused an upset in the buffer helium system, which functions as the interface between the high pressure bearing water being supplied to the circulator shaft and the primary coolant helium. The buffer helium upset automatically tripped "A" circulator, but difficulty in setting the shutdown seal was experienced. Reactor power was manually run back to 30%, the Interlock Sequence Switch (ISS) was placed in the "low power" position, and the regulating control rod was returned to automatic control.

Several minutes later, evidence of rising primary coolant moisture levels were seen on both the Plant Protective System (PPS) Moisture Monitors and the analytical system moisture monitor in service. The analytical moisture monitor stabilized in the range of 40-70 ppm, and was subsequently monitored to establish primary coolant moisture levels.

"A" circulator was available for restart about 60 minutes after the incident started and was returned to service around 1620. The reactor power channels indicated an increase in power to about 40% due to primary system cooldown. Full circulator operation continued until about 2000, at which time the decision was made to begin an orderly shutdown on account of moisture. At this time, it became evident that the helium purification train, which is used in decreasing vessel pressure in accordance with power level, was icing up due to the high moisture levels. The turbine was tripped at 2144 with power at about 30%.

At 0029, with reactor power at 23% and being decreased, the reactor automatically scrammed on programmed vessel pressure high. Although the reactor was verified subcritical following the automatic scram, it was noted that 6 of the 37 control rods (in Regions 6, 7, 10, 14, 25, and 28) had failed to automatically insert and these were driven in over the following 20 minute interval (see Figure 4). A subsequent calculation using a computer code analysis (Gauge) verified that a shutdown margin of 0.0225 delta ρ ($K_{eff} = 0.978$) existed even with the above rods not scrammed. The Fort St. Vrain Technical Specifications consider 0.01 delta ρ to be an acceptable shutdown margin.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Fort St. Vrain, Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 6 7 8 4	LER NUMBER (4)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0 1 0 8	0 1	0 5	OF	1 2

TEXT (If more space is required, use additional NRC Form 388A's) (17)

ANALYSIS OF EVENT:

The PPS scram circuitry correctly sensed above normal pressure in the PCRV and initiated protective action as designed. However, protective action was not necessary during this condition since the high pressure was not the result of a steam generator tube or subheader rupture which would have the potential for increasing reactor pressure beyond the setting of the PCRV safety valve resulting in an unplanned radiological release. The temporary introduction of moisture through a malfunction of the backup bearing water system and the circulator shutdown seal is considered an operational concern and is under investigation.

| The icing up of the helium purification system was not abnormal under the observed | high moisture conditions. Prior to the trip, the high pressure setpoint was | decreasing as programmed with circulator inlet temperature (indicating a power | reduction). When the depressurization flow path was blocked, the trip point was | exceeded as temperature continued to decrease without a corresponding decrease in | pressure (Figure 5).

| The blockage of the on-line helium purification train caused a loss of the helium | purge flow which normally provides the control rod drive assembly with a supply of | purified helium and mitigates to some extent the upward flow rate of high | temperature, contaminated, potentially moisture-laden primary coolant helium. The | significance of a loss of purge flow coincident with high primary coolant moisture | levels has been investigated with respect to control rod operability through | recent evaluation. It has been determined that the migration of moisture from the | PCRV into the CRD motor area would not have been prevented even under full design | purge flow conditions.

| The cause of the six control rod automatic insertion failures is believed to be | due to the migration of moisture from the PCRV into the CRD motor area.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Fort St. Vrain, Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 6 7 8 4 - 0 0 8 - 0 1 1 0 6 OF 12	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (If more space is required, use additional NRC Form 386A's) (17)

CORRECTIVE ACTIONS:

The preliminary results, conclusions, and future plans for continuing the investigation program are described in the following summary:

- 1) A number of tests have been developed throughout the CRD work in order to better ascertain the mechanism for the apparent binding of the drive system. The most conclusive of these tests is "Back-EMF Testing", which provides a sensitive indication of control rod drive train performance during a scram. A "Back-EMF" voltage is generated by the CRD shim motor as its control rod is scrambling under the velocity limiting system. Such testing may be used to confirm control rod operability prior to reactor startup and during power operation.
 - 2) The six control rods that failed to automatically insert, along with two that did insert, have been inspected, evaluated, refurbished, and tested.
 - 3) A meeting is presently being scheduled with the NRC to discuss the details of the investigations and testing to date and receive concurrence that our conclusions and maintenance will assure that all control rods will scram as required in the future.
 - 4) The functional testing of the two reserve shutdown hoppers, along with material examination, is still planned.
 - 5) A final engineering report summarizing resolution of all past and present CRD concerns will be issued in the future.
- Another supplemental report will follow.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)

Fort St. Vrain, Unit No. 1

DOCKET NUMBER (2)

0 | 5 | 0 | 0 | 0 | 2 | 6 | 7

LER NUMBER (6)


YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
------	-------------------	-----------------

84	-0108	-01
----	-------	-----

PAGE (3)

07 OF 12

TEXT (If more space is required, use additional NRC Form 368A's) (17)



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)

Fort St. Vrain, Unit No. 1

DOCKET NUMBER (2)

0 5 0 0 0 | 2 6 7 8 | 4 - 0 0 8 - 0 1 0 9 OF 1 2


LER NUMBER (8)

PAGE (3)

YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
------	-------------------	-----------------

TEXT (If more space is required, use additional NRC Form 366A's) (17)

FIGURE 3



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Fort St. Vrain, Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 6 7 8 4	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		84	008	011	10	OF 12

TEXT (If more space is required, use additional NRC Form 388A's) (17)

FIGURE 4

CORE MAP


A - Affected Regions

T - Temperature Indication
(as of 6-22-84)

R3 - Refueled,
February-March, 1984

R2 - Refueled,
June-July, 1981


R1 - Refueled 1979



FACILITY NAME (1) Fort St. Vrain, Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 6 7 8 4	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	1 1	OF 1 2
		— 0 0 8	— 0 1			

TEXT (If more space is required, use additional NRC Form 388A's) (17):

FIGURE 5



Programmed Reactor Pressure High-Low Trip Points

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Fort St. Vrain, Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 6 7 8 4	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
			0 0 8	0 1	1 2	OF 1 2

TEXT (if more space is required, use additional NRC Form 386A's) (17)

Mark A. Joseph
 Mark A. Joseph
 Technical Services Engineer

Jim Eggebroten
 Jim Eggebroten
 Technical Services Engineering Supervisor

Licensing Review By:

Jim Gramling
 Jim Gramling
 Nuclear Licensing-Operations Supervisor

C. H. Fuller
 C. H. Fuller
 Station Manager

J. W. Gahm
 J. W. Gahm
 Manager, Nuclear Production