

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | J | O | C | I | P | I | 1 | 2 | 0 | 0 | 1 | - | 0 | 0 | 0 | b | | 0 | - | | d | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

CONF 01 | REPORT SOURCE | L | 6 | 0 | 1 | 5 | 10 | 10 | 10 | 2 | 1 | 19 | 7 | 0 | 1 | 2 | 2 | 18 | 13 | 8 | 1 | 1 | 10 | 2 | 18 | 14 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
07 | Local leak rate testing revealed that ten containment isolation valves  
08 | and one gasket failed to meet their acceptance criteria. The failure of  
09 | Drywell Vent Isolation Valves V-27-3 and 4 and Drywell Head gasket to  
10 | meet required acceptance criteria could have resulted in exceeding 10CFR  
11 | 100 limits during design basis accident conditions. All other contain-  
12 | ment isolation valves failing leak testing were in series with redundant  
13 | valves which passed. Reportable per Tech Specs, paragraph 6.9.2.a.2.

09 | SYSTEM CODE | C | D | 11 | CAUSE CODE | X | 17 | CAUSE SUBCODE | Z | 15 | COMPONENT CODE | V | I | A | L | V | I | E | X | 14 | COMP SUBCODE | F | 15 | VALVE SUBCODE | D | 16 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
17 | LE/R/O REPORT NUMBER | 8 | 3 | 21 | 22 | EVENT YEAR | 8 | 3 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 0 | 1 | 9 | 23 | 24 | OCCURRENCE CODE | 0 | 1 | 25 | 26 | REPORT TYPE | X | 27 | 28 | REVISION NO. | 1 | 29 | 30 |  
ACTION TAKEN | B | 18 | 31 | FUTURE ACTION | Z | 19 | 32 | EFFECT ON PLANT | Z | 20 | 33 | SHUTDOWN METHOD | Z | 21 | 34 | HOURS | 0 | 0 | 0 | 0 | 22 | 35 | ATTACHMENT SUBMITTED | Y | 23 | 36 | NRC-8 FORM SUB | N | 24 | 37 | PRIME COMP. SUPPLIER | N | 25 | 38 | COMPONENT MANUFACTURER | A | 15 | 18 | 15 | 39

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 | Drywell Purge valve V-27-1 stem was out of alignment. Other valves had  
11 | deterioration of internals. All valves were either repaired or replaced.  
12 | Although appearing to be in good condition, the Drywell head gasket was  
13 | replaced. All penetrations passed their subsequent local leak rate  
14 | tests.

15 | FACILITY STATUS | H | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Local Leak Rate Test Program | 32

16 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39


18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

20 | PUBLICITY ISSUED DESCRIPTION | N | 44 | NA | 45

NAME OF PREPARER Kenneth Hutko PHONE 609-971-4698

IEV  
1/1



**GPU Nuclear Corporation**  
Post Office Box 388  
Route 9 South  
Forked River, New Jersey 08731-0388  
609 971-4000  
Writer's Direct Dial Number:

November 2, 1984

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station  
Docket No. 50-219  
Licensee Event Report

This letter forwards Reportable Occurrence No. 50-219/83-09/01X-1, a Licensee Event Report revision, in compliance with paragraph 6.9.2.a.2 of the Technical Specifications.

Very truly yours,

Peter D. Fiedler  
Vice President and Director  
Oyster Creek

PBF/dam  
Enclosures

cc: Dr. Thomas E. Murley, Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

NRC Resident Inspector  
Oyster Creek Nuclear Generating Station  
Forked River, NJ 08731

OYSTER CREEK NUCLEAR GENERATING STATION  
Forked River, New Jersey 08731

Licensee Event Report  
Reportable Occurrence No. 50-219/83-09/01X-1

Report Date

November 2, 1984

Occurrence Date

February 22, 1983

Identification of Occurrence

The results of local leak rate testing identified ten containment isolation valves and one gasket that failed to meet their acceptance criteria. This constitutes operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in Technical Specifications, paragraph 4.5.F.d.

This event is considered to be a reportable occurrence as defined in Technical Specification, paragraph 6.9.2.a.2.

Conditions Prior to Occurrence

The plant was in cold shutdown with reactor coolant temperature less than 212°F and the reactor vented at the time the occurrence was identified. The reactor was in various operating modes prior to the occurrence.

Description of Occurrence

Local leak rate testing identified the following ten (10) valves and one (1) gasket with leakage in excess of the acceptance criteria of 12.08 SCFH @20psig. The results of the leak rate test program for these valves and gasket are as follows:

<u>DESCRIPTION</u>	<u>PENETRATION</u>	<u>DATE TESTED</u>	<u>LEAKAGE @20 PSIG (SCFH)</u>
Instrument Air and Nitrogen System	V-6-395	3/4/83	30.49
MSIV	NS04A	2/14/83	16.34
MSIV	NS04B	2/14/83	17.21
MSIV Drain Valves	V-1-106, 107	2/14/83	19.44
Drywell Headseal	Gasket	2/16/83	544.68
Drywell Purge	V-27-1	2/18/83	20.24
Drywell Sump Discharge	V-22-28, 29	3/17/83	12.4
Drywell Vent	V-27-3, 4	2/27/83	37.03

IE22  
11

Apparent Cause of Occurrence

The cause of the leakage is as follows:

- I. V-6-395, V-1-106, V-1-107, V-22-28, V-22-29, V-27-3, V-27-4, NS04A, and NS04B had deterioration of valve internals.
- II. Drywell Headseal - cause unknown, seal appeared to be in good condition.
- III. V-27-1 stem was found to be out of proper alignment.

Analysis of Occurrence

For valves V-27-1, V-6-395, NS04A, NS04B, V-1-106, and V-1-107 at least one redundant valve for each containment penetration met the acceptance criteria.

The purpose of the Containment System is to provide a barrier to limit the release of radioactive material to the environment to less than 10CFR100 limits during design basis accident conditions. The failure of Containment Isolation Valves V-27-3, 4 and the Drywell Head Seal Gasket to meet required acceptance criteria could have resulted in these limits being exceeded. All other individual containment isolation valves which failed leak testing were in series with other redundant isolation valves which did meet the acceptance criteria.

Corrective Action

Valves V-1-106, 107, and V-6-395 have been replaced with new valves. NS04A and NS04B had their seats lapped, stems replaced, and packing changed. V-27-1 stem was adjusted. V-22-28 received a new seat, stem, and plug. V-22-29 had its seat lapped. V-27-3, 4 received new seats and the Drywell Head had a new seal installed.

All penetrations passed their subsequent Local Leak Rate Tests.