

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Dresden Nuclear Power Station	DOCKET NUMBER (2) 0 5 0 0 0 2 3 7	PAGE (3) 1 OF 2
---	---	---------------------------

TITLE (4)
Inoperable Fire Hose Reels

EVENT DATE (6)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					
									N/A					
1	0	1	0	8	4	8	4	0	0	2	0	0	0	0
						0	0	1	1	0	7	8	4	
									DOCKET NUMBER(S) 0 5 0 0 0					
									DOCKET NUMBER(S) 0 5 0 0 0					

OPERATING MODE (8) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 0 1 0 1 0	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.38(a)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)						
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.38(a)(2)	<input type="checkbox"/> 50.72(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 388A)						
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(vii)(B)							
	<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)							

LICENSEE CONTACT FOR THIS LER (12)

NAME S. Merritt	TELEPHONE NUMBER (X-421)	AREA CODE 8 1 5
		9 4 2 - 2 9 2 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs
D				N					

SUPPLEMENTAL REPORT EXPECTED (14)

<input type="checkbox"/> YES (If Yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

As part of Dresden Station's Appendix R review, a Shift Foreman walked down seven recently installed hose stations to determine the status of hose station root valves (F80A, F80B, F82A, F82B, F67A, F61, F85). Two of the seven, F67A and F80B, were valved out. The Shift Foreman opened the valves immediately. The 7 hose stations were additions to the original fire protection system through Modification Package M12-2/3-78-4 which was the result of a station commitment to the NRC. When the procedures were revised to add these hose stations, surveillance of root valve position for these stations was inadvertently not added. To maintain operability, the hose stations' root valves will be added to DFPP 4114-2, Reactor Building Monthly Fire Equipment Inspection and DFPP 4114-3, Turbine Building Monthly Fire Equipment Inspection respectively.

8411160337 841107
PDR ADDCK 05000237
S PDR

JEZZ
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Dresden Nuclear Power Station	DOCKET NUMBER (2) 0 5 0 0 0 2 3 7 8 4	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 4	- 0 2 0	- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 386A's) (17)

As part of Dresden Station's Appendix R review, a Shift Foreman was checking the status of seven (7) hose stations' root valves (F80A, F80B, F82A, F82B, F67A, F61, F85). During this walkdown he found two (2) hose reels, F67A and F80B, whose root valves were valved out. He immediately opened the two root valves. The other five hose reels' root valves were open (operable) as specified in T.S. 3.12.E.1. The addition of the seven hose stations was part of Modification Package M12-2/3-78-4. This modification was a commitment made to the NRC to provide additional hose reels. This is documented in the 1978 Safety Evaluation Report, Section 3.1.4. During installation of this modification an additional root valve was added so that the hose station additions could be completed or an operable fire suppression system. When the procedures were revised to add these hose stations, surveillance of root valve position for these stations was inadvertently not added. Due to this fact, the root valve positions were not previously checked on a monthly surveillance. These seven hose stations' root valves will be added to DFPP 4114-2 Reactor Building Monthly Fire Equipment Inspection and DFPP 4114-3 Turbine Building Monthly Fire Equipment Inspection so that the proper positions can be maintained and verified. Safety significance is considered to be minimal. There were no functional problems with the valves which were fully operable after valving in. This is the first occurrence of this kind at Dresden Station.



Commonwealth Edison

Dresden Nuclear Power Station

R.F. #1

Morris, Illinois 60450

Telephone 815/942-2920

November 7, 1984

DJS Ltr #84-1259

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Licensee Event Report #84-020-0, Docket #050237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(i)(B).

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/NRC
File/Numerical

IE22
1/1