

587

DOCKETED
USNRC

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

'84 DEC 12 A11:10

Before the Atomic Safety and Licensing Appeal Board

OFFICE OF SECRETARY
DOCKETING & SERVICE
BRANCH

In the Matter of)
)
LONG ISLAND LIGHTING COMPANY)
)
(Shoreham Nuclear Power Station,)
Unit 1))
)
)
)

Docket No. 50-322-OL-4
(Low Power)

SUFFOLK COUNTY AND STATE OF NEW YORK BRIEF
IN SUPPORT OF APPEAL OF OCTOBER 29, 1984
ASLB DECISION ON LILCO'S EXEMPTION REQUEST

Fabian G. Palomino
Special Counsel to the Governor
of the State of New York
Executive Chamber, Room 229
Capitol Building
Albany, New York 12224

Herbert H. Brown
Lawrence Coe Lanpher
Karla J. Letsche
KIRKPATRICK & LOCKHART
1900 M Street, N.W., Suite 800
Washington, D.C.

Attorney for Mario M. Cuomo
Governor of the State of New York

Attorneys for Suffolk County

8412130339 841211
PDR ADOCK 05000322
PDR

December 11, 1984

*add: York
OCA*

D503

TABLE OF CONTENTS

I.	Introduction.	1
II.	Argument.	4
	A. Errors Relating to Public Interest Finding.	8
	1. Exclusion of County and State Evidence Concerning Economic and Financial Disadvantages Resulting from Granting Exemption, and Admission of LILCO Evidence Concerning Alleged Economic and Financial Benefits of Granting the Exemption	8
	2. Exclusion of County and State Testimony Concerning Where the Public Interest Lies With Respect to the Grant of the Exemption and Admission of All LILCO Testimony Concerning the Same Issue	12
	3. Lack of Independent Basis for Public Interest Finding.	14
	4. Failure to Consider Evidence Concerning Whether There is a Need for the Electric Power to be Provided by Shoreham.	16
	B. Errors Relating to Security Determination	18
	1. Denial of Hearing on Security Issues Arising from Proposed Change in AC Power Configuration	18
	2. Findings Relating to Security Without Any Basis in Evidentiary Record	23
	C. Errors Relating to Exigent Circumstances Finding.	25
	1. Exclusion of Suffolk County Evidence Concerning LILCO's Alleged Good Faith Attempt to Comply with GDC 17 and Admission of LILCO Evidence on the Same Subject	25
	2. Improper Reliance Upon Evidence Concerning the Length and Costs to LILCO of the Shoreham Licensing Proceeding	29

3.	Improper Consideration of Prior Staff Practices as Basis for Finding Exigent Circumstances to Support Exemption.	31
D.	Errors Relating to the As Safe As Determination	32
1.	Exclusion of Suffolk County Testimony Which Demonstrated that Operation With the Alternate AC Power Configuration Would Not Be As Safe As Operation With a Fully Qualified On-Site Power System, and Admission of All Evidence Submitted by the Staff and LILCO Concerning the "As Safe As" Comparison	32
2.	Improper Application of Commission's As Safe As Standard	36
3.	Improper Consideration of Offsite Power System.	42
E.	The September 5 Phase I and II Miller Board Order Violates the Commission's Rulings and Regulations	43
F.	Miller Board's Issuance of a Low Power License Violates Section 50.57.	57

Attachments

- Attachment 1
Pages 41-47 of Testimony of Messrs. Madan and Dirmeier

- Attachment 2
Testimony of Richard Kessel, Chairman of the State of New York Consumer Protection Board

- Attachment 3
Testimony of Messrs. Hubbard and Bridenbaugh

- Attachment 4
Testimony of Messrs. Weatherwax and Minor

TABLE OF AUTHORITIES

CASES

<u>Aberdeen & Rockfish Co. v. United States</u> 565 F.2d 327 (5th Cir. 1977)	18
<u>Amos Treat & Co. v. SEC,</u> 306 F.2d 260 (D.C. Cir. 1962)	7
<u>Carnation Co. v. Secretary of Labor,</u> 641 F.2d 801 (9th Cir. 1981)	8
<u>Cotter v. Harris,</u> 642 F.2d 700 (3d Cir. 1981)	18
<u>Courts v. Economic Opportunity Auth.,</u> 451 F. Supp. 587 (S.D. Ga. 1978)	5
<u>Cuomo v. NRC,</u> Civil Action No. 84-1264, Nuclear Reg. Rep. (CCH) ¶ 20,304 (D.D.C. 1984)	5, 7
<u>Fitzgerald v. Hampton,</u> 457 F.2d 755 (D.C. Cir. 1972).	7
<u>Great Lakes Screw Corp. v. NLRB,</u> 409 F.2d 375 (7th Cir. 1969)	18
<u>Hupart v. Bd. of Higher Ed. of City of New York,</u> 420 F. Supp. 1087 (S.D.N.Y. 1976).	5
<u>Inland Steel Co. v. NLRB,</u> 109 F.2d 9 (7th Cir. 1940)	4
<u>Marshall v. Manzo,</u> 380 U.S. 545 (1965).	7
<u>Montgomery Ward & Co. v. NLRB,</u> 103 F.2d 147 (8th Cir. 1939)	4
<u>NLRB v. Phelps,</u> 136 F.2d 562 (5th Cir. 1943)	4
<u>NLRB v. Washington Dehydrated Food Co.,</u> 118 F.2d 980 (9th Cir. 1941)	8
<u>Ohio Bell Telephone Co. v. Public Utilities Comm.,</u> 301 U.S. 292 (1937).	7

<u>Service v. Dulles,</u> 354 U.S. 363 (1957)	5
<u>Superior Sav. Ass'n v. City of Cleveland,</u> 501 F. Supp. 1244 (N.D. Ohio 1980)	5
<u>Taylor v. Heckler,</u> F. Supp. _____, No. 83-398 (D.D.C. Sept. 5, 1984)	18
<u>Union Bag - Camp Paper Corp. v. FTC,</u> 233 F. Supp. 660 (S.D.N.Y. 1964)	8
<u>United States v. 478.34 Acres of Land Tract No. 400,</u> 578 F.2d 156 (5th Cir. 1978)	8
<u>Vitarelli v. Seaton,</u> 359 U.S. 535 (1959)	5

ADMINISTRATIVE DECISIONS

<u>Connecticut Yankee,</u> 2 AEC 393 (1964)	15
<u>Houston Lighting and Power Co.,</u> (Allens Creek Nuclear Generating Station, Unit 1), ALAB-590, 11 NRC 542 (1980)	23
<u>Long Island Lighting Co.,</u> (Shoreham Nuclear Power Station, Unit 1), LBP-83-57, 18 NRC 445 (1983)	2
<u>Long Island Lighting Co.,</u> (Shoreham Nuclear Power Station, Unit 1), CLI-84-8, 19 NRC 1154 (1984)	<u>passim</u>
<u>Long Island Lighting Co.,</u> (Shoreham Nuclear Power Station, Unit 1), CLI-84-21, _____ NRC _____ (1984)	10, 43
<u>Long Island Lighting Co.,</u> (Shoreham Nuclear Power Station, Unit 1), CLI-83-13, 17 NRC 741 (1983)	10
<u>Long Island Lighting Co.,</u> (Shoreham Nuclear Power Station, Unit 1), NRC Memorandum and Order, _____ NRC _____ (July 18, 1984)	18, 19

<u>Long Island Lighting Co.,</u> (Shoreham Nuclear Power Station, Unit 1), NRC Memorandum and Order, _____ NRC _____ (August 20, 1984).	19
<u>Long Island Lighting Co.,</u> (Shoreham Nuclear Power Station, Unit 1), ALAB-788, _____ NRC _____ (1984)	34
<u>Mississippi Power and Light Co.,</u> (Grand Gulf Nuclear Station, Units 1 and 2), ALAB-130, 6 AEC 423 (1973)	23
<u>Pacific Gas & Electric Co.,</u> (Diablo Canyon Nuclear Power Plant, Units 1 and 2), CLI-83-87, 18 NRC 1146 (1983).	56
<u>Philadelphia Electric Co.,</u> (Peach Bottom Atomic Power Station, Units 1 and 2), ALAB-216, 8 AEC 13 (1974).	23
<u>Public Service Co. of New Hampshire,</u> (Seabrook Station, Units 1 and 2), ALAB-422, 6 NRC 33 (1977).	52, 53
<u>Shearon Harris II,</u> CLI-74-22, 7 AEC 938 (1974).	16
<u>United States Department of Energy</u> (Clinch River Breeder Reactor Plant), CLI-83-1, 17 NRC 1 (1983).	16, 25
<u>Virginia Electric and Power Co.,</u> (North Anna Power Station, Units 1 and 2), LBP-77-64, 6 NRC 808 (1977).	22, 61
<u>Washington Public Power Supply System,</u> (WPPSS Nuclear Projects Nos. 3 and 5), CLI-77-11, 5 NRC 719 (1977).	16

STATUTES

Atomic Energy Act, 42 USC § 2131, § 2133, § 2232, § 2235.	54
--	----

REGULATIONS

10 CFR § 2.717(b)	21
-----------------------------	----

10 CFR § 2.762.	1
10 CFR § 2.764(g)	43
10 CFR § 50.12(a)	<u>passim</u>
10 CFR § 50.23.	54
10 CFR § 50.30.	54
10 CFR § 50.33.	54
10 CFR § 50.47(d)	39
10 CFR § 50.51.	54
10 CFR § 50.55(d)	54
10 CFR § 50.56.	55
10 CFR § 50.57.	55
10 CFR Part 50, Appendix A	
GDC 1.	58
GDC 2.	58
GDC 3.	58
GDC 4.	58
GDC 17	<u>passim</u>
GDC 18	58
GDC 33	58
GDC 34	58
GDC 35	58
GDC 37	58
GDC 38	58
GDC 40	58
GDC 41	58
GDC 43	58
GDC 44	58
GDC 46	58
10 CFR Part 50, Appendix B.	58
10 CFR Part 73.	22
 <u>OTHER</u>	
47 Fed. Reg. 30,234 (1982)	37
49 Fed. Reg. 13,611-12 (1984)	3
Letter dated June 15, 1984 from Nunzio J. Palladino to the Honorable Edward J. Markey.	34

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

Before the Atomic Safety and Licensing Appeal Board

_____)
In the Matter of)

LONG ISLAND LIGHTING COMPANY)

(Shoreham Nuclear Power Station,)
Unit 1))
_____)

Docket No. 50-322-OL-4
(Low Power)

SUFFOLK COUNTY AND STATE OF NEW YORK BRIEF
IN SUPPORT OF APPEAL OF OCTOBER 29, 1984
ASLB DECISION ON LILCO'S EXEMPTION REQUEST

I. INTRODUCTION

Pursuant to 10 CFR § 2.762, this Brief is submitted in support of the appeal by Suffolk County and the State of New York of the Initial Decision issued by the Licensing Board chaired by Marshall Miller ("Miller Board") on October 29, 1984 (LBP-84-45) (hereinafter, the "Decision"). The Decision at issue recommended approval of two LILCO requests: (1) its request for an exemption from compliance with the NRC's regulations under 10 CFR § 50.12(a); and (2) its request for a low power license. For the reasons we detail below, the Miller Board erred in recommending approval of those LILCO requests.

LILCO's need for an exemption arises from its inability to comply with the requirements of 10 CFR Part 50, GDC 17. That criterion requires that there be an on-site electric power system which, assuming the off-site electric power system is not functioning, has sufficient capacity and capability to assure the functioning of structures, systems and components important to safety.

According to GDC 17, such an on-site electric power system must also have

sufficient independence, redundancy and testability to perform its safety function assuming a single failure.

The Shoreham plant was designed to include three emergency diesel generators manufactured by TransAmerica Delaval, Inc. ("TDI") to comprise the on-site source of AC power. However, following failures of those TDI diesels during preoperational testing and the admission for litigation of contentions concerning the adequacy of the TDIs, the Brenner Licensing Board ruled that no low power license could be issued for Shoreham until LILCO had established in the TDI litigation that the TDIs complied with all applicable regulations and Shoreham design requirements. See Long Island Lighting Co. (Shoreham Nuclear Power Station, Unit 1), LBP-83-57, 18 NRC 445, 634 (1983); Tr. 21,615 (Brenner).

Subsequently, the Commission ruled on May 16, 1984 that in order to obtain a low power license prior to completion of the TDI litigation pending before the Brenner Board, LILCO must satisfy the requirements necessary to obtain an exemption from the regulations under 10 CFR § 50.12(a). See Long Island Lighting Co. (Shoreham Nuclear Power Station, Unit 1), CLI-84-8, 19 NRC 1154 (1984) (hereinafter, "May 16 Order").

LILCO has proposed that it be permitted to operate Shoreham at up to 5 percent of rated power using an alternate AC power configuration in place of the TDI diesels. The proposed alternate configuration consists of a set of four mobile diesel generators manufactured by the Electromotive Division of General Motors (the "EMDs") which are sitting on railroad ties next to the plant buildings, and a 70 MW gas turbine which sits in the 69 KV switchyard near the plant. LILCO asserted that through the use of the EMDs and/or the gas turbine, emergency AC power could be supplied in the event that a loss of offsite power occurred

during low power operation. See LILCO's Application for Exemption, May 22, 1984.

After having established the Miller Board to deal with LILCO's low power license request (see 49 Fed. Reg. 13,611-12 (1984)), the Commission set forth the particular determinations which the Miller Board was required to make in ruling upon LILCO's exemption application. In its May 16 Order, the Commission held that in addition to the determinations expressly set forth in Section 50.12(a) itself (i.e., that the exemption (1) is authorized by law, (2) will not endanger life or property, (3) will not endanger common defense and security, and (4) is otherwise in the public interest), LILCO also had to demonstrate that: (a) there exist exigent circumstances that favor the granting of an exemption; and, (b) operation at up to 5 percent power would be as safe under the alternate power configuration proposed by LILCO, as operation would have been with a fully qualified on-site AC power source. 19 NRC at 1155-56. The legal errors committed by the Miller Board during the course of the exemption proceeding enabled that Board to make each of those findings desired and needed by LILCO to obtain a license. Thus, as a direct result of the due process violations we detail below, the Miller Board found that LILCO had demonstrated that granting the exemption would be in the public interest; that granting the exemption would not endanger life, property, or the common defense or security by giving rise to any physical security risks; that exigent circumstances exist that favor granting the exemption; and that low power operation of Shoreham under the alternate configuration proposed by LILCO would be as safe as operation would have been with the fully qualified TDI diesels. Each of these findings was erroneous and must be reversed by this Appeal Board.^{1/}

^{1/} The detailed position of Suffolk County and the State of New York concerning the LILCO exemption request (on issues other than the denial of securi-

II. ARGUMENT

The Miller Board Decision which recommends approval of LILCO's exemption request must be summarily reversed because the fundamental due process rights of Suffolk County and the State of New York were irremediably violated in the course of the "proceeding" conducted by the Miller Board. Thus, although some testimony was accepted into an evidentiary record, some cross examination and argument of counsel were permitted, and briefs were accepted purportedly on the issues identified in the May 16 Order, in fact what occurred during the exemption proceeding did not constitute a fair hearing at all. It was merely a vehicle by which the Miller Board itself became an advocate for LILCO's self-interest. In pursuing that advocacy, the Miller Board abused the NRC hearing process and trounced upon the fundamental constitutionally protected rights of the Intervenors. See NLRB v. Phelps, 136 F.2d 562 (5th Cir. 1943); Inland Steel Co. v. NLRB, 109 F.2d 9 (7th Cir. 1940) (petitioner denied full and fair hearing where trial examiner limited scope of cross examination, and conducted coercive examination of witnesses, becoming advocate); Montgomery Ward & Co. v.

(Footnote cont'd from previous page)

ty contentions) is set forth in the following filings with the Miller Board: the Suffolk County and State of New York Proposed Findings of Fact (hereinafter, "County and State Findings"), the Brief of Suffolk County in Opposition to LILCO's Motion for a Low Power Operating License and Application for Exemption, and the Brief of the State of New York in Opposition to LILCO's Application for a Low Power Operating License on the Basis of an Exemption from the Regulations Pursuant to 10 CFR § 50.12(a), all dated August 31, 1984; Suffolk County and State of New York Memorandum in Opposition to LILCO's May 22, 1984 Motions for Summary Disposition on Phase I and Phase II of LILCO's Proposed "Low Power Testing," dated June 13, 1984; and Suffolk County and State of New York Views on Why the ASLB's September 5 Order May Not Serve as the Basis for Phase I and II License, dated September 14, 1984.

NLRB, 103 F.2d 147 (8th Cir. 1939) (due process denied where trial examiner "assumed the place of attorney supporting the complaint," placed unfair restriction on examination of witnesses, and omitted from the record occurrences at the hearing).

The fundamental due process right to a fair hearing was emphatically recognized by the United States District Court in its April 25, 1984, decision which enjoined the previous attempts by the Miller Board to conduct a proceeding in violation of the Constitution. See Cuomo v. NRC, Civil Action No. 84-1264, Nuclear Reg. Rep. (CCH) ¶ 20,304 (D.D.C. 1984).^{2/} While the U.S. District Court's April 25 Temporary Restraining Order against the NRC and the Miller Board put an end to the first showing of regulatory abuses, the exemption proceeding which followed proved that the past was just prologue. The Miller Board pursued a pattern of behavior which included a series of errors of such nature as to deny the County and State procedural and substantive due process guaranteed by the Fifth Amendment to the U.S. Constitution, the Atomic Energy Act, the Administrative Procedure Act, and the Commission's own Rules of Practice.^{3/} The

^{2/} In addition, the necessity for a fair hearing was recognized by the Commission in the May 16 Order, which required that the Licensing Board "shall conduct the proceeding . . . in accordance with the Commission's rules." 19 NRC at 1156.

^{3/} For the reasons detailed in this Brief, it is clear that the Miller Board failed to follow the NRC's rules in conducting the exemption proceeding. This failure constitutes an independent basis for finding a due process violation. See Vitarelli v. Seaton, 359 U.S. 535 (1959) (denial of due process for any government agency not to follow its own regulations pertaining to adjudication processes); Service v. Dulles, 354 U.S. 363 (1957) (administrative agency bound to observe its own regulations and denies due process if it does not). See also Superior Sav. Ass'n v. City of Cleveland, 501 F.Supp. 1244, 1249 (N.D. Ohio 1980); Courts v. Economic Opportunity Auth., 451 F.Supp. 587, 592 (S.D. Ga. 1978); Hupart v. Bd. of Higher Ed. of City of New York, 420 F.Supp. 1087, 1107 (S.D.N.Y. 1976) (agency's failure to "scrupulously observe" rules, regulations, or procedures it has established may in and of itself constitute due process violation).

Miller Board's denial of the Intervenors' due process right to a fair hearing led directly to the Board's rulings, in LILCO's favor, with respect to each of the specific determinations identified in the regulations and by the Commission as being prerequisites to the grant of an exemption.

The most blatant of the Miller Board's denials of due process was its repeated pattern of refusing to admit evidence submitted by the County and the State on issues articulated by the Commission in its May 16 Order, with accompanying rulings that LILCO and Staff evidence on precisely the same issues was admissible.^{4/} Each of these rulings was made by the Miller Board at LILCO's request. This denial of the fundamental right to submit evidence on the central matters at issue was made even more prejudicial by the Miller Board's subsequent reliance upon the one-sided LILCO and Staff evidence to make the findings necessary to support LILCO's exemption request.

The Miller Board also made findings relating to the adequacy of LILCO's security plan to protect the proposed alternate AC power configuration. Such findings are required by Section 50.12(a) and the Commission's July 18, 1984 Memorandum and Order. However, there was absolutely no basis in the record for any such findings since the Miller Board had violated Commission guidance and refused to permit litigation of security contentions submitted by New York and Suffolk County, the admissibility and the substantive accuracy of which, in material part, were supported by the NRC Staff. Thus, without having conducted an

^{4/} As we describe in detail below, this consistent Miller Board denial of the Intervenors' rights occurred with respect to the issues of whether the public interest favors the exemption, whether exigent circumstances exist, and whether operation with the alternate configuration proposed by LILCO would be as safe as operation with a fully qualified source of AC power.

evidentiary proceeding (much less having admitted security contentions), the Miller Board could not possibly have made any security findings. Yet that is precisely what it did.

The Miller Board also refused to consider matters which the Commission's own Section 50.12 precedents and its May 16 Order identify as key considerations in exemption decisions, its ruling on Phases I and II violated the Commission's rulings and the NRC's regulations, and it made clearly erroneous rulings on other legal and factual issues.

These errors, all discussed in Sections II.A. through II.F below, constitute a denial of a fair hearing which must be recognized and remedied by this Board. A fair trial before a fair tribunal is a basic requirement of due process. Fitzgerald v. Hampton, 467 F.2d 755, 764 (D.C. Cir. 1972). This Board cannot close its eyes to the gross deprivation of rights which has been permitted to take place. Due process requires the resolution of contested questions by an impartial and disinterested tribunal in a fair proceeding. Amos Treat & Co. v. SEC, 306 F.2d 260, 263-64 (D.C. Cir. 1962). As both the Amos Treat Court and the U.S. District Court in the NRC TRO case held:

[A]n administrative hearing of such importance and vast potential consequences must be attended, not only with every element of fairness but with the very appearance of complete fairness. Only then can the tribunal conducting a quasi-adjudicatory proceeding meet the basic requirements of due process.

Cuomo v. NRC; supra, slip op. at 5, citing Amos Treat, 306 F.2d at 267. See also Marshall v. Manzo, 380 U.S. 545, 552 (1965) (due process requires that parties be afforded the opportunity to be heard "at a meaningful time and in a meaningful manner"); Ohio Bell Telephone Co. v. Public Utilities Comm., 301 U.S. 292, 304-05 (1937) (right to fair hearing is "one of the 'rudiments of fair

play' . . . assured to every litigant by the Fourteenth Amendment as a minimal requirement"); Carnation Co. v. Secretary of Labor, 641 F.2d 801 (9th Cir. 1981) (procedural due process requires that a party against whom an agency has proceeded be allowed to rebut evidence offered by the agency if that evidence is relevant); United States v. 478.34 Acres of Land Tract No. 400, 578 F.2d 156 (6th Cir. 1978); NLRB v. Washington Dehydrated Food Co., 118 F.2d 980 (9th Cir. 1941) (due process requires a tribunal both impartial and mentally competent to afford a hearing); Union Bag - Camp Paper Corp. v. FTC, 233 F. Supp. 660, 666 (S.D.N.Y. 1964) (agency action denying party the right to present its evidence and summon the witnesses of its choice violates the constitutional right of due process of law as well as the concept of fairness necessary to every proceeding). We demonstrate below that the Miller Board's conduct of the exemption proceeding violated these basic due process principles.

A. Errors Relating to Public Interest Finding

1. Exclusion of County and State Evidence Concerning Economic and Financial Disadvantages Resulting from Granting Exemption, and Admission of LILCO Evidence Concerning Alleged Economic and Financial Benefits of Granting the Exemption

10 CFR § 50.12(a) requires that before an exemption from the requirements in the NRC's regulations can be granted, the Commission must determine that the exemption will not endanger life, property, or the common defense and security, and that the exemption is "otherwise in the public interest." (emphasis supplied). LILCO asserted there were at least two public benefits of low power operation following the granting of an exemption which the Miller Board should consider as exigent circumstances weighing in favor of granting the exemption: (1) the reduction in dependence on foreign oil; and, (2) certain economic benefits to LILCO ratepayers.^{5/} Both these alleged public interest "benefits,"

^{5/} In its Application, LILCO improperly linked the exigent circumstances finding required by the Commission with the "otherwise in the public interest"

according to LILCO, would be achieved when Shoreham begins full power operation. See Application for Exemption at 15-16, 20-21.^{6/} LILCO submitted testimony to the Miller Board which discussed these so-called benefits. See Tr. 1336-43, 1402-10. The LILCO testimony, however, did not deal with any benefits which could result from the conduct of low power testing, which is what would be authorized by the exemption; rather, it dealt with possible benefits which could result only if it were assumed that full power operation of Shoreham would eventually occur.^{7/}

(Footnote cont'd from previous page)

finding expressly mandated by Section 50.12(a). See, e.g., Application for Exemption at 15-16. As we discuss in Section II.A.3 below, the Miller Board did the same thing -- it failed to make an independent public interest finding, despite the fact that the Commission made clear that the exigent circumstances finding represents a threshold that an exemption applicant must meet separate from, and in addition to, the requirements set forth in Section 50.12(a). See 19 NRC at 1156, n.3, and discussion in Section II.C.1 below. In its Post-Trial Brief, LILCO argued that these two alleged "benefits" related to the required public interest finding. See LILCO's Post Hearing Brief in Support of Application for Exemption, at 58-66. Even though the Miller Board nonetheless considered the possibility that the "benefits" alleged by LILCO would be achieved as constituting "exigent circumstances" (see Decision, at 60-63), we discuss them here since purportedly, they would constitute "benefits" to the general public.

^{6/} Thus, reducing dependence upon foreign oil cannot occur until after a full power license is issued to Shoreham, the plant has been tied into the LILCO grid, and it begins to produce electricity in commercial operation. See, e.g., Tr. 1235-36, 1249-50, 1330. Similarly, the alleged ratepayer "benefit" which, according to LILCO, would be received by the public in 1997 from beginning commercial operation three months earlier than would be possible without an exemption, can only come into being after commercial full power operation begins and Shoreham goes into LILCO's rate base. See, e.g., Tr. 1372, 1405-10.

^{7/} The County and the State moved to strike such testimony as irrelevant and speculative because it did not deal with "benefits" which would accrue as the result of the grant of the exemption -- the matter at issue -- nor would such benefits even materialize until after the plant achieved full power operation. The Miller Board denied those motions. See Tr. 1237-68, 1356.

The County submitted testimony concerning the substantial financial and economic harm to the public that would result from the grant of the exemption if the assumption that is the converse of LILCO's -- i.e., that there would be no full power operation of Shoreham -- was a premise for evaluating the public interest. At LILCO's urging (see Tr. 2122-23), the Miller Board refused to accept such evidence. Thus, the County's testimony which discussed the economic penalties to the public which would result from contaminating Shoreham to perform low power testing assuming that authorization for full power operation did not follow was not admitted by the Miller Board. See Tr. 2145-48.^{8/}

According to the Commission's own statements, the assumption that full power operation of Shoreham will never be achieved is at least as appropriate as the opposite assumption which is preferred by LILCO and which was adopted by the Miller Board. Thus, in its November 21, 1984 Memorandum and Order (CLI-84-21), the Commission expressly rejected the suggestion that "once a Phase I and II license is granted, the eventual issuance of a full power license is a foregone conclusion." Long Island Lighting Co. (Shoreham Nuclear Power Station, Unit 1), CLI-84-21, _____ NRC _____ (1984) (slip op. at 5).^{9/} There was no basis, therefore, for the Miller Board's refusal to consider evidence premised on the

^{8/} A copy of the referenced portion of Messrs. Madan and Dirmeier's testimony (that is, pages 41-47), which was among that stricken by the Board, is Attachment 1 hereto.

^{9/} See also Long Island Lighting Co., (Shoreham Nuclear Power Station, Unit 1), CLI-83-13, 17 NRC 741, 744 (1983) (separate views of Commissioner Gilinsky) ("There cannot be adequate emergency preparedness for surrounding population without the participation of a responsible government entity. And, however they may qualify their views now, I do not believe that a single Commissioner would actually approve the operation of the plant without such participation.") (emphasis added).

assumption proffered by the County, since Shoreham's not obtaining a full power license is at least as probable as the converse assumption proffered by LILCO and adopted without question or explanation by the Miller Board.

The prejudice resulting from the Miller Board's admission of LILCO's testimony concerning alleged economic benefits of the exemption and its refusal to admit the County testimony based on the converse assumption, is manifest in the Board's Decision. The Board's rulings concerning alleged financial and economic hardships rely only upon testimony submitted by LILCO. See Decision at 60-63.^{10/} Moreover, the specific findings concerning alleged possible fuel savings, reduced dependence on foreign oil, and possible benefits to ratepayers, are all based solely upon the LILCO-proffered assumption of eventual full power

^{10/} Richard Kessel, the Chairman of the State of New York Consumer Protection Board, whose job it is to represent the consumers of the State of New York, submitted testimony on behalf of New York. A copy of his testimony, marked to reflect the Miller Board's rulings (see Tr. 2893-908), is Attachment 2 hereto. As can be seen, much of it was stricken by the Board in response to LILCO's motions (see Tr. 2893-908), but sentences stating that it is not in the public interest to contaminate a nuclear facility before uncertainties surrounding its future operation have been resolved, and that if Shoreham were operated at low power and subsequently were abandoned, the costs that ratepayers would ultimately bear would be increased, were (inexplicably, in light of its other rulings) let in by the Board. LILCO argued that Mr. Kessel's testimony should be disregarded because it was incompetent and not supported by any facts. See, e.g., Tr. 3104-105; LILCO's Post-Hearing Brief in Support of Application for Exemption, at 54. The County testimony stricken by the Miller Board provided substantial factual support for Mr. Kessel's more summary testimony, and Mr. Kessel expressly referenced the County's witnesses in his testimony. See Tr. 2145-48 and Attachment 2 hereto. Consistent with LILCO's suggestion, however, the Miller Board's Decision fails even to acknowledge the existence of Mr. Kessel's testimony on this matter of the public interest. See Section II.A.2 below. The one citation to Mr. Kessel's oral testimony (see last transcript citation in n.125 in Decision) is incorrect; Mr. Kessel's statement does not support the Board's assertion, for which it is cited, that there would be fuel savings or reduced dependence on foreign oil as a result of granting LILCO's exemption request.

operation. Id. at 61. The fact that only such one-sided evidence, and only the assumption favorable to LILCO, was considered by the Miller Board in its finding concerning the economic impact on the public of the requested exemption constitutes clear error and the denial of a fair hearing.

Similarly, the Miller Board's reliance in the Decision upon LILCO's testimony about the relationship between the issuance of a license and its own private financial needs was also clearly erroneous. Thus, the Board apparently accepted as "an equity" weighing in favor of the exemption, the LILCO testimony that "the granting of a low-power exemption would send a positive signal to the capital markets that would help to alleviate LILCO's financial distress in obtaining vitally needed cash by the issuance of securities." Decision at 61. This Board cannot countenance such a clearly improper attempt by the Miller Board to base, even in part, a decision to permit the operation of a nuclear power plant upon a perceived need to "send a signal" to the capital markets on LILCO's behalf.

2. Exclusion of County and State Testimony Concerning Where the Public Interest Lies with Respect to the Grant of the Exemption, and Admission of All LILCO Testimony Concerning the Same Issue

Although LILCO was permitted to submit testimony concerning LILCO's view of the public's interest, the Miller Board refused to admit evidence submitted by the actual elected representatives of the public -- the Governor of New York and Suffolk County -- which would have set forth several reasons why it is not in the public interest to grant an exemption to LILCO. Thus, Suffolk County submitted testimony which discussed the impact upon electrical service to LILCO's customers which would result from the exemption, and New York submitted

testimony that the electrical power from Shoreham is not needed for at least ten years. See Attachments 1 and 2. Similarly, as discussed in Section II.A.1 above, the County submitted testimony concerning the economic harm to the public that could result if the exemption were granted, resulting in contamination of the plant, but if a full power license were not subsequently issued, as LILCO assumed. At LILCO's urging, none of this evidence was admitted by the Miller Board. See Tr. 2122-23, 2145-48, 2902-903.

It cannot be disputed that the public servants who were denied the right to present evidence are in a far better position to advise the NRC regarding where the public interest lies than LILCO. Indeed, a year ago, in the Commission's brief before the U.S. Court of Appeals in a case involving the Diablo Canyon plant, the Commission argued for the legitimacy of its action by citing the "great weight" it gives to the views of a State government:

Finally, the Supreme Court has noted that the debate over nuclear power is one in which the States have a vital stake. [Citing Vermont Yankee.] In this case the Governor of California, as representative of the people and the public interest, has indicated in hearings before the Appeal Board that he does not oppose this action. The views of the chief elected representative of the people of California should be accorded great weight in fixing where the public interest lies.

NRC Brief, page 34 (emphasis supplied, citations omitted). In the Diablo case, the Governor of California had supported the NRC's action reinstating a license for the plant. Here, in the Shoreham case, the chief elected representative of the people of New York and the elected government of the people of Suffolk County oppose issuance of a low power license, and they submitted testimony as to why such an action by the NRC would be contrary to the public interest. The Miller Board not only refused to give such testimony "great weight" as the

Commission did in pleading before the Court of Appeals, but at LILCO's urging, it refused to consider such evidence at all.

The Miller Board's reliance upon LILCO's purported public interest testimony (see Decision at 60-63), and its refusal even to consider the testimony submitted by the Governor, representing the millions of residents of the State, and Suffolk County, which has 1.3 million residents, whose obligation and responsibility it is to serve and protect the public who have elected them, constitutes clear error. It also constitutes a denial of the State's and County's due process right to a hearing on this issue which is central to the granting of an exemption under Section 50.12(a).

3. Lack of Independent Basis for Public Interest Finding

The Miller Board concluded that LILCO's Exemption Application "meets the 'otherwise in the public interest' provision of 10 CFR § 50.12(a)." Decision at 104, ¶6. That "conclusion," however, by the Board's own admission, is solely "[r]ased upon [the Board's] finding that the Application for Exemption meets the 'exigent circumstances' test set forth by the Commission," (id.); and, that finding, in turn, is based solely upon the Board's so-called "balancing of the equities" and its finding that "the Application and evidence adduced in support thereof demonstrate the 'exigent circumstances' that favor the granting of an exemption" Id. at 103, ¶ 5.11/ This wholly circular analysis is devoid of any substantive content or basis in logic or fact, and must be rejected.

11/ As noted in Section II.A.1 above and Section II.C.1 below, the exigent circumstances finding and so-called "balancing" of equities were based solely upon LILCO's evidence concerning purported "benefits" which would result from eventual full power operation of Shoreham, and purported efforts of LILCO relating to the TDI diesels. The County and State evidence on these matters was not admitted.

There is no support in Commission precedent, nor did the Miller Board cite any, for the Board's tortured reasoning that meeting an exigent circumstances test established by the Commission, automatically satisfies the wholly separate Section 50.12(a) requirement that an exemption "otherwise" be "in the public interest." Furthermore, the Miller Board's treatment of the public interest finding required under Section 50.12(a) violates Connecticut Yankee, 2 AEC 393 (1964), which held that the public interest determination "constitutes a distinct and separate aspect" of an exemption decision. Id. at 394, n.1.

In fact, the "public interest" is mentioned only twice in the Decision: in the one-sentence "conclusion of law" in paragraph 6 on page 104 which is cited above, and in a six-sentence section under "Exigent Circumstances" which is headed "Public Interest in Adherence to Regulations." The discussion in that section of the Decision, however, makes no reference to any of the evidence which the County and State submitted or attempted to submit concerning the actual interests of the public living in Suffolk County and New York State concerning the exemption. See Decision at 68-69. For that matter, it also makes no reference to any LILCO evidence concerning the alleged public interest. Instead, it references the "demonstrated safety of low power testing as proposed" by LILCO, the general principle that administrative agencies have the authority to provide for exemption procedures, and the Board's public health and safety findings. It concludes, without citation to any evidence, that "there is minimal public interest in strict or mechanical adherence to the regulations."

Id.^{12/} Thus, in actual fact, and as the Decision itself makes clear, the Miller

^{12/} The Miller Board's circular reasoning that its health and safety findings establish the basis for a public interest finding again violates Connecticut Yankee, which held that the public interest determination is

(Footnote cont'd next page)

Board never even considered the interests of the public with respect to the LILCO exemption request; rather, it considered only the one-sided "evidence" which dealt with LILCO's interests in signalling the capital markets and in obtaining a full power license. Thus it had no basis in the record for making the "otherwise in the public interest" finding required under Section 50.12(a).

4. Failure to Consider Evidence Concerning Whether There is a Need for the Electric Power to be Provided by Shoreham

At LILCO's request, the Miller Board refused to admit New York testimony which established that there is no need for Shoreham's power for at least 10 years and perhaps longer. See Tr. 2902-03. Commission precedent makes clear, however, that the need for power is very relevant to decisions on exemption requests. See United States Department of Energy (Clinch River Breeder Reactor Plant), CLI-83-1, 17 NRC 1, 4 (1983); Washington Public Power Supply System (WPPSS Nuclear Projects Nos. 3 and 5), CLI-77-11, 5 NRC 719 (1977).^{13/} In direct conflict with this legal authority, however, the Miller Board struck the New York testimony on the question of the need for electric power. See Tr. 2903. The Board's refusal to consider whether there is any need for the power to be supplied by Shoreham was clearly erroneous, and the prejudicial impact of this ruling was substantial.

(Footnote cont'd from previous page)

not intended to be a repetition of the factors considered in making the health and safety findings. 2 AEC at 394, n.1.

^{13/} The Miller Board appears to acknowledge the significance of this fact by its citation of Shearon Harris II, CLI-74-22, 7 AEC 938 (1974), which it quotes as holding that "the timely satisfaction of public needs by reducing unanticipated delays in the realization of facility benefits . . ." constitutes an example of an exigent circumstance. Decision at 58.

First, the fact that Shoreham's power is not needed for at least 10 years totally obviates the need for the exemption requested by LILCO, which has resulted in the unprecedented rush to license Shoreham by means that violate the parties' constitutional rights and defy logic and reason. Because there is no need for Shoreham's electricity, there is simply no need to dispense with the normal NRC requirement that LILCO comply with safety regulations before a license is issued.^{14/} Thus, the fact that there is no need for Shoreham's power for at least 10 years is dispositive of LILCO's exemption request. In refusing to consider evidence on this subject, therefore, the Miller Board not only ignored Commission precedent but also ignored clearly dispositive evidence.^{15/}

Second, the Miller Board's reliance upon LILCO's evidence concerning so-called "benefits" of bringing Shoreham into full power -- a speculative conclusion which assumes the existence of a need for the power (as well as the eventual issuance of a full power license) -- substantially increases the prejudice resulting from its refusal to admit Intervenors' evidence concerning the absence of need for that power. Thus, this Miller Board ruling is yet another example of the Board's consistent pattern of considering and relying upon

^{14/} Moreover, the fact that Shoreham's electricity is not needed means that the only logical and reasonable course of action -- resolving the uncertainties relating to emergency planning before any contamination of the reactor -- can be followed without any adverse impact on the provision of electricity to Long Island.

^{15/} The fact that ample LILCO generating capacity exists to satisfy probable demand for at least 10 years was contained in an exhibit which was admitted into evidence. SC LP Ex. 20. However, it is clear from the Miller Board's Decision and from its ruling that the evidence concerning the need for electric power in Mr. Kessel's testimony was inadmissible, that the Miller Board failed to consider at all these undeniably significant data in granting LILCO's exemption request.

evidence which favored LILCO's position and ignoring any evidence which could point to a result other than one in LILCO's favor.^{16/}

B. Errors Relating to Security Determination

1. Denial of Hearing on Security Issues Arising from Proposed Change in AC Power Configuration

The Commission has recognized that physical security issues are pertinent to the granting of an exemption. See Long Island Lighting Co. (Shoreham Nuclear Power Station, Unit 1), NRC Memorandum and Order, _____ NRC _____ (July 18, 1984) (slip op. at 2-3, and n.1). That Order was issued in response to the County/State motion for directed certification of a June 20, 1984 Miller Board Order which precluded intervenors from raising any physical security issues.^{17/}

^{16/} Fundamental due process requires an administrative agency, in issuing an order, to make a reasoned analysis based on adequate findings supported by substantial evidence in the record. See Cotter v. Harris, 642 F.2d 700, 706-07 (3d Cir. 1981) (administrative judge cannot reject evidence for no reason or for wrong reason; an explanation why probative evidence has been rejected is required); Aberdeen & Rockfish Co. v. United States, 565 F.2d 327, 334-35 (5th Cir. 1977), rev'd on other grounds sub nom, Long Island Ry. Company v. Aberdeen & Rockfish Ry. Company, 439 U.S. 1 (1978), modified sub nom, Aberdeen Rockfish Ry. Company v. United States, 586 F.2d 609 (5th Cir. 1979); Great Lakes Screw Corp. v. NLRB, 409 F.2d 375, 379 (7th Cir. 1969); Taylor v. Heckler, _____ F.Supp. _____ No. 83-398 (D.D.C. Sept. 5, 1984).

^{17/} As the Commission recognized, the County and State sought to raise the following issues before the Commission:

Is a showing that a requested exemption from the NRC's regulations will not endanger the common defense and security required in order to obtain an exemption under 10 CFR §50.12(a)?

Is evidence relating to such a showing by LILCO relevant and admissible in the proceeding to be held on LILCO's Application for Exemption?

July 18 Order at 2, n.1. The Commission observed that while "it is not at all clear that a physical security (sabotage) issue involving a light water

(Footnote cont'd next page)

The Commission also recognized that LILCO's exemption application "represent[ed] a new development in this proceeding, and it raise[d] some new issues not heretofore considered." Id. at 2. Furthermore, the Commission later stated that in issuing its July 18 Order, it had "specifically considered the full text of the 1982 settlement agreement" between LILCO and Suffolk County relating to LILCO's then existing security plan. Long Island Lighting Co. (Shoreham Nuclear Power Station, Unit 1), NRC Memorandum and Order, _____ NRC _____ (August 20, 1984) (slip op. at 2). In its July 18 Security Order, the Commission held that the parties "were to be afforded the opportunity to raise new contentions, so long as they were responsive to new issues raised by LILCO's exemption request, relevant to the exemption application and decision criteria cited and explained in the May 16, 1984 Order, and reasonably specific and otherwise capable of on-the-record litigation." July 18 Order at 2-3.

Suffolk County and the State of New York submitted seven detailed contentions concerning the security issues raised by LILCO's exemption proposal.^{18/}

(Footnote cont'd from previous page)

power reactor is cognizable as a 'common defense and security' concern," that was "only an academic legal point, since a light water power reactor physical security issue is, in any event, cognizable as a public health and safety concern or, using the language of the standards for exemptions in 10 CFR 50.12(a), a concern bearing on whether the exemption will 'endanger life or property.'" Id.

^{18/} Due to safeguards considerations, we do not discuss the details of those contentions in this pleading, but instead refer the Board to the Security Contentions of Suffolk County and the State of New York filed August 13, 1984; LILCO's Response to Board's August 14, 1984 Request for Information on the Shoreham Security Program and Reply to Proposed Security Contentions, dated August 24, 1984; Suffolk County and State of New York Reply to LILCO Security Filing, dated August 28, 1984; the transcripts from conferences held August 16, 1984 (Tr. S-1 to S-94); August 30, 1984 (Tr. S-95 to S-184), and September 14, 1984 (Tr. S-185 to S-333); and the Miller Board's September 19, 1984 Order Denying Revised Security Contentions (Restricted Version).

In its Decision, the Miller Board characterized the contentions as follows:

A pervasive issue throughout the proffered revised security contentions was whether LILCO's power "enhancement" equipment should be treated as "vital," thus located in "vital areas" under NRC regulations. . . .

The Intervenor also argued that the "change in configuration" wrought by the addition of the enhancements created new or different vulnerabilities for the site.

Decision at 20.

On September 19, 1984, the Miller Board denied admission of all the proposed security contentions, despite the fact that the Staff had agreed that certain of the contentions were both admissible for litigation and raised legitimate substantive concerns with which the NRC Staff agreed. See, e.g., Tr. S-81, S-133, S-144-48, S-190-91, S-195; Letter, dated September 11, 1984, from A. Schwencer to J.D. Leonard. This Miller Board ruling was also made in the face of LILCO's admission that the existing physical security plan had never been modified to take into account the configuration changes proposed for low power operation. See e.g., Tr. S-10, S-70; LILCO's Response to Board's August 14, 1984 Request for Information on the Shoreham Security Program and Reply to Proposed Security Contentions, at 1-9.

The Miller Board Order of September 19 was clearly erroneous. First, it appears to be premised largely on the fact that, based on a re-evaluation of LILCO's proposed alternate configuration, the NRC Staff decided to support some of Intervenor's security contentions. Consistent with that position, the Staff requested LILCO to amend its security plan in ways alleged to be necessary in those contentions. The Staff's position was explained in a letter to LILCO which was transmitted prior to the Board's ruling on the proposed security contentions. A copy of the Staff's letter was provided to the Board, and prompted

the Board to hold a conference of counsel purportedly to discuss the Staff's position. See Order Scheduling Conference of Counsel, September 11, 1984, and September 14, 1984 Transcript (Tr. S-186 to S-333).^{19/}

The Miller Board rejected the Staff's position on the substantive safety and security question which was raised in Intervenor's contentions and supported by the Staff. In its September 19 Order (at 7), the Miller Board characterized its action as "overruling" the Staff's position "as a matter of law" pursuant to 10 CFR § 2.717(b). In its October 29 Decision, the Miller Board described its action as follows:

We held as a matter of law that under a request for exemption from certain regulations for the purpose of low power testing, the power enhancements need not be treated as "vital." To require this equipment to be treated as vital would, in effect, negate the exemption provisions. Thus, we rejected contentions which asserted that the enhancements must be so treated.

Decision at 20.

The Miller Board made its September 19 ruling based on some unexplained theory of allegedly improper NRC Staff "attempts to frustrate" the "Board's adjudicatory independence and integrity," along with bizarre and undocumented suggestions of improper Staff conduct characterized by the Board as "efforts at intimidation by vituperation." See Order Denying Revised Security Contentions (Restricted Version), September 19, 1984, at 4-7. The Board further

^{19/} We urge this Board to review the transcript of the September 14, 1984 conference of counsel because, in our view, it will document in glaring detail the Miller Board's incapability of dealing fairly with the issues. Thus, it will reveal a concerted attack by the Board on the Staff, prompted so far as we can tell by the Board's outrage that the Staff had changed its substantive position on a security matter to a view which supported the County and State.

characterized the Staff's statement of position in support of Intervenor's contentions as "an apparent attempt to influence the Board's imminent adjudicatory ruling on the identical issue." Id. at 6. There was no basis for the Board's rejection of the Staff's position, nor for its use of such rejection as the basis for its rejection of the Intervenor's contentions. (Again, as indicated in note 19, above, this Appeal Board should read the September 14 transcript to get a fuller understanding of the Miller Board's conduct).

Second, the Board determined that it could "overrule as a matter of law" the Staff's position in support of certain of the Intervenor's contentions apparently based on the Board's assumption that LILCO intended its exemption request to encompass a request for an exemption from the requirements of 10 CFR Part 73. See Decision at 7-8. There is no basis for this assumption; moreover, even if LILCO had so intended (without so indicating in its Application for Exemption), that does not in any way justify the Board's ruling that the Staff's position in supporting Intervenor's contentions was wrong "as a matter of law," or its ruling that the contentions were not admissible for litigation in the exemption proceeding. Indeed, the Board's rulings directly contradict the July 18 Order of the Commission which recognized that security issues could arise and could be litigated in the context of LILCO's exemption application for low power operation. Furthermore, even if LILCO's request had included a request for an exemption from the security regulations, its entitlement to that exemption clearly would have been within the ambit of the exemption proceeding being conducted by the Miller Board.^{20/}

^{20/} The Board's so-called ruling "as a matter of law" also contradicts NRC precedent, Virginia Electric and Power Co. (North Anna Power Station, Units 1 and 2), LBP-77-64, 6 NRC 808, 813 (1977), in which full implementation of all aspects of a physical security plan was required prior to fuel loading.

Third, the Board's rulings concerning the individual contentions themselves (see Restricted September 19 Order at 12-19), are clearly erroneous. Those rulings are: (a) reiterations of the erroneous and baseless so-called "conclusion of law" discussed above; (b) findings on the merits of the contentions, based solely upon representations made by LILCO's counsel, and improper in the context of ruling on the admissibility of contentions; (c) distortions or misstatements of the allegations contained in the contentions themselves, which are readily apparent upon reading the contentions; or (d) contrary to the well established Commission precedent concerning the basis and specificity requirements for admissible contentions. See Houston Lighting and Power Co. (Allens Creek Nuclear Generating Station, Unit 1), ALAB-590, 11 NRC 542 (1980); Philadelphia Electric Co. (Peach Bottom Atomic Power Station, Units 1 and 2), ALAB-216, 8 AEC 13 (1974); Mississippi Power and Light Co. (Grand Gulf Nuclear Station, Units 1 and 2), ALAB-130, 6 AEC 423 (1973). For all these reasons, the Miller Board's September 19 Order precluding the litigation of security issues identified by Intervenors and the NRC Staff arising out of LILCO's proposed alternate power configuration and pertinent to low power operation, was clearly erroneous, in violation of the Commission's Orders, and constituted a deprivation of Intervenors' right to a hearing on the security aspect of the exemption question.

2. Findings Relating to Security Without Any Basis in Evidentiary Record

Despite its refusal even to consider specifically identified security issues, much less to obtain evidence on those issues, the Miller Board nonetheless made so-called "Findings of Fact" concerning the alleged adequacy of LILCO's

physical security arrangements. See Decision at 76-77, ¶¶ 21-25. Moreover, the Miller Board's findings 22, 23 and 24 actually track, in some respects almost verbatim, the very contentions proposed by the State and County, concerning which the Board had precluded Intervenor's from submitting evidence. One of these findings purports to rely upon extra-record LILCO and Staff representations made after the Board had improperly rejected the proposed contentions. The remainder have no stated basis whatsoever. As could be predicted, the substance of each of these Miller Board findings is as LILCO had argued: that Intervenor's contentions are wrong.^{21/}

Given the language of Section 50.12(a) and the Commission's July 18 Order, the Miller Board knew that it had to make affirmative security findings that were favorable to LILCO in order to grant LILCO's exemption request, particularly in view of the security vulnerabilities created by LILCO's alternate AC power configuration which had been recognized by the Staff (but "overruled" by the Miller Board). The Miller Board's findings relating to security, however, are clearly without any factual basis in the evidentiary record, since the Board refused to permit any evidentiary record to be compiled. Thus, in addition to the errors embodied in the Board's September 19 Order denying admission of the security contentions, the Miller Board's subsequent issuance of so-called "findings"

^{21/} Thus, the Miller Board purported to "find" as "facts" that: "Placement of additional equipment outside of and a reasonable distance from the Shoreham plants vital areas, does not impair nor impact upon established security procedures for protection of the vital areas"; "the need for security of emergency AC power systems during low-power is diminished"; "in the posture of a request for exemption from certain regulations for purpose of low power testing, emergency AC power sources need not be protected as 'vital' equipment"; and, "LILCO's security arrangements provide reasonable assurance that its emergency power enhancements will be protected during the occurrence of a security-related event." Decision at 76-77.

concerning the alleged adequacy of LILCO's security provisions constitutes an additional and even more flagrant and prejudicial violation of Intervenor's due process rights.

C. Errors Relating to Exigent Circumstances Finding

1. Exclusion of Suffolk County Evidence Concerning LILCO's Alleged Good Faith Attempt to Comply with GDC 17 and Admission of LILCO Evidence on the Same Subject

The Commission stated that it "regards the use of the exemption authority under 10 CFR 50.12 as extraordinary," and that such a method of relief "has previously been made available by the Commission only in the presence of exceptional circumstances," citing United States Department of Energy (Clinch River Breeder Reactor Plant), CLI-83-1, 17 NRC 1, 4-6, and the cases cited therein. 19 NRC at 1156, n.3. Thus, the Commission held that "A finding of exceptional circumstances . . . governs the availability of an exemption." Id. (emphasis added). The Commission further emphasized the significance of this required finding that extraordinary conditions exist to justify granting the exceptional relief of an exemption, by expressly distinguishing the exceptional circumstances finding from the separate requisite findings on public health and safety and common defense and security. Id. The Commission also stated that "the applicant's good-faith effort to comply with the regulation from which an exemption is sought" is one example of an "equity" to consider in determining whether exceptional circumstances exist to justify the granting of a Section 50.12(a) exemption. Id.

LILCO asserted in its exemption application that "LILCO's strenuous efforts to comply with GDC-17 . . . weigh in favor of the exemption." Application for Exemption, at 24. LILCO also submitted testimony to the Miller Board concerning

LILCO's alleged good faith efforts to comply with GDC 17, and asserted that among LILCO's "efforts" which justify the grant of the exemption were: LILCO's efforts relating to the procurement of TDI diesels which were designed and manufactured to meet performance standards identified by LILCO; LILCO's quality assurance efforts relating to the procurement, design, and installation of the TDI diesels; LILCO's pre-operational testing program relating to the TDI diesels; and, LILCO's efforts following the catastrophic failure of one of the TDI diesels at Shoreham to remedy that failure. See Tr. 1703-15.

In response, Suffolk County submitted pre-filed testimony on precisely the subject addressed by LILCO. The County's testimony established: that LILCO had failed to take reasonable actions with respect to the TDIs to ensure compliance with GDC 17; that LILCO's failures began with procurement efforts in 1974 and continued through the early 1980's; and that the failures involved, among other things, LILCO's quality assurance efforts and pre-operational testing efforts which were discussed in LILCO's testimony.^{22/} For no explicable reason, the Miller Board denied the admission of the County's testimony even though it admitted LILCO's testimony on the same subject. See Tr. 2385-89.^{23/} This Board

^{22/} For the Appeal Board's convenience, copies of the County's testimony are provided herewith since, due to the Board's ruling, the testimony is not included in the hearing transcript. See Attachment 3.

^{23/} The Miller Board purported to identify grounds for its ruling striking the County's evidence, but a review of the statements by Judge Miller which constitute that ruling provides no indication that any rational basis existed for the ruling. Thus, his ruling consisted of the following observations:

"The grounds upon which the Board strikes this proffered direct testimony is, first of all, the fact that a good deal of it goes to the issue of alleged or perceived negligence, fault or whatever." Tr. 2385.

(Footnote cont'd next page)

action was taken at LILCO's request. See Tr. 2370-85. Clearly, there is a

(Footnote cont'd from previous page)

"We think, first of all, that the good faith or bad faith issues as framed by the Commission is not an issue of contributory negligence." Tr. 2385.

"[T]he product of this testimony is that this direct written testimony does invade the province of the finder of fact" Tr. 2386.

"[W]e have no quarrel with the qualifications of these witnesses. We consider them to be qualified in the areas in which they have testified on voir dire" Tr. 2386.

"[T]he expression here of those opinions is not consistent with (a) the nature of opinion testimony, and this is proffered as opinion testimony. . . . We just don't think those opinions are admissible by this panel and probably by any panel in this proceeding." Tr. 2386.

"[M]any of the instances where criticisms are made are not areas in which the Board deems it necessary to inquire. We are not holding an inquiry on the TDI matter." Tr. 2386-87.

"[W]e don't attach any significance one way or the other to the Brenner Board's inquiry" Tr. 2387.

"[T]he witnesses say 'It is our position that LILCO was in effect responsible,' and so forth. Well, we don't want that kind of position from a witness." Tr. 2387.

"Farther down in the answer [the witnesses state] 'Our point is that it is not in the public interest [. . .]' Well, I don't want a witness to have a point. I want him to testify. It is only because they are experts that they can give opinions, but this is not an area for opinion testimony." Tr. 2388.

"[W]e have indicated that good faith efforts cannot be equated with negligence or should have's in a hindsight manner and then suddenly some conclusions are drawn that bingo." Tr. 2388.

"[The witnesses state] 'Nor is it equitable to reward a utility by waiving [. . .],' now that is argumentative, it is conclusionary and again it invades a problem." (sic) Tr. 2388.

"[T]his is improper opinion testimony" Tr. 2389.

denial of a fair hearing and due process when a fact finder admits one party's testimony on a subject and refuses even to consider the testimony submitted by another party on the identical subject.^{24/}

The prejudicial impact of this Miller Board error is manifest in its Decision. The Board found, for example, the following:

The testimony of [LILCO's witness] Brian McCaffrey showed that the TDI diesels were purchased under specifications designed to comply with GDC-17. When problems were discovered, extensive efforts were undertaken to cure the deficiencies.

LILCO provided a specification which called for certain performance standards and assumed through a preoperational test programs that the machines were capable of running at the performance rating LILCO utilized its own and its architect/engineer's quality assurance program to oversee TDI's quality assurance programs

The preoperational test program identified problems needed correction. LILCO responded by correcting individual problems and by initiating a . . . Review Program

Decision at 67. 98-101. And, based on these findings, the Board concluded that "LILCO's efforts as described in detail constitute the good faith to be considered in evaluating the equities, and support the grant of an exemption." Id. at 67.

The Miller Board thus relied solely upon the LILCO testimony in purportedly "weighing the equities" as required by the May 16 Order; in reality, of course, no such "weighing" occurred, nor could it have occurred, in the presence of only LILCO's one-sided evidence. Moreover, despite its having stricken the County's

^{24/} The Board also denied the County's motion to strike the LILCO evidence on its alleged good faith efforts concerning the TDIs in light of the Board's ruling that the County's evidence on that subject was inadmissible. See Tr. 2866-72.

testimony concerning LILCO's efforts relating to the TDIs, the Miller Board nonetheless made numerous findings, based solely on LILCO's evidence, on precisely that subject -- LILCO's efforts relating to the TDIs. In refusing to admit the County's evidence, the Miller Board clearly denied Intervenors the right to a hearing on the subject of LILCO's good faith efforts to comply with GDC 17 and whether such efforts constitute exigent circumstances, one of the issues the Commission had expressly identified as pertinent to an exemption ruling.

2. Improper Reliance Upon Evidence Concerning the Length and Costs to LILCO of the Shoreham Licensing Proceeding

LILCO's evidence concerning the alleged existence of exigent circumstances to justify an exemption also included testimony concerning the length and costs of the NRC licensing proceeding. Intervenors moved to strike as irrelevant this testimony (Tr. 1715-31), in which LILCO (a) complains that the Shoreham proceeding has lasted for several years, (b) alleges that the Staff has imposed extra and technically unjustified burdens on LILCO, and (c) complains that LILCO has had to expend a great deal of resources in pursuing its quest for a license. See Tr. 1680-92. The Staff agreed that this testimony was irrelevant and supported the motion to strike. Tr. 1693. Once again granting LILCO's request (Tr. 1693-97), the Miller Board overruled the Intervenors' and Staff's motion and admitted the testimony submitted by LILCO. Tr. 1698.

There is no indication in any Commission precedent that such evidence (even if believed) would support the extraordinary relief of an exemption. This LILCO testimony amounts to nothing but an assertion of LILCO's apparent belief that it has a right to receive a license from the NRC. In fact, however, it is clear that nobody has a right to an NRC license; all persons applying for such

licenses do so at their own risk and subject themselves to the NRC's rules and regulations, to the rulings of Licensing Boards and the Commission, and to the technical judgments and requirements of the NRC Staff. There is simply no basis for LILCO to complain about the NRC licensing process, actions of the NRC Staff, or the length of the proceeding. There is certainly no basis for LILCO's audacious non sequitur that because it has been involved in a contested NRC licensing proceeding convened to test LILCO's compliance with NRC safety requirements, "fairness requires" it should now be granted an exemption from complying with those very NRC safety requirements.

Nonetheless, the Miller Board relied heavily upon this LILCO testimony in its Decision:

The costs of unusually heavy and protracted litigation may also properly be considered in evaluating financial or economic hardship as an equity in this exemption proceeding. . . . It is beside the point to argue that such litigation is permitted under NRC regulations. Although not illegal, such interminable litigation has resulted in great expense to LILCO, both in terms of time and resources. . . .

The unusually heavy financial and economic hardships associated with the very protracted Shoreham licensing proceedings constitute a significant equity, which we hold can reasonably be held to amount to exceptional circumstances in the context of granting a low power exemption.

Decision at 62-63 (emphasis added). See also id. at 59-60. There is no legal, factual, or logical basis for the Board's conclusion that LILCO's litigation costs constitute exigent circumstances which justify an exemption from compliance with important safety regulations.^{25/} The Board's reliance upon LILCO's

^{25/} The Staff and the Commission's Licensing Boards are required to make specific findings concerning the safety of a nuclear plant, and they undertake whatever reviews are necessary to enable them to make the requisite findings. The fact that for Shoreham extensive Staff review and hearings on contentions admitted by Licensing Boards have been necessary to enable the

(Footnote cont'd next page)

clearly irrelevant testimony, as well as its consideration only of the alleged financial and economic hardships borne by LILCO and its refusal even to consider those put forth by the State and the County which would be borne by the public (see Section II.A above), constitute clear error, and one more instance of the Board's denial of a fair trial to Intervenors.

3. Improper Consideration of Prior Staff Practices as Basis for Finding Exigent Circumstances to Support Exemption

In purportedly "weighing the equities" and determining that exigent circumstances exist, the Miller Board considered alleged prior Staff practices in permitting the issuance of licenses despite noncompliance with safety regulations. See Decision at 63-66. The information apparently relied upon by the Miller Board concerning such prior Staff practices is not in the evidentiary record and was never available to be cross-examined. Clearly, the Intervenors had no opportunity to challenge the relevance, similarity or applicability to the facts at issue in this proceeding of the information apparently relied upon by the Miller Board. The Miller Board's reliance upon such extra-record information is clearly erroneous, and constitutes another example of its abuse of due process in an effort to provide a license for LILCO.

Further, the Miller Board's suggestion that the Staff's behavior in situations involving other utilities or regulations somehow justifies the issuance of a license in the face of LILCO's non-compliance which is at issue in this

(Footnote cont'd from previous page)

Staff and Boards to make the findings required under the regulations, does not constitute the kind of "exigent circumstances" which justify the grant of an exemption or the issuance of a license.

proceeding, whether on the basis of a "constitutional equal protection" theory,^{26/} or for the sake of "consistency," is patently absurd. The Commission has ruled expressly on how LILCO's noncompliance with the Commission's regulations must be handled. See 19 NRC at 1155-56. Whatever the Staff may have done prior, or even subsequent, to the Commission's Shoreham rulings with respect to other plants, and whether such actions were right or wrong, cannot change the Commission's ruling that LILCO must meet the Section 50.12 standards as enunciated in the May 16 Order. The Board's finding that allegedly "inconsistent" Staff practices constitute an exigent circumstance that justifies granting the exemption request is without any legal or factual basis and is clearly erroneous.

D. Errors Relating to the As Safe As Determination

1. Exclusion of Suffolk County Testimony Which Demonstrated that Operation With the Alternate AC Power Configuration Would Not Be As Safe As Operation With a Fully Qualified On-Site Power System, and Admission of All Evidence Submitted by the Staff and LILCO Concerning the "As Safe As" Comparison

In its May 16 Order, the Commission established that to obtain an exemption, LILCO must demonstrate "that, at the power levels for which it seeks authorization to operate, operation would be as safe under the conditions proposed by it, as operation would have been under a fully qualified on-site AC power source." 19 NRC at 1156.

LILCO, the Staff, and Suffolk County submitted testimony concerning: (1) the reliability and operational capabilities of the individual items of

^{26/} See ASLE Order Reconsidering Summary Disposition of Phase I and Phase II Low-Power Testing, September 5, 1984, at 7, referenced in Decision at 64, n.133.

equipment which make up LILCO's proposed alternate power configuration (i.e., the EMD diesels and the gas turbine); and (2) whether low power operation with the alternate AC power configuration as a whole, would be as safe as operation with a fully qualified onsite AC power system.^{27/} The Board admitted substantially all the submitted testimony on the first subject, including that submitted by Suffolk County. The Board also admitted LILCO and Staff testimony which asserted that operation of Shoreham with the alternate AC power configuration as a whole would be as safe as operation with a fully qualified on-site AC power system. At LILCO's urging, however, the Board refused to consider the Suffolk County testimony which compared the safety of low power operation with the alternate AC power configuration as a whole, with that of such operation with a qualified on-site configuration. See Tr. 2844, 2856-58. In making this ruling, the Miller Board once again followed its pattern of denying Intervenors a fair hearing on one of the issues central to the exemption proceeding.

It is not surprising that LILCO and the Miller Board did not want the County's testimony in the evidentiary record: the County testimony demonstrated that operation of Shoreham with the alternate AC power configuration would not be as safe as operation with a fully qualified onsite power system.^{28/} The County witnesses had performed both qualitative and quantitative (PRA) analyses in support of their opinions. Their testimony documents that low power operation with the alternate AC power system is quantifiably less safe than low

^{27/} See Tr. 198-228, 265-323, 480-524, 554-78, 845-68, 962-1021, 1160-1211 (LILCO); Tr. 1782-1800, 1849-53, 2337-57 (Staff); Tr. 2572-635, 2762-819, 2842-44 (submitted, but denied admission) (Suffolk County).

^{28/} Copies of the County testimony, which due to the Board's ruling is not contained in the hearing transcript, are provided herewith as Attachment 4.

power operation with a fully qualified AC power system: a loss of off-site power transient during low power operation of Shoreham is seven times more likely to lead to a core vulnerable condition with the alternate configuration than with a fully qualified source of on-site AC power; and the likelihood that Shoreham would experience an event leading to core vulnerability during low power operation is two and one-half times greater under the alternate configuration than it would be under a qualified configuration. See Attachment 4. Such testimony was directly responsive to the comparison mandated by the Commission's May 16 Order.

The Miller Board clearly erred in refusing to admit this testimony.^{29/} The

^{29/} The Board's assertion that a probabilistic risk assessment is not "a proper method to be used in this proceeding" (Tr. 2858) as a basis for its ruling is simply wrong and, in any event, is beside the point. PRAs have been required by the Staff in some proceedings (see, e.g., Tr. 2857), and the full power PRA performed by LILCO has been reviewed by the Staff and was considered by the Brenner Board and, indeed, by this Board in ALAB-788. See Long Island Lighting Co. (Shoreham Nuclear Power Station, Unit 1), ALAB-788, ___ NRC ___ (1984) (Slip op. at 42-48). Furthermore, while there may be no requirement to perform PRA analyses as a general matter, there is also no bar to the use of probabalistic data, if available, to evaluate the relative safety of operation in different configurations. See, e.g., Letter dated June 15, 1984 from Nunzio J. Palladino to the Honorable Edward J. Markey and attachments thereto. The remainder of the Board's observations which comprise its "ruling" also state no rational basis for its refusal to admit the County's evidence:

"[The testimony] is not relevant to the issues raised by this low power licensing proceeding."

"We do not believe that it would aid the Board in decision-making. We believe that there is sufficient deterministic evidence from which determinations can be made for an examination of the record, and we believe that that is the present situation, both insofar as the Commission's rules are concerned, and in the way in which such rules, particularly those relating to probabalistic risk assessments should be determined in this case."

"We have no desire under those circumstances to go into

(Footnote cont'd next page)

prejudice to Intervenor which resulted from the Board's ruling is again manifest in its Decision. Although the Board discussed to a limited extent the reliability of individual items of equipment involved in the alternate AC power configuration, as to which the County's evidence was admitted, it also asserted that a "point-by-point comparison of Shoreham's emergency power configuration with TDI diesels and without them" is not a proper comparison; rather, the Board asserted, a "functional comparison," which was urged by LILCO, is proper. See Decision at 22, 25-26. By its "functional comparison" the Miller Board apparently meant a system comparison rather than a component comparison. Id. In discussing its "functional comparison," however, the Board considered only the LILCO and Staff testimony, since the County's evidence which compared the safety of the functioning of the two systems during low power operation was denied admission by the Board.^{30/}

(Footnote cont'd from previous page)

[the substance of the testimony] can in any way have a relevance to this proceeding." (sic)

Tr. 2858 (Miller).

^{30/} The Board improperly characterized the County's position in the hearing as being limited to "a point-by-point comparison of components of systems." Decision at 22-23, 25. The Board similarly incorrectly asserted that:

Suffolk County's testimony was devoted almost exclusively to showing that each unit in the enhanced system (the gas turbine and the EMDs) was either inferior to the qualified system or, in the case of the EMDs, that the potential existed for a single failure which would disable all four of them.

Id. at 50-51. Such characterizations of the County's testimony are in fact largely a reflection of the Board's own erroneous rulings. See also discussion in Section II.D.2 below.

Despite its refusal to consider the County's testimony, the Miller Board found that operation with the alternate AC power configuration "provides a comparable level of protection as a fully-qualified system would and thus meets the 'as safe as' standard set by the Commission in CLI-84-8." Id. at 55 (emphasis added). See also id. at 102. Clearly, in reaching its "as safe as" -- or "comparability" -- conclusion without even considering the County evidence concerning the precise comparison mandated by the Commission, the Board erred, and denied Intervenors a hearing on an issue central to the exemption request. Indeed, in ignoring evidence that low power operation under the exemption would be seven times less safe than with a qualified AC power system, the Miller Board made a mockery of the entire proceeding.

2. Improper Application of Commission's As Safe As Standard

The Commission's requirement that low power operation "be as safe under the conditions proposed by [LILCO], as operation would have been under a fully qualified on-site AC power source" (19 NRC at 1156) was mandatory and binding upon the Miller Board. In its Decision, the Board appears to adopt the view that the Commission's "as safe as" standard means "a comparable level of protection." See Decision at 27.

The Board's interpretation and application of the Commission's standard, as manifested in the Decision, was clearly erroneous. The Commission's standard calls for a direct comparison of the two AC power configurations -- the alternate system versus the fully qualified system. If the safety provided by operation with the alternate system does not fully measure up to that provided by operation with a fully qualified system, then under the Commission's standard the exemption must be denied.

The Commission's requirement that the safety of operation under each configuration be the same, is a reasonable one. Moreover, it is particularly critical in the context of low power operation, which is at issue here, since the Commission's regulations (10 CFR § 50.47(d)) permitting low power operation without an approved off-site emergency plan are premised on there being a margin of safety during low power operation that is greater than that present during full power operation. See 47 Fed. Reg. 30,234 (July 13, 1982). Clearly, any reduction in safety margins during low power operation due to the use of the alternate AC power configuration would undercut completely the rationale underlying 10 CFR §50.47(d), and thus render it illegal for the NRC to authorize a low power license without a fully approved and implemented offsite emergency plan. Accordingly, the Commission's clear requirement that for an exemption to be granted for low power operation there must be no erosion in the margin of safety that would be provided by a system in full compliance with the regulations during low power operation, makes sense and indeed must be applied strictly. The Miller Board refused to apply that requirement in ruling on LILCO's exemption request.

For example, in its Decision, the Miller Board recognized, but then ignored by ruling in LILCO's favor, the obvious reduction in safety that would result from low power operation with the proposed alternate configuration. Thus, the Miller Board admitted that "there is unquestionably a lesser margin of safety provided by LILCO's alternate power system" (Decision at 24, emphasis added), thereby establishing that LILCO does not satisfy the Commission's straightforward "as safe as" standard. Similarly, the Board found that "It is, of course, obvious that a fully qualified system would have an established and documented

higher resistance to seismic events than does the system proposed by LILCO . . . , " (id., at 52), again establishing that operation with LILCO's alternate configuration inherently provides a lesser margin of safety. For this Board to affirm the Miller Board's recommendation of a low power license given these factual findings would be to violate the May 16 Order and 10 CFR § 50.47(d) as well.

The Miller Board also rejected as irrelevant the fact that a qualified system could provide emergency power to safety loads within 15 seconds, whereas the alternate configuration could not supply power for a minimum of several, but up to 30, minutes. The Board thus found that since there are at least 55 minutes to restore power before core damage results during low power operation, it is not significant that under LILCO's alternate configuration 30 minutes of that time (as opposed to 15 seconds) could be necessary before any power is available -- or before it is even known by plant personnel that power will not be available. See id. at 23-25. Such a finding is plainly inconsistent with the Commission's "as safe as" standard.

The Miller Board's finding that evidence concerning the inferiority of the alternate equipment proposed to be used by LILCO, and its vulnerability to single failures was "irrelevant" (id. at 51) is inexplicable, and clearly erroneous. What could be more relevant to findings under the "as safe as" criterion than a discussion of the vulnerabilities and inferiorities of such equipment as compared to those in a fully qualified system? Similarly, the Board's assertion that "there is no need to consider the relative merits of the two systems per se, because for the purpose of the exemption request, it is only necessary to establish that the enhanced system is capable of performing its intended

function" (id. at 52 (emphasis added)), is yet another example of the Board's improper application of the standard set by the Commission. The capability of performing a particular function is clearly important; however, the finding mandated by the Commission must go beyond mere abstract capabilities to determine whether in light of the alternate system's capabilities, actual plant operation would be as safe as operation would be given the capabilities of a qualified system.

Clearly, the Miller Board ignored the standard set by the Commission: the Commission did not set a standard of whether operation with the alternate configuration would, in the judgment of the Board, be safe enough, nor did the Commission instruct the Miller Board to come up with a definition of how much safety is "enough." Rather, the Commission, certainly mindful of the impact of the exemption request on other NRC regulations (such as 10 CFR § 50.47(d) discussed above), instructed the Miller Board to determine whether operation with the alternate configuration would be as safe as operation would have been with fully qualified TDI diesels. A reduction in the margin of safety, or a reduction in the defense in depth protection which is central to the NRC's licensing concept, cannot be ignored under the Commission's as safe as standard. Plainly, however, the Miller Board did exactly that.

Apparently as a result of its distortion and misapplication of the "as safe as" standard, the Miller Board failed to consider, or simply chose to ignore, facts set forth in Suffolk County's expert testimony, which document a real reduction in safety that would result from operation with the alternate configuration as compared to that with a qualified configuration. All these facts, with citations to the record, are set forth in the County and State Findings submitted to the Miller Board. Some example are set forth below.^{31/}

^{31/} We note, where appropriate, that the Decision did at least acknowledge that some of the facts were presented by the County; however, the Miller Board

1. The alternate configuration contains only two power sources, whereas the qualified configuration contains three power sources. Clearly, there is less redundancy and thus, a reduced margin of safety, with the alternate configuration.

2. Portions of the two-part alternate configuration share common elements with the off-site power system and also share common features with each other, thus making the alternate system subject to single failures. In contrast, each of the three qualified diesels is a completely independent power source that is physically isolated from each of the other two and is fully independent of off-site power sources. See County and State Findings 107, 108, 285-91 and citations therein. Clearly, the alternate system's vulnerability to single failures, and its vulnerability to a common mode failure of the offsite system, represents a substantially reduced margin of safety as compared to a qualified system.

3. One-half of LILCO's alternate configuration -- the set of four EMD diesels -- is subject to single failures that would disable the entire set of diesels, because the four units share a common fuel system, a common starting system, common output cables and common controls. In contrast, each of the three qualified diesels meets the single failure criterion. See County and State Findings 104, 105, 108-130 and citations therein; Decision at 88, ¶ 68. Again, the vulnerability of one-half the alternate system to disabling single failures

(Footnote cont'd from previous page)

inexplicably concluded that operation with the alternate configuration would be as safe as operation with a qualified system in the face of the clear evidence to the contrary which we summarize in the text.

makes the margin of safety and defense in depth protection substantially less than that available with three single failure-proof power sources.

4. Operation of the alternate configuration requires many manual operations, in several different locations both inside and outside plant buildings, giving rise to many opportunities for human error. In contrast, a qualified system is fully automatic. See County and State Findings 164-65, 167-78, 267-78, 263-64, and citations therein; Decision at 88, ¶¶ 66 and 89, ¶ 73. Clearly, the reliance upon human operators to perform both properly and rapidly in the event of a station blackout, reduces the margin of safety from that available with a fully automatic emergency power system.

5. The alternate configuration is vulnerable to seismic events and is likely to fail in an SSE; a fully qualified system is designed to withstand the SSE. See County and State Findings 15-71, 77-80, and citations therein. See also Decision at 52 ("It is, of course, obvious that a fully qualified system would have an established and documented higher resistance to seismic events than does the system proposed by LILCO"). Clearly, a reduced resistance to seismic events and a likelihood of failure in an SSE, means that there is a smaller margin of safety of operation with the alternate configuration.

6. The alternate configuration has essentially no local fire detection or extinguishing systems, and there is a potential for fire and explosion because of the EMDs' battery starting system and poor ventilation. In addition, the abnormal condition alarms associated with the alternate configuration are not annunciated in the control room. In contrast, a qualified system includes both fixed fire detection and extinguishing systems for each generator, no battery system, and a comprehensive alarm system which is annunciated in the control

room. See County and State Findings 131-63, 260-62 and citations therein; see Decision at 88, ¶ 69. Clearly, there is a substantial reduction in safety margins, as compared to those present with a fully qualified system, if necessary equipment, such as that in the alternate configuration, is vulnerable to fire which may not be detected or extinguished, and if information concerning the abnormal status of necessary equipment is not immediately available to the plant operators.^{32/}

3. Improper Consideration of Offsite Power System

In its Decision, the Miller Board discusses what it terms the "reliability of LILCO's normal off-site power system." Decision at 40-46, 82-85. After describing various aspects of LILCO's off-site AC power system, the Board concludes that it is "unlikely that power would be unavailable to either the NSST or the RSST from normal off-site sources." Id. at 46 (emphasis added).

However, this exemption proceeding exists because LILCO does not have an on-site electric power system. The Miller Board was instructed by the Commission to consider whether LILCO's alternate configuration -- offered as a substituted for a qualified onsite system -- would result in low power operation that would be as safe as that available with a fully qualified on-site power system. Thus, LILCO's offsite power system is simply irrelevant to the required safety finding. Clearly, the focus of this proceeding was not meant to be LILCO's normal offsite power system: that is a constant which appears on both sides of

^{32/} Further, at least 16 additional technical specification requirements and 9 license conditions must be imposed before operation with the alternate configuration would be acceptable to the Staff; none of these requirements or conditions would be needed with a qualified source of AC power. See County and State Finding 297, and citations therein.

the comparison mandated by the Commission. Rather, the focus was to be the reliability and capability of LILCO's proposed alternate configuration (the gas turbine and EMIs) as compared to a fully qualified on-site system. Thus, to compare the relative safety of operation with a qualified on-site system and with LILCO's proposed alternate configuration, it must be assumed that the off-site system is not functioning. GDC 17 itself mandates the assumption that the onsite system will function assuming the offsite system is not functioning. The Miller Board's speculation about the adequacy of LILCO's off-site system and whether a loss of off-site power would be likely was irrelevant. Its reliance upon such speculation in making its "as safe as" finding was a clearly erroneous misapplication of the law and the Commission's rulings.

E. The September 5 Phase I and II Miller Board Order Violates the Commission's Rulings and Regulations.

In its September 5, 1984 Order Reconsidering Summary Disposition of Phase I and Phase II Low-Power Testing (hereinafter, "September 5 Order"), the Miller Board ruled that LILCO could load fuel and perform certain low power testing prior to a decision on its pending exemption application.^{33/} That ruling violated the Commission's May 16 Order, and was clearly erroneous as a matter of law.^{34/}

^{33/} See Decision at 5 for the Miller Board's definition of Phases I and II.

^{34/} Although the Commission stated that it had performed an immediate effectiveness review and, subject to certain conditions, ruled that the Miller Board's September 5 Order could become effective (see Memorandum and Order dated November 21, 1984 (CLI-84-21)), pursuant to 10 CFR § 2.764(g), this Appeal Board is prohibited from attaching any weight to either the Commission's effectiveness determination or any comments contained in the Commission's November 21 Order.

LILCO first requested the summary issuance of a license for Phase I and Phase II activities by its filing of Summary Disposition Motions directly with the Commission on May 4, 1984.^{35/} During the May 7 oral argument before the Commission which preceded the May 16 Order, LILCO's counsel discussed Phases I and II at considerable length in arguing that no exemption from GDC 17 was required prior to the issuance of a low power license to perform Phase I and Phase II activities. For example, the following statements were made to the Commission by LILCO's counsel:

We meet [GDC 17] in light of its application to a low power license. We do not have an onsite power system strictly speaking. However, in order to apply GDC-17 at this level of operation, you have to take into consideration the meaning of 50.57(c). And what LILCO says is that in interpreting the regulation for low power licensing, one ought to look at the level of operation intended and interpret the regulation, the General Design Criterion, accordingly (Rolfe, Tr. 15).

[F]or Phases 1 and 2 there is no risk to public health and safety because there is no need for AC power And for those reasons, LILCO asks that the Commission rule now and grant its motions for summary disposition for Phases 1 and 2. (Rolfe, Tr. 24).

However, the Commission rejected LILCO's express arguments that no exemption from GDC 17 was necessary for Phases I or II of its low power proposal. It stated:

After reviewing the oral arguments and written submissions of the parties, the Commission has determined that 10 C.F.R. 50.57(c) should not be read to make General Design Criteria inapplicable to low-power operation.

19 NRC at 1155. The Commission stated further:

^{35/} See LILCO's Motion for Summary Disposition on Phase I Low Power Testing dated May 4, 1984, and Motion for Summary Disposition on Phase II Low Power Testing, dated May 4, 1984.

[T]he applicant made clear at the May 7 oral argument its intent to seek an exemption under 10 C.F.R. 50.12(a). If it intends to follow that course, the applicant should modify its application to address the determinations to be made under 10 C.F.R. 50.12(a).

Id. at 2 (emphasis added).^{36/} Thus, the Commission's rulings that GDC 17 is applicable to LILCO's low power proposal and that LILCO must address in a modified application for a low power license the determinations which must be made in granting an exemption from regulatory requirements under 10 C.F.R. § 50.12, are applicable to Phase I and Phase II of LILCO's proposal.

Furthermore, if the Commission had intended to limit its ruling on the requirement for an exemption to only portions of LILCO's low power license application, it certainly would have said so. Indeed, LILCO had expressly requested the Commission to rule that it could obtain a license for Phase I and II activities without having first obtained an exemption. However, the Commission refused to grant LILCO's summary disposition motions, and it did not in any way limit or restrict the applicability of its May 16 ruling on LILCO's need for an exemption in order to obtain its requested low power license. That is the unmistakable law of this case, which simply cannot be ignored.

Despite its failure to persuade the Commission that without having met the standards for an exemption and in the absence of an onsite AC power system, LILCO nonetheless made the identical arguments as to why it should receive a license in its May 22 Summary Disposition Motions filed with the Miller Board.

^{36/} The "application" referenced by the Commission necessarily meant the items submitted by LILCO for the Commission's consideration -- that is, LILCO's Supplemental Motion for Low Power Operating License (which included Phases I and II), and LILCO's Summary Disposition Motions on Phases I and II.

Thus, in those motions, LILCO argued that obtaining an exemption from GDC 17 was not a prerequisite to the issuance of LILCO's self-styled licenses for Phases I and II. LILCO asserted that summary disposition was proper on Phases I and II because "the reliability of LILCO's onsite diesel generators is not material" to either of those phases since, according to LILCO, "there is no need for any AC power" during those phases. LILCO used this logic to conclude that the requirements of GDC 17 would be met during Phases I and II, even assuming LILCO's onsite diesel generators do not operate. See Phase I Motion dated May 22, at 4, 5; Phase II Motion dated May 22, at 3, 6.

However, even LILCO was forced to recognize that its argument flew in the face of the Commission's May 16 Order. Thus, LILCO stated in its Phase I Summary Disposition Motion filed with the Miller Board (at 5, n.1):

If the Licensing Board believes the Commission's May 16 Order requires an exemption from the regulations for all four phases of low power testing, then the Board should treat this motion as a motion for summary disposition of all health and safety issues with respect to Phase I.

An identical statement, with "Phase II" substituted for "Phase I" is in footnote 2 of the May 22 Phase II Motion filed with the Miller Board.

On July 24, 1984 the Miller Board held that an exemption was required before a Phase I or Phase II license could be issued. In so ruling, the Miller Board accepted the positions of the NRC Staff, the State of New York, and Suffolk County, that the Commission's May 16 Order prohibited the issuance of the licenses requested by LILCO, prior to completion of the exemption proceeding.^{37/}

^{37/} Suffolk County, the State of New York, and the Staff had all urged the Licensing Board to apply the May 16 Order and to hold that an exemption was

(Footnote cont'd next page)

Thus, in its July 24 Order Granting in Part and Denying in Part LILCO's Motions for Summary Disposition on Phase I and Phase II Low-Power Testing, the Miller Board held:

The Commission's May 16 Order (CLI-84-8) stated that it "has determined that 10 CFR 50.57(c) should not be read to make General Design Criterion 17 inapplicable to low-power operation" (slip opinion, page 1). That order therefore stands for the proposition that GDC-17 means the same for low-power operations as for full-power operation, and it must be completely satisfied before any license (including low-power) may be issued. Accordingly, the only recourse available to LILCO in this proceeding is to seek an exemption under the provisions of 10 CFR § 50.12(a), which is the subject of the instant evidentiary hearing.

The Board does not have the power or jurisdiction to grant LILCO's motion for summary disposition of Phases I and II of its low-power testing program, even though such activities do not require a qualified source of onsite AC power in order to perform the safety functions specified by GDC-17. The Commission's order requires that the GDC-17 requirements be completely satisfied even for fuel loading and precriticality testing. In its motion LILCO did not seek summary disposition of its exemption request, nor did it even address the factual issues involved therein. Accordingly, the ultimate issues involved in Phase I and II activities cannot be disposed of summarily, and that portion of the summary disposition motion is denied.

July 24, 1984 Order at 9-10 (emphasis added).

Then, without having a motion for reconsideration before it, and in the absence of any material changes in circumstances, facts, or the law, the Miller Board sua sponte issued its September 5, 1984 Order in which it reversed itself

(Footnote cont'd from previous page)

required for Phases I and II. See NRC Staff Response to LILCO Motions for Summary Disposition of Phases I and II, June 13, 1984; Suffolk County and State of New York Memorandum in Opposition to LILCO's May 22, 1984 Motions for Summary Disposition on Phase I and Phase II of LILCO's Proposed "Low Power Testing," June 13, 1984 (hereinafter, "June 13 filing").

(and apparently discovered "power" and "jurisdiction" where none previously existed). Thus, in a complete reversal, the Miller Board held in the September 5 Order that LILCO need not demonstrate the bases for a Section 50.12(a) exemption prior to issuance of a Phase I and Phase II license.

However, the Board had no reason for changing its mind on September 5. Indeed, nothing material had changed since July 24. For the Miller Board to have changed its July 24 decision in the face of no new material facts merely underscores the capricious and unsupported nature of its action.

Two purported "bases" for the Miller Board's abrupt reversal of position were set forth in the September 5 Order. Neither bear up under scrutiny. First, the Miller Board once again sought to get around an instance where the Staff had supported the Intervenors in a position contrary to LILCO's interests by its having opposed the LILCO summary disposition motions. In the September 5 Order, the Miller Board attempted to create the appearance of Staff support for LILCO's Phase I and II license request, and then bootstrapped that wholly illusory Staff "support" conjured up by the Board, into support for the Board's own, independent, desire to grant LILCO's request. Thus, the Board seized upon the Staff's August 17 Response to LILCO's Motion for Directed Certification of the Licensing Board's July 24 Order, in which the Staff reiterated its view that under the Commission's May 16 Order an exemption was required for Phases I and II (see Staff Response at 3-4), and because the Staff also stated that "Commission guidance would be helpful," the Board stated "the Staff rather abruptly and without adequate explanation again changed its position." September 5 Order at 4 (emphasis added). Clearly, the Staff's position concerning the need to deny LILCO's Phase I and II license request remained unchanged; its belief that

Commission guidance would be helpful could well have reflected a belief that the Miller Board was incapable of properly conducting the exemption proceeding on its own -- a belief shared by Suffolk County, New York, and two of the Commissioners.^{38/}

Furthermore, although the Miller Board purported to find support for its own changed position in the Commission's meeting held on July 25, 1984 and Staff statements discussed during that meeting (see September 5 Order at 4-6), the actual outcome of that meeting was that the May 16 Order would continue to apply to Shoreham. The Commission itself confirmed that outcome in a vote recorded in Mr. Chilk's July 27 Memorandum to the General Counsel and EDO. Thus, despite the defensive rhetoric in the September 5 Order, in fact the Miller Board had no legal or factual basis whatever for its abrupt, and clearly improper reversal.

Second, the Board also purported to base its September 5 Order on its concern:

that a court of law reviewing these orders might well conclude that LILCO was being discriminated against and treated differently than other utilities similarly situated, contrary to the equal protection of the laws and the due process requirements of the Fifth Amendment to the United States Constitution.

September 5 Order at 7. This is a baseless statement which this Appeal Board should discard summarily. Indeed, a court "might well" do one thing or another. It is no more than playing with a crystal ball for the Board to engage in such wholesale speculation. The fact is that the issue with which the Miller Board was apparently so concerned "might well" never even get to court. What is most

^{38/} See May 16 Order, Separate Views of Commissioner Gilinsky and Additional Views of Commissioner Asselstine, 19 NRC at 1159-60.

important here is not what "might well" be done by someone else some day, but what should have been done by the Miller Board (apply the Commission's May 16 Order), and what now must be done by this Appeal Board under the rule of law and the facts of record.

Further, as this Brief makes clear, the Board's invocation of the spectre of due process and equal protection of the laws with respect to its treatment of LILCO in the exemption proceeding is totally unfounded and clearly misplaced. The Miller Board's solicitous attention and concern for protecting LILCO's rights is particularly indefensible in light of its consistent actions to deny the Intervenors' due process rights. The Board's "constitutional" concerns for LILCO's welfare are nothing but abstract rhetoric, wholly lacking any reference to the particular facts of record in this proceeding, and the Board cited no legal authority whatever to support its conclusory statement. For these and the reasons stated in Section II.C.3 above, the Miller Board's constitutional theory must be rejected.

Moreover, the issue presented by the Miller Board's September 5 Order has nothing to do with that Board's alleged concern for "similarly situated" utilities -- Grand Gulf, Catawba, or any other.^{39/} The issue has only to do

^{39/} In fact, contrary to the unsupported assertions of the Miller Board, these other utilities are not "similarly situated." If the Board had asked for the parties' views prior to its sua sponte September 5 Order, the County and State would have so informed the Board. For example, Shoreham's TDI diesels are straight, 8 cylinder diesels; those at Catawba and Grand Gulf are V-8 or V-16's. Thus, the diesels at Shoreham are different in important respects. Second, the crankshafts at Shoreham are totally different from those at Catawba and Grand Gulf. Third, at Shoreham the crankshafts have cracked, the replacement crankshafts have been found by the Staff not to meet the DEMA standards set forth in Reg. Guide 1.9, and the engine blocks have had extensive cracking. None of these problems has occurred at Catawba or Grand Gulf.

with the Miller Board's clear failure to apply the Commission's May 16 Order to Shoreham. The Miller Board contradicted and repudiated the Commission's ruling that the GDC 17 requirement of an onsite AC power source is applicable to all phases of LILCO's proposed low power proposal.

Third, the Miller Board's ruling, adopting LILCO's argument that the requirements of GDC 17 would be met during its proposed Phase I and Phase II, ignores the plain language of that criterion. The first sentence of GDC 17 states:

An onsite electric power system and an offsite electric power system shall be provided

(emphasis added). There is no operable onsite power system at Shoreham. All the Miller Board's words about LILCO's supposed "compliance" with GDC 17 in reality constitutes a challenge to GDC 17, since they amount to nothing but a rehash of LILCO's view that despite the plain words of GDC 17, an onsite electric source does not have to be provided in order to obtain a license. The Commission properly rejected that challenge to the regulations in its May 16 Order.^{40/} This Appeal Board must do the same thing and reverse the Miller Board's erroneous Phase I and II ruling.^{41/}

^{40/} Indeed, the Miller Board's September 5 ruling is reminiscent of its April 6, 1984 Order, which the Commission reversed, in which it read GDC 17 out of the regulations by "harmonizing" the GDC into Section 50.57(c). Clearly, what was "harmonizing" then became "implication" and "interpretation" in the September 5 Order.

^{41/} Clearly, the argument that because AC power is allegedly not necessary during Phases I and II, non-compliance with GDC 17 does not matter (see September 5 Order at 7-8), must be rejected. The same argument could be made, for example, to support a low power license request even if the primary containment of a plant were not completed. Since there are no fission products in the core during fuel loading, arguably there is no need for a

(Footnote cont'd next page)

Fourth, the Board's September 5 Order is erroneous because it completely ignores the fact, fully briefed by the County and State, that the Commission has no authority to issue the licenses requested by LILCO for Phases I and II. This violates the fundamental requirement that adjudicators address the issues raised, confront the arguments made by the parties, decide the issues, and provide a meaningful explanation of the reasons for the decision. See Public Service Co. of New Hampshire (Seabrook Station, Units 1 and 2), ALAB-422, 6 NRC 33, 40-42 (1977). There is thus no adequate predicate -- no basis -- for an NRC decision on LILCO's request for a Phase I and II license. Consequently, it is necessary for this Board to make a de novo review of the merits of the arguments made by the County and State with respect to the issue of a Phase I and II license, so that a decision properly can be rendered. We outline the arguments briefly below.

In its request for issuance of a license for Phase I, LILCO stated that during "Phase I" it intends to load fuel into the reactor, and to perform various procedures, involving the loaded fuel, described as "core verification." Phase I Motion dated May 22, at 2. According to LILCO, during Phase I "the reactor will not be taken critical." Statement of Material Facts attached to Phase I Motion, para. 5. Indeed, throughout Phase I, the pressure vessel will be uncovered. Thus, if all goes according to plan during Phase I, no power would or could be generated by the reactor.

(Footnote cont'd from previous page)

containment structure. The proposition of issuing a Phase I/II license to a plant with no containment is, analytically, no different from the proposition adopted by the Miller Board with respect to Shoreham with no onsite power system.

It is clear that none of the activities contemplated during Phase I can be said to constitute "operation" of the Shoreham reactor. Although fuel will be loaded into the core and certain manipulations performed, and although during and following Phase I the reactor will be closer to being ready for future operation, the Phase I license which LILCO seeks is a "no power" license that is nowhere authorized or contemplated in the NRC's regulations or the Atomic Energy Act. Similarly, the so-called Phase II license is also not an operating license, since in Phase II LILCO proposes only to perform cold criticality testing, a step which again only brings the reactor closer to being ready for future operation. Accordingly, the Commission has no authority to issue the license that is requested by LILCO for Phases I and II and thus the Miller Board's Order recommending a Phase I and II license must be summarily reversed.

In the County/State June 13, the lack of authority for issuance of a "no power" license was thoroughly discussed. However, the Miller Board never even alluded to the issue in any of its orders, much less confronted the County/State arguments. Since the Board has recommended approval of a Phase I/II license, it effectively has rejected the County/State position. However, under settled NRC law, the Board was required to explain why it rejected the County and State position. See Public Service Co. of New Hampshire (Seabrook Station, Units 1 and 2), ALAB-422, 5 NRC 33, 40-42 (1977). The Miller Board unquestionably violated this longstanding rule, as well as the NRC's directive in the May 16 Order to conduct the proceeding in accordance with the NRC's rules. This alone is sufficient basis to reverse the September 5 Order.

The Atomic Energy Act contemplates the issuance of only construction permits and operating licenses for nuclear reactors. There is no authorization

in that Act for the issuance of a license to load fuel, or to manipulate a loaded core, as an end in itself without operating the reactor. See 42 USC § 2133 (authorization to issue commercial licenses pursuant to § 2131 et seq.); § 2232 (requirements of license applications for "a construction permit or an operating license"); and § 2235 (granting of construction permits, and granting of a license "upon finding that the facility authorized has been constructed and will operate"). And, the legislative history of the Act provides no indication that any such non-operating license was contemplated, intended, or authorized by the statute. What LILCO requested and the Miller Board agreed to, therefore, has no foundation in the Atomic Energy Act.

Similarly, the Commission's regulations, which implement the Atomic Energy Act, authorize the issuance of only construction permits and operating licenses with respect to nuclear power plants. See, e.g., 10 CFR §§ 50.23, 50.30, 50.57. The regulations do not even mention -- let alone authorize -- the issuance of a license to a holder of a construction permit for the purpose of using but not operating a commercial power reactor. To the contrary, the regulations clearly contemplate only two types of licensing: the issuance of a construction permit and the issuance of an operating license. See, e.g., 10 CFR § 50.33 on contents of applications (references only construction permits and operating licenses), and 10 CFR § 50.51 on duration and renewals of licenses ("Where the operation of a facility is involved . . . [and] Where construction of a facility is involved.").

For example, 10 CFR § 50.55(d) provides:

At or about the time of completion of the construction or modification of the facility, the applicant will file any additional information needed to bring the original application for license up to date, and will file an application for an operating license or an amendment to an application

for a license to construct and operate the facility for the issuance of an operating license, as appropriate

(emphasis added). Similarly, Section 50.56 states in pertinent part:

Upon completion of the construction or alteration of a facility, in compliance with the terms and conditions of the construction permit . . . the Commission will . . . issue a license of the class for which the construction permit was issued . . . ,

and Section 50.57 follows with:

Pursuant to §50.56, an operating license may be issued by the Commission . . . upon finding that:

(1) Construction of the facility has been substantially completed . . . and

(2) The facility will operate

(emphasis added). The fact that Section 50.57 provides for both low power and full power licenses does not change the limitation of authority, set forth in that section, to the issuance of only licenses for operation.

Clearly, if the NRC had been authorized by Congress to establish an interim "no operation" or "no power" stage in the licensing process between construction completion and low power operation, the Commission could have done so in its regulations. Pursuant to its authority under the Atomic Energy Act, the Commission has created in its regulations an elaborate scheme of specific licenses for particularized activities, such as licenses concerning by-products, 10 CFR Parts 30-33 and 35, licenses concerning radiographic operations, 10 CFR Part 34, licenses concerning source materials, 10 CFR Part 40, licenses respecting the packaging of radioactive materials for transport, 10 CFR Part 71, and licenses concerning the storage of spent fuel in independent spent fuel facilities, 10 CFR Part 72. The fact that this extensive licensing scheme does not include provision for a license limited to loading fuel and the other no power

activities included in the Phase I and Phase II licenses approved by the Miller Board is further evidence of the Commission's lack of authority to issue such a license.^{42/}

Thus, LILCO's No Power License request and the Miller Board's Order approving that request fragmented improperly the Commission's licensing process into the smallest particle of a license that LILCO had a chance of getting. The goal of the Miller Board, therefore, was not to comply with or apply the mandatory two-staged licensing process which Congress and the NRC have established, but rather to circumvent that process by adding more licensing stages which dilute the substance of the central issues. Condoning this kind of circumvention of the regulations would undermine the licensing process itself, and would invite applicants to customize their license requests in any piecemeal fashion that suits their momentary ends. The Miller Board's September 5 Order approving LILCO's Phase I and Phase II license request should be reversed.

^{42/} We note that the alleged "precedents" cited by LILCO in support of its no power license request in fact fail to support the legality of the Miller Board's action. First, Pacific Gas & Electric Co. (Diablo Canyon Nuclear Power Plant, Units 1 and 2), CLI-83-87, 18 NRC 1146 (1983), is completely distinguishable: the Commission had already granted an operating license; the operating license had been suspended; and the Commission ordered a staged reinstatement of the license in the context of an enforcement proceeding. Second, the Licensing Board decision in Virginia Electric and Power Co. (North Anna Power Station, Units 1 and 2), LBP-77-64 6 NRC 808 (1977), also constitutes no precedent here. No party contested, and no portion of the Board's opinion concerns, whether a "no power" license is legal under the Atomic Energy Act or the NRC's regulations. Thus, the issue raised herein is one of first impression.

Finally the Miller Board's September 5 Order relies upon the Staff's action in letting Duke Power load fuel and conduct pre-criticality testing at Catawba. September 5 Order at 10. Our understanding is that at Catawba the intervenors agreed to such a license and there was no adjudication of the issue. Thus, again this was not a contested case where the no power license issue was squarely confronted.

F. Miller Board's Issuance of a Low Power License Violates Section 50.57.

LILCO's Phase I and II Motions were premised upon the unavailability of the TDI diesel generators and the absence of any operable onsite AC power system. As recognized by the Commission in its May 16 Order, and reflected in LILCO's Application for Exemption, the Shoreham plant configuration postulated by LILCO for its proposed "low power" operation (including its Phases I and II activities) differs substantially from the configuration mandated by the regulations. Thus, in its Application for Exemption, LILCO stated that it

seeks an exemption under § 50.12(a) from that portion of General Design Criterion 17, and from other applicable regulations, if any, requiring that the TDI diesel generators be fully adjudicated prior to conducting the low power testing described in LILCO's March 20 Motion

Application for Exemption at 4 (emphasis added). LILCO thus acknowledged that its proposal to operate Shoreham with its unique electric power configuration rather than that required by the regulations and identified in the Shoreham FSAR, requires an examination of that configuration's compliance with applicable regulations" in addition to GDC 17. Although LILCO failed to identify the "other applicable regulations" from which it needed and sought an exemption, the state of compliance of its newly proposed plant configuration with those "other regulations" raises factual issues which (1) were not identified or addressed in LILCO's summary disposition motions, and (2) under the regulations were required to be resolved prior to the issuance of the licenses for Phase I and II sought by LILCO. The Miller Board ignored this fact, even though LILCO's failure to comply with other regulations had been explicitly raised in the State/County June 13 filing, and such lack of compliance made the approval of any license under Section 50.57 clearly erroneous.^{43/}

^{43/} Here again, the Miller Board ignored the Seabrook requirement that the bases for a decision must be explained in a board's opinion.

As set forth in the Affidavit of Gregory C. Minor and Dale G. Bridenbaugh, which was attached to the County/State June 13 Opposition to LILCO's summary disposition motions, the plant configuration proposed by LILCO does not satisfy the requirements in the following regulations:

- GDC 1 -- Quality Standards and Records
- GDC 2 -- Natural Phenomena
- GDC 3 -- Fire Protection
- GDC 4 -- Environmental and Missile Design Bases
- GDC 17 -- Electric Power Systems
- GDC 18 -- Inspection and Test of Electric Power Systems
- GDC 33 -- Reactor Coolant Makeup
- GDC 34 -- Residual Heat Removal
- GDC 35 -- Emergency Core Cooling
- GDC 37 -- Testing of Emergency Core Cooling System
- GDC 38 -- Containment Heat Removal
- GDC 40 -- Testing of Containment Heat Removal System
- GDC 41 -- Containment Atmosphere Cleanup
- GDC 43 -- Testing of Containment Atmosphere Cleanup Systems
- GDC 44 -- Cooling Water
- GDC 46 -- Testing of Cooling Water System
- Part 50, Appendix B -- Quality Assurance Criteria

See Minor and Bridenbaugh Affidavit at paras. 6-8. LILCO has not complied with GDC 1, 2, 3 and 4 because its proposed plant configuration does not include any safety-related, seismically or environmentally qualified onsite AC power sources. Id. at para. 6. LILCO does not comply with GDC 17, 18, 33, 34, 35, 37, 38, 40, 41, 43, 44 and 46, because (a) there is no onsite emergency AC power source in the proposed new plant configuration, and (b) since there is no such source, the transfer from offsite to onsite power cannot be tested as required by those criteria. Id. at paras. 7, 10. Finally, the proposed alternate plant configuration has not been designed, installed, tested, nor will it be operated in accordance with the criteria set forth in Part 50 Appendix B. Id. at para. 8.

On the state of the record before the Miller Board on September 5, LILCO's non-compliance with these regulations was undisputed. Therefore, under the May 16 Order, LILCO clearly was required to obtain an exemption from compliance with all the above regulations before any kind of license for Phase I or Phase II activities even arguably could lawfully have been approved. However, LILCO's summary disposition motions and the Miller Board's September 5 Order completely ignore this fact, by discussing only GDC 17. This Appeal Board, therefore, must reverse the grant of LILCO's motions for failure to resolve the issues raised by LILCO's non-compliance with these NRC regulations.

Clearly, given the state of the record on September 5, the Miller Board could not properly have made the findings required for the issuance of a license under Section 50.57. Indeed, the September 5 Order is totally silent on that subject, despite the unequivocal requirement in that section that:

Prior to taking any action on such a motion [for a low power operating license] which any party opposes, the presiding officer shall make findings on the matters specified in paragraph (a) of this section as to which there is a controversy, in the form of an initial decision with respect to the contested activity sought to be authorized.

As detailed in the affidavit of Messrs. Minor and Bridenbaugh, which was submitted to the Miller Board, the Shoreham plant with LILCO's proposed alternate AC power configuration, does not satisfy the requirements set forth in Section 50.57(a).

Neither LILCO's March 20, 1984 Supplemental Motion for Low Power License, its Phase I and Phase II Summary Disposition Motions, nor the Miller Board's erroneous September 5 Order even address the Section 50.57(a) requirements, or the Section 50.57(c) requirement that the 50.57(a) findings must be made.^{44/} While

^{44/} In its original Motion for Low Power Operating License filed with the Brenner Board on June 8, 1983, LILCO asserted that the only matters in con-

it may generally be true that in the normal case, where a low power license application is based upon the same plant configuration as the full power license application (as was the version of LILCO's Motion filed in 1983 before the failure of the TDI diesels), prior Partial Initial Decisions may limit or cover the matters in controversy for purposes of Section 50.57(c), it cannot be denied that this is not the normal case. Here, LILCO has itself placed into controversy an entirely new proposal for the provision of onsite AC power in connection with its most recent version of its low power license motion and exemption request.

Although aspects of prior litigation or decisions may be pertinent to LILCO's new proposed plant configuration, they cannot be said to have eliminated from controversy in this proceeding the question whether the new configuration satisfies the requirements set forth in Section 50.57(a). Thus, by the mere fact of its having requested that a brand new, previously unheard of plant configuration be licensed for fuel load and the activities proposed for Phases I and II, LILCO itself placed into controversy -- indeed, it created -- the factual issue whether the required Section 50.57 findings can be made with respect to

(Footnote cont'd from previous page)

trovery (apart from offsite emergency planning) for purposes of Section 50.57(c), were those identified in the contentions upon which hearings were held in 1982 and 1983. At the time of that filing -- June 1983 -- LILCO may have been correct. Clearly, however, the facts subsequently changed as a result of the failure of the TDI diesels, the totally new alternate AC power configuration first proposed by LILCO as a part of its Supplemental Motion for Low Power Operating License in March 1984, and the security-related concerns raised by the new AC power configuration. The prior contentions, the litigation thereon, the Security Settlement Agreement of December 1982, and the Partial Initial Decision issued in September 1983, did not consider -- and could not have considered -- the new AC power configuration which LILCO first proposed as a basis for licensing Shoreham operation in March 1984.

that new Shoreham plant configuration. For the reasons discussed below, there are material issues of fact concerning each of the Section 50.57(a) findings which were never addressed by LILCO or the Miller Board, and accordingly, summary disposition on LILCO's license requests was clearly erroneous and must be reversed.

First, there was no basis upon which the Miller Board could find -- nor did it -- that construction of Shoreham has been substantially completed in conformity with the construction permit and LILCO's operating license application. Thus, LILCO's operating license application, as detailed in its primary licensing document, the FSAR, includes the provision of onsite emergency AC power by three independent, environmentally and seismically qualified, safety grade, TDI diesel generators. The FSAR postulates the inclusion of such diesels for both full and low power operation. Those diesel generators were to be designed and constructed in accordance with Part 50 Appendix B quality assurance and quality control standards, and were to be designed to meet the single failure criterion. See Minor and Bridenbaugh Affidavit, para. 4. LILCO's Supplemental Low Power License Motion requests a license for a plant without the diesel generators relied upon in the FSAR. Instead, LILCO proposes to use four mobile diesel generators and one gas turbine, none of which is seismically or environmentally qualified, safety-grade, designed or constructed in accordance with Appendix B, or designed to meet the single failure criterion. The new LILCO proposal is nowhere mentioned in the FSAR. Thus, the plant configuration proposed as a basis for the requested Phase I and Phase II licenses, is radically different from the configuration postulated in LILCO's licensing application documentation. Accordingly, the Miller Board could not, and did not, make the findings required under Sections 50.57(a)(1), (a)(2), or (a)(3).


Second, there was no basis upon which the Miller Board could find in its September 5 Order -- nor did it -- that the issuance of licenses for Phases I and II would not be inimical to the security of the public, as required under Section 50.57(a)(6). As set forth in Section II.B above, there were material facts in dispute concerning physical security, and pending security contentions before the Miller Board, at the time it issued its September 5 Order. Clearly, there was no basis then upon which the Board could have made the required Section 50.57(a)(6) finding. Moreover, for the reasons we detail in Section II.B above, due to the Miller Board's unlawful dismissal of Intervenor's security contentions and erroneous and baseless actions reflected in its October 29 Decision, there remains no basis in the evidentiary record to support those required security findings. Accordingly, the Miller Board's approval of Phase I and Phase II licenses violated the clear requirements of Section 50.57 and must be reversed.

III. CONCLUSION

For the foregoing reasons, the Miller Board's October 29, 1984 Decision, and its September 5, 1984 Order must be reversed.

Respectfully submitted,

Martin Bradley Ashare
Suffolk County Department of Law
Veterans Memorial Highway
Hauppauge, New York 11788


Herbert H. Brown

Lawrence Coe Lanpher
Karla J. Letsche
KIRKPATRICK & LOCKHART
1900 M Street, N.W., Suite 800
Washington, D.C. 20036

Attorneys for Suffolk County

Fabian G. Palomino (R)

Fabian G. Palomino
Special Counsel to the Governor
of the State of New York
Executive Chamber, Room 229
Capitol Building
Albany, New York 12224

Attorney for Mario M. Cuomo
Governor of the State of New York

December 11, 1984

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

Before the Atomic Safety and Licensing Appeal Board

In the Matter of)
)
LONG ISLAND LIGHTING COMPANY)
)
(Shoreham Nuclear Power Station,)
Unit 1))
)
)
)

Docket No. 50-322-OL-4
(Low Power)

CERTIFICATE OF SERVICE

I hereby certify that copies of Suffolk County and State of New York Brief in Support of Appeal of October 29, 1934 ASLB Decision on LILCO's Exemption Request have been served on the following this 11th day of December 1934, by U.S. mail, first class, except as otherwise noted.***

* Alan S. Rosenthal, Chairman
Atomic Safety and Licensing
Appeal Board
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Edward M. Barrett, Esquire
General Counsel
Long Island Lighting Company
250 Old Country Road
Mineola, New York 11501

* Mr. Howard A. Wilber
Atomic Safety and Licensing
Appeal Board
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

** W. Taylor Reveley III, Esquire
Hunton & Williams
P.O. Box 1535
707 East Main Street
Richmond, Virginia 23212

* Mr. Gary J. Edles
Atomic Safety and Licensing
Appeal Board
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Jay Dunkleberger
New York State Energy Office
Agency Building 2
Empire State Plaza
Albany, New York 12223

Judge Marshall E. Miller, Chairman
Atomic Safety and Licensing Board
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Judge Glenn O. Bright
Atomic Safety and Licensing Board
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Judge Elizabeth B. Johnson
Oak Ridge National Laboratory
P.O. Box X, Building 3500
Oak Ridge, Tennessee 37830

Mr. Brian McCaffrey
Long Island Lighting Company
Shoreham Nuclear Power Station
P.O. Box 618
North Country Road
Wading River, New York 11792

MHB Technical Associates
1723 Hamilton Avenue
Suite K
San Jose, California 95125

Fabian Palomino, Esquire
Special Counsel to the Governor
Executive Chamber
Room 229
State Capitol
Albany, New York 12224

Spence Perry, Esquire
Associate General Counsel
Federal Emergency Management Agency
Washington, D.C. 20471

James B. Dougherty, Esquire
3045 Porter Street, N.W.
Washington, D.C. 20008

Nora Bredes
Executive Director
Shoreham Opponents Coalition
195 East Main Street
Smithtown, New York 11787

Stuart Diamond
Business/Financial
New York Times
229 W. 43rd Street
New York, New York 10036

Stephen B. Latham, Esquire
Twomey, Latham & Shea
P.O. Box 398
33 West Second Street
Riverhead, New York 11901

Hon. Peter F. Cohalan
Suffolk County Executive
H. Lee Dennison Building
Veterans Memorial Highway
Hauppauge, New York 11788

Martin Bradley Ashare, Esquire
Suffolk County Attorney
H. Lee Dennison Building
Veterans Memorial Highway
Hauppauge, New York 11788

Jonathan D. Feinberg, Esquire
Staff Counsel, New York State
Public Service Commission
3 Rockefeller Plaza
Albany, New York 12223

Stewart M. Glass, Esquire
Regional Counsel
Federal Emergency Management
Agency
26 Federal Plaza
New York, New York 10278

Docketing and Service Section
Office of the Secretary
U.S. Nuclear Regulatory
Commission
1717 H Street, N.W.
Washington, D.C. 20555

* Edwin J. Reis, Esquire
Bernard M. Bordenick, Esquire
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555


Atomic Safety and Licensing
Board Panel
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Eleanor L. Frucci, Esquire
Atomic Safety and Licensing
Board Panel
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Atomic Safety and Licensing
Appeal Board
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Joel Blau, Esquire
New York Public Service Commission
The Governor Nelson A. Rockefeller
Building
Empire State Plaza
Albany, New York 12223

Mr. Martin Suibert
c/o Congressman William Carney
1113 Longworth House Office Bldg.
Washington, D.C. 20515



Karla J. Letsche
KIRKPATRICK & LOCKHART
1900 M Street, N.W., Suite 800
Washington, D.C. 20036

Date: December 11, 1984

-
- * By Hand
 - ** By Federal Express
 - *** The attachments to the Brief are being served only on Docketing and Service, the Appeal Board, the NRC Staff and LILCO.

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

Before the Atomic Safety and Licensing Appeal Board

In the Matter of)
)
LONG ISLAND LIGHTING COMPANY)
)
(Shoreham Nuclear Power Station,)
Unit 1))
_____)

Docket No. 50-322-OL-4
(Low Power)

SUFFOLK COUNTY AND STATE OF NEW YORK BRIEF
IN SUPPORT OF APPEAL OF OCTOBER 29, 1984
ASLB DECISION ON LILCO'S EXEMPTION REQUEST

ATTACHMENTS

Fabian G. Palomino
Special Counsel to the Governor
of the State of New York
Executive Chamber, Room 229
Capitol Building
Albany, New York 12224

Attorney for Mario M. Cuomo
Governor of the State of New York

Herbert H. Brown
Lawrence Coe Lanpher
Karla J. Letsche
KIRKPATRICK & LOCKHART
1900 M Street, N.W., Suite 800
Washington, D.C.

Attorneys for Suffolk County

December 11, 1984

ATTACHMENT 1

ATTACHMENT 1

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

Before the Atomic Safety and Licensing Board

_____)
In the Matter of)

LONG ISLAND LIGHTING COMPANY)

(Shoreham Nuclear Power Station,)
Unit 1))
_____)

Docket No. 50-322-OL-4
(Low Power)

TESTIMONY OF MICHAEL D. DIRMEIER AND
JAMSHED K. MADAN ON BEHALF OF SUFFOLK COUNTY

I. STATEMENT OF QUALIFICATIONS

Q. Please state your names and occupations.

A. My name is Jamshed K. Madan and my business address is 456 Main Street, Ridgefield, Connecticut. I am a principal in the management consulting firm of Georgetown Consulting Group, Inc.

My name is Michael D. Dirmeier and my business address is 456 Main Street, Ridgefield, Connecticut. I am a member of the firm of Georgetown Consulting Group, Inc..

Q. Please describe the general nature of your firm's services.

LILCO's financial condition, external financing is not presently available, and the Company's current estimates show that it will run out of cash in September 1984."

(Position Paper at 1). Additionally, the Position Paper reveals, again for the first time, that additional austerity measures would not suffice to avert bankruptcy.

"Other austerity measures and suspension of preferred dividends cannot solve LILCO's financial crisis, nor can they avert the threat of bankruptcy." (Position Paper at 47).

Q. How is the public interest affected by the austerity program?

A. At December 31, 1983, LILCO had 5,947 employees. The austerity program eliminated 741 LILCO positions and 246 jobs with outside contractors. This represents a 12.5 percent reduction in presumably needed and necessary positions. There can be no question that this action reduces LILCO's ability to provide safe and adequate service. The public interest is directly affected by any event that reduces that ability.

Further, the Position Paper revealed that LILCO's customers are already suffering as a result of the

Company's financial problems. In LILCO's words, "The effects of LILCO's financial crisis are presently being suffered . . . by its customers, who are subject to longer service response times and reduced customer service under the austerity plan." (Position Paper at 46).^{7/} The grant of an exemption would only further the adverse impact on LILCO ratepayers: low power operation at an early date in the midst of the financial crisis would lead to more nuclear expenditures and less resources to be spent for customer service. This not in the public interest.

Thus, LILCO is at reduced service levels, having cut back on current operation and maintenance programs in order to conserve cash. Apparently, not even Shoreham was exempted from austerity, since the Appendix to the Position Paper shows that austerity shifted \$50 million of capital expenditures at the unit from 1984 to 1985.

2. Is your conclusion regarding the public interest in present low power testing affected by consideration of

^{7/} In addition, LILCO's counsel has stated "LILCO is now assuring safe and adequate service for the short run -- not the long haul." (June 21, 1984 letter from Gerard A. Maher, Counsel for LILCO, to Hon. Frank S. Robinson, Administrative Law Judge, NYPSC, attached hereto as Attachment 9).

what might happen if Shoreham goes into low power testing but fails ultimately to receive a full power license?

A. No, it is not. Our conclusion regarding near-term low power testing versus testing at a later date after diesel uncertainties are cleared up hinges on LILCO's current cash situation and financing capability, its low capability to deal with contingencies, and the grave uncertainties resulting from the Nine Mile Point No. 2 default and the possibility that Shoreham costs will not be recovered. In addition, however, we believe that if Shoreham is allowed to undergo testing and then does not receive a full power license, the result would clearly be a public detriment approaching, if not exceeding, \$100 million.

Q. How do you compute the \$100 million detriment from low power testing without subsequent full power operation?

A. Before discussing the computation of this amount, it should be recognized that if Shoreham does not achieve commercial operation, it will provide no benefit to the Company's customers from low power testing. However, if low power testing is permitted and Shoreham does not operate commercially, a new economic detriment is created.

The tangible economic costs resulting from low power testing, with subsequent abandonment, are estimated to be at least \$100 million. This is composed of the following elements:

1. Reduction in salvage value of the Shoreham plant, and in the value of nuclear fuel.
 2. Increased costs of decommissioning an irradiated nuclear facility.
 3. Increased costs that will be incurred in handling and storing high level (fuel) waste and low level nuclear reactor system wastes.
 4. Reduction in reclamation value of the Shoreham site, while radioactive materials are stored.
 5. The increased costs incurred to perform low power testing activities will, themselves, have been incurred with no benefit.
- Q. What is your understanding of the effect of low power testing on Shoreham's salvage value and nuclear fuel?

A. The state of the nuclear power industry in the United States is well known, with many plants having been abandoned, so there is some question as to whether there would be significant salvage proceeds from Shoreham relative to its \$4.1 billion cost. However, there should be no question that the salvage proceeds would be reduced once the nuclear reactor internals and piping are irradiated.

In addition to the irradiation of the nuclear reactor internals, low power testing would also involve irradiation of the initial nuclear fuel load. LILCO's Office of Engineering Report indicates that "If Shoreham receives a low power license and operates before it is abandoned, there would be no salvage value for this core." (p. 22 of "Shoreham Operation versus Abandonment.") The cost in terms of lost nuclear fuel value is estimated at \$70 million.

Q. How would low power testing affect the costs of decommissioning Shoreham?

A. At the present time, we understand that no portion of Shoreham has been irradiated. Consequently, dismantling it can be performed using conventional power plant

techniques. After irradiation, even at low power levels, it would be necessary to employ increased safety measures during the plant's dismantlement, in order to control releases of radioactive materials to the environment and to limit worker exposure. Constant monitoring of the plant and workers would become a necessity. In the PSC phase-in hearings, LILCO estimated that the total cost of decommissioning (assuming full power operation had occurred) would be \$407 million in after-tax dollars at the expiration of the plant's book life. This equates to approximately \$130 million in today's terms. We have no information as to how much of that \$130 million cost is due to the need to deal with irradiated fuel and components as opposed to dismantling the plant if it were never irradiated. Although the cost of decommissioning a plant that has operated only at 5 percent power would be less than that of a plant that had operated at full power, we do not know the point of the differential. Thus, the cost of decommissioning Shoreham following 5 percent operation would be some number lower than \$130 million in today's terms.

Similarly, it is difficult at this time to estimate the lost value of the Shoreham site during the period in

which radioactive materials would have to be stored there. It is our understanding that the federal government repository for nuclear wastes will not be ready until late in the 1990's, so it is likely that the period of storage, and thereby the period of lost value, is in the 15 to 20 year range.

Based on the preceding -- nuclear fuel loss, salvage loss, decommissioning and decontamination, and storage -- we believe the economic effect of testing without operation could easily exceed \$100 million.

Q. Please summarize your conclusions.

A. In our opinion, there is a \$49 million economic detriment associated with accelerating low power testing of Shoreham by three months. In addition, the public will be adversely affected by allowing LILCO to proceed with low power testing in the near term, so long as LILCO's financial future is so questionable as it is at the present time. Finally, so long as there is serious question as to whether Shoreham will receive a full power license, receipt of a low power license is not in the public interest.

ATTACHMENT 9

MAHER & BABINECZ, P.C.

ATTORNEYS AT LAW
1010 FRANKLIN AVENUE
GARDEN CITY, NEW YORK 11530
(516) 248-8444

GERARD A. MAHER
RICHARD W. BABINECZ
ANDREW GANSBERG

MAURA A. KILROY
DAVID N. BODER

DAVID K. KADANE
OF COUNSEL

June 21, 1984

Hon. Frank S. Robinson
Administrative Law Judge
Public Service Commission
Empire State Plaza
Agency Building No. 3
Albany, New York 12223

Re: Case 28553


Dear Judge Robinson:

At the June 12 hearing Company witness Mr. Sideris testified that LILCO's updated current cash flow projections would be available shortly (Tr. 4590). Those projections, in the format of Exhibit 119 and using the same underlying assumptions, are appended hereto as Attachment A. In sum they show the following changes in LILCO's indicated cash deficits for the remainder of 1984, assuming the Company's total rate relief request for \$281 million becomes effective October 1, 1984:

	<u>Month-end Cash Deficit</u>	
	<u>Exhibit 119</u>	<u>Attachment A</u>
September	\$(17.3) million	\$(43.3) million
October	(8.8) million	(28.6) million
November	14.1 million	(15.2) million
December	(43.8) million	(60.9) million

Aside from substitution of actual data for the April and May estimates in Exhibit 119, the changes reflected in Attachment A are principally due to the matters Mr. Sideris addressed in his cross-examination i.e., fuel and interest costs. Other, more minor, changes are addressed in the Explanatory Notes to the Schedule in Attachment "A".

Very truly yours,


Gerard A. Maher

GAM/sd

cc: All parties

RECEIPTS

	Jan	Feb	March	April	May	June	July	Aug	Sept	Oct	Nov	Dec	
1 Total Contingent Payments	143.1	187.7	196.3	188.3	172.7	176.9	234.9	184.1	142.4	178.2	133.0	164.3	2436.3
2 Other non-financing receipts	4.9	0.3	0.7	3.4	6.3	0.3	6.3	0.7	0.7	7.1	0.7	0.0	79.8
3 Total non-financing receipts	148.0	188.0	197.0	191.7	179.0	177.2	241.2	184.8	143.1	185.3	133.7	164.3	2516.1
DISBURSEMENTS													
4 Fuel	54.0	92.2	81.0	88.6	77.2	76.2	71.3	53.8	89.1	70.7	71.9	51.9	926.2
5 Taxes (incl. Excise)	25.6	32.2	43.8	11.4	92.2	48.2	16.1	30.3	32.4	22.2	31.2	38.3	494.9
6 Group Plans	4.2	4.2	4.7	3.7	2.2	2.2	2.9	6.3	0.0	4.6	4.3	3.0	32.3
7 Insurance Payments	6.1	6.6	6.3	6.2	6.2	6.7	2.2	6.3	6.3	7.2	6.7	6.7	16.3
8 Interest on Bonds (incl. PDB's)	2.3	4.2	18.2	19.8	18.0	20.7	6.2	4.7	19.1	19.8	11.6	36.7	187.3
9 Dividend Payments-Preferred	7.7	3.2	4.7	9.4	2.2	4.6	9.6	2.2	6.6	9.6	3.2	6.4	83.0
10 Common	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
11 Senior Debt Payable-Savings	16.4	26.9	11.7	12.6	13.7	17.6	0.6	8.4	8.4	1.4	8.4	8.4	181.9
12 Other	0.4	0.1	0.3	0.1	0.4	0.3	0.5	0.3	0.3	0.4	0.3	0.3	3.0
13 General Accts Payable	7.0	3.2	4.7	4.3	7.2	3.7	7.9	7.9	4.4	7.7	6.3	4.7	81.6
14 Rise into Point-Interest	17.7	0.0	0.0	19.4	0.0	0.0	28.8	0.0	0.0	21.4	0.0	0.0	81.3
15 Construction	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
16 Interest-Other measured debt	11.3	4.0	6.6	13.9	0.0	0.0	11.2	7.0	0.0	11.2	0.0	7.0	60.4
17 Public Service Payments	0.0	0.0	1.3	0.6	0.6	1.3	0.8	0.6	1.3	0.6	0.6	1.4	5.3
18 Payroll	0.9	7.1	7.2	7.6	8.6	7.2	9.0	7.4	7.8	8.7	7.1	7.6	92.2
19 Union	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	1.2
20 Redemption-Preferred Stock	0.0	0.0	0.0	1.0	0.0	0.0	3.6	0.0	2.4	0.0	2.0	3.0	19.4
21 Redemption-Bonds	0.3	0.0	3.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	12.0	0.0	18.0
22 Sources Trust-Interest	4.0	0.0	0.0	4.0	0.0	0.0	0.3	0.0	0.0	0.3	0.0	0.0	24.0
23 Liability of Supplier &	0.0	0.0	0.0	0.0	0.0	0.0	0.0	75.0	0.0	0.0	0.0	0.0	75.0
24 Special Deposits	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
25 Total Disbursements	242.5	319.0	312.3	310.4	297.0	297.0	330.7	234.0	188.4	402.7	163.9	196.3	2394.9
26 Change during 1983													
27 Receipts & Disbursements	-94.3	0.0	-15.0	-18.7	-18.0	-20.0	-10.2	-49.2	-45.3	1.6	-30.2	-32.0	-338.8
28 Short Term Investments	-31.0	0.0	-21.0	-3.1	-46.9	-36.0	-16.7	-41.0	-17.1	1.6	-0.3	-23.2	-238.8
29 PROCEEDS FROM FINANCING													
30 ADP	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
31 Sale of Stock to Employees	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
32 Sale of Bonds	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
33 Sale of Stock-Preferred	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
34 Sale of Stock-Common	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
35 Pollution Control Bonds	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
36 Loss Financing Expenses	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
37 Change in Cash Balance	-0.9	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
38 FINCH (BY MACE) Inc. 12/21/83													
39 Cash	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0
40 Short Term Investments	-100.3	-171.0	-123.3	-198.2	-213.1	-179.9	-252.1	-244.1	-203.1	-181.4	-109.9	-103.0	-103.0
41 Operating full 1983 million rate	-148.0	-117.1	-127.0	-111.0	-101.7	-104.2	-104.9	-216.9	-215.6	-104.7	-126.8	-107.0	-45
42 relief effective 10/1/84 -18.9													

1 Operating amount 1983 million includes electric rate increase effective September 15, 1981 resulting in effect throughout 1983.
 (2) Does not reflect any business combination that would be post operational cost savings.

3 All figures adjusted for business structure tabulation 1983.0 million.

EXPLANATORY NOTES

RECEIPTS

Line 2 of Page 1 "Other Non-Financing Receipts" for 1984 shows these receipts are now expected to be \$5.5 million more than anticipated previously, partly due to increases in interest rates and partly due to repayments to LILCO by members of the TDI diesel emergency generator owners group. The changes in the 1985 estimates on page 2 of Attachment A are primarily due to changes in interest rates and reflection of payments from the Nine Mile Point II Construction Trust for borrowings from LILCO. There is a corresponding increase in Line 14 "Nine Mile Interest" disbursements.

DISBURSEMENTS

Line 4 of Page 1 "Fuels" shows disbursements to be greater than previously expected (Exh. 119) by about \$18 million for 1984 (see, Tr. 4571). This was caused primarily by a refinement of the prior estimates for fuel supplies needed to satisfy the expected fuel consumption for anticipated sales (\$14 million of the change occurred in the month of May). This revised fuel expense does not reflect any change in forecasted fuel consumption or sales. Thus, there is no increase in anticipated revenues in Line 1 caused by the refinement in the "Fuel" disbursements.

ATTACHMENT 2

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

.....
In the Matter of .
LONG ISLAND LIGHTING COMPANY . Docket No. 50-322-OL-4
(Shoreham Nuclear Power Station, . (Low Power)
Unit 1) .
.....

TESTIMONY OF RICHARD KESSEL ON BEHALF
OF THE STATE OF NEW YORK

Dated: July 13, 1984
Albany, New York

RICHARD M. KESSEL
EXECUTIVE DIRECTOR
NEW YORK STATE CONSUMER PROTECTION BOARD
99 WASHINGTON AVENUE
ALBANY, NEW YORK 12210

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

.....
In the Matter of .
LONG ISLAND LIGHTING COMPANY . Docket No. 50-322-OL-4
(Shoreham Nuclear Power Station, . (Low Power)
Unit 1) .
.....

TESTIMONY OF RICHARD KESSEL ON BEHALF
OF THE STATE OF NEW YORK

Q. Please state your name.

A. Richard Kessel.

Q. By whom are you employed and in what capacity?

A. I am employed by the State of New York as the Director of the State Consumer Protection Board ("CPB").

Q. Please describe your educational background, employment history and responsibilities as CPB Director?

A. I have annexed a biographical sketch to this testimony which explains my educational background, employment history and role as a Long Island consumer advocate.

As Executive Director of the CPB I am responsible for the development and implementation of various energy and other consumer related programs and policies before regulatory, legislative, judicial and public forums. I am also responsible for the development of consumer education programs and the preparation of educational materials to

guide consumers in making economically sound decisions. In my role as Executive Director of the CPB, I have been integrally involved in developing the CPB's position in the Shoreham Prudence - Phase II (Case No. 27563), the Shoreham Ratemaking (Case No. 28252), and the current Long Island Lighting Company, Inc. (LILCO or the Company) Rate (Case No. 28553) Cases. I have also written many articles and publicly stated my position regarding LILCO and Shoreham related issues. The most recent was an extensive Op Ed article contained in the June 27, 1984 issue of Newsday, a Long Island daily newspaper.

Q. What is the purpose of your testimony?

A. LILCO has requested an NRC exception from a rule which normally requires a nuclear power plant, even operating at low power levels, to have a fully qualified and dependable onsite electric power system. I also understand that LILCO's request for an exception is based upon a special NRC rule which indicates that the "public interest" must be considered in an exemption proceeding. My testimony states my belief, and that of the State of New York, that approval of such an exemption is not in the public interest.

Q. What is your understanding of LILCO's exemption request?

A. I understand that LILCO seeks NRC permission to commence testing Shoreham at up to 5% power without a fully

qualified onsite power system. Instead, LILCO proposes to use its existing offsite power system, enhanced primarily by the addition of a 20 MW gas turbine and four 2.5 MW mobile diesels manufactured by the Electromotive Division of General Motors. Neither the GM diesels nor the gas turbine is fully qualified for nuclear service as "onsite power"; hence, LILCO has sought the instant exception.

- Q. What is your understanding of the alleged benefits LILCO contends will result from granting its exemption?
- A. These "benefits" are discussed in LILCO's May 22, 1984 Application for Exemption. LILCO has stated that the entire low power testing program, i.e., from fuel load to testing completion, will be completed within 2 to 3 months. If the Company receives an exemption, LILCO contends, it may be able to achieve commercial operation 2 to 3 months earlier than would have been the case without an exemption. This LILCO contention is based upon two speculative assumptions. First, that the Company will be able to convince the NRC that the serious problems which have plagued its onsite power system, i.e., the Transamerica Deleval, Inc. ("TDI") diesels, are resolved. Second, that LILCO can secure NRC approval of its emergency offsite response plan. I also understand that LILCO asserted that savings of \$90 to \$135 million can be attributed to favorable consideration of its exemption

proposal. I have been advised recently LILCO has reduced its estimate of this alleged saving from \$8 to \$42 million.

Q. Do you believe that it is in the public interest for LILCO to be granted the requested exemption?

A. No.

Q. Please describe your reasons for opposing this exemption.

A. I have several bases for my opposition to LILCO's requested exemption. They are as follows:

1. It is not in the public interest to permit contamination of a nuclear facility before the uncertainties surrounding its future operation have been resolved. ~~There is no basis to assume that the NRC will allow LILCO a Shoreham full power operating license.~~ If Shoreham were to be operated at low power, and subsequently abandoned, costs would increase unnecessarily as a consequence of several factors.

Stricken by
Board
Tr. 2895-96

~~First, the reactor vessel and other equipment will have become contaminated, causing decommissioning costs to increase.~~ ^{First} ~~Second,~~ the value of the nuclear fuel will be substantially reduced. Finally, the salvage value of irradiated equipment will be

Withdrawn in light
of prior Board
ruling
Tr. 2878

Withdrawn in
light of prior
Board ruling
Tr. 2878

reduced. I have been informed that the costs associated with these three factors have been estimated to be approximately \$100 million. (Testimony of Michael Dirmeier and Jamshad Madan who have filed testimony on behalf of Suffolk County in this phase of this proceeding) These increased costs would offset the possible fuel savings resulting from an NRC exemption allowing low power testing.

Furthermore, additional direct and unnecessary economic costs may be absorbed by LILCO's customers if LILCO is allowed to recover the above described diminutions in value from ratepayers. These incremental costs would be caused solely by the approval of an expedited decision to allow low power testing. LILCO has consistently taken the position that all Shoreham related costs have been incurred prudently and are recoverable from ratepayers whether Shoreham does or does not become commercially operable.

Stricken by the
Board
Tr. 2897

2. LILCO's rush to license Shoreham has already resulted in a decline of quality of service. The Company expects either to implement or to

continue austerity reduction measures to reduce costs by \$60 to \$80 million for the 12 month period ending September 30, 1985. This sum is an addition to approximately \$30 to \$40 million in austerity budget cuts already implemented by LILCO. All of these cost reduction measures have affected non-nuclear operations. LILCO's proposal to accelerate low power testing will probably require additional funds which the Company will obtain by reducing non-nuclear related costs, thereby impairing its already diminished quality of service. This will cause further unacceptable deterioration of electric service which is not in the public interest. I believe the public interest will be better served if LILCO incurred only those nuclear expenses related to its attempt to secure a commercial operating license by complying with normal NRC safety regulations.

3. ~~New York does not require Shoreham's capacity now nor for many years in the future. Thus, adequacy of generating capacity is not a concern should Shoreham's commercial operation date be delayed for an additional 2~~

Stricken by
the Board
Tr. 2903

to 3 months. LILCO's Office of Engineering in a June 1983 publication entitled "Shoreham Operation V. Abandonment (An Economic Analysis)" stated that Shoreham is not required for capacity purposes until 1994-1995. (Appendix B-1) The New York Power Pool in its "Long Range Plan - Electric Supply And Demand 1984-2000" has concluded that, on a statewide basis, Shoreham is not required for reliability purposes until the turn of the century. (pp. 32, 37-38)

Stricken by
the Board
Tr. 2903

4. It makes little sense to allow LILCO to support a request for an exemption to relieve it from economic problems caused by managerial imprudence. LILCO selected the TDI diesels which have already caused the Company's low power testing schedule to slip significantly. The CPB and the County of Suffolk have shown, through testimony submitted in a New York Public Service Commission Shoreham prudence proceeding (Case No. 27563), that LILCO's selection of and testing procedures regarding the TDI diesels were deficient. It is certainly not in the public interest to reward LILCO with an

Stricken by
the Board
Tr. 2904

~~exemption to allow it to commence low power testing with unqualified on-site and off-site power systems particularly when a prudent utility would have replaced the defective TDI diesels with safety grade equipment many years ago.~~

Stricken by
the Board
Tr. 2904

5. It is inconsistent with the public interest to allow a financially weakened and nearly bankrupt company to operate a nuclear facility. Consumers' fears regarding Shoreham's operation will not be alleviated with the knowledge that LILCO's financial condition may preclude it from expending the funds necessary to operate Shoreham safely at low power. I note that these financial problems have recently caused a strike of the Company's unionized employees. This indicates that the LILCO's precarious financial condition has undermined the reliability of its personnel and operations. It does not make any sense to impose additional safety responsibilities upon a company which is so close to insolvency. In the July 13, 1984 issue of the Wall Street Journal, LILCO's chairman and chief operating

officer, Dr. Catacosinos, stated that he "... cannot be as optimistic about the possibilities of averting bankruptcy as I was at our annual meeting in May". (p. 8)

6. ~~LILCO has mismanaged the entire Shoreham project. It is incredible that the Company can now seek to cut corners by requesting a low power license, even though it cannot meet minimum safety requirements applicable to other nuclear power plants. Approval of this exemption will neither instill public confidence regarding the impartiality of the NRC nor allay the public perception that LILCO, a Company considered by many to have mismanaged Shoreham, received expedited and unwarranted regulatory treatment. To grant LILCO this exemption, thereby allowing the Company to circuitiously evade normal NRC rules designed to insure safe nuclear power plant operations, would increase public concern that Shoreham is less safe than other nuclear power plants. This is not in the public interest and should not be permitted.~~

Stricken by
the Board
Tr. 2905

Q. Does this conclude your testimony?

A. Yes.



STATE OF NEW YORK
EXECUTIVE DEPARTMENT
STATE CONSUMER PROTECTION BOARD

RICHARD M. KESSEL
CHAIR AND EXECUTIVE DIRECTOR

X REPLY TO:
99 WASHINGTON AVENUE
ALBANY NEW YORK 12210
(518) 474-3514

REPLY TO:
250 BROADWAY, 17TH FLOOR
NEW YORK, NEW YORK 10007
(212) 587-4482

July 19, 1984

ALL PARTIES (Docket No. 50-322-OL-4)

The enclosed biography was omitted from my testimony filed on July 13 in the above numbered docket.

I apologize for any inconvenience.

Sincerely,

Richard M. Kessel

Enc.





STATE OF NEW YORK
EXECUTIVE DEPARTMENT

STATE CONSUMER PROTECTION BOARD

REPLY TO:
99 WASHINGTON AVENUE
ALBANY, NEW YORK 12210
(518) 474-3514

RICHARD M. KESSEL
EXECUTIVE DIRECTOR

REPLY TO:
250 BROADWAY, ROOM 1748
NEW YORK, NEW YORK 10007
(212) 587-4482

BIOGRAPHICAL SKETCH

Richard M. Kessel of Bellmore, Long Island, was appointed by Governor Mario M. Cuomo as Executive Director of the New York State Consumer Protection Board in January of 1984 and confirmed by the Senate in February. Kessel is well-known for his consumer advocacy on Long Island and previously served as a consultant to the Borough of Manhattan on utility rate matters.

Since 1981, Kessel has been a member of the Board of Trustees at Nassau Community College. After being appointed by then-Governor Hugh L. Carey, Kessel led the Board of Trustees in adopting major reforms in the administrative practices of the college. Kessel introduced measures which banned nepotism on the college payroll, restricted the number of hours for which administrators could receive extra compensation, and helped develop a reorganization plan which reduced the administration by one-third.

A 1971 graduate of New York University, Kessel also attended Colgate University from 1967-1969. He received his Masters in Political Science at Columbia University in 1974.

Kessel has taught consumer economics at Brooklyn College and has developed course outlines for such courses as: Introduction to Consumer Studies, Consumer Resources and the Consumer and Energy.

As a Long Island consumer advocate, Kessel was instrumental in having the Nassau County Board of Supervisors adopt consumer-oriented legislation including an item pricing law, a ban on multiple pricing and a requirement that all perishable foods be marked with the last date of sale. Kessel also led the fight to eliminate Nassau County's 3% sales tax on home heating fuels.

Kessel has appeared before the New York State Public Service Commission on numerous occasions to advocate the interest of consumers. In 1980 he successfully petitioned the Public Service Commission to issue a policy statement allowing the introduction of evidence of



economic impact on ratepayers in all rate cases. Prior to that, Kessel convinced the Commission to hold evening hearings in utility rate cases. He has actively intervened in the last five LILCO rate cases, the last four New York Telephone cases, the last three Con Edison rate cases, and several generic proceedings. He was the first person to petition the PSC for both a management audit and a phase-in of costs for LILCO's Shoreham Nuclear Power Station.

In 1980 Kessel made history by organizing the first commuter strike against the Long Island Rail Road in response to massive breakdowns in service. He also gained national attention when he successfully sued the LIRR for failing to provide reliable air conditioning service during the summer months. That successful lawsuit, which was never appealed, established the right of commuters to receive a fair standard of service.

Kessel, 34 years old, has also conducted many consumer surveys and studies which have helped inform consumers about their rights as well as marketplace conditions. His "holiday" surveys of prices for such items as Halloween Candies, Thanksgiving Turkeys, Valentine Hearts and Mother's Day Roses have been reported throughout the nation.

He has also revealed numerous consumer abuses including 'butterless' buttered popcorn, 'alcoholless' apple champagne and 'leaded' lead-free gasoline.

Kessel is a member of the Board of Directors of the New York University Alumni Federation. He is also a member of the Board of Directors of the American Jewish Congress.

ATTACHMENT 3

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

BEFORE THE ATOMIC SAFETY AND LICENSING BOARD

In the Matter of)	
)	
LONG ISLAND LIGHTING COMPANY)	Docket No. 50-322-OL-4
)	(Low Power)
(Shoreham Nuclear Power Station,)	
Unit 1))	

DIRECT TESTIMONY OF
DALE G. BRIDENBAUGH AND RICHARD B. HUBBARD
ON BEHALF OF SUFFOLK COUNTY

I. INTRODUCTION

Q: Mr. Bridenbaugh, please state your name, address, occupation and professional qualifications.

A: My name is Dale G. Bridenbaugh, and my business address is 1723 Hamilton Avenue, San Jose, California. I am president of MHB Technical Associates. My qualifications are attached hereto as Attachment 1.

Q: Mr. Hubbard, please state your name, address, occupation and professional qualifications.

A: My name is Richard B. Hubbard, and my business address is 1723 Hamilton Avenue, San Jose, California. I am vice-president of MHB Technical Associates. My qualifications are attached hereto as Attachment 2.

II. PURPOSE OF TESTIMONY

Q: What is the purpose of your testimony?

A: LILCO has sought an exemption from NRC regulations to permit low power operation in advance of any NRC decision on the adequacy of its onsite emergency diesel generators. Under 10 CFR §50.12(a) and the NRC's May 16, 1984 decision (CLI-84-8), a relevant consideration is whether the public interest and a balance of the equities are in favor of the grant of an exemption. Further, in its May 22 Application for Exemption, LILCO has expressed the view that it is only due to problems arising during preoperational testing of the Transamerica DeLaval, Inc. ("DeLaval") diesels that the diesels have not yet been licensed. See Application for Exemption at 25.

The purpose of our testimony is to summarize the results of an investigation we have undertaken into the facts and circumstances involving LILCO's selection and procurement of the DeLaval emergency diesel generators ("diesels") and of the actions taken by LILCO in conjunction with the failures subsequently experienced with these engines.

Q: In summary, what are your conclusions?

A: We conclude that the delays and costs associated with the Shoreham diesels are the responsibility of LILCO (or of LILCO suppliers or contractors). These problems did not only arise during preoperational testing. Rather, since 1974 there have been repeated indications that there might be serious problems with the DeLaval diesels. In our opinion, LILCO knew or should have known of these problems at an early date and should have taken steps to ensure that reliable diesels were procured. LILCO failed to take such steps. Such steps would have been to (i) commence a complete design review and revalidation program far in advance of the September 1983 date when such a program actually was started, thus laying the basis for potential repair and/or qualification of the DeLaval diesels in a timely manner which would not necessitate application for an exemption; or (ii) to procure replacement diesels at a far earlier date, thus having reliable diesels on hand now instead of the Summer of 1985 when the Colt diesels are scheduled to be ready. Accordingly, it is our opinion that it would not be in the public interest and that a balance of equities would not favor the grant of an exception from applicable regulations when the primary

reason that LILCO now seeks an exemption is because of its own failure to take reasonable steps to ensure procurement of reliable diesels at an earlier time.

Q: Prior to seeking an exemption, how did LILCO propose to comply with GDC 17 during low power operation?

A: Since January 1976 when the Shoreham FSAR first came out, LILCO has always relied for onsite emergency AC power on three DeLaval diesels. These diesels, as will be discussed later in our testimony, were ordered from DeLaval in 1974 and arrived at Shoreham in 1976. They were stored for some period of time, and then installed. Turnover to the startup organization for testing occurred in August 1980 for Diesel Generator 102, and in October 1981 for Diesel Generators 101 and 103. Intensive preoperational testing began in September 1982.^{1/}

^{1/} Direct Testimony of William J. Museler and Edward J. Youngling, New York PSC Case No. 27563, November 4, 1983.

Q: In a previous answer you referenced an investigation of LILCO's handling of issues related to the DeLaval diesels. Please explain.

A: We submitted written testimony on February 10, 1984 in the ongoing proceeding before the New York Public Service Commission in PSC Case No. 27563 (Phase II), a case designed to investigate the cost of Shoreham. The purpose of that testimony was to examine the reasons for the dramatic increase in the estimated cost of the Shoreham Nuclear Plant, from an estimated \$65-75 million in 1966 to a January 1984 estimate of \$3.877 billion or more. In preparing that testimony, we evaluated the amount of the cost increase that is attributable to LILCO's allegedly imprudent responses to regulatory, design, and technical problems. Among the issues addressed was how the cost of Shoreham was affected by LILCO's procurement, installation, and testing of the DeLaval diesels.

Our investigation concerning the costs incurred at Shoreham consisted primarily of our participation in the PSC Phase II discovery process. We reviewed documents provided to Suffolk County and the Public Service Commission Staff by LILCO. In addition, we assisted

Suffolk County in the preparation of interrogatories and reviewed LILCO's responses to them. MHB representatives also attended and participated in many of the interviews that the Public Service Commission Staff and its consultants conducted with employees of LILCO and Stone and Webster (LILCO's Contractor Architect-Engineer).

In addition to our role in the discovery and testimony phase of the Phase II proceeding, Gregory Minor and Dale Bridenbaugh of MHB also provided testimony regarding the likely cost and schedule to complete Shoreham in Phase I of that proceeding. Finally, since 1977 MHB has been consultant to Suffolk County in the Atomic Safety and Licensing Board proceeding to determine whether LILCO has met the requirements necessary to receive an Operating License, participating actively in the DeLaval diesel proceeding, among others.

III. LILCO'S EMERGENCY DIESEL GENERATOR PROBLEMS

Q: Briefly describe the major problems LILCO has encountered recently with its DeLaval diesels.

A: The three DeLaval diesels at Shoreham have experienced repeated deficiencies as set forth herein and in the

Attachments. For example, operational problems with the diesels at Shoreham occurring a relatively short time prior to the August 1983 crankshaft failure included cylinder head cracks, rocker arm assembly hold-down bolt failures, turbocharger bearing failures, and cracks in the engine block casting. Further, LILCO was fined \$40,000 by the NRC during 1983 for its failure to follow required procedures during the preoperational testing of the diesels.

On August 12, 1983, during the testing of replacements for cylinder heads that had cracked, one of the three diesels, 102, experienced excessive vibration and erratic load swings. On August 13, 1983, it was discovered that the crankshaft on diesel 102 was completely severed. During disassembly of the diesels, the crankshafts of the other two diesels were found to contain cracks.

In addition, following the crankshaft failure in August 1983, other problems were subsequently revealed, including cracked connecting rod bearings and pistons.^{2/}

^{2/} Millard S. Pollock to Harold R. Denton, Nov. 23, 1983, SNRC-986.

Ultimately, 23 of 24 pistons in the Shoreham engines were found to be cracked.^{3/}

In Fall, 1983, following the crankshaft failure, and in recognition of other operational deficiencies as set forth later herein which have occurred with DeLaval diesels, LILCO instituted a recovery program aimed at determining the cause of the crankshaft failure, correcting it, and attempting to ensure that other components of the Shoreham diesels would operate reliably in the future.^{4/} In our opinion, this recovery program came far too late in time.

Q: Were the recent DeLaval problems you just described a complete surprise or were these problems to have been expected?

^{3/} LILCO Diesel Generator Status Report, November 17, 1983.

^{4/} Brian R. McCaffrey to Harold R. Denton, January 6, 1984, Shoreham Diesel Generator Recovery Program Summary, SNRC-1003. The NRC has also recognized the need for such a recovery program. Indeed, the NRC determined that a broad pattern of deficiencies in critical engine components has become evident at Shoreham and at other nuclear and non-nuclear facilities employing DeLaval diesels. The NRC now believes that the deficiencies stem from inadequacies in design, manufacture and quality control by DeLaval. "Order Requiring Diesel Generator Inspection," Grand Gulf Nuclear Station, Docket No. 50-416, May 22, 1984. (In particular, see Attachment 4 thereto.)

A: The precise problems or failures which have been experienced in the Shoreham DeLaval diesels in the last year and a half were perhaps not expected. However, given prior events related to the diesels, serious problems cannot be deemed to have been a surprise. Indeed, the reported cause of the current problems (discussed later in this testimony) can be traced directly to failures that occurred early in the design and manufacturing process.^{5/}

Q: How do these problems relate to LILCO's Application For Exemption?

^{5/} For example, LILCO retained Failure Analysis Associates ("Failure Analysis") to investigate the August 1983 crankshaft failure. Failure Analysis concluded that the crankshaft failed because it was not designed to withstand the cyclic torsional stresses that would be experienced during the diesels' operation. The conclusion was reached, based on a ~~relatively simple~~^{standard} calculation, that DeLaval had misdesigned the crankshaft, leading to insufficient capacity to withstand anticipated loads. Emergency Diesel Generator Crankshaft Failure Investigation, Failure Analysis, October 31, 1983. LILCO attributed the crankshaft problem to a design error in the torsional stress analysis performed by DeLaval. LILCO Diesel Generator Status Report, November 17, 1983. As will be addressed later in this testimony, the LILCO and Stone and Webster audit of DeLaval in 1975 did not even address the crucial area of design control. If it had, perhaps the design deficiency in the crankshaft would have been a notice of the need for a thorough design review.

Corrections
made by
witnesses

A: It is our position that LILCO was, in effect, responsible for failing to detect these deficiencies and for failing at a far earlier date (i.e., well in advance of Fall 1983) to institute necessary steps to repair (if possible) or replace the DeLaval diesels. Thus the need for LILCO now to seek an exemption is really the result of LILCO's own fault. Indeed, as set forth in the following portions of this testimony, our review indicates that from 1974 to 1983, LILCO's approach has been to treat the symptoms rather than the root cause(s) underlying the problems disclosed in the design and fabrication of the Shoreham diesels. Thus, there have been repeated problems with these diesels which put LILCO on notice far before Fall 1983 that something was fundamentally wrong with its diesels. LILCO ignored the warning signs and never sought to determine adequately why the problems existed. The need for LILCO now to seek an exemption is a direct result of LILCO's failure to detect and remedy in a timely manner the broad pattern of deficiencies in the design and manufacture of the DeLaval diesels.

Q: Does the fact that LILCO initiated a program in Fall 1983 to attempt to mitigate and correct the problems with the DeLaval diesels change your opinion that LILCO's need for

an exemption is a result of LILCO's own failure to take appropriate actions at an earlier date?

A: No. The fact that LILCO has eventually begun to attempt to deal with the difficult (perhaps insurmountable) DeLaval diesel problems does not make its prior failure to act any less the cause of the problem in the first place. Our point is that it is not in the public interest, and it is not equitable to reward a utility by waiving a compulsory safety regulation, when the reason the utility is unable to comply with that regulation is a result of its own insufficient actions.

Q: When did LILCO first become aware of the potential for serious deficiencies relating to the DeLaval diesels?

A: In 1974 LILCO was on notice that heightened QA/QC audit treatment of DeLaval would be necessary to ensure that a reliable and top quality product would be designed and manufactured. In fact, however, despite obvious warning signals, LILCO and Stone and Webster failed to implement an adequate QA/QC audit program for the design and manufacture of the DeLaval diesels.

Q: Please state the basis(es) for your prior answer.

A: The diesels supplied for Shoreham were DeLaval's first ever contract for supply of a diesel for a nuclear application. To the best of our knowledge, DeLaval had never even attempted to develop or implement a 10 CFR 50 Appendix B QA program before 1974. DeLaval's newness to nuclear work and Appendix B QA matters, in our opinion, made it incumbent on LILCO or its delegate to pay close attention, from the beginning, to how well DeLaval was doing in designing and manufacturing the Shoreham diesels. Indeed, the fact that DeLaval was new to the nuclear field made it absolutely incumbent on LILCO to ensure that a stringent audit program was instituted to ensure that all nuclear requirements were met. In fact, however, LILCO did not institute such a program.^{6/}

^{6/} Since the Shoreham diesels were DeLaval's first attempt to design and manufacture diesels pursuant to the regulatory requirements of Appendix A and Appendix B to 10 CFR Part 50, LILCO and Stone and Webster should have anticipated "bugs" in the DeLaval QA program. Thus, Stone and Webster should have increased its audits of DeLaval activities during the design and fabrication of the Shoreham diesels because the need to detect and correct the "bugs" in the DeLaval QA/QC process was obvious. LILCO's failure to assure that this was done is another basis for our belief that LILCO's present need for the requested exemption is its own fault.

The purchase order for the DeLaval diesels was issued by LILCO in May 1974 following a QA survey of the DeLaval shop conducted by Stone and Webster on February 26, 1974.^{7/} The DeLaval QA manual had been reviewed by Stone and Webster one week earlier (on February 19, 1974) and had been found not to meet several of the regulatory requirements of Appendix B to 10 CFR Part 50. The major deficiencies discovered by Stone and Webster were that design control and a number of measures for vendor corrective action, QA record retention, and audits, were not addressed in the DeLaval manual.^{8/} It was not until March 14, 1974, that Stone and Webster determined that the DeLaval QA manual, as revised on March 1, 1974, was in compliance with the intent of 10 CFR Part 50, Appendix B.

Based on the preceding, we conclude that the Stone and Webster shop survey should have put Stone and Webster and LILCO even more on alert (aside from DeLaval's lack of nuclear experience) in early 1974 of the need to closely watch DeLaval's QA implementation. They did not.

^{7/} Stone and Webster Procurement Quality Control Survey of DeLaval, G. I. Beaman, February 26, 1974.

^{8/} Stone and Webster Manual Checklist, DeLaval QA Manual dated May 1, 1970, Ellen O'Connor, February 19, 1974.

The fact that the February 1974 shop survey was conducted on a QA manual and program which were in transition should have led to a new survey and audits of QA implementation shortly after March 14, 1974 when the QA manual was found to be adequate or shortly after May 1974 when the purchase order was issued. This would have allowed an early judgment, during the key diesel design phase, regarding whether essential QA functions were being properly performed. LILCO failed to do any such audits in a timely manner.

Stone & Webster did, much later, conduct an audit of DeLaval. However, the audit findings, the time of the audit, its scope, and the lack of additional audits, support our view that LILCO should be deemed to be responsible for the difficulties with the DeLaval diesels. This one audit of DeLaval by Stone and Webster was not conducted until October 28 to 30, 1975, more than 18 months after the initial ^{manual review} ~~shop survey~~ that found DeLaval QA to be deficient and about 18 months after the purchase order had been placed. Reaudits of the corrective action measures required of DeLaval as a result of the October 1975 audit were performed on February 23, 1976 and June 18, 1976. In both the 1975 audit report and the February

reaudit, Stone and Webster auditors concluded that DeLaval had failed to fully comply with the requirements set forth in its QA manual or with the regulations in Appendix B to 10 CFR Part 50.

The three diesels were shipped to LILCO on the following dates: diesel 101, February 27, 1976; diesel 102, March 27, 1976; diesel 103, May 14, 1976. Therefore, all three diesels were designed, fabricated, tested, and shipped prior to implementation of the required QA measures, in effect without full regard for the potential impact of the identified discrepancies on the hardware. Indeed, even at the time of the first audit in late 1975, DeLaval's design and procurement activities were nearly complete, and the fabrication of components at the DeLaval casting and manufacturing facility was well advanced. Thus, in many respects, the Stone and Webster audit largely represented an after-the-fact evaluation which resulted in little or no effect on the Shoreham diesels.

Rather prophetically, Mr. Bienduga, Stone and Webster Procurement Quality Control District Chief, observed in a January 29, 1976 memorandum which concerned the October 1975 audit:

I feel that DeLaval's response is too little too late as the audit was conducted to verify compliance to the P.O. and approved Q/A program, not to upgrade their system for future work. We should either get a positive response as to what actions are being taken now or we should stop the job!

Furthermore, there were significant limitations in the scope of the audit conducted on behalf of LILCO by Stone and Webster. The 1975 audit, as well as the reaudits, investigated DeLaval's compliance with only 11 of the 18 criteria of Appendix B: Criteria 4, 7, 9, 10 and 12 to 18. The areas audited by Stone and Webster primarily involved procurement and fabrication. Critical areas including design control (Criterion 3),^{9/} procedural control (Criterion 5), and document control (Criterion 6) were not addressed in the Stone and Webster audit or reaudits. Thus, during the entire course of DeLaval's design and manufacture of the diesels for Shoreham, critical Appendix B criteria were never audited by LILCO or its representative. Stone and Websters' failure to audit the DeLaval design activities, including the design verification program, is a significant omission. Stone and

^{9/} We note that the critical crankshaft failure of August 1983 resulted from design errors. See note 4 in this testimony.

Webster, in effect, delegated responsibility for design QA activities to DeLaval. Further, Stone and Webster failed to recognize early in the design and fabrication schedule the potential problems that DeLaval might confront in supplying its first diesels for nuclear application. Indeed, Mr. Bienduga came to this conclusion after the fact:

My personal feelings regarding this reaudit is that too much responsibility has been given a relatively young, inexperienced, quality engineering group. There seems to be passive acceptance by the Q/C Mgr. of excuses and not enough supervisory follow up to get things done.

Granted the LILCO order is their first 'nuclear' contract and there are many 'bugs' to be ironed out but that doesn't help our situation unless the Q/C Mgr. is willing to take positive steps to get the 'bugs' out of the system.^{10/}

In light of DeLaval's failure to meet adequate QA standards in other areas, DeLaval's lack of nuclear experience, and Stone and Webster's knowledge of such failure and inexperience, this was a particularly deficient action by LILCO's contractor, which supports our belief that the problems with the DeLaval diesels could possibly have been prevented by LILCO.

^{10/} Stone and Webster Interoffice memorandum, W. V. Bienduga, February 25, 1976.

Q: What actions should LILCO have taken after the knowledge it gained or should have gained in the 1974-76 period?

A: The serious deficiencies in the QA implementation deficiencies identified in 1974-76 should have alerted LILCO to the need to carefully assess the adequacy of these diesels at an early date.

Q: Did LILCO commence such an early reassessment program?

A: No. As noted above, LILCO did not start such a program until Fall 1983.

Q: Between 1976 and the Fall of 1983 did LILCO acquire (or should it have acquired) further data to indicate the need for an early revalidation or diesel replacement program, which, if implemented, would have eliminated the need for LILCO to seek the instant exemption?

A: Yes. LILCO's experience with the DeLaval diesels commencing in 1977 should have alerted LILCO at an early date to potential QA problems, so that at an early date LILCO should have taken steps to avoid the situation which it presently confronts.

Since late 1977, LILCO has discovered and repaired or sought to remedy numerous problems with the Shoreham diesels. For example, 21 problems with the diesels that LILCO experienced prior to 1981 are set forth in a January 15, 1981 letter from D.D. Terry of LILCO Start-Up to Mr. Taylor. The letter is appended as Attachment 3 hereto. These deficiencies also necessitated a number of Engineering and Design Coordination Reports (see Attachment 4 hereto) in order to attempt to achieve engineering resolution of these problems, leading one LILCO employee to observe "we bought the low bidder."

In addition, in 1983, Energy Consultants Incorporated conducted a retrospective assessment for the NRC of selected operational problems identified in LILCO Deficiency Reports, Repair/Rework Requests, and failure reports issued by LILCO and DeLaval. Energy Consultants' report, issued prior to the DeLaval crankshaft failure, concluded:

A large number and variety of problems that have been experienced can be attributed to vendor workmanship. These errors, in conjunction with the problems identified during audits of DeLaval's Quality Assurance Program [audits/reaudits conducted October 1975, February 1976, and June 1976], indicate a weakly implemented Quality Control Program.

(Emphasis supplied). Energy Consultants also observed that:

During the detailed review of various Deficiency Reports, Failure Reports and Repair/Rework Requests, a significant number of problems or errors have been identified which seem to have occurred due to errors and incomplete or improperly completed work by the manufacturer.^{11/}

Examples of specific problems with the DeLaval diesels that Energy Consultants concluded fell into this category are set forth in Attachment 1 of its report.

Other documents also reveal a broad pattern of problems with the diesels. Indeed, even LILCO now asserts that:

Prior to the crankshaft failure, LILCO had experienced a number of occurrences attributable to defectively designed or fabricated diesel generator components, including three leaking cylinder heads, defective jacket water pumps, leaking fuel oil injection lines, inadequate turbocharger thrust bearing lubrication, inadequate piston skirt to piston crown

^{11/} Energy Consultants Incorporated, "Witness and Evaluation of Emergency Diesel Generator Testing at Shoreham Nuclear Power Station for Nuclear Regulatory Commission, Region I Staff, Final Report of NRC Contract No. 05-82-249 Parameter Purchase Order No. NRC-IE-82/83, Task 38", July 12, 1983, appended as Attachment 5.

attachment, broken rocker arm shaft bolts and cracked subcover assemblies. While these occurrences were generally of the type experienced in the shakedown of large diesel engines, they appear, nonetheless, to be attributable to defective design or fabrication.^{12/}

In our opinion, LILCO could and should have recognized far before Fall 1983 that the DeLaval diesels were probably not reliable, and thus, should have taken steps at an earlier time to remedy the diesel problem. However, LILCO failed to do so. Instead, it let the situation deteriorate to the point of a catastrophic failure of the machines, and now seeks special treatment from the NRC.

LILCO's failure to take timely early action to address the root causes of DeLaval failures is also reflected in LILCO's failure to take heed of the significant NRC findings of deficiencies in the DeLaval QA program. For example, the NRC Staff has observed that "the number of minor problems experienced by the TDI machines in nuclear service appears to be abnormally high."^{13/} A summary of

^{12/} Letter, E.M. Barrett of LILCO to Robert E. Smith, counsel for DeLaval, December 2, 1983, appended as Attachment 6.

^{13/} Nuclear Regulatory Commission Board Notification 83-160, October 21, 1983, page 1. Enclosures 2 and 4 to the Board

(Footnote cont'd next page)

operating problems experienced with DeLaval diesels, which was compiled by the NRC Staff, is appended to this testimony as Attachment 8.^{14/} In addition, during its vendor inspections in 1983, the NRC inspectors identified "conditions which imply that portions of the DeLaval QA Program have not been carried out in accordance with the provisions of 10 CFR 50, Appendix B."^{15/}

Further, the NRC vendor inspection program previously had identified problems in the implementation of the DeLaval QA program. Beginning in 1979 and continuing through 1983, the NRC conducted nine inspections at DeLaval. Sixty-two instances of regulatory violations or nonconformances were documented.^{16/} This number of

(Footnote cont'd from previous page)

Notification identify a number of problems that have occurred with DeLaval diesels over the last three years. It is appended as Attachment 7.

^{14/} DeLaval Diesel Generator Operation Experience, handout prepared by the Nuclear Regulatory Commission at a meeting on DeLaval diesels held by the Staff in Bethesda, Maryland on January 26, 1984. Appended as Attachment 8.

^{15/} Nuclear Regulatory Commission Board Notification 83-160, October 21, 1983, page 2 (attached as Attachment 7). The details of the allegations have not been revealed by the NRC to avoid compromising the ongoing investigation of DeLaval being conducted by the NRC's Office of Investigations.

^{16/} Nuclear Regulatory Commission Vendor Inspection Reports (October 14 to 17, 1980), issued January 22, 1981; 81-01,

(Footnote cont'd next page)

problems in the DeLaval QA program, many of which remained uncorrected over three years after the completion of the Shoreham diesels, further demonstrates that the DeLaval QA process was suspect and that LILCO, far before Fall 1983, should have recognized the unreliability of the DeLaval diesels and taken steps to institute a comprehensive revalidation program or to replace them completely.

Attached to this testimony as Attachment 9 is a summary of the DeLaval inspection history prepared by the NRC's Vendor Inspection Branch. The vendor inspection history was discussed by John Collins, Regional Administrator for Region IV of the Nuclear Regulatory Commission, at a January 26, 1984 meeting NRC Staff/DeLaval Owners' Group meeting. Mr. Collins expressed serious reservations about the adequacy of both the DeLaval and utilities' QA/QC program, as follows:

As we indicated at the beginning, we have summarized in these slides the findings. But, more that's of interest. If you carefully review the findings that were handed

(Footnote cont'd from previous page) .

to 16, 1981), issued September 18, 1981; 82-01, (January 25 to 29, 1982), issued April 15, 1982; 82-02, (August 23 to 26, 1982), issued December 8, 1982; and 83-01, (July 11 to 15, 1983), issued October 3, 1983.

to you that were documented in the handout to you, one thing it says to me, in my opinion, is that not only has there been problems at the manufacturing shop, but also, in my opinion, calls into question the adequacy of the vendor programs or surveillance programs that are being conducted by the utilities. Had some of these been identified up front by utilities on-site inspection programs, or receiving inspection programs, or procurement programs, I think they could have been identified even sooner than now. So, it really calls into question your own programs.^{17/}

(Emphasis added). Similarly, Mr. William Foster of the NRC Staff stated recently that the number and nature of violations and nonconformances at DeLaval indicated to him that the DeLaval QA System was "ineffective."^{18/}

Q: What is the significance in the context of this proceeding of the NRC's findings concerning DeLaval with respect to LILCO's responsibility for the diesel failures that have required it to seek an exemption?

^{17/} John Collins, "Transcript of Meeting on DeLaval Diesel Generators," held at the Nuclear Regulatory Commission headquarters, Bethesda, Maryland, January 26, 1984, appended as Attachment 10.

^{18/} Deposition of William Foster, May 22, 1984, at 16.

A: LILCO should have been aware of the NRC's DeLaval inspection findings since the reports were publicly available. LILCO should have read these NRC inspection reports and taken appropriate actions. This is especially the case regarding LILCO since the 1974-76 experience (discussed above) had given bases for concern. We have found little evidence, however, of any systematic response by LILCO management to determine the root cause(s) in the OA/QC program implementation which resulted in the numerous nonconformances found at DeLaval by the NRC. This failure by LILCO further supports our belief that LILCO's need for an exemption is the result of its own inappropriate actions or inaction.^{19/}

^{19/} LILCO should also have been alerted to potential problems with the Shoreham diesels as a result of the pattern of deficiencies in DeLaval's production of other diesel engines for nuclear service, which resulted in numerous operational problems. These problems were generally reported by DeLaval in Part 21, Title 10 of the Code of Federal Regulations reports, or by the owners of the diesels in Part 50.55(e), Title 10 of the Code of Federal Regulations reports. Copies of such Part 21 reports were sent to LILCO by DeLaval.

Q: Is there any other basis for your opinion that LILCO's need for an exemption results from LILCO's own inappropriate actions?

A: Yes. DeLaval diesel owners have documented serious operational problems in non-nuclear applications similar to those experienced by nuclear users. Thus, in addition to the problems LILCO itself experienced with the DeLaval diesels prior to 1983, if LILCO had looked, it would have found much additional evidence of the unsatisfactory design and manufacture of DeLaval diesels similar to the Shoreham diesels. In our opinion, in view of the history known to LILCO of QA problems with DeLaval, LILCO, prior to 1983, should have tracked and responded to the significant problems with DeLaval diesels in non-nuclear applications. This is especially the case since the lack of operating experience of DeLaval diesels in nuclear applications should have led LILCO to inquire how DeLaval diesels were performing in non-nuclear applications.

For example, the DeLaval diesels supplied for the ship M.V. Columbia have experienced many component failures including:

- o Cylinder heads - design and manufacturing defects
- o Cylinder liner distortion and wear - due to block distortion
- o Piston ring distortion and wear - due to block distortion
- o Cylinder blocks - distortion and cracking
- o Connecting rod bearings - design of articulated connecting rod assembly
- o Main bearings - premature wear, high loading
- o Camshafts - premature wear^{20/}

Based on the preceding, the authors of the M.V. Columbia evaluation concluded:

[M]ajor moving components of the engine failed or required an inordinate amount of corrective maintenance at a significantly higher rate as compared to either DeLaval's recommended scheduled maintenance or other

^{20/} Seaworthy Engine Systems Report No. 124-01, Evaluation Of The Operational And Maintenance History Of, And Recent Modifications To, The Main Engines In the M.V. Columbia, April, 1983. Other shipboard failures of the same nature experienced by the Pride of Texas are set forth in Attachment A to letter from C.C. Wei, Falcon Carriers, Inc. to C. Matthews, DeLaval, Re: Pride of Texas Engine Problems, July 22, 1982.

typical diesel manufacturer's TBOs. The types of failures and number of failures of some of the major components indicates design deficiencies in these components. Two critical components which have been subject to failure, which are not typically expected to routinely fail, were the articulated connecting rods and cylinder blocks.^{21/}

Q: Why do you believe that LILCO's failure to consider non-nuclear data concerning the DeLaval diesels was inappropriate?

A: As noted above, the lack of DeLaval diesels in nuclear applications should have led LILCO to inquire regarding their performance in non-nuclear service. Indeed, LILCO itself apparently considered non-nuclear applications of the DeLaval diesels to be relevant to the use of the diesels at Shoreham. For example, LILCO relied upon DeLaval's allegedly good non-nuclear experience in other aspects of this proceeding. In his affidavit attached to LILCO's Opposition to Suffolk County's Motion to Add an Emergency Diesel Generator Contention, May 16, 1983, Mr. Youngling of LILCO testified:

^{21/} Seaworthy Engine Systems Report No. 124-01, Evaluation Of The Operational And Maintenance History Of, And Recent Modifications To, The Main Engines In the M.V. Columbia, April, 1983.

The vendor has advised LILCO that the basic diesel engine in the Shoreham diesel generators has been in production since the early 1950's. There are 97 diesel engines in this country that are essentially identical or very similar to the Shoreham diesels.

(Emphasis added). Mr. Youngling later testified that:

Some of the diesels that we have cited in our 97 are marine application diesels, others are stationary application for power production and some are nuclear applications.^{22/}

If LILCO had carefully scrutinized available data, however, it would have found actually that very serious problems were being experienced in non-nuclear DeLaval diesels.

In our opinion, a careful and timely look by LILCO at the non-nuclear experience with DeLaval diesels would have caused LILCO to review the adequacy of the Shoreham diesels well before their catastrophic failure in 1983. However, there is no evidence prior to 1983 that LILCO management sought to conduct such reviews, despite the fact that diesel operation was critical to the startup of

^{22/} Transcript of diesel proceeding, June 10, 1983 ("Hearing Transcript"), at 21,291.

Shoreham and despite the evidence, that grew stronger through the years, and of which LILCO had both direct and indirect knowledge, that DeLaval's diesels were seriously deficient for nuclear application.

Q: Does LILCO's purchase of alternate diesel generators, as stated in the Application for Exemption (p. 25), support the requested exemption?

A: No. At the October 26, 1983 LILCO Board of Directors meeting, the LILCO Board ratified a contract with the Fairbanks Morse Engine Division of Colt Industries ("Colt") for three 4400 kilowatt diesels for Shoreham at a cost of \$12.985 million. However, that action does not change our opinion about the reasons LILCO should not be granted the requested exemption. Long before 1983, LILCO could, indeed should, have recognized the extremely serious problem with the DeLaval diesels and have perhaps purchased diesels from Colt. Indeed, LILCO could have selected the Colt diesels originally, and thus have avoided altogether the problems with the DeLaval diesels and the need for an exemption.

Colt submitted a bid in 1974 for three 4,296 kilowatt units. The Colt bid exceeded the DeLaval proposal by only

\$100,967 (i.e., \$2,210,967 for the Colt diesels versus \$2,110,000 for the DeLaval diesels), but the Colt offer was determined to be technically unacceptable by LILCO because the kilowatt rating was deemed larger than required.^{23/} We believe that LILCO was in error in excluding Colt on this basis. Colt's prior experience in supplying nuclear grade diesels was given insufficient weight in LILCO's technical evaluation. In our opinion LILCO should have considered whether the QA/QC and other critical processes would have gone as smoothly with DeLaval, a vendor that had no previous nuclear experience, as they might have with Colt, which had extensive experience in qualifying its diesels for nuclear application. In this sense, perhaps DeLaval was not the lowest qualified bidder.

Q: What impact have the diesel problems had on the date for the operation of Shoreham?

A: LILCO contends that it would have been able to proceed with low power operation of Shoreham shortly after the

^{23/} "Technical Evaluation, Diesel Generator Sets - SHI-89," April 5, 1974, attached to letter from J.P. Allen, Stone & Webster project engineer, to H.C. Buckley, LILCO Purchasing Agent, April 11, 1974.

Atomic Safety Licensing Board issued its Partial Initial Decision on September 21, 1983 had it not been for the problems encountered with the diesels. Therefore, it appears that the DeLaval diesel problems are responsible for the delays from September 21, 1983 until such time as Shoreham begins low power operation, and constitute the reason for LILCO's alleged need for an exemption. As noted previously, however, LILCO had ample opportunity prior to Fall 1983 to take actions to head off the diesels being in the critical path. LILCO failed to take advantage of these numerous opportunities.

IV. CONCLUSIONS

Q: What are your conclusions concerning the selection, procurement, and installation of Shoreham's diesel generators?

A: Our investigation of these problems reveals that LILCO, directly or through its contractor, Stone and Webster, failed to act appropriately to assure that it acquired and installed emergency diesel generators suited for use at Shoreham.

- o LILCO and Stone and Webster failed to properly or promptly obtain, review, and follow up on available information that demonstrated deficiencies in the DeLaval QA program as well as numerous flaws in the product resulting from that program;
- o LILCO improperly excluded full consideration of the other potential diesel generator suppliers, specifically the Colt bid, and failed to properly evaluate Colt's nuclear experience;
- o LILCO relied too heavily upon DeLaval to design and manufacture the diesels, and thus failed to assure that DeLaval and Stone and Webster carried out their delegated QA tasks;
- o LILCO failed to conduct a suitable design verification of the DeLaval diesels at an early date, and thus failed to detect that the diesels may have significant deficiencies that prevent their approval for nuclear application.
- o LILCO failed to adhere to the NRC's QA/QC requirements and thus failed to take the planned and systematic actions necessary to provide adequate

confidence that the diesels will perform satisfactorily in service; and

- o LILCO failed to initiate promptly appropriate remedial measures to address the numerous known deficiencies in the Shoreham diesels.

The result of the preceding is that the efforts required to remedy the diesels have significantly delayed fuel load and low power testing at Shoreham.

Q: What is the significance of your findings with regard to LILCO's Application for Exemption and the proposed Low Power Operating License?

A: LILCO proposes, contrary to regulation and past practice, that low power operation should be permitted without benefit of a qualified, on-site supply of emergency AC power. LILCO argues that this unusual step should be taken because of the "good faith" shown by LILCO's "strenuous efforts to comply with GDC 17."^{1/} LILCO further states that "[i]t is only because of problems arising during preoperational tests that they (the DeLaval diesels) have not yet been licensed." We disagree

^{1/} May 22, 1984 Application for Exemption, page 24.

with this position. Rather, it is because of LILCO's insufficient actions since 1974 in the total diesel generator procurement and installation process described above that this delay has occurred. The problems arose far in advance of LILCO's late 1982 preoperational testing program and with prompt action could have been addressed at a far earlier date, thus eliminating any possible need for the exemption application. Thus, we conclude that the exceptional circumstances claimed by LILCO do not exist, particularly since LILCO itself is largely responsible for the problems which have occurred, and thus no exemption is warranted.

PROFESSIONAL QUALIFICATIONS OF DALE G. BRIDENBAUGH

DALE G. BRIDENBAUGH
1723 Hamilton Avenue
Suite K
San Jose, CA 95125
(408) 266-2716

EXPERIENCE:

1976 - PRESENT

President - MHB Technical Associates, San Jose, California

Co-founder and partner of technical consulting firm. Specialists in energy consulting to governmental and other groups interested in evaluation of nuclear plant safety and licensing. Consultant in this capacity to state agencies in California, New York, Illinois, New Jersey, Pennsylvania, Oklahoma and Minnesota and to the Norwegian Nuclear Power Committee, Swedish Nuclear Inspectorate, and various other organizations and environmental groups. Performed extensive safety analysis for Swedish Energy Commission and contributed to the Union of Concerned Scientist's Review of WASH-1400. Consultant to the U.S. NRC - LWR Safety Improvement Program, performed Cost Analysis of Spent Fuel Disposal for the Natural Resources Defense Council, and contributed to the Department of Energy LWR Safety Improvement Program for Sandia Laboratories. Served as expert witness in NRC and state utility commission hearings.

1976 - (FEBRUARY - AUGUST)

Consultant, Project Survival, Palo Alto, California

Volunteer work on Nuclear Safeguards Initiative campaigns in California, Oregon, Washington, Arizona, and Colorado. Numerous presentations on nuclear power and alternative energy options to civic, government, and college groups. Also resource person for public service presentations on radio and television.

1973 - 1976

Manager, Performance Evaluation and Improvement, General Electric Company - Nuclear Energy Division, San Jose, California

Managed seventeen technical and seven clerical personnel with responsibility for establishment and management of systems to monitor and

measure Boiling Water Reactor equipment and system operational performance. Integrated General Electric resources in customer plant modifications, coordinated correction of causes of forced outages and of efforts to improve reliability and performance of BWR systems. Also responsible for development of Division Master Performance Improvement Plan as well as for numerous Staff special assignments on long-range studies. Was on special assignment for the management of two different ad hoc projects formed to resolve unique technical problems.

1972 - 1973

Manager, Product Service, General Electric Company - Nuclear Energy Division, San Jose, California

Managed group of twenty-one technical and four clerical personnel. Prime responsibility was to direct interface and liaison personnel involved in corrective actions required under contract warranties. Also in charge of refueling and service planning, performance analysis, and service communication functions supporting all completed commercial nuclear power reactors supplied by General Electric, both domestic and overseas (Spain, Germany, Italy, Japan, India, and Switzerland).

1968 - 1972

Manager, Product Service, General Electric Company - Nuclear Energy Division, San Jose, California

Managed sixteen technical and six clerical personnel with the responsibility for all customer contact, planning and execution of work required after the customer acceptance of department-supplied plants and/or equipment. This included quotation, sale and delivery of spare and renewal parts. Sales volume of parts increased from \$1,000,000 in 1968 to over \$3,000,000 in 1972.

1966 - 1968

Manager, Complaint and Warranty Service, General Electric Company - Nuclear Energy Division, San Jose, California

Managed group of six persons with the responsibility for customer contacts, planning and execution of work required after customer acceptance of department-supplied plants and/or equipment--both domestic and overseas.

1963 - 1966

Field Engineering Supervisor, General Electric Company, Installation and Service Engineering Department, Los Angeles, California

Supervised approximately eight field representatives with responsibility for General Electric steam and gas turbine installation and maintenance

work in Southern California, Arizona, and Southern Nevada. During this period was responsible for the installation of eight different central station steam turbine-generator units, plus much maintenance activity. Work included customer contact, preparation of quotations, and contract negotiations.

1956 - 1963

Field Engineer, General Electric Company, Installation and Service Engineering Department, Chicago, Illinois

Supervised installation and maintenance of steam turbines of all sizes. Supervised crews of from ten to more than one hundred men, depending on the job. Worked primarily with large utilities but had significant work with steel, petroleum and other process industries. Had four years of experience at construction, startup, trouble-shooting and refueling of the first large-scale commercial nuclear power unit.

1955 - 1956

Engineering Training Program, General Electric Company, Erie, Pennsylvania, and Schenectady, New York

Training assignments in plant facilities design and in steam turbine testing at two General Electric factory locations.

1953 - 1955

United States Army - Ordnance School, Aberdeen, Maryland

Instructor - Heavy Artillery Repair. Taught classroom and shop disassembly of artillery pieces.

1953

Engineering Training Program, General Electric Company, Evendale, Ohio

Training assignment with Aircraft Gas Turbine Department.

EDUCATION & AFFILIATIONS:

BSME - 1953, South Dakota School of Mines and Technology, Rapid City, South Dakota, Upper 1/4 of class.

Professional Nuclear Engineer - California. Certificate No. 0973.

Member - American Nuclear Society

Various Company Training Courses during career including Professional Business Management, Kepner Tregoe Decision Making, Effective Presentation, and numerous technical seminars.

HONORS & AWARDS:

Sigma Tau - Honorary Engineering Fraternity.

General Managers Award, General Electric Company.

PERSONAL DATA:

Born November 20, 1931, Miller, South Dakota.
Married, three children
6'2", 190 lbs., health - excellent
Honorable discharge from United States Army
Hobbies: Skiing, hiking, work with Boy Scout Groups

PUBLICATIONS & TESTIMONY:

1. Operating and Maintenance Experience, presented at Twelfth Annual Seminar for Electric Utility Executives, Pebble Beach, California, October 1972, published in General Electric NEDC-10697, December 1972.
2. Maintenance and In-Service Inspection, presented at IAEA Symposium on Experience From Operating and Fueling of Nuclear Power Plants, Bridenbaugh, Lloyd & Turner, Vienna, Austria, October, 1973.
3. Operating and Maintenance Experience, presented at Thirteenth Annual Seminar for Electric Utility Executives, Pebble Beach, California, November 1973, published in General Electric NEDO-20222, January, 1974.
4. Improving Plant Availability, presented at Thirteenth Annual Seminar for Electric Utility Executives, Pebble Beach, California, November 1973, published in General Electric NEDO-20222, January, 1974.
5. Application of Plant Outage Experience to Improve Plant Performance, Bridenbaugh and Burdsall, American Power Conference, Chicago, Illinois, April 14, 1974.
6. Nuclear Valve Testing Cuts Cost, Time, Electrical World, October 15, 1974.

7. Testimony of D. G. Bridenbaugh, R. B. Hubbard, and G. C. Minor before the United States Congress, Joint Committee on Atomic Energy, February 18, 1976, Washington, D.C. (Published by the Union of Concerned Scientists, Cambridge, Massachusetts.)
8. Testimony of D. G. Bridenbaugh, R. B. Hubbard, G. C. Minor to the California State Assembly Committee on Resources, Land Use, and Energy, March 8, 1976.
9. Testimony by D. G. Bridenbaugh before the California Energy Commission, entitled, Initiation of Catastrophic Accidents at Diablo Canyon, Hearings on Emergency Planning, Avila Beach, California, November 4, 1976.
10. Testimony by D. G. Bridenbaugh before the U. S. Nuclear Regulatory Commission, subject: Diablo Canyon Nuclear Plant Performance, Atomic Safety and Licensing Board Hearings, December, 1976.
11. Testimony by D. G. Bridenbaugh before the California Energy Commission, subject: Interim Spent Fuel Storage Considerations, March 10, 1977.
12. Testimony of D. G. Bridenbaugh before the New York State Public Service Commission Siting Board Hearings concerning the Jamesport Nuclear Power Station, subject: Effect of Technical and Safety Deficiencies on Nuclear Plant Cost and Reliability, April, 1977.
13. Testimony by D. G. Bridenbaugh before the California State Energy Commission, subject: Decommissioning of Pressurized Water Reactors, Sundesert Nuclear Plant Hearings, June 9, 1977.
14. Testimony by D. G. Bridenbaugh before the California State Energy Commission, subject: Economic Relationships of Decommissioning, Sundesert Nuclear Plant, for the Natural Resources Defense Council, July 15, 1977.
15. The Risks of Nuclear Power Reactors: A Review of the NRC Reactor Safety Study WASH-1400, Kendall, Hubbard, Minor & Bridenbaugh, et al, for the Union of Concerned Scientists, August, 1977.
16. Testimony by D. G. Bridenbaugh before the Vermont State Board of Health, subject: Operation of Vermont Yankee Nuclear Plant and Its Impact on Public Health and Safety, October 6, 1977.
17. Testimony by D. G. Bridenbaugh before the U.S. Nuclear Regulatory Commission, Atomic Safety and Licensing Board, subject: Deficiencies in Safety Evaluation of Non-Seismic Issues, Lack of a Definitive Finding of Safety, Diablo Canyon Nuclear Units, October 18, 1977, Avila Beach, California.

18. Testimony by D. G. Bridenbaugh before the Norwegian Commission on Nuclear Power, subject: Reactor Safety/Risk, October 26, 1977.
19. Swedish Reactor Safety Study: Barseback Risk Assessment, MHB Technical Associates, January, 1978. (Published by the Swedish Department of Industry as Document DsI 1978:1)
20. Testimony by D. G. Bridenbaugh before the Louisiana State Legislature Committee on Natural Resources, subject: Nuclear Power Plant Deficiencies Impacting on Safety & Reliability, Baton Rouge, Louisiana, February 13, 1978.
21. Spent Fuel Disposal Costs, report prepared by D. G. Bridenbaugh for the Natural Resources Defense Council (NRDC), August 31, 1978.
22. Testimony of D. G. Bridenbaugh, G. C. Minor, and R. B. Hubbard before the Atomic Safety and Licensing Board, in the matter of the Black Fox Nuclear Power Station Construction Permit Hearings, September 25, 1978, Tulsa, Oklahoma.
23. Testimony of D. G. Bridenbaugh and R. B. Hubbard before the Louisiana Public Service Commission, Nuclear Plant and Power Generation Costs, November 19, 1978, Baton Rouge, Louisiana.
24. Testimony by D. G. Bridenbaugh before the City Council and Electric Utility Commission of Austin, Texas, Design, Construction, and Operating Experience of Nuclear Generating Facilities, December 5, 1978, Austin, Texas.
25. Testimony by D. G. Bridenbaugh for the Commonwealth of Massachusetts, Department of Public Utilities, Impact of Unresolved Safety Issues, Generic Deficiencies, and Three Mile Island-Initiated Modifications on Power Generation Cost at the Proposed Pilgrim-2 Nuclear Plant, June 8, 1979.
26. Improving the Safety of LWR Power Plants, MHB Technical Associates, prepared for U.S. Dept. of Energy, Sandia Laboratories, September 28, 1979.
27. BWR Pipe and Nozzle Cracks, MHB Technical Associates, for the Swedish Nuclear Power Inspectorate (SKI), October, 1979.
28. Uncertainty in Nuclear Risk Assessment Methodology. MHB Technical Associates, for the Swedish Nuclear Power Inspectorate (SKI), January 1980.

29. Testimony of D. G. Bridenbaugh and G. C. Minor before the Atomic Safety and Licensing Board, in the matter of Sacramento Municipal Utility District, Rancho Seco Nuclear Generating Station following TMI-2 accident, subject: Operator Training and Human Factors Engineering, for the California Energy Commission, February 11, 1980.
30. Italian Reactor Safety Study: Caorso Risk Assessment, MHB Technical Associates, for Friends of the Earth, Italy, March, 1980.
31. Decontamination of Krypton-85 from Three Mile Island Nuclear Plant, H. Kendall, R. Pollard, & D. G. Bridenbaugh, et al, The Union of Concerned Scientists, delivered to the Governor of Pennsylvania, May 15, 1980.
32. Testimony by D. G. Bridenbaugh before the New Jersey Board of Public Utilities, on behalf of New Jersey Public Advocate's Office, Division of Rate Counsel, Analysis of 1979 Salem-1 Refueling Outage, August, 1980.
33. Minnesota Nuclear Plants Gaseous Emissions Study, MHB Technical Associates, for Minnesota Pollution Control Agency, September, 1980.
34. Position Statement, Proposed Rulemaking on the Storage and Disposal of Nuclear Waste, Joint Cross-Statement of Position of the New England Coalition on Nuclear Pollution and the Natural Resources Defense Council, September, 1980.
35. Testimony by D. G. Bridenbaugh and G. C. Minor, before the New York State Public Service Commission, In the Matter of Long Island Lighting Company Temporary Rate Case, prepared for the Shoreham Opponents Coalition, September 22, 1980, Shoreham Nuclear Plant Construction Schedule.
36. Supplemental Testimony by D. G. Bridenbaugh before the New Jersey Board of Public Utilities, on behalf of New Jersey Department of the Public Advocate, Division of Rate Counsel, Analysis of 1979 Salem-1 Refueling Outage, December, 1980.
37. Testimony by D. G. Bridenbaugh and G. C. Minor, before the New Jersey Board of Public Utilities, on behalf of New Jersey Department of the Public Advocate, Division of Rate Counsel, Oyster Creek 1980 Refueling Outage Investigation, February 1981.
38. Economic Assessment: Ownership Interest in Palo Verde Nuclear Station, MHB Technical Associates, for the City of Riverside, September 11, 1981.

39. Testimony of D. G. Bridenbaugh before the Public Utilities Commission of Ohio, in the Matter of the Regulation of the Electric Fuel Component Contained Within the Rate Schedules of the Toledo Edison Company and Related Matters, subject: Davis-Besse Nuclear Power Station 1980-81 Outage Review, November, 1981.
40. Supplemental Testimony of D. G. Bridenbaugh before the Public Utilities Commission of Ohio, in the matter of the Regulation of the Electric Fuel Component Contained within the Rate Schedules of the Toledo Edison Company and Related Matters, subject: Davis-Besse Nuclear Power Station 1980-81 Outage Review, November 1981.
41. Systems Interaction and Single Failure Criterion, Phase 2 Report, MHB Technical Associates for the Swedish Nuclear Power Inspectorate (SKI), January, 1982.
42. Testimony of D. G. Bridenbaugh and G. C. Minor on behalf of Governor Edmund G. Brown Jr., before the Atomic Safety and Licensing Board, regarding Contention 10, Pressurizer Heaters, January 11, 1982.
43. Testimony of D. G. Bridenbaugh and G. C. Minor on behalf of Governor Edmund G. Brown Jr., before the Atomic Safety and Licensing Board, regarding Contention 12, Block and Pilot Operated Relief Valves, January 11, 1982.
44. Testimony of D. G. Bridenbaugh before the Commonwealth of Massachusetts, Department of Public Utilities, on behalf of the Massachusetts Attorney General, Pilgrim Nuclear Power Station, 1981-82 Outage Investigation, March 11, 1982.
45. Testimony of D. G. Bridenbaugh before the Pennsylvania Public Utility Commission, on behalf of the Pennsylvania Office of Consumer Advocate, Beaver Valley Outage, March, 1982.
46. Interim testimony of D. G. Bridenbaugh before the Illinois Commerce Commission, on behalf of the Illinois Attorney General's Office, Expected Lifetimes and Performance of Nuclear Power Plants, March, 1982.
47. Testimony of D. G. Bridenbaugh and G. C. Minor before the Atomic Safety and Licensing Board, on behalf of Suffolk County, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station, Unit 1, regarding Suffolk County Contention 11, Passive Mechanical Valve Failures, April 13, 1982.
48. Testimony of D. G. Bridenbaugh and R. B. Hubbard, in the Matter of Jersey Central Power and Light Company For an Increase in Rates for Electrical Service, on behalf of New Jersey Department of the Public Advocate, Division of Rate Counsel, Three Mile Island Units 1 & 2, Cleanup and Modification Programs, May, 1982.

49. Testimony of D. G. Bridenbaugh and G. C. Minor on behalf of Suffolk County, before the Atomic Safety and Licensing Board, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station, Unit 1, regarding Suffolk County Contention 22, SRV Test Program, May 25, 1982.
50. Testimony of D. G. Bridenbaugh and G. C. Minor on behalf of Suffolk County, before the Atomic Safety and Licensing Board, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station, Unit 1, regarding Suffolk County Contention 28(a)(vi) and SOC Contention 7A(6), Reduction of SRV Challenges, June 14, 1982.
51. Testimony of D. G. Bridenbaugh before the Illinois Commerce Commission, on behalf of the Illinois Attorney General's Office, Expected Lifetimes and Performance of Nuclear Power Plants, June 18, 1982.
52. Testimony of D. G. Bridenbaugh and R. B. Hubbard on behalf of the Ohio Consumers Counsel, before the Public Utilities Commission of Ohio, regarding Construction of Perry Nuclear Generating Unit No. 1, October 7, 1982.
53. Issues Affecting the Viability and Acceptability of Nuclear Power Usage in the United States, prepared by MHB Technical Associates for Congress of the United States, Office of Technology Assessment for use in conjunction with Workshop on Technological and Regulatory Changes in Nuclear Power, December 8 & 9, 1982.
54. Testimony of D. G. Bridenbaugh on behalf of Rockford League of Women Voters, before the Atomic Safety and Licensing Board, in the matter of Commonwealth Edison Company, Byron Station, Units 1 and 2, regarding Contention 22, Steam Generators, March 1, 1983.
55. Testimony of G. C. Minor and D. G. Bridenbaugh before the Pennsylvania Public Utility Commission, on behalf of the Office of Consumer Advocate, Regarding the Cost of Constructing the Susquehanna Steam Electric Station, Unit I, Re: Pennsylvania Power and Light, March 18, 1983.
56. Surrebuttal Testimony of D. G. Bridenbaugh before the Pennsylvania Public Utility Commission, on behalf of the Office of Consumer Advocate, Regarding the Cost of Constructing the Susquehanna Steam Electric Station, Unit I, Re: Pennsylvania Power and Light, April 20, 1983.
57. Testimony of D. G. Bridenbaugh In the Matter of Public Service Gas & Electric, Base Rate Case, Nuclear Construction Expenditures, on behalf of New Jersey Department of the Public Advocate, Division of Rate Counsel, October 13, 1983

58. Affidavit of D. G. Bridenbaugh, in the Matter of Jersey Central Power and Light, on behalf of New Jersey Department of the Public Advocate, Division of Rate Counsel, TMI Fault Investigation, November 23, 1983.
59. Testimony of D. G. Bridenbaugh, in the Matter of Public Service Electric & Gas, on behalf of New Jersey Department of the Public Advocate, Division of Rate Counsel, LEAC Investigation, Salem-1 Outages, December 1, 1983.
60. Rebuttal Testimony of D. G. Bridenbaugh, in the Matter of public Service Electric & Gas, on behalf of New Jersey Department of the Public Advocate, Division of Rate Counsel, LEAC Investigation, Salem-1 Outages, January 18, 1984.
61. Testimony of D. G. Bridenbaugh, L. M. Danielson, R. B. Hubbard and G. C. Minor before the State of New York Public Service Commission, PSC Case No. 27563, in the matter of Long Island Lighting Company Proceeding to Investigate the Cost of the Shoreham Nuclear Generating Facility -- Phase II, on behalf of County of Suffolk, February 10, 1984.
62. Status Report, WJ Zimmer Plant, Assessment of Options, MHB Technical Associates, prepared for The Ohio Office of the Consumer's Counsel, February 23, 1984.

ATTACHMENT 2

PROFESSIONAL QUALIFICATIONS OF RICHARD B. HUBBARD

RICHARD B. HUBBARD
MHB Technical Associates
1723 Hamilton Avenue
Suite K
San Jose, California 95125

EXPERIENCE:

9/76 - PRESENT

Vice-President - MHB Technical Associates, San Jose, California.
Founder, and Vice-President of technical consulting firm. Specialists in independent energy assessments for government agencies, particularly technical and economic evaluation of nuclear power facilities. Consultant in this capacity to California, Massachusetts, Oklahoma and Illinois Attorney Generals, Minnesota Pollution Control Agency, German Ministry for Research and Technology, Governor of California, Swedish Energy Commission, Swedish Nuclear Inspectorate, Suffolk County, Ohio Consumer's Counsel, New Jersey Public Advocate, and the U. S. Department of Energy. Also provided studies and testimony for various public interest groups including the Center for Law in the Public Interest, Los Angeles; Public Law Utility Group, Baton Rouge, Louisiana; Friends of the Earth (FOE), Italy; and the Union of Concerned Scientists, Cambridge, Massachusetts. Provided testimony to the U.S. Senate/House Joint Committee on Atomic Energy, the U.S. House Committee on Interior and Insular Affairs, the California Assembly, Land Use, and Energy Committee, the Advisory Committee on Reactor Safeguards, and the Atomic Safety and Licensing Board. Performed comprehensive risk analysis of the accident probabilities and consequences at the Barseback Nuclear Plant for the Swedish Energy Commission and edited, as well as contributed to, the Union of Concerned Scientist's technical review of the NRC's Reactor Safety Study (WASH-1400).

2/76 - 9/76

Consultant, Project Survival, Palo Alto, California.
Volunteer work on Nuclear Safeguards Initiative campaigns in California, Oregon, Washington, Arizona, and Colorado. Numerous presentations on nuclear power and alternative energy options to civic, government, and college groups. Also resource person for public service presentations on radio and television.

5/75 - 1/76

Manager - Quality Assurance Section, Nuclear Energy Control and Instrumentation Department, General Electric Company, San Jose, California.
Report to the Department General Manager. Develop and implement quality plans, programs, methods, and equipment which assure that products produced by the Department meet quality requirements as defined in NRC regulation 10 CFR 50, Appendix B, ASME Boiler and Pressure Vessel Code, customer contracts, and GE Corporate policies and procedures. Product areas include radiation sensors, reactor vessel internals, fuel handling and servicing tools, nuclear plant control and protection instrumentation systems, and nuclear steam supply and Balance of Plant control room panels. Responsible for approximately 45 exempt personnel, 22 non-exempt personnel, and 129 hourly personnel with an expense budget of nearly 4 million dollars and equipment investment budget of approximately 1.2 million dollars.

11/71 - 5/75

Manager - Quality Assurance Subsection, Manufacturing Section of Atomic Power Equipment Department, General Electric Company, San Jose, California.
Report to the Manager of Manufacturing. Same functional and product responsibilities as in Engagement #1, except at a lower organizational report level. Developed a quality system which received NRC certification in 1975. The system was also successfully surveyed for ASME "N" and "NPT" symbol authorization in 1972 and 1975, plus ASME "U" and "S" symbol authorizations in 1975. Responsible for from 23 to 39 exempt personnel, 7 to 14 non-exempt personnel, and 53 to 97 hourly personnel.

3/70 - 11/71

Manager - Application Engineering Subsection, Nuclear Instrumentation Department, General Electric Company, San Jose, California.
Responsible for the post order technical interface with architect engineers and power plant owners to define and schedule the instrumentation and control systems for the Nuclear Steam Supply and Balance of Plant portion of nuclear power generating stations. Responsibilities included preparation of the plant instrument list with approximate location, review of interface drawings to define functional design requirements, and release of functional requirements for detailed equipment designs. Personnel supervised included 17 engineers and 5 non-exempt personnel.

12/69 - 3/70

Chairman - Equipment Room Task Force, Nuclear Instrumentation Department, General Electric Company, San Jose, California.
Responsible for a special task force reporting to the Department General Manager to define methods to improve the quality and reduce the

installation time and cost of nuclear power plant control rooms. Study resulted in the conception of a factory-fabricated control room consisting of signal conditioning and operator control panels mounted on modular floor sections which are completely assembled in the factory and thoroughly tested for proper operation of interacting devices. Personnel supervised included 10 exempt personnel.

12/65 - 12/69

Manager - Proposal Engineering Subsection, Nuclear Instrumentation Department, General Electric Company, San Jose, California.

Responsible for the application of instrumentation systems for nuclear power reactors during the proposal and pre-order period. Responsible for technical review of bid specifications, preparation of technical bid clarifications and exceptions, definition of material list for cost estimating, and the "as sold" review of contracts prior to turnover to Application Engineering. Personnel supervised varied from 2 to 9 engineers.

8/64 - 12/65

Sales Engineer, Nuclear Electronics Business Section of Atomic Power Equipment Department, General Electric Company, San Jose, California.

Responsible for the bid review, contract negotiation, and sale of instrumentation systems and components for nuclear power plants, test reactors, and radiation hot cells. Also responsible for industrial sales of radiation sensing systems for measurement of chemical properties, level, and density.

10/61 - 8/64

Application Engineer, Low Voltage Switchgear Department, General Electric Company, Philadelphia, Pennsylvania

Responsible for the application and design of advanced diode and silicon-controlled rectifier (SCR) constant voltage DC power systems and variable voltage DC power systems for industrial applications. Designed, followed manufacturing and personally tested an advanced SCR power supply for product introduction at the Iron and Steel Show. Project Engineer for a DC power system for an aluminum pot line provided to Anaconda beginning at the 161KV switchyard and encompassing all the equipment to convert the power to 700 volts DC at 160,000 amperes.

9/60 - 10/61

GE Rotational Training Program

Four 3-month assignments on the GE Rotational Training Program for college technical graduates as follows:

- a. Installation and Service Eng. - Detroit, Michigan
Installation and startup testing of the world's largest automated hot strip steel mill.
- b. Tester - Industry Control - Roanoke, Virginia
Factory testing of control panels for control of steel, paper, pulp, and utility mills and power plants.
- c. Engineer - Light Military Electronics - Johnson City, New York
Design of ground support equipment for testing the auto pilots on the F-105.
- d. Sales Engineer - Morrison, Illinois
Sales of appliance controls including range timers and refrigerator cold controls.

EDUCATION:

Bachelor of Science Electrical Engineering, University of Arizona, 1960.

Master of Business Administration, University of Santa Clara, 1969.

PROFESSIONAL AFFILIATION:

Registered Quality Engineer, License No. QU805, State of California.

Member of Subcommittee 8 of the Nuclear Power Engineering Committee of the IEEE Power Engineering Society responsible for the preparation and revision of the following national Q.A. Standards:

- a. IEEE 498 (ANSI N45.2.16): Requirements for the Calibration and Control of Measuring and Test Equipment used in the Construction and Maintenance of Nuclear Power Generating Stations.
- b. IEEE 336 (ANSI N45.2.4): Installation, Inspection, and Testing Requirements for Class 1E Instrumentation and Electric Equipment at Nuclear Power Generating Stations.
- c. IEEE 467 : Quality Assurance Program Requirements for the Design and Manufacture of Class 1E Instrumentation and Electric Equipment for Nuclear Power Generating Stations.

I am currently a member of the IEEE Committee which is preparing a standard relating to the selection and utilization of replacement parts for Class 1E equipment during the construction and operation phase.

PUBLICATIONS AND TESTIMONY:

1. In-Core System Provides Continuous Flux Map of Reactor Cores, R. B. Hubbard and C. E. Foreman, Power, November, 1967.
2. Quality Assurance: Providing It, Proving It, R. B. Hubbard, Power, May, 1972.
3. Testimony of R. B. Hubbard, D. G. Bridenbaugh, and G. C. Minor before the United States Congress, Joint Committee on Atomic Energy, February 18, 1976, Washington, D.C. (Published by the Union of Concerned Scientists, Cambridge, Massachusetts.) Excerpts from testimony published in Quote Without Comment, Chemtech, May, 1976.
4. Testimony of R. B. Hubbard, D. G. Bridenbaugh, and G. C. Minor to the California State Assembly Committee on Resources, Land Use, and Energy, Sacramento, California, March 8, 1976.
5. Testimony of R. B. Hubbard and G. C. Minor before California State Senate Committee on Public Utilities, Transit, and Energy, Sacramento, California, March 23, 1976.
6. Testimony of R. B. Hubbard and G. C. Minor, Judicial Hearings Regarding Grafenrheinfeld Nuclear Plant, March 16 & 17, 1977, Wurzburg, Germany.
7. Testimony of R. B. Hubbard to United States House of Representatives, Subcommittee on Energy and the Environment, June 30, 1977, Washington, D.C., entitled, Effectiveness of NRC Regulations - Modifications to Diablo Canyon Nuclear Units.
8. Testimony of R. B. Hubbard to the Advisory Committee on Reactor Safeguards, August 12, 1977, Washington, D.C., Risk Uncertainty Due to Deficiencies in Diablo Canyon Quality Assurance Program and Failure to Implement Current NRC Practices.
9. The Risks of Nuclear Power Reactors: A Review of the NRC Reactor Safety Study WASH-1400, Kendall, et. al., edited by R. B. Hubbard and G. C. Minor for the Union of Concerned Scientists, August, 1977.
10. Swedish Reactor Safety Study: Barseback Risk Assessment, MHB Technical Associates, January 1978 (Published by Swedish Department of Industry as Document DSI (1978:1)).
11. Testimony of R. B. Hubbard before the Energy Facility Siting Council, March 31, 1978, in the matter of Pebble Springs Nuclear Power Plant, Risk Assessment: Pebble Springs Nuclear Plant, Portland, Oregon.

12. Presentation by R. B. Hubbard before the Federal Ministry for Research and Technology (BMFT), August 31 and September 1, 1978, Meeting on Reactor Safety Research, Risk Analysis. Bonn, Germany.
13. Testimony by R. B. Hubbard, D. G. Bridenbaugh, and G. C. Minor before the Atomic Safety and Licensing Board, September 25, 1978, in the matter of the Black Fox Nuclear Power Station Construction Permit hearings, Tulsa, Oklahoma.
14. Testimony of R. B. Hubbard before the Atomic Safety and Licensing Board, November 17, 1978, in the matter of Diablo Canyon Nuclear Power Plant Operating License Hearings, Operating Basis Earthquake and Seismic Reanalysis of Structures, Systems, and Components, Avila Beach, California.
15. Testimony of R. B. Hubbard and D. G. Bridenbaugh before the Louisiana Public Service Commission, November 19, 1978, Nuclear Plant and Power Generation Costs, Baton Rouge, Louisiana.
16. Testimony of R. B. Hubbard before the California Legislature, Subcommittee on Energy, Los Angeles, April 12, 1979.
17. Testimony of R. B. Hubbard and G. C. Minor before the Federal Trade Commission, on behalf of the Union of Concerned Scientists, Standards and Certification Proposed Rule 16 CFR Part 457, May 18, 1979.
18. ALO-62, Improving the Safety of LWR Power Plants, MHB Technical Associates, prepared for U.S. Department of Energy, Sandia National Laboratories, September, 1979, available from NTIS.
19. Testimony by R. B. Hubbard before the Arizona State Legislature, Special Interim House Committee on Atomic Energy, Overview of Nuclear Safety, Phoenix, AZ, September 20, 1979.
20. "The Role of the Technical Consultant", Practising Law Institute program on "Nuclear Litigation", New York City and Chicago, November, 1979. Available from PLI, New York City.
21. Uncertainty in Nuclear Risk Assessment Methodology, MHB Technical Associates, March, 1980, prepared for and available from Swedish Nuclear Power Inspectorate, Stockholm, Sweden.
22. Italian Reactor Safety Study: Caorso Risk Assessment, MHB Technical Associates, March, 1980, prepared for and available from Friends of the Earth, Rome, Italy.

23. Development of Study Plans: Safety Assessment of Monticello and Prairie Island Nuclear Stations, MHB Technical Associates, August, 1980, prepared for and available from the Minnesota Pollution Control Agency.
24. Affidavit of Richard B. Hubbard and Gregory C. Minor before the Illinois Commerce Commission, In the Matter of an Investigation of the Plant Construction Program of the Commonwealth Edison Company, prepared for the League of Women Voters of Rockford, Illinois, November 12, 1980, ICC Case No. 78-0646.
25. Systems Interaction and Single Failure Criterion, MHB Technical Associates, January, 1981, prepared for and available from the Swedish Nuclear Power Inspectorate, Stockholm, Sweden.
26. Summary of Emergency Response Planning Criteria for Regional and Local Authorities Near Nuclear Electric Generating Stations, MHB Technical Associates, June, 1981, prepared for and available from Friends of the Earth, Rome, Italy.
27. Economic Assessment: Ownership Interest In Palo Verde Nuclear Station, September 11, 1981, prepared for and available from the City of Riverside, California.
28. Systems Interaction and Single Failure Criterion: Phase II report, MHB Technical Associates, December, 1981, prepared for and available from the Swedish Nuclear Power Inspectorate, Stockholm, Sweden.
29. Testimony of Richard Hubbard and Gregory Minor on Emergency Response Planning, Diablo Canyon Operating License hearings before ASLB, January 11, 1982.
30. Statement of Richard Hubbard before the U.S. House Subcommittee on Energy and Environment concerning QA program breakdowns, November 19, 1981.
31. Testimony of Richard Hubbard on Quality Assurance, South Texas Operating License hearing before ASLB, prefiled June, 1981.
32. Presentation of Richard Hubbard for Governor Edmund G. Brown, jr. concerning PG&E's Proposed Seismic Design Reverification Program, Diablo Canyon Nuclear Power Plant, February 1982.
33. Testimony of R. B. Hubbard, G. C. Minor, M. W. Goldsmith, S. J. Harwood on behalf of Suffolk County, before the Atomic Safety and Licensing Board, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station, Unit 1, regarding Contention 7B, Safety Classification and Systems Interaction, April 13, 1982.

34. Testimony of R. B. Hubbard and D. G. Bridenbaugh, in the matter of Jersey Central Power and Light Company For an Increase in Rates for Electrical Service, on behalf of New Jersey Department of the Public Advocate, Division of Rate Counsel, Three Mile Island Units 1 & 2, Cleanup and Modification Programs, May, 1982.
35. Testimony of R. B. Hubbard and G. C. Minor on behalf of Suffolk County, before the Atomic Safety and Licensing Board, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station, Unit 1, regarding Suffolk County Contention 27 and SOC Contention 3, Post-Accident Monitoring, May 25, 1982.
36. Presentation of R. B. Hubbard for Governor Edmund G. Brown, Jr. concerning Diablo Canyon Reverification Program, Diablo Canyon Nuclear Power Plant, September, 1982.
37. Testimony of R. B. Hubbard on behalf of Suffolk County, before the Atomic Safety and Licensing Board, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station, Unit 1, regarding Suffolk County Contentions 12, 13, 14, and 15, Quality Assurance/Quality Control, June 29, 1982.
38. Presentation of Richard B. Hubbard on Behalf of the State of California, Before the NRC Commissioners, Proposed Phase II Diablo Canyon Reverification Program (IDVP), November 10, 1982.
39. Testimony of R. B. Hubbard and Dr. Francisco J. Samaniego on behalf of Suffolk County, Before the Atomic Safety and Licensing Board, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station, Unit 1, regarding Torrey Pines Technology's Inspection of Shoreham Nuclear Power Station, December 21, 1982.
40. Supplemental testimony of G. C. Minor, R. R. Hubbard, and M. W. Goldsmith on behalf of Suffolk County, before the Atomic Safety and Licensing Board, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station, Unit 1, regarding Suffolk County Contention 7B, Safety Classification and Systems Interaction, March 23, 1983.
41. Supplemental Affidavit of R. B. Hubbard before the Atomic Safety and Licensing Appeal Board Concerning Breakdowns in the Diablo Canyon Quality Assurance Program, March 29, 1983.
42. Declaration of R. B. Hubbard before the Atomic Safety and Licensing Appeal Board, Concerning Breakdowns in Construction Quality Assurance at Diablo Canyon, May 6, 1983.

43. Presentation by R. B. Hubbard on behalf of Suffolk County to Cuomo Commission regarding Quality Assurance/Quality Control (QA/QC).
44. Testimony of R. B. Hubbard on Behalf of the State of California, Before the Atomic Safety and Licensing Appeal Board, in the matter of Pacific Gas and Electric Co., Regarding Design Quality Assurance, October, 1983.
45. Testimony of D. G. Bridenbaugh, L. M. Danielson, R. B. Hubbard and G. C. Minor before the State of New York Public Service Commission, PSC Case No. 27563, in the matter of Long Island Lighting Company Proceeding to Investigate the Cost of the Shoreham Nuclear Generating Facility — Phase II, on behalf of County of Suffolk, February 10, 1984.
46. Status Report, WJ Zimmer Plant, Assessment of Options, MHB Technical Associates, prepared for The Ohio Office of the Consumer's Counsel, February 23, 1984.

5CLP-29

ATTACHMENT 3

SR2-R43.010

January 15, 1981

J.H. Taylor

Emergency Diesel Generator 102 Problems Encountered To Date
Shoreham Nuclear Power Station - Unit No. 1
W.O. 44430/48923

The attached report, prepared by T. Brown, J. Higgins and
W. Cook accurately state the problems we have had to date.

An attempt to resolve many of the items was tried on December
18, 1980 when Startup arranged a meeting between ourselves,
S&W and Delaval. Regretfully, Delaval could not attend and no
real progress on problem solutions were made.

Another meeting is scheduled for January 20, 1981 at Shoreham
and hopefully resolution to many problems will be achieved.

Many of the problems encountered by Startup to date have been
the result of the "Skid Mounted Equipment", as with this type,
the Construction organization has very minimal involvement other
than "hooking up" to it. Along these lines, alignment deficiencies
have been identified, storage problems have been corrected etc.,
all of which adds to Startup's scope of work as related to placing
the equipment into service.

A rescheduling effort of the Diesel generators must be conducted
due to the recent Proposed Site policy to primarily support the
Integrated Flush. At the present time, we can not project a
preop start date due to many unresolved problems and no projected
turnover date for Engines 101 and 103.

D. D. Terry
D.D. Terry
Lead Startup Engineer

DDT:bc

cc: T. Brown
J. Higgins
W. Cook
L.W. Lewin
W.M. Matejek
SR2-R43.010

FLAG	0	SYR	1R43
COMP		SYJ	
FILE	010	DOC	

PROBLEM REPORT

R43- EMERGENCY DIESEL GENERATORS

- 1- Procedure that had been JTG approved for subsystem flushes were not adequate. Specifically, the lube oil flush did not provide sufficient flow to clean the system. (this test procedure used B&A pump (40GPM.) which has a normal flow of about 250GPM. Also, the JW system flush procedure uses the J.W. heater circulating pump (50GPM) for a system with a normal flow of 800 GPM. This procedure will be revised to incorporate a temporary flush pump.

- 2- Excessive amounts of time were required to review component lists since (a) initial list missed many items (b) isometrics are continually changing resulting in added and/or deleted sections, and (c) hanger listings change as isos are revised and the designation changes (E&DCR F 29376). Changes in component lists are no longer to be reviewed - only marked noted by test engineer.

- 3- Excessive amounts of time was required to review punchlist items. This was compounded by (a) reorganization of lists by renumbering all items, (b) excessive number of items, (c) failure to perform verification of completion by turnover and (d) non-informative responsibility assignment.

Responsibility is not discussed with the individual resulting frequently in the wrong discipline being assigned, the individual being unaware of his responsibility, and the wrong completion code being assigned. The issuing of the complete list each month instead of a list of changes results in an impossible review task.

- 4- Excessive amounts of time are required for review of preliminaries. New preliminary release packages are submitted for review with little or no change in the punchlists. Meetings are called to discuss package updates with the only change being requests for further concessions on number of items required for turnover. R43A has had six preliminaries and the punchlist is still some 46 pages long.

- 5- ~~Construction status for release was poor--we received~~
a minimum of requested storage history information. Final engine alignment was not performed. There was no record of foundation bolt torquing. Megger readings of generator stator were not up to date. Megger reading of generator field and bearing pillow block were non-existent.

6- Numerous design and construction errors necessitated initiation of E&DCR's (65 to date). This has resulted in an exorbitant amount of time being expended reviewing drawings and documents. Many of the original problem solutions were incorrect which resulted in rewriting the E&DCR, or calling SEO to request the next issue. We have attempted to get the drawings updated to reflect the system as it was designed and to get the drawings that the diesels were built to, but usually we are requested to mark up prints reflecting as built conditions. Problem solutions are at a standstill at present, only one has been answered since the end of October - nineteen are unanswered.

7- Numerous repair-reworks (38) have been written because of many incomplete or defective items. Some of these are a result of E&DCR's, some are a result of poor factory assembly practices, some are a result of a forced turnover with incomplete/deficient components, and some are a result of poor construction practices. A great amount of time was expended in obtaining documentations for rework of factory wiring. This has also been expended on attempts to expedite parts and tools for reworks.

- 8- Extra time has been expended because of numerous technician changes with no overlap. This has resulted in some rework, additional time locating equipment, and additional time locating documents.
- 9- Many hours have been expended attempting to get information for C&IO work (especially the tach-relay, the fuel oil Booster Pump D.C. motor loss of field relay) with incomplete results. Many hours have been expended attempting to set up for testing D.C. Circuit breakers since there is no regulated DC power supply of 30 amp capacity on site.
- 10- ~~Poor storage conditions and work area controls during construction phases~~ had to be compensated by cleaning of the 102 generator by Startup support.
- 11- Poor design of panel cable support and poor housekeeping during construction resulted in a prolonged cleaning effort to achieve error free operation of relays.
- 12- Original schedules did not allow time for rewriting procedures, reperforming C&IO work because of design changes, performing design and construction review.
- 13- Original C&IO schedule by previous test engineer allowed six weeks. A recalculation including all equipment with the same allowed time for devices, indicates that fifteen weeks should be allowed.

- 14- Modification of diesel generators to upgrade design are being incorporated. This was not allowed for this in the assigned schedule.
- 15- Additional time and manpower was required to clean crank cases of diesel since preservative of wrong type was suspected to have been used on engine during storage.
- 16- Additional Test Engineer time was expended clearing construction red tags after system release.
- 17- Failure to be able to control access to the Diesel room because construction activities were in progress slowed Startup activities. Construction work on rewiring MCC, installing scaffolds (for X60 actuators, service water line walk, and conduit resupport), and reworks assigned to construction. Temporary doors were unlocked, knocked down and holes were cut in them.
- 18- Power feed (120VAC) Repair/Rework (R35-6) prevented complete testing of accessories.
- 19- ASME piping was not turned over at original "B" release. There has been confusion in this area concerning who owns which components. We are still unable to use Startup Support to break flanges on these systems - this results in poor control of activities by Startup.

- 20- Lack of personnel continuity has impacted progress - three turnover engineers have been responsible for R43 since May 1980.
- 21- Many hours have been spent listing problems with design, drawings, construction, and documentation. Many hours have been spent attending meetings - the only result thus far has been requests for more paperwork, (lists & copies of specific E&DCR's) and more meetings. We need to have the diesel generators placed on a higher priority if we are to meet a date required to support other plant activities.

SC LP-30

ATTACHMENT 4

Diesel Generator

Many EDCRs have been written for the R43 System, diesel generators, with most of these EDCRs being initiated by LILCO Start-Up.

The diesel generator specification SM1-089 is mainly a performance specification, i.e. design output parameters, with detailed design of the system to be supplied by DeLaval. The specification, however, does require certain specific details such as alarms and shutdown initiation signals. With a performance specification as a basis S&W has relied on the manufacturer's ability to provide a design that accomplishes the desired performance. Construction forces have completed the 102 diesel; however, Start-up is encountering problems a majority of which are details required to check out instruments and subsystems because the installation and maintenance manual furnished by DeLaval doesn't provide enough information on set points and design parameters to check various instrumentation.

There are also cases where additional details on S&W drawings would have helped to eliminate construction and start-up problems.

Start-up is also reviewing things in general with a different perspective, sometimes reviewing the maintainability to a much greater extent than S&W has.

In looking back through some of the EDCRs we see many requests for additional information, sometimes not the appropriate vehicle for requesting the information, but a means by which a documented answer is required.

There are cases where vendors' drawings did not match the equipment thus resulting in inconsistencies between vendor and S&W drawings. Inspection could have uncovered this.

We do not anticipate similar problems with security, except probably with Vicomac.

P.S. We bought the low bidder.

SC LP-31

ATTACHMENT 5

Energy Consultants, Inc.

121 SEVENTH STREET · PITTSBURGH, PA. 15222-3487 · 412/434-5200

JAK-ENG-83-181

July 12, 1983

Mr. E. B. McCabe
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUBJECT: WITNESS AND EVALUATION OF EMERGENCY DIESEL GENERATOR TESTING AT SHOREHAM NUCLEAR POWER STATION FOR NUCLEAR REGULATORY COMMISSION, REGION I STAFF, FINAL REPORT OF NRC CONTRACT NO. 05-82-249 PARAMETER PURCHASE ORDER NG. NRC-IE-82/83, TASK 38

Dear Mr. McCabe:

Enclosed are five (5) copies of the final report of the Evaluation and Witnessing of Emergency Diesel Generator Testing Problems at Shoreham Nuclear Power Station which was performed at Shoreham, New York by Mr. Gaillard Kunkle and the Energy Consultants, Inc. staff in accordance with the reference contract. The final report incorporates the NRC comments on the preliminary report provided to Mr. G. Kunkle at the meeting in Region I on June 29, 1983. The preliminary report was submitted to you previously by JAK-ENG-83-161 dated June 17, 1983.

If you should have any questions or comments, please contact me.

Sincerely,


ENERGY CONSULTANTS, INC.

Richard A. Lofy for
John A. Kaye
Manager
Design and Consulting
Engineering Department

RJA/cw

Enclosures

cc: Jim Higgins - U. S. Nuclear Regulatory Commission
Richard A. Lofy - Parameter Incorporated



DESIGN & CONSULTING ENGINEERING

FINAL REPORT TO
U. S. NUCLEAR REGULATORY COMMISSION
REGION I

FOR
TEST REVIEW, DATA ANALYSIS AND REVIEW OF
EMERGENCY DIESEL GENERATOR OPERATIONAL/RELIABILITY
PROBLEMS AT SHOREHAM NUCLEAR POWER STATION, UNIT I,
SHOREHAM, NEW YORK

NRC CONTRACT NO. 05-82-249
PARAMETER CONTRACT NO. NRC-IE-82/83, TASK 38
FROM APRIL 25, 1983 TO MAY 19, 1983

PRESENTED ON JULY 12, 1983

BY
DESIGN AND CONSULTING ENGINEERING DEPARTMENT
ENERGY CONSULTANTS, INC.
121 SEVENTH STREET
PITTSBURGH, PENNSYLVANIA 15222-3487
(412) 434-5230

PREPARED BY G. L. Kunkle / RJA

REVIEWED BY A. B. Bennett / RJA

R. J. Addison

TABLE OF CONTENTS

<u>Section</u>	<u>Title</u>	<u>Page</u>
I	Introduction	1
	A. Summary.	1
	B. Equipment Identification	3
	C. Background	3
	D. Inspection Objectives.	4
	E. Persons Contacted.	4
II	Testing.	6
III	Corrective/Preventive Maintenance and Maintenance Records.	10
IV	Visual Inspections of Diesel Generators.	14
V	Review of Component Problems/Failures.	15
	A. Engine Head Cracks	15
	B. Turbocharger Failure	16
	C. Engine Block Casting Indications	17
	D. General Review of Problems	18
V	General Recommendations.	22

EVALUATION OF DIESEL ENGINE PROBLEMS AND TESTING AT SHOREHAM, NEW YORK

I. INTRODUCTION

A. Summary:

An in depth assessment of selected operational problems was conducted which included areas such as corrective maintenance, preventive maintenance and component failure. This assessment included detailed reviews of selected problems identified in Long Island Lighting Company (LILCO) Deficiency Reports, Repair/Rework Requests issued by the Start-up Group and failure reports issued by LILCO, Delaval and other vendors. In addition, observation of maintenance activities as well as a physical inspection of each emergency diesel generator unit was conducted during both standby and, when possible, running conditions.

During the review of each item, an attempt was made to determine the following:

- (a) Was the work accomplished in accordance with approved procedures?
- (b) Were properly calibrated tools (if applicable) used during maintenance?
- (c) Were measurements, adjustments, torquing, etc. values within prescribed ranges?
- (d) Were any trends detectable in readings or component failures?
- (e) Were problems/failures caused by design, engine vibration, incomplete or improper workmanship?

A review of selected preoperational diesel testing was also conducted. This review included observations of in-process testing, reviews of test procedures, reviews of completed test procedures and evaluation of completed test data.

During these reviews and evaluations of the diesel generators, a number of problem areas were found to exist and are identified in the following report. In addition to specific problems/comments, which are identified, a number of recommendations and observations are also included which should be considered for corrective actions.

Although some problems are still occurring during operation/testing, the frequency at which they occur seems to be decreasing. Additional testing and corrective action is needed to provide a high level of confidence that the engines will start and operate reliably. Specific comments and recommendations are provided in various sections of this report. Section VI provides the specific recommendations for additional testing. Once these recommendations have been adopted (in conjunction with the recommendations of the LILCO Task Force), and the testing completed with no problems, this should provide the necessary assurance that the emergency diesel can accomplish their design functions.

As identified in the recommendations of NUREG/CR-0660, the training and performance of personnel (including Q/A) involved with maintenance and operation of emergency diesels contributed significantly to the reliability of the various emergency engines. This same area appears to be a problem at Shoreham. The Repair/Rework program including records was felt to need improvement.

Additional review and evaluation is also needed of various test results as identified in Section II. In addition, Section V.B provides recommendations for further investigation as a result of the turbocharger failure.

ENERGY CONSULTANTS, INC.
FOR U. S. NUCLEAR REGULATORY COMMISSION REGION I

Contract No. NRC Contract No. 05-82-249 Parameter Purchase Order
No. NRC-IE-82/83, Task 38

Docket No. 50-322

License No. CPPR-95

Licensee: Long Island Lighting Company
175 East Old Country Road
Hicksville, NY

Facility Name: Shoreham Nuclear Power Station

Inspection Location: Shoreham, New York

Inspection Conducted: April 25, 1983 - May 19, 1983

Inspector: G. L. Kunkle / RJA
Gailard L. Kunkle, Senior Consultant, Energy Consultants, Inc.

B. Equipment Identification:

Manufacturer: Engine - Transamerica Delaval Company
Generator - Portec Electric Products Division

Model: DSR-48

Serial Numbers: 74010, 74011 and 74012

Ratings: 4,889 horsepower
3,500 kilowatts (continuous)
3,900 kilowatts (2 hour rating)
0.8 power factor
4,375 kilovolt amps
4,160 kilovolts
607.2 amperage

C. Background:

The three emergency diesel generators at the Shoreham Nuclear Power Station, Unit I, have experienced repeated problems during preoperational full load and endurance tests. The operational problems have included cylinder head

problems (5 heads replaced), rocker arm assembly hold-down bolt failures, turbocharger bearing failure and linear indications in engine block casting.

D. Inspection Objectives:

Provide an independent review and assessment of emergency diesel generator operability and the ability of the diesels to perform their design function, based on a comparison of design capabilities/performance ratings (as described in the Shoreham Final Safety Analysis Report, design specifications and vendor technical manuals) with actual operational data (as described in licensee preoperational test records). Witness ongoing emergency diesel generator testing, if applicable, and assess test results.

Perform an assessment of past preoperational problems, including material failures, and determine the appropriateness of corrective actions to provide assurance of future diesel operability. Review, as appropriate, licensee records of emergency diesel generator preventive and corrective maintenance actions since January 1, 1981 and the licensee's written analysis of diesel failures and corrective actions. Assess the need for independent NRC, contractor material testing and for additional licensee material testing, as may be required.

E. Persons contacted:

Long Island Lighting Company

E. Youngling

J. Rivello

Stone & Webster Engineering Corporation

R. Purcell

N. Rudikoff

T. Paulantonio

A. Stakutis

R. Lawrance

W. Dick

T. Brown

J. Kamayer

W. Cook

T. Gray

Transamerica Delaval, Inc.

L. McHugh

R. D. Jacobs and Associates

R. Jacobs

U.S. Nuclear Regulatory Commission

J. Higgins

E. McCabe

H. Nicholas

L. Bettenhausen

II. TESTING

Background:

To verify the ability of the diesels to perform their design function, the operational data in the preoperational test records were compared to the design capabilities/performance ratings described in the Shoreham Final Safety Analysis Report, design specifications and vendor technical manuals. Actual testing was witnessed where possible.

Summary:

Portions of testing on diesel engines 102 and 103 were observed over a period of two weeks. This testing was being performed in accordance with preoperational test procedures PT. 307.003 B-1 and PT. 307.005C TCN-1. In addition, the results of a completed test procedure PT. 307.005A were reviewed. (It should be noted that the results of this completed procedure have not been reviewed nor accepted by the LILCO Joint Test Group.) The comments resulting from these reviews are as follows:

Comment #1: The Nuclear Regulatory Commission Regulatory Guide 1.108 (Revision 1, August 1977) Section C.2(3) requires the emergency diesel generators to be tested at a load equivalent to the continuous rating for 22 hours and for 2 hours at the 2 hour rating. The continuous full load rating of each emergency diesel generator set is shown in Table I. Typical values of data recorded in PT. 307.005A for the full load run are shown in the last column of Table I.

	TABLE I	
	<u>Continuous Full Load Rating</u>	<u>Test Load Values</u>
Kilowatts (KW)	3,500	3,510
Volts (V)	4,160	4,225
Amps (A)	607.2	480
Power Factor (PF)	0.8	1.0*
Kilovolt-Amps (KVA)	4,375	3,513*

*Calculated

The low amperage (480 vs. 607.2) and calculated KVA (3,513 vs. 4,375) shows the diesel generator was not tested at its continuous full load rating considering current, power factor and KVA ratings. (Note: the higher voltage of 4,225 would only account for a 10 amp lower reading.)

Typical data for the 2 hour load run also shows the engine was not fully loaded to its 2 hour load rating on a current/power factor basis. Note: During the 2-hour full load run at the 530 amp load, the engine fuel racks were very near their full travel stops. If the amperage load were increased, the fuel racks may have reached full travel before the 110% amperage load was achieved.

Note: The lower than rated current obtained during the test did not simulate normal bus load conditions (actual bus load would probably have a lower power factor). The lower current would not result in the maximum generator I^2R heat loss. The effects that are caused by heating, therefore, were not effectively simulated.

To ensure the emergency diesels are capable of carrying their design emergency loads, additional testing should be conducted at the emergency limits (voltage, amperage & KVA) while operating at a 0.8 power factor.

Comment #2: Step 8.3.7 of PT. 307.005A states load diesel generator to full load then defines full load as 3500 ± 70 KW and 1500 ± 100 KVAR. Table I of the test procedure records KW but does not record KVAR so the data cannot be verified. In addition, Step 8.4.1 performs the 22 hour full load run, however, this step only specifies a load of 3500 ± 70 , - 0 KW and does not address KVAR load.

If step 8.3.7 definition of full load is correct, then the generator may not have been at full load in step 8.4.1 since only about 500 KVAR's were maintained throughout the test. This inconsistency should be investigated and resolved.

Comment #3: In evaluating the recorded data, it was found that the calculated KW (using the recorded voltage and amperage) did not always

meet the acceptance criteria unless a power factor of almost one (1) was assumed. Some examples were observed where the voltage dropped and amperage decreased by about 10% and the recorded KW went up slightly (KVAR would remain constant). These inconsistencies need further evaluation to determine if test requirements were actually met.

Comment #4: On April 27, observed that the official copy of PT. 307.005C in use for diesel testing did not contain TCN #1. (The step in progress had been changed by TCN #1. This TCN had been issued about two weeks earlier.)

Comment #5: The data sheets in test procedure PT. 307.005C were not signed by and therefore did not indicate who the data takers were.

Comment #6: Some instrumentation on the diesels being tested were not marked to indicate their calibration status as required by ANSI N45.2 and N18.7. For example, engine tachometer, cooling water thermometers, turbocharger air pressure, voltage, amperage and lube oil filter inlet and outlet pressure gages.

Comment #7: Some data had been changed/corrected by write overs making it difficult to read.

Comment #8: In test procedure PT. 307.005A&C precaution 4.7 states diesel room temperature and humidity should be frequently monitored. There was no objective evidence that this was being done.

Comment #9: Initial condition 5.5 in procedure PT. 307.005C was signed off (with no exception indicated) indicating the HVAC was in operation. However, the ventilation was not in normal operation as the ventilation damper was temporarily bypassed and failed open.

Comment #10: Step 8.4.1 of PT. 307.005A states "ensure total KVA of generator does not exceed 4375 KVA". Since there is no method provided to measure or requirement to calculate this value, it is not clear how this requirement was met.

Comment #11: The diesel generator load values in Table II of PT. 307.005A are not recorded in the correct units. The table specifies KW while values are actually recorded in MW.

Comment #12: Various steps in PT. 307.005A were designated to be witnessed by Operations Q/A. The following steps have been completed but were not signed by Operations Q/A to indicate they witnessed the steps: 8.3.9, 8.3.11, 8.5.3 and 8.6.1.

Recommendation #1: The readability of some of the test instrumentation does not seem to be accurate enough to meet the test requirements. For example, the minimum subdivision for KW on the recorder was 200 KW while the tolerance band specified in the procedure was +40 and -19 KW. Similar problems existed for amperage and voltage. Test instruments should be accurate enough to be compatible with the tolerance of the acceptance criteria in the procedure, e.g., the readability of most analog instruments is one-half the smallest scale subdivision. The high speed recorder and charts should be analyzed to verify that their accuracy will actually permit reading (interpolating) these charts to one-quarter or one-eighth of the smallest scale subdivision as necessary to assure compliance with the test requirements.

III. CORRECTIVE/PREVENTIVE MAINTENANCE AND MAINTENANCE RECORDS

Background:

Approximately eight percent of the maintenance records (including Repair/Rework Requests, Rework Supervisor Work Summaries and Quality Assurance Verification Reports) were reviewed to determine if the work was accomplished in accordance with all vendor technical requirements. This review also determined if the maintenance and maintenance records properly implemented both local and NRC requirements. In addition, problems were reviewed to determine (where possible) if the "root cause" had actually been identified and corrected.

Summary:

In many cases it was not possible to verify, based on the maintenance records identified below, that the work had been properly conducted in accordance with both technical and administrative requirements. These problems fell into the following categories:

1. Torquing - The Delaval Technical Manual, Volume I, Appendix IV provides a table of torque values to be used for various threaded fasteners. This table also stated that all torque values are based on the use of a thread lubricant consisting of a 50/50 mixture of graphite and engine oil.

Comment A: Some maintenance records indicate incorrect torque values may have been used. For example, Repair/Rework 408 indicates the rocker arm assembly was only torqued to 120 ft lbs instead of the required 365 ft lbs; Repair/Rework 417 indicates the rocker arm assembly and sub cover were torqued to 365 ft lbs, (i.e., overtorqued) although the sub cover is only required to be torqued to 120 ft lbs. The consequences of over or under torquing should be evaluated.

Comment B: A number of maintenance records do not provide any documentation or assurance that threaded fasteners were properly torqued since no torque values are recorded in the space provided (Start-up Instruction No. 6) and since the records do not provide any reference to the use of calibrated torque wrenches (i.e., there were no Measuring and Test Equipment (M&TE) numbers and calibration due dates recorded in the space provided). The following Repair/Rework Packages are typical of this type of problem:

- (1) 751 - no torque value and no M&TE number
- (2) 577 - no torque value and no M&TE number
- (3) 596 - no torque value and no M&TE numbers (similar work on 805 & 808 had required information)
- (4) 554 - states "no torque value, vendor specs"
- (5) 637 - no torque values recorded
- (6) 712 - no M&TE number for torque wrench used on head studs
- (7) 394 - no torque values and no M&TE numbers
- (8) 423 - no torque values and no M&TE numbers

Comment C: A number of maintenance records do not provide any assurance that the required thread lubricant was used during reassembly and torquing. Some records specifically indicate "none" or "NA" in the space provided on the form. Other packages did not include a copy of this completed form to show a lubricant had been used. Start-up Instruction No. 6 provides a place for recording type of thread lubricant. Typical examples are found in the following Repair/Rework Packages:

- (1) 612 and 744 - indicate lubricant was used on head studs, other studs and bolts were not addressed
- (2) 712 - states "none"
- (3) 670 - states "NA"
- (4) There is no reference of any lubricant in packages 596, 360, 359, 511, 636, 637, 714 and 820.

Comment D: In many of the maintenance records, the Quality Assurance verification report is so brief or general it is not possible to determine what was witnessed and verified. Typical examples are found in the following Repair/Rework Packages: 612, 349, 351, 360, 670, 712, 423 and 577.

Comment E: Some maintenance records indicated repairs and/or inspections were performed but the acceptance criteria is not clear. Typical examples can be found in the following Repair/Rework Packages:

- (1) 751 - A jacket water pump was disassembled and the pump impeller was "inspected and found to be satisfactory". It is not clear what this acceptance was based on since no measurements were recorded and instructions do not specify what kind of inspection to perform (i.e., visual, measurement, dye penetrant).
- (2) 546 - During repairs to a jacket water pump, this package states "started lapping and blue checking bore to shaft. Attained 85% contact on blue check." No reference is made to any acceptance criteria for the required percentage of contact.

2. Maintenance Procedures - Several Repair/Rework Packages were found which indicated the repair work had been performed in accordance

with verbal directions from the Delaval service representative. The specific directions or adjustments were not normally recorded making it impossible to verify that the work was completed in accordance with the technical specifications in the Delaval service manual. One example was found where a thrust reading outside the specified tolerance was apparently accepted based on verbal direction of the vendor. Typical examples of these problems are found in the following Repair/Rework Packages:

Comment A: 590 - The work summary in this package "checked total thrust of rotor assembly - 0.007* (okay from Al Scott Delaval representative)". A Delaval letter of December 6, 1982 (attached to LDR-926) states the Elliott specifications call for a thrust of 0.008 to 0.018.

Comment B: 374 - The work summary in this package states "adjusted rocker arms accordingly as per Delaval representative".

Comment C: 546 - The work summary in this package states "installed water pump with new gasket, tighten down bolts to representative approval".

Comment D: 554 - This package documented disassembly a jacket water pump for inspection and replaced the impeller nut. The work summary states "no torque value, vendor specs".

IV. VISUAL INSPECTION OF DIESEL GENERATORS

Background:

Visual inspections of each diesel generator unit was performed. When possible, inspections were also performed while the engines were running. These inspections were performed to determine the general condition of each engine and detect possible abnormal conditions.

Summary:

While no major problems were observed on any of the engines, some conditions were noted which should be corrected to ensure future problems do not occur. Several other conditions were observed which should be evaluated to determine the need for further corrective actions. Comments resulting from these inspections are as follows:

Comment #1: Many instrumentation, control and gage lines (1/4 inch to 3/4 inch size) are inadequately braced and vibrate excessively during operation. Some lines appear to need additional brackets while others have been removed from the brackets provided and were never reinstalled. For example, the lube oil supply line to the turbocharger failed due to vibration while in its design brackets.

Comment #2: A label plate on each diesel specified required torque values. These values do not all agree with the torque values currently in the technical manual.

Comment #3: Some bolts on the air inlet elbows to the head were loose and partially unthreaded apparently due to vibration during operation. Some bolts had washers, some lock washers and others no washers. The application of washers and/or lock washers should be specified.

V. REVIEW OF COMPONENT PROBLEMS/FAILURES

A. Engine Head Cracks

Background:

LILCO Deficiency Reports 1040, 1065, 1056 and 1141, various Repair/Rework Requests and correspondence with Delaval documents the identification of cracks in three cylinder heads. The Delaval Failure Analysis Reports indicate the cracks found in the three cylinder heads occurred as a result of manufacturing defects (hot tears resulting from sand inclusions in the casting and uneven cooling). The small amount of leakage that might occur would be blown out with the exhaust. Since these cracks were self-relieving and non-propagating, Delaval stated they would not affect operability or availability in stand-by service. The Delaval reports also indicate improved casting, manufacturing and testing techniques would preclude cracks in the latest head design.

LILCO letter SNRC-873 indicates that a leak detection procedure recommended by Delaval will be implemented until the permanent corrective action can be accomplished. This permanent corrective action will install cylinder heads of the latest available design.

Summary:

LILCO's corrective action of installing the latest design heads should eliminate this problem once the work is completed. This work is currently scheduled to be completed on a non-controlling basis. The leak detection procedure recommended by Delaval would identify any future cracks should they occur.

Based on a review of the actions being taken by LILCO, additional independent NRC/contractor material testing is not recommended.

Recommendations:

- (a) Since water leakage/build up into a cylinder during long idle periods could have drastic consequences in an emergency start, it is recommended that if an engine does not have the new design heads installed, then it should be barred over with the indicator cocks open on a weekly basis after reactor critical testing has started. This barring procedure, in conjunction with the barring procedures recommended by Transamerica Delaval, should assure the engines will operate satisfactorily with the existing heads.
- (b) Since Delaval has indicated stricter manufacturing controls assures the new heads are a high quality product, consideration should be given to either auditing or monitoring the production of some of these new heads or performing detailed receipt inspection and testing of one or two of these new heads.

B. Turbocharger Failure

Background:

LILCO Deficiency Report #926 documents the failure of a turbocharger thrust bearing. The initial evaluation by Delaval indicated the failure occurred due to a missing guide vane on the nozzle ring. A subsequent report from the turbocharger manufacturer (United Technologies Elliott) concluded the missing blade (vane) had failed in service apparently due to mechanical fatigue. In addition, Elliott indicated that additional analysis was being conducted on the nozzle ring and that pressure and temperature readings just upstream of the turbine inlet casing during a rapid start-up cycle would be helpful.

Summary:

Based on the type of failure (mechanical fatigue), it is recommended that this not be considered an isolated occurrence until it has been determined exactly what conditions caused the fatigue failure.

Recommendation:

Consideration should be given to:

- (a) Checking the other turbochargers for possible cracking
- (b) Evaluating the possibility of the missing blade having been knocked back into the exhaust manifold as postulated by Elliott.

C. Engine Block Casting Indications

Background:

LILCO Deficiency Report #1224 and Repair/Rework Request numbers 867, 868, 369, 870, 871 and 880 provide the details of Stone & Webster Engineering Corporation's (S&W's) investigation and engineering evaluation of linear indications which were found in the cam galley area of the engine block casting. The investigation required the indications on each engine to be checked and mapped using non-destructive examination. A similar design engine with a substantial number of operating hours was checked by S&W engineers using nondestructive examination. Indications were found of the same approximate size with no evidence of any propagation. S&W engineers found similar indication on a new engine block casting at the factory. This shows the indications occur during manufacture and are not a result of operations. Calculations by Delaval showed the regions where the indications are located are subject to compressive stresses which would not cause the indications to propagate. Discussions with S&W lead engineers indicated Delaval is conducting tests on an operating engine in order to verify their calculations and will issue a report when this testing is completed. Based on their evaluation of these indications, S&W has concluded that this indication will present no problems to the operation and reliability of the emergency diesel generators.

Summary:

After a review of the actions taken by S&W and Delaval and discussions with the S&W engineers, who conducted the evaluation, it is felt that their actions were adequate and the conclusions correct. However the test results should be reviewed to ensure they verify the calculations.

D. General Review of Problems

Background:

During the detailed review of various Deficiency Reports, Failure Reports and Repair/Rework Requests, a significant number of problems or errors have been identified which seem to have occurred due to errors and incomplete or improperly completed work by the manufacturer. Attachment I to this section provides examples of specific problems that fall into this category.

Summary:

A large number and variety of problems that have been experienced can be attributed to vendor workmanship. These errors, in conjunction with the problems identified during audits of Delaval's Quality Assurance Program (audits/reaudits conducted October 1975, February 1976 and June 1976), indicate a weakly implemented Quality Control Program.

Recommendation:

Although the number of problems is decreasing significantly, they have not been completely eliminated and, therefore, reliability has not been demonstrated. Based on this, strong consideration should be given to continued operation or testing until problems have been eliminated and the engines run reliably. Once the required testing has been completed and all problems corrected, at least one engine should be started and run for the design seven days at a nominal load of 3,500 KW.

The actions taken by Delaval to eliminate these quality-related problems should also be determined and evaluated. This would ensure problems with future spare parts will not occur.

To provide the confidence factor that the emergency diesel engines will operate reliably, the periodic surveillance testing should be increased to perform a four hour load test each month. If at the end of six months no failures have occurred, return to the surveillance testing specified in the technical specifications.

GENERAL REVIEW OF PROBLEMS

394 - A memo in this package from a Delaval representative indicates the casing discharge on a jacket water pump was found partially blocked by excess casting material.

442 - E&DCR-F41289 - attached to this package indicates Delaval supplied a jacket water pump with the wrong impeller.

551 - (See LDR-0832) - A memo attached to this package indicates a jacket water pump had been assembled with an extra washer behind the impeller castle nut and that the impeller had been machined to the wrong drawing which had been provided by Delaval. A second pump failed and investigation showed the impeller had been improperly installed at the factory.

577 - A Delaval Failure Analysis Report (attached to E&DCR-F43525) indicates the jacket water pump shaft failure was induced by an improperly tightened impeller hub nut. (There were no records to indicate this pump had been disassembled since it left the factory.)

LDR-816 - This deficiency report indicates incorrect springs were installed on the internal relief valves of the engine driven fuel oil pumps.

359 and 360 - (See LDR-654) - During a pre-start inspection of the gear cases, it was found that two of the engines were missing some fitted bolts required on the cam gear. Delaval drawings require drilling holes and installing and torquing these bolts after final engine timing.

701 & 702 - (See LDRs 1006 and 1024) - During inspection of the Governor Drive assembly, the following problems were found:

- (a) Coupling grid was broken due to misalignment of the governor
- (b) A key of the wrong size was found installed on one engine

VI. GENERAL RECOMMENDATIONS

Background:

During the review of the Diesel Generator operations, testing and maintenance, a number of conditions were observed which did not specifically violate or deviate from requirements but which did, in the opinion of the inspector, indicate weakness or areas which could be improved. Other conditions in this category are those for which insufficient information was available to make a judgement and should be considered for further evaluation.

Summary:

The following list of observations and recommendations should be considered for further evaluation and/or possible corrective action:

Recommendation #1: Repair/Rework Requests do not reference specific repair procedures. They normally only reference the Diesel Construction specification SHI-089. This makes it difficult or impossible for either Q/A inspectors or other reviewer/auditors to determine what instructions were actually to be followed. A system that requires identifying the specific repair procedures would be a major improvement. This would allow Q/A personnel to review the specific procedure and establish hold/witness points as necessary. This could be similar to the procedure for Maintenance Work Requests.

Recommendation #2: Based on the problems identified in the 1975 audit of Delaval of the failure to have calibrated torque wrenches plus the lack of adequate documentation in maintenance records for torque value makes it impossible to ensure all components have been properly torqued. Based on the work completed to date, it is recommended that all components/parts should have their torque values verified by analysis or tests.

Recommendation #3: As stated in other sections of this report, some problems or failures are still being experienced when an engine is run for testing. Some problems result in the engine being shutdown for

ATTACHMENT 1 (CONT'D)

(c) A coupling half was found pinned to the coupling adapter although this pin was not shown on the Delaval Drawing.

712, 744, 408, 636, 661, 663, 670, 714, 715 and 717 - (See LDRs 1040, 1065, 1056 and 1141) - Part of the problems with the cracked cylinder heads was attributed to manufacturing defects and thin castings. The factory inspections and testing had failed to identify these deficiencies.

046 - (See LDR-0503) - Lube oil cooler tubes leaked due to improper rolling of tubes into the tube sheet which were not identified by vendor quality control.

236 - (See LDR-0560) - The lube oil pump suction line on one engine was found without a drilled passageway for the relief valve. This problem was attributed to an oversight at the factory.

331 - During a routine gear inspection, an extra loose bolt was found in the gear train. The bolt was badly beaten and chipped.

convenience to correct the problem. Other problems such as lube oil line failure and jacket water temperature pneumatic switch failure resulted in immediate engine shutdown. Testing/operation should continue until the engines all operate reliably. After all work and testing is completed, it is recommended that at least one emergency diesel generator should be started and run for seven days at about 3,500 KW. If a failure occurs, testing should continue until all three engines have demonstrated their ability to operate reliably under load for the seven-day period.

Recommendation #4: Obtain the results of audits performed on Delaval by other utilities and evaluate their findings and corrective actions (i.e., Texas Utilities, Gulf States Utilities and San Diego Gas & Electric). Based on this information, determine the need for further additional audits of Delaval.

Recommendation #5: The engine exhaust inlet and outlet elbow from the turbocharger are uninsulated and could present a fire hazard from a fuel oil or lube oil line failure. The need for insulating this area should be reconsidered or some other assurance provided that shows such a fire could not occur.

Recommendation #6: There is a substantial opening (about four (4) inches wide and several feet long) between the flywheel and the protective cage around the generator. Since this opening is on the top of the generator adjacent to the baring device, it presents a possibility of items falling into the generator causing damage or short circuits. Consideration should be given to install a protective cover over this opening.

Recommendation #7: In several of the problems/failures which Long Island Lighting Company has experienced, Delaval already had an improved/upgraded replacement part which effectively eliminated the problem. S&W and LILCO should make a strong effort to have Delaval supply them with a list of modifications, design changes, product upgrade, etc. which have been made to this type of engine since the LILCO engines were manufactured. LILCO and S&W could then review this list and decide which of the modifications they want to implement.

Recommendation #8: During operation, a significant number of fuel oil and lube oil leaks are apparent. These leaks keep one individual busy cleaning up. During an emergency, personnel may not be available to keep these leaks cleaned up. This could result in substantial accumulations presenting a fire hazard. Action should be taken to eliminate as much of this leakage as practical.

Observation #1: Some of the LILCO Maintenance Support Division personnel have completed a diesel maintenance training program a few months ago. There was insufficient time available to determine the diesel experience or training for maintenance personnel from the construction groups who have also performed repair work on the diesels.

Observation #2: As noted in other portions of this report, there are examples that vendor field representatives operate somewhat informally at times in directing repairs. While he is assigned in the field, the Delaval representative is not clearly under the umbrella of the Delaval factory quality assurance plan. The utility (LILCO) personnel tend to accept his comments/actions since he is the "vendor expert". When a Delaval representative is performing or directing work at the site, his actions should comply with the LILCO Q/A Program just the same as any other plant worker.

Observation #3: The jacket water pumps do not have unique serial numbers making it very difficult or impossible to maintain traceability especially during multiple pump changeouts or maintenance.

Observation #4: The FSAR response to NRC question (request) 223.85 states, "As shown on Figure 9.5.7-1, a check valve prevents lubricating oil from being circulated through the turbocharger" when shutdown. However, a subsequent modification (E&DCR F-34540) has now added a small lube oil supply to the turbocharger in the shutdown condition. This response and figure should be reviewed and revised as necessary.

Observation #5: In general, it was felt that the quality assurance, engineering and testing administrative procedures that applied to

start-up activities were weakly implemented. A specific concern is the fact that most of the problems identified in this report have existed for over a year and were not identified and corrected by supervisory reviews or the audit program.

SC LP-32

ATTACHMENT 6



LONG ISLAND LIGHTING COMPANY

EXECUTIVE OFFICES: 250 OLD COUNTRY ROAD • MINEOLA, NEW YORK 11501

(516) 228-2244

EDWARD M. BARRETT
GENERAL COUNSEL

December 2, 1983

*file 2
74010*

Robert E. Smith, Esq.
Guggenheimer & Untermyer
80 Pine Street
New York, New York 10005

*Robt. Smith will
sign*

Dear Mr. Smith:

This letter is sent to you in your capacity as counsel to Transamerica Delaval Incorporated (Delaval).

As you know, on August 12, 1983, the crankshaft in emergency diesel generator 102 at our Shoreham Nuclear Power Station failed in the course of performance tests of the engine. LILCO retained Failure Analysis Associates (FaAA) to conduct a thorough investigation of this failure. In the course of this investigation, cracks were found in the crankshafts of diesel generators 101 and 103 as well.

FaAA's final report on the cause or causes of the crankshaft failure demonstrates that the crankshaft failure occurred as a result of inadequate or defective design. FaAA also investigated cracked connecting rod bearings and cracked pistons discovered on the engines. FaAA's interim report on the cracked bearings indicates those failures occurred as a result of a combination of causes, including inadequate or defective design and manufacture. FaAA's investigation of the cracked pistons and other matters observed in the inspection of the engines is continuing, but preliminary indications are that these, too, occurred as a result of defective or inadequate design.


Prior to the crankshaft failure, LILCO had experienced a number of occurrences attributable to defectively designed or fabricated diesel generator components, including three leaking cylinder heads, defective jacket water pumps, leaking fuel oil injection lines, inadequate turbocharger thrust bearing lubrication, inadequate piston skirt to piston crown attachment, broken rocker arm shaft bolts and cracked sub-cover assemblies. While these occurrences were generally of the type experienced in the shakedown of large diesel engines, they appear, nonetheless, to be attributable to defective design or fabrication.

December 2, 1983

Based on LILCO's currently available information, LILCO believes the defects in the diesel generator sets provided us by Delaval constitute a breach of the contract between LILCO and Delaval for the purchase and sale of those diesel generator sets, including but not limited to a breach of warranties contained in and arising out of that contract. This letter is solely for the purpose of providing notice of the breach. Nothing contained herein should be construed as a release of any other claims that LILCO may have against Delaval or as a waiver of any rights and remedies LILCO may have in this matter.

Although LILCO is now giving Delaval notice of claims, we believe it is in LILCO's and Delaval's best interests to pursue aggressively the prompt repair and licensing of the Shoreham diesel generators. We believe substantial progress has been made toward this goal and hope that Delaval and LILCO can work together in the future to complete this important project.

Sincerely,



Edward M. Barrett

EMB:lbs

ATTACHMENT 7



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20585

October 21, 1983

Docket No. 80-416

MEMORANDUM FOR: Chairman Palladino
Commissioner Gilinsky
Commissioner Roberts
Commissioner Asselstine
Commissioner Bernthal

FROM: Darrell G. Eisenhut, Director
Division of Licensing

SUBJECT: NEW INFORMATION CONCERNING TRANSAMERICA DELAVAL (TDI) EMERGENCY
DIESEL GENERATORS, BOARD NOTIFICATION 83-160

In accordance with NRC procedures for board notifications, the following information is being provided directly to the Commission. The appropriate boards and parties are being provided with a copy of this memorandum. The information is applicable to Grand Gulf (an uncontested case), which will be before the Commission for full power authorization in November, 1983.

On August 12, 1983, during post-modification testing, the main crankshaft on one of the three emergency diesel generators (EDG) at the Shoreham Nuclear Power Station failed and broke into two pieces. The applicant subsequently inspected the remaining two diesel generators at Shoreham and identified additional flaws in the crankshafts of those machines in locations similar to the failure of the first machine. A more detailed description of the failure is contained in Enclosure 1 (IE Information Notice No. 83-58).

The EDGs at Shoreham were manufactured by Transamerica DeLaval Incorporated (TDI). TDI has also provided EDGs to several other nuclear power plants (see Enclosure 1). The only currently operating reactor with TDI diesels is Grand Gulf. The TDI diesel at San Onofre is used by Unit 1, which is shutdown for seismic modifications, and the diesels at Rancho Seco are not yet installed.


Besides the failure of the crankshaft at Shoreham, the staff has noted the occurrence of many minor problems with TDI EDGs, which are summarized in Enclosure 2. The staff would expect minor problems to occur during the startup testing of any large piece of machinery, such as a diesel generator, but the number of minor problems experienced by the TDI machines in nuclear service appears to be abnormally high (also See Enclosure 4).

8308710050

Additionally, during vendor inspections of TDI which were performed recently by Region IV, in response to allegations, the staff identified conditions which imply that portions of the TDI Quality Assurance (QA) Program have not been carried out in accordance with the provisions of 10 CFR 50, Appendix B. Region IV has referred the QA problems to the Office of Investigations, which has requested that details not be revealed to avoid compromising the investigation. As a result of an inspection performed in July 1983, the staff identified a potential violation and several potential nonconformances which are described in IE Inspection Report No. 99900334/83-01, dated October 3, 1983 (Enclosure 5).

The Shoreham applicant is investigating the crankshaft failure, but does not expect to publish a report until later in October. The staff has asked the applicant to address a series of questions concerning the Shoreham EDG design, fabrication, operation, and maintenance in its failure report (see Enclosure 3). A similar list of questions is being developed for other applicants.

The identification of QA problems at TDI, taken together with the number of operational problems and the Shoreham crankshaft failure, has reduced the staff's level of confidence in the reliability of all TDI diesel generators. The staff will require, on a case by case basis, a demonstration that these concerns are not applicable to specific diesel generators because of subsequent inspections or testing performed specifically to address the above matters. Further developments and additional information on this subject will be reported to the appropriate Boards.


Darrell G. Eisenhut, Director
Division of Licensing

Enclosures:

- (1) IE Information Notice 83-58
- (2) Summary of DeLaval DG Problems
(12/80-8/83)
- (3) Summary of September 2, 1983
EDG Meeting on Shoreham
- (4) IE Information Notice 83-51
- (5) IE Inspection Report No. 99900334/83-01
With October 3, 1983 Transmittal Letter
to TransAmerica DeLaval, Inc.

cc: See next page

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

August 30, 1983

RE INFORMATION NOTICE NO. 83-58: TRANSAMERICA DELAVAL DIESEL GENERATOR
CRANKSHAFT FAILUREAddressees:

All nuclear power facilities holding an operating license (OL) or a construction permit (CP).

Purpose:

This information notice is provided to bring to the attention of licensees and construction permit holders a recent event at the Shoreham Nuclear Station in which a diesel generator crankshaft failed during post-modification full load testing. The Nuclear Regulatory Commission staff is reviewing the problem and its effects. If the evaluation so indicates, the NRC may request explicit licensee or CP holder action. In the interim, we expect the addressees of this information notice to review the information herein for applicability to their facilities. No specific action or response is required at this time.

Description of Circumstances:

After installation of eight new cylinder heads, emergency diesel generator (EDG) No. 102 failed during post-modification testing when its crankshaft assembly fractured at the crankpin and crankarm (web) on the generator side of the Cylinder No. 7 crank. This failure occurred during the last 15 minutes of testing at the two-hour overload rating. EDG-102 had a total of 12 hours and 25 minutes of two-hour overload testing when failure occurred. Its installed crankshaft assembly has a crankshaft diameter of 13" and a crankpin diameter of 12". Replacement crankshaft assemblies with 12" diameter crankpins are being procured.

Subsequent to this failure of EDG-102, the licensee examined the crankshafts of the two other diesel generator units at the Shoreham site, EDG-101 and EDG-103, by opening the crankshaft area. The examination of the EDG-101 crankshaft assembly showed cracking on the Cylinder No. 7 crankweb (generator side) and dye penetrant indications on the cranks at Cylinder Nos. 3 and 5. Examination of the EDG-103 crankshaft assembly identified a crack about 2" long and 3/8" deep on the Cylinder No. 6 crankweb (governor side) and a connecting rod to crankpin bearing failure on Cylinder No. 5. The bearing failure involved breaking off of approximately a 1" x 3" piece and overheating of

the surrounding area for about 2". Most of the other cracks found are similar in location and orientation to the one which resulted in EDG-102 crankshaft assembly fracture.

Transamerica Delaval reported that the following nuclear sites have Transamerica Delaval diesel generators:

Shoreham	Perry -	Midland
Grand Gulf	Bellefonte	Kartsville
Catawba	WPPS	Phipps Bend
San Onofre	Comanche Peak	River Bend
Vogtle	Rancho Seco	Shearon Harris
Clinch River		

The preliminary information from the manufacturer is that the diesels at Shoreham, River Bend and Rancho Seco* are eight cylinder in-line engines. However, the crankpin diameter is 11" in the Shoreham units and 12" in the units at the other two sites. The diesel engines at the remainder of the sites listed above are of a "V" design and have 12, 16, or 20 cylinders. The shaft material for all the engines is the same, with the possible exception of the 20 cylinder engines. All the engines are designed to have approximately the same brake mean effective pressure. The torsional systems of the engines differ. At this time it is not clear to what extent other diesel generators manufactured by Transamerica Delaval are vulnerable to the same or similar failures as these experienced by the Shoreham engines.

If you have any questions regarding this matter, please contact the Regional Administrator of the appropriate NRC Regional Office, or this office.

Edward L. Jordan, Director
Division of Emergency Preparedness
and Engineering Response
Office of Inspection and Enforcement

Technical Contact: W. Laudan, IE
(301) 492-9759

Attachment:
List of Recently Issued IE Information Notices

*The Rancho Seco units are not installed; they will be used to replace the existing diesel generators.

cc: SECY
OPE
OGC
EDO

ASLB FOR:

Shorenham 50-322 (Brenner, Ferguson, Morris, Laurenson, Kline, Shon)
Perry 50-440/441 (Bloch, Bright, Kline)
Comanche Peak 50-445/446 (Bloch, Jordan, McCollan)
Midland 50-329/330 (Bechhoefer, Cowan, Harbour)
Catawba 50-413/414 (Kelley, Callihan, Foster)
Clinch River 50-537 (Miller, Hand, Linenberger)

ASLAB FOR:

Shorenham 50-322 (Rosenthal, Edles, Wilber)
Clinch River 50-537 (Edles, Johnson, Wilber)

ENCLOSURE 2

OVERALL SUMMARYEMERGENCY DIESEL GENERATORS MP&S - TRANSCONTINENTAL TELEPHONESELECTED PROBLEMS IN LAST 3 YEARS

02/12/83	<ul style="list-style-type: none"> • Crankshaft failure • Cause unknown, as yet • Shoreham ED-102 	<ul style="list-style-type: none"> • Being investigated
03/30/83	<ul style="list-style-type: none"> • holddown capscrews, rocker arm assy. • Shoreham EDG-103 	<ul style="list-style-type: none"> • replaced with new design • TDI says isolated failure
03/08/83	<ul style="list-style-type: none"> • cracked cylinder heads • water in cylinders • Shoreham EDG-101,-102,-103 	<ul style="list-style-type: none"> • replaced with new TDI design • TDI says no affect on operability
03/03/83	<ul style="list-style-type: none"> • hi-press fuel line • manufacturing defects • Shoreham EDG-102,-103 • Also failed at Grand Gulf on 8/2/83 	<ul style="list-style-type: none"> • replaced with new design fuel line w/steel shroud
12/13/82	<ul style="list-style-type: none"> • unqualified control cables • failed IEEE flame test 	<ul style="list-style-type: none"> • reported by Grand Gulf only
09/17/82	<ul style="list-style-type: none"> • jacket water pump shaft failures • fatigue cracking at shaft keyway • Shoreham EDG-102 (50 hours), -103 (170 hours) 	<ul style="list-style-type: none"> • new design after foreign failure • new design failed • 3rd design includes: new impeller mat'l., removing shaft key, size of hub washer, new assembly instructions
07/22/82	<ul style="list-style-type: none"> • hi water jacket temp. trip • closed cooling outlet valve • incorrect valve pos. indication • Grand Gulf Div. 2 	<ul style="list-style-type: none"> • design deficiency
06/23/82	<ul style="list-style-type: none"> • governor flex. drive coupling • misapplication of materials • isoprene intended for atmospheric application • being used at hi-temp. oil environment inside gear case • Grand Gulf 	<ul style="list-style-type: none"> • replaced w/neoprene

- 08/18/81
 - cast screws, starting air valve assy.
 - too long, bottom out
 - Grand Gulf
 - new design - shorter

- 08/19/81
 - loss of starting air (5 minutes)
 - sensing line not seismically qualified
 - TDI recommends reconfiguring orifice to slow bleed down time to 50 minutes and operator action to isolate line

- 08/18/82
 - sheared bolts, rear crankshaft cover
 - Grand Gulf, 24-hr. test run
 - TDI said vibration due to firing of rear cylinder
 - Incessant tests showed no inordinate vibration
 - switched to higher strength (50,000 psi) carbon steel bolts
 - failure of 50,000 psi bolts now expected
 - MP&L now using 150,000 psi alloy steel bolts, with proper heat treatment records

- 12/09/81
 - governor lube oil cooler assy.
 - air trapped in lines
 - improper mounting location
 - TDI recommends lower mounting location

- 11/06/81
 - piston crown separated from skirt
 - failure of attachment stud bolts
 - improperly mfgd. spherical washers
 - TDI design changed to Belleville washers (Service Info. Memo No. 324)
 - cylinder liner grooving
 - TDI says debris during assembly or initial startup
 - grooving of crankshaft bearing
 - crank pin discolored
 - TDI says "transient mat'l." in lube oil
 - cylinder link rod wrist pin grooved and pitted; wrist pin discolored
 - TDI says blockage of lube oil, foreign matter in lube oil
 - Grand Gulf

- 07/14/83
 - fire-lube oil spray
 - cracked instr. line
 - vibration
 - SONGS-1

03/23/81

- use of non-qualified motors
- aux. lube oil pump, aux. jacket water pump
- TDI supplied commercial grade motors with "equivalency" vs. Class 1E motors
- Equivalency data retracted
- motors at Grand Gulf being replaced by A-E

12/15/80

- Turbocharger lube oil sys.
- lube drains out of thrust bearings during standby operation
- causes excessive wear
- SONES-1
- design modification to permit pre-lube for test starts
- occasional "fast starts" acceptable



ENCLOSURE 3

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

SEP 21 1983

Docket No.: 50-322

APPLICANT: Long Island Lighting Company
FACILITY: Shoreham Nuclear Power Station
SUBJECT: SUMMARY OF SEPTEMBER 2, 1983 EMERGENCY DIESEL GENERATOR MEETING

On September 2, 1983, a team composed of NRC staff members from the Office of Nuclear Reactor Regulation and from the Region I office, and NRC contractors, met with representatives of the Long Island Lighting Company (LILCO) to discuss LILCO's plans to investigate the cause of the failure of the #102 Emergency Diesel Generator at Shoreham. A list of attendees is enclosed (Enclosure 1).

On August 12, 1983, during a load test, the main crankshaft of the #102 EDG failed. Subsequent inspection of the #101 and #103 EDG crankshafts revealed cracks in locations similar to that of the break in the #102 crankshaft.


An investigation of the cause of causes of the failure is underway and will be conducted in accordance with a master plan (Enclosure 2) which generally describes the steps to be taken. LILCO intends to use the resources of appropriate LILCO organizations, Transamerica Delaval (TDI), Stone & Webster Engineering Corporation, and appropriate contractors to carry out the steps outlined in the master plan. Failure Analysis Associates (FAA) will conduct the investigation to determine the cause of the crankshaft failure and the cracks.

Mr. Youngling described the various phases of the program, which include an independent review of the crankshaft torsional design by FAA, an overall design review of the entire EDG, and a review of other crankshaft failures. He reported that FAA's torsional analysis results, to date, agreed very closely with both the TDI torsional analysis and with the values measured by TDI in a torsional test run on the #101 EDG at the TDI factory. LILCO has decided to use the #101 EDG as a test-bed to gather additional torsional test information and was in the process of instrumenting the machine at the time of this meeting. The test data will be used to verify analytical models and to try to correlate the observed problems with the effects of previous EDG qualification testing.

Members of the NRC staff discussed some of the philosophy behind the EDG test requirements contained in the Regulatory Guides, and explained the need to understand the potential generic implications of these failures. The staff is concerned that the failures may indicate a deficiency in the TDI design process which may show up in other TDI diesel generators in other nuclear power plants. The staff then presented LILCO with a list of questions and concerns which must be addressed before the staff can have confidence in the ability of the diesel generators (Enclosure 3). LILCO was requested to respond to these items as quickly as possible, as the necessary information becomes available, and Mr. Youngling and Mr. Museler assured that that could be done.

Mr. Museler reported that TDI had committed to provide LILCO with all the support necessary to solve this problem. He also explained that FAA would be the team leader and that it had been instructed to consider all possible failure mechanisms and root causes, and not arbitrarily dismiss unlikely causes.

Mr. Dynner and Mr. Christensen, representing Suffolk County, asked several questions concerning the design of the machine which LILCO promised to answer, and were assured that they would be promptly notified of the results of the inspections. The staff concluded that LILCO's plan appeared to be basically sound and proceeding in the right direction.



Ralph Caruso, Project Manager
Licensing Branch No. 2
Division of Licensing

Enclosures:
As stated

cc: See next page

Shoreham

Mr. A. S. Pollock
Vice President - Nuclear
Long Island Lighting Company
175 East Old Country Road
Hicksville, New York 11801

cc. Howard L. Blau, Esquire
Blau and Cohn, PC.
217 Newbridge Road
Hicksville, New York 11801

Mr. Jay Dunkleber, Jr.
New York State Energy Office
Agency Building 2
Empire State Plaza
Albany, New York 12223

Energy Research Group, Inc.
400-1 Totten Pond Road
Waltham, Massachusetts 02154

Mr. Jeff Smith
Shoreham Nuclear Power Station
Post Office Box 618
Wading River, New York 11792

W. Taylor Reveley, III, Esquire
Hunton & Williams
Post Office Box 1535
Richmond, Virginia 23212

Ralph Shapiro, Esquire
Cammer & Shapiro
9 East 40th Street
New York, New York 10016

Mr. Brian McCaffrey
Long Island Lighting Company
175 E. Old Country Road
Hicksville, New York 11801

Honorable Peter Cohan
Suffolk County Executive
County Executive/Legislative Bldg.
Veteran's Memorial Highway
Hauppauge, New York 11788

David Gilmartin, Esquire
Suffolk County Attorney
County Executive/Legislative Bldg.
Veteran's Memorial Highway
Hauppauge, New York 11788

MHB Technical Associates
1723 Hamilton Avenue, Suite K
San Jose, California 95125

Stephen Latham, Esquire
Twomey, Latham & Shea
Post Office Box 398
33 West Second Street
Riverhead, New York 11901

Jonathan D. Feinberg, Esquire
New York State
Dept. of Public Service
Three Empire State Plaza
Albany, New York 12223

Ezra I. Bialik, Esquire
Assistant Attorney General
Environmental Protection Bureau
New York State Department of Law
2 World Trade Center
New York, New York 10047

Resident Inspector
Shoreham NPS, U.S. NRC
Post Office Box B
Rocky Point, New York 11778

Herbert H. Brown, Esquire
Kirkpatrick, Lockhart, Hill,
Christopher & Phillips
1900 M Street, N.W.
Washington, D.C. 20036

Lawrence Coe Lanpher, Esquire
Kirkpatrick, Lockhart, Hill,
Christopher & Phillips
1900 M Street, N.W.
Washington, D.C. 20036

Karla J. Letsche, Esquire
Kirkpatrick, Lockhart, Hill,
Christopher & Phillips
1900 M Street, N.W.
Washington, D.C. 20036

Shoreham

- 2 -

James B. Dougherty, Esq.
3045 Porter Street
Washington, D. C. -20008

Mr. James Rivello
Plant Manager
Shoreham Nuclear Power Station
P. O. Box 628
Wading River, New York 11792

Lawrence Brenner, Esq.
Administrative Judge
Atomic Safety & Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. George A. Ferguson
School of Engineering
Howard University
2300 - 6th Street, NW
Washington, D. C. 20059

Dr. Peter A. Morris
Administrative Judge
Atomic Safety & Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTENDANCE LIST

September 2, 1983

NRC

T. Caruso
Robert J. Giardina
Charles Petrone
J. C. Higgins
J. T. Beard
D. J. Vito

WILCO

Ivan Ostrowski
E. J. Youngling
W. J. Museler
Kenneth Simes

Franklin Research Center

R. Clyde Herrick
Harry W. Raines
Shalid Ahmed

Newsday

Stuart Diamond

KLHCP - Counsel for Suffolk County

Alan Roy Dynner
Stanley Christensen

Hunton & Williams

Anthony F. Earley

Shearman Nuclear Power Station
Emergency Diesel Generator 102
Crankshaft Failure Analysis/Recovery
Master Plan

Approvals:

William M. Judge
Project Engineer *FOR APPROVAL*

William Rice
Operational Quality Assurance Engineer

[Signature]
Startup Manager

[Signature]
Chairman Joint Test Group

[Signature]
Plant Manager

[Signature]
Vice President Nuclear

Dated: August 11, 1981

I. PURPOSE:

The purpose of this plan is to provide a systematic and organized approach to the investigation and analysis of the cause of the failure of the Emergency Diesel Generator 102. The plan is designed to ensure that the investigation is thorough and that the results are documented and disseminated to the appropriate personnel. The plan is intended to be used as a guide for the investigation and analysis of the failure of the Emergency Diesel Generator 102. The plan is intended to be used as a guide for the investigation and analysis of the failure of the Emergency Diesel Generator 102. The plan is intended to be used as a guide for the investigation and analysis of the failure of the Emergency Diesel Generator 102.

It is the intent of this plan to ensure that the investigation is thorough and that the results are documented and disseminated to the appropriate personnel. The plan is intended to be used as a guide for the investigation and analysis of the failure of the Emergency Diesel Generator 102. The plan is intended to be used as a guide for the investigation and analysis of the failure of the Emergency Diesel Generator 102.

This Emergency plan has been put in place by the organization. The plan has been reviewed by representatives of the Nuclear Power Plant, the Engineering Department, the Operations Department, the Maintenance Department, the Quality Assurance Department and the Vice President of Nuclear. In addition, this plan has been developed with the assistance of Management Delay, Inc. of Oakland, California and Failure Analysis Associates of Palo Alto, California.

II. ORGANIZATION:

As a result of the failure of the Emergency Diesel Generator 102, an organization has been put in place consisting of the necessary expertise to assess the cause or causes of the generator failure; to recover from that failure and perform suitable testing following recovery and to determine the implications of this failure on diesel generators 101 and 103. The essential areas of expertise are shown in Attachment No. 1 Organizational Structure Diagram and consist of the following:

- a. Supervisory Personnel
- b. Technical Personnel
- c. Management Personnel
- d. Vendor Representatives (TDI)

The following information will describe the...
...with the...
...the...
...the...

C. ILCO Project Engineering

ILCO Project Engineering (IPE) consists of the State & Western Site Engineering Office (SSEO) will provide engineering support and is responsible for the failure analysis. To accomplish these tasks IPE will use its own resources supplemented by State & Western Engineering Corporation, IPE, Failure Analysis Associates and other consultants as required. Failure Analysis Associates has been engaged to take whatever steps are necessary to determine the cause or causes of the failure.

D. Quality Assurance

Operational Quality Assurance will provide the required Quality Assurance coverage in accordance with the ILCO Quality Assurance Program. IPE QA representatives will be present during the period of engine disassembly and reassembly by the IPE work force. The ILCO Quality Assurance Department will provide support to the OCA organization for quality assurance matters.

E. Shift Complement

During this investigation and the subsequent recovery the on shift complement will consist of the following:

- Senior Test Engineer
- Engineering Representative
- IPE Representative
- Failure Analysis Associates Representative
- OCA Representative
- Maintenance Support Supervisor







The Test Engineer will be the Shift Director and is responsible for implementing the activities designated to be accomplished during that shift. A pre shift meeting will be held to insure proper coverage is available and to review those activities with the shift complement.

F. Stop Work Authority

OCA has the authority to "STOP WORK" based on the OCA manual.

Consistent to the manual from the Shift Manager, Assistant #2 and #3 the on shift QA representative and IPE representative have been authorized to stop work through the Test Engineer.

IMAGE EVALUATION
TEST TARGET (MT-3)



C. Review and Audit

The overall work effort will be under the review and audit of the Joint Test Group as described in the Shorten Startup Manual.

III. DIESEL GENERATOR 102 CRANKSHAFT FAILURE ANALYSIS AND CRANKSHAFT DESIGN ADEQUACY ASSESSMENT

A. Failure Analysis

Conduct an investigation of, and develop a detailed failure analysis for the Diesel Generator 102 crankshaft to determine causes for failure. This effort consists of the following:

- 1) Attendance, inspection and documentation of Diesel Generator 102 during teardown and reassembly.
- 2) Appropriate analysis of the failed crankshaft.
- 3) Review maintenance and operational history.

B. Crankshaft Design

Conduct an inspection and assessment of the adequacy of the existing (13" x 11") and replacement (13" x 12") Transamerica DeLaval Crank Shafts for Diesel Generators 101, 102 and 103. This effort consists of the following:

- 1) Review of the TDI design calculations.
- 2) Performance of independent calculations, as required.
- 3) Performance of operational torsional vibration tests at various speeds and engine loads on the existing 13" x 11" crankshafts in diesel-generators 101 and 103 and on the replacement 13" x 12" crankshaft for diesel-generator 102.

IV. DIESEL GENERATOR REWORK & INSPECTION

A. Inspections & Tests - Diesel Generator 102

The inspections and tests on diesel generator 102 include but may not be limited to the following:

- 1.) The connecting rod for cylinder no. 7 will be pulled to allow for inspection/examination for cylinder liner damage.
- 2.) Main bearings #8, 9, 10 & 11 adjacent to the failure will be pulled to inspect for damage to the bearing, bearing shell and bedplate. This will be performed as soon as possible to allow evaluation of damage.
- 3.) Analysis of engine oil, jacket water and bearing metal will be performed.
- 4.) An overall engine inspection during detailed disassembly for crankshaft removal will be performed.

- 5.) A generator inspection will be performed.
NOTE: Item 1 and 2 above to be completed prior to removing the diesel generator from the room.

- B. Inspection and Tests - Diesel Generator 101 and 102
The inspections and tests on diesel generator 101 and 102 include but may not be limited to the following:
- 1.) 100% visual inspection of crankshaft wear and dye penetrant tests where appropriate.
 - 2.) The connecting rods on cylinder ~~6-1-1~~ ¹⁰¹ will be pulled to perform 100% I₂ and U₂ of the connecting rod journal.
 - 3.) Torsional vibration testing of the crankshaft in the 101 ~~102~~ ¹⁰¹ will be performed following the above inspections per procedure provided by TDI.

C. Diesel Generator 102 Rework

LILCO has overall responsibility for the Diesel Generator 102 rework effort. The Startup Test Engineer on shift will supervise the various aspects of the work described below.

Catalytic personnel will remove pipe, tubing and electrical connections, disconnect the turbocharger, and disconnect the generator in preparation for jacking and skidding the engine out of the room.

Gerosa personnel will rig and jack the engine, skid it out of the room and move it around via flat bed to the turbine building truck bay. The engine will be lifted via the turbine building crane and set inside an existing caged-in area on the turbine building deck. A clean room will be set up and access control will be established.

TDI personnel will perform the disassembly allowing the appropriate inspections to take place. The TDI Service Representative will be the responsible supervisor for the TDI workman. The generator will also be inspected for damage while on the turbine deck. LILCO and TMA inspections will be performed during this work.

Once removed, the damaged shaft will be sent off site for failure analysis.


TDI personnel will rebuild the engine under the supervision of a TDI Service Representative and following reassembly, the engine will be transported back into the diesel generator room by Gerosa personnel.

Qualification personnel will recheck all equipment.
At this point reworking will begin.

V. REWORKING DIESEL GENERATOR 102

Upon completion of the Emergency Diesel Generator 102
rework and reinstallation, the check test program for this
engine will be reperfomed as follows.

- a. All components disturbed by the rework will be
subjected to appropriate C.I.O, including calibrations,
electrical wire checks, and pneumatic tubing
connection verifications.
- b. The Lube Oil, Jacket Water, Fuel Oil and Air Start
systems will be rechecked as required.
- c. Initial engine start in per ICI direction.
- d. The Mechanical check test will be reperfomed in its
entirety.
- e. The two Electrical Preop tests will be reperfomed.
- f. Following completion of the above and review and
concurrence by the JTC, the Qualification Preop test
will be reperfomed.



OFFICE OF THE DIRECTOR
 NATIONAL SECURITY AGENCY

ADVISORY RELATIONSHIP
 DIRECT REPORTING RELATIONSHIP

Enclosure 3

Information Requests on Diesel Generators (D/Gs)

I. General

1. Provide a written summary of the approach to be used on the Failure analysis for DG 102 on an expedited basis.
2. Provide the preoperational NDE records of the three DG crankshafts.
3. Provide the number of crankshaft failures and population size for all Delaval D/Gs, all nuclear service Delaval D/Gs, and all R-4 D/Gs.
4. Provide the failure analysis, if any, for the above crankshaft failures.
5. Provide the total number of operating hours on each D/G and the total number of hours at 3900 KW or greater.
6. Provide copies of all LILCO/S&W audits of Delaval and responses.
- 7.1 What is the maximum load to which these D/Gs could be upgraded?
- 7.2 What modifications would be required to make the upgrade?
- 7.3 What are the limiting components?
- 7.4 Provide an early reply as to whether these three questions can be answered and an estimate as to when.
8. Provide an explanation of the claim in the June 10, 1983 letter of Delaval to LILCO that the LILCO DGs are "state of the art" with no other product improvements which could positively affect reliability in light of the subcover cracks and crankshaft failure and the fact that modified parts were available but not identified. Also provide a commitment to review all product improvements available for the Shoreham D/Gs, if these D/Gs are to be repaired and used.
9. Does Delaval have a program where parts/components etc. are modified (such as design margins reduced) in order to improve ~~profitability~~?
Does this apply to any D/G parts for Shoreham? *profitability*
10. Provide responses to all NRC open items on D/Gs.
11. Provide responses to all items in NRC consultants's report.
12. Provide all vendor documentation on crankshafts, certifications of conformance, specs, NDE records, etc. Include statements of how and where from each crank shaft originated.

13. Provide justification for grinding cracks out of 101 DG crankshaft w/o failure analysis - before any grinding is done.
14. Provide a commitment for testing to demonstrate adequate vibration after reinstallation.
15. Response to 5/13/82 Delaval Part 21 report on starting air valve assembly.

II. Procurement

1. Provide procurement specifications to which the diesel generators were ordered. In addition, provide the performance specification; and the inspections performed upon receiving the diesels to show that the procurement specifications were met.
2. Discuss all tests performed on the DG's that were observed by LILCo at the manufacturing facilities. Describe all the tests performed at the manufacturing facilities that were not observed by LILCo. The description should include test procedures, pertinent instrumentation diagrams, and test data and results.
3. In addition to the qualification tests performed in accordance with the guidelines RG's 1.9 and 1.108 and IEEE Standard 287, describe all onsite tests that were performed on the DGs. Provide test procedures for these tests and also the data and tests results.
4. In addition to the deficiency reports already provided to the NRC, describe any installation problems encountered during the installation and operation of the DGs. Provide complete operating histories of the DGs.
5. Provide a description of the original design basis of the straight eight DGs used at Shoreham and a complete and detailed list of all product improvements made in this product line of DGs. Include in the description the recommended continuous and maximum loads and the operating hours for each rating for each modification.
6. Provide a latest copy of the technical instruction manual for these DGs.

III. Conditions of the Failure Occurance

1. Provide the test procedures that were being used at the time of the failure.
2. Describe the conditions in the test area prior to, during, and after the failure. The description should include all pertinent test information, vital signs, and test conditions such as test grid condition, all instrument reading prior to failure and post-failure, dither, all traces, vibrations noticed and recorded, and noises.

IV. Failure Investigation

1. Provide a copy of the Failure Analysis Associates (FAA) charter.
2. Provide the manufacturer's design calculations for the torsional analysis of the DGs. In addition, provide the models used, methods of arriving at the lumped parameters, justifications of any correlating factors used, calculations of all the natural frequencies, their mode shapes including the mode locations.
3. Describe all the torsional testing that was performed by the manufacturers on the straight-eight DGs. The description should include the test procedure, test data, test results, configurations and components of the DGs and loading devices during the test, and the instrumentation used and their locations.
4. Compare the DGs presently at Shoreham with all either TDI emergency DGs models now in use or to be used in other nuclear generating stations to show that the conditions and/or failure modes present at Shoreham will not occur at these other nuclear plants.
5. Describe the analytical investigations that FAA is or will be performing on the DGs. The description shall include the torsional vibration analysis, the stress analysis and the evaluation of the TDI torsional vibration and stress analysis.
6. Describe all the testing that will be performed by FAA on the emergency DGs at Shoreham. The description shall include test procedures and objectives, instrumentation and location, test data, test results, test loadings, test configuration, power factors, and methods of evaluation load interaction.
7. Based on the results of the analytical investigations and the test results, describe the effects, if any, that fast starts had on the failure.
8. Describe all the metallurgical and failure analysis of the crankshaft that will be performed by FAA.

V New Crankshaft/Refurbishing of DG's

1. Describe any new or additional problems or design deficiencies that may occur as a result of the installation of the 16x12 crankshaft.
2. Describe and justify the requalification testing program that will be performed on the modified DGs. The description shall include torsional vibration and stress testing, any testing in addition to the testing required in RGs 1.9 and 1.108 and IEEE Standard 387.
3. Describe the impact of the previous multiplicity of failures on the modified DGs.

VI Root-Cause Analysis

1. Provide a root-cause analysis which shows that the various failures documented in various deficiency reports and other documentations are not causally linked; for example, could cooling water leakage contribute to crankshaft failure?

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

August 5, 1983

IE INFORMATION NOTICE NO. 83-51: DIESEL GENERATOR EVENTS

Addressees:

All nuclear power facilities holding an operating license (OL) or a construction permit (CP).

Purpose:

This information notice is provided to bring to the attention of licensees and construction permit holders some events and experience of generic diesel generator problems and corrective action taken. It is expected that recipients will review the information for applicability to their facilities. No other action or response is required.


Description of Circumstances:

In its continuing review of licensee event reports (LERs), NRC has identified during the past five months more than 100 LERs pertaining to diesel generator problems. Most of these appear to be material, equipment, or component failures. No single common trend can be identified.

NRC is concerned about the large number of diesel generator events. During discussions with diesel manufacturers and licensees, it appears that many of these events could have been eliminated or prevented by implementation of a conscientious maintenance and inspection program as well as monitoring equipment through a plant's trend program. Some licensees have instituted such a program to determine the underlying cause of the failures (see IE Information Notice 82-10) and to prevent their recurrence. Components or materials that have experienced failures are monitored or inspected more frequently. Many affected items are repaired or replaced before actual breakdown. For example, cooling water heat exchangers that were found to be ineffective after a certain period of time because of tube fouling were replaced. Cooling jacket circulating water pump bearings are inspected for wear and replaced in certain intervals. Pressure switches and timers have been found with drifting setpoints and were recalibrated or replaced frequently.

Because of the large number of diesel generator events it is not feasible to describe all the events reported. However, Attachment 1 to this information notice gives several representative examples and corrective actions taken.

If there are any questions regarding this matter, please contact the Regional Administrator of the appropriate NRC Regional Office, or this office.



Edward L. Jordan, Director
Division of Emergency Preparedness
and Engineering Response
Office of Inspection and Enforcement

Technical Contact: Wolfgang Laudan, IE
301-492-9759

Attachments:

1. Selected Examples of Licensee Event Reports
Related to Emergency Diesel Generators
2. List of Recently Issued IE Information Notices

SELECTED EXAMPLES OF LICENSEE EVENT REPORTS AND VENDOR REPORTS
RELATED TO EMERGENCY DIESEL GENERATORS

QUAD-CITIES 2, OCTOBER 6, 1982

During the monthly preventive maintenance testing of Unit 2 diesel generator, the diesel tripped on high temperature 10 minutes after loading. The cause was determined to be fouling in the cooling water heat exchanger. The heat exchanger was replaced and the diesel testing was satisfactorily completed. The licensee placed the heat exchanger on a preventive maintenance schedule for cleaning.

SEDOYAH 2, OCTOBER 20, 1982

During a performance test of diesel generator 2B-8, the cooling jacket circulating water pump on the diesel generator was found to be inoperable as a result of a ball bearing failure in the pump. The bearing was replaced and the diesel generator was returned to service.

SUSQUEHANNA, OCTOBER 27, 1982

During a performance test of a diesel generator, the diesel generator tripped on high vibration. It was postulated that a vibration switch and a pressure regulator were both involved in the trip. Both were repaired and the diesel generator was returned to service. The equipment will be monitored through the plant's trend program.

BRUNSWICK 1, NOVEMBER 5, 1982

During a quick start testing program of diesel generator No. 4, the diesel generator tripped on "low lube oil pressure." The same problem occurred 2 days later on the same unit. Both events resulted from intermittent failures of the "low lube oil pressure start time relay" (STR). The relay timed out before actual pressure was above the low trip setpoint. The relay was replaced and the diesel testing was satisfactorily completed.

DRESDEN 3, NOVEMBER 9, 1982

During a Unit 3 diesel generator surveillance test, the diesel generator tripped on low cooling water pressure. A defective low cooling water pressure switch caused this event. The switch was replaced and the testing was satisfactorily completed.

RANCHO SECO, MAY 25, 1983

During startup testing, the diesel generator would not reach full operating speed. The Woodward governor speed adjustment on the unit stopped at about 650 rpm. It was found that the pointer disk was hanging up behind the dial plate. The manufacturer recommended filing about 1/16-inch off the pointer disk to allow free movement. After that the diesel achieved proper speed.

CALVERT CLIFFS, APRIL 7, 1983

During a routine inspection of the intake air check valve of No. 11 diesel generator, the licensee found a check valve holding pin sheared and the check valve loose. The same valve on two other diesel generators at Calvert Cliffs had been found to be cracked when inspected during 1982. The disk of one of these valves was found broken in two pieces. The engines in question are Fairbanks Morse Model 38TD81/8.

Because these failures did not render the diesel generators inoperable, as evidenced by successful completion of weekly operational tests, no LER was issued. The licensee pointed out that there were internal baffles between the check valves and the diesel turbocharger which made it unlikely to have a piece of the check valve enter the diesel's turbocharger. The check valve in question diverts air between the diesel turbocharger and integral air-blower. Failure of the check valve would result in air being available through the turbocharger at low loads and would affect the load control.

SHOREHAM, OCTOBER 15, 1982; APRIL 15, 1983; APRIL 20, 1983; MAY 4, 1983

During preoperational testing of Shoreham's three Transamerica Delaval, Inc. emergency diesel generators, the following mechanical problems were identified in the past 9 months and reported by the licensee under 10 CFR 50.55 (e):

- October 15, 1982 - The jacket waterpump shaft failed.
- April 15, 1983 - The engine head cracked.
- April 20, 1983 - The fuel injection line failed.
- May 4, 1983 - The rocker arm bolt failed.

Approximately 2 years before these problems occurred, the licensee discovered the following:

1. Loose hardware in cam gears during initial onsite inspection.
2. Multiple broken cylinder head exhaust bolts resulting from insufficient pipe guide clearances in the exhaust manifold.
3. Cracks in the fuel oil ejector that connects to the fuel oil drip line.
4. Absence of a drilled passageway for the relief valve on one lube oil pump line as required by design.
5. Leaky lube oil cooler tubes resulting from improper rolling in the tube sheet.
6. Cracks in rocker arm push rod socket (or cup).
7. Cam gear fitted bolts not installed at the factory as required.

The problems were corrected under the surveillance of vendor representatives. Nuclear sites with Transamerica Delaval diesel generators are listed on page 4 of this attachment.

LOUIS ALLIS REPORTED TWO DIFFERENT POTENTIAL PROBLEMS. MAY 20, 1983

(Louis Allis is the successor to Belouit Power Systems, Inc., and to Coit-Fairbanks Engine Division)

1. At the diesel generator in the Clinton Nuclear Plant, a three-phase rectifier assembly in the exciter was not connected in parallel, which could cause field winding insulation to deteriorate. Louis Allis field service took corrective action by making the necessary connections.
2. Detroit Edison experienced high vibration on its diesel generator. The cause was loose pole wedges. Louis Allis performed a detailed engineering evaluation of this problem and found that in 1976 a material change from HRS 1020 steel to 1045 steel was made. This means that diesel generators manufactured before this change may experience the same loose pole wedge problem. The affected plants are Fermi, Millstone Unit 2, and Hatch. These plants were notified by copy of the Part 21 report dated May 20, 1983.

TRANSAMERICA DELAVAL - 1981 TO 1983

The manufacturer reported the following turbocharger thrust bearing lubrication problem:

The design of the lubricating oil system permits the oil flow to the turbocharger bearing only when the diesel generator is running. When the diesel generator is in the standby mode, the turbocharger bearing lube oil system is bypassed to prevent a possible fire hazard should pressurized oil leak around the bearing seals onto hot impellers. Therefore, during startup, a sufficient amount of oil would not be available to adequately lubricate the turbocharger bearing. Because diesels are started once a month and run for a short length of time, premature bearing wear was experienced because of insufficient lubrication.

At San Onofre, the wear rate for this condition after 100 hours of operation was equivalent to 15,000 to 20,000 hours of continuous operation.

To ensure proper lubrication during startup, a design modification in the form of a lubrication oil drip system causing the lubricating oil to drip on the bearings through an orifice at a given rate was proposed, installed, and tested. An alternate method to this design modification is a change in the operating procedure. Before a monthly start, an operator would manually run the auxiliary lube oil pump for 30 to 60 seconds and confirm lube oil pressure. In the event of an emergency start, the bearings will function until oil pressure is developed.

Transamerica Delaval reported that the following nuclear sites were affected:


Shoreham	Perry	WPPSS 4
Grand Gulf	Bellefonte	Midland 1 & 2
Catawba	WPPSS 1	Hartsville
San Onofre	Comanche Peak 1 & 2	Phipps Bend

The licensees of the above plants were notified by copy of Transamerica Delaval Part 21 report dated September 19, 1980.

LIST OF RECENTLY ISSUED
 IE INFORMATION NOTICES

Information Notice No.	Subject	Date of Issue	Issued to
83-80	Failure of Class 1E Safety-Related Switchgear Circuit Breakers to Close on Demand	8/1/83	All power reactor facilities holding an OL or CP
83-49	Sampling and Prevention of Intrusion of Organic Chemicals Into Reactor Coolant Systems	07/25/83	All power reactor facilities holding an OL or CP
83-48	Gaseous Effluent Releases of Radioactive Iodine-125 and Iodine-131 in Excess of NRC Limits	07/14/83	NRC licensed byproduct material licensees, including medical and academic institutions, radiopharmaceutical suppliers, and industrial research
83-47	Failure of Hydraulic Snubbers as a Result of Contaminated Hydraulic Fluid	07/12/83	All power reactor facilities holding an OL or CP
83-46	Common-Mode Valve Failures Degrade Surry's Recirculation Spray Subsystem	07/11/83	All power reactor facilities holding an OL or CP
83-45	Environmental Qualification Test Of General Electric Company "CR-2940" Position Selector Control Switch	07/01/83	All power reactor facilities holding an OL or CP
83-44	Potential Damage to Redundant Safety Equipment as a Result of Backflow Through the Equipment	07/01/83	All power reactor facilities holding an OL or CP
83-43	Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints	06/24/83	All power reactor facilities holding an OL or CP
83-42	Reactor Mode Switch Modifications	06/23/83	All BWR facilities holding an OL or CP

OL = Operating License
 CP = Construction Permit



ENCLOSURE 5

UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

OCT 03 1993

~~THIS DOCUMENT IS NOT TO BE
REPRODUCED OR TRANSMITTED IN ANY
FORM OR BY ANY MEANS, ELECTRONIC
OR MECHANICAL, INCLUDING PHOTOCOPYING,
RECORDING, OR BY ANY INFORMATION
SYSTEMS TECHNOLOGY, WITHOUT
PERMISSION FROM THE NRC OFFICE OF
GENERAL INVESTIGATION AND
SECTION 2.750~~

Docket No. 99900334/83-01

Transamerica Delaval, Incorporated
Engine and Compressor Division
ATTN: Mr. C. Mathews
General Manager
550 85th Avenue
Oakland, California 94251

Gentlemen:

This refers to the inspection conducted by Mr. J. W. Sutton of this office on July 11-15, 1993, of your facility at Oakland, California, associated with the manufacture of emergency diesel generators and to the discussions of our findings with you and members of your staff at the conclusion of the inspection.

This inspection was made as a result of the issuance of several 10 CFR Parts 21 and 50.55(e) reports. The reports pertained to: (1) incorrectly identified bolt material, (2) failure of high pressure fuel oil injection lines, (3) failure of jacket water pump shafts, (3) failure of a crankcase cover bolt, (4) unqualified isoprene material, and (5) deficient piston skirts. These conditions were observed singly or in combination at one or more nuclear generating stations.

Areas examined and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedures and representative records, interviews with personnel, and observations by the inspector.

During the inspection it was found that the implementation of your QA program failed to meet certain NRC requirements. The specific findings and references to the pertinent requirements are identified in the enclosures to this letter.

This Notice of Violation is sent to you pursuant to the provisions of Section 206 of the Energy Reorganization Act of 1974. You are required to submit to this office within 30 days from the date of this letter, a written statement containing: (1) a description of steps that have been or will be taken to correct these items; (2) a description of steps that have been or will be taken to prevent recurrence; and (3) the dates your corrective actions and preventive measures were or will be completed. Consideration may be given to extending your response time for good cause shown.

You are also requested to submit a similar written statement for each item which appears in the enclosed Notice of Nonconformance.

Transamerica Delaval, Incorporated
Engine and Compressor Division

-2-

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR PROPRIETARY
INFORMATION PER 10 CFR
SECTION 2.790~~

The responses requested by this letter are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be exempt from disclosure under 10 CFR 9.5(a)(4), it is necessary that you (a) notify this office by telephone within 10 days from the date of this letter of your intention to file a request for withholding; and (b) submit within 25 days from the date of this letter a written application to this office to withhold such information. If your receipt of this letter has been delayed such that less than 7 days are available for your review, please notify this office promptly so that a new due date may be established. Consistent with Section 2.790(b)(1), any such application must be accompanied by an affidavit executed by the owner of the information which identifies the document or part sought to be withheld, and which contains a full statement of the reasons on the basis which it is claimed that the information should be withheld from public disclosure. This section further requires the statement to address with specificity the considerations listed in 10 CFR 2.790(b)(4). The information sought to be withheld shall be incorporated as far as possible into a separate part of the affidavit. If we do not hear from you in this regard within the specified periods noted above, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,


Udis Potapovs, Chief
Vendor Program Branch

Enclosures:

1. Appendix A - Notice of Violation
2. Appendix B - Notice of Nonconformance
3. Appendix C - Inspection Report No. 99900334/83-01
4. Appendix D - Inspection Data Sheets (11 pages)

~~THIS DOCUMENT HAS BEEN~~
~~CLASSIFIED "SECRET" BY~~
~~DATE 01-10-83 BY 1041~~
~~SECTION 2.730~~

APPENDIX A

Transamerica Delaval, Incorporated
Engine and Compressor Division
Docket No. 99900334/83-01

NOTICE OF VIOLATION

As a result of the inspection conducted on July 11-15, 1983, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and has been categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987 (March 9, 1982):

Section 21.21(b)(1) of 10 CFR Part 21, dated December 30, 1982, states, in part:

- A director or responsible officer subject to the regulations of this part or a designated person shall notify the Commission when he obtains information reasonably indicating a failure to comply or a defect affecting . . . a basic component that is within his organization's responsibility and is supplied for a facility or activity within the United States that is subject to the licensing requirements under Parts 30, 40, 50, 60, 61, 70, 71, or 72 of this chapter. The above notification is not required if such individual has actual knowledge that the Commission has been adequately informed of such defect or such failure to comply.

Contrary to the above, a director, responsible officer, or designated person had not notified the Commission in regard to:

1. Jacket water pump shaft failures on the emergency diesel generators (EDG) that had been furnished to the Shoreham Nuclear Power Station.
2. A potential defect in the fuel injection line tubing that was used on EDGs furnished to Grand Gulf and San Onofre.

This is a Severity Level IV violation (Supplement VII).

~~THIS DOCUMENT IS UNCLASSIFIED~~
~~DATE 08-08-00 BY 60322 UC/STP~~
~~SECTION 2.700~~

APPENDIX B

Transamerica Delaval, Incorporated
Engine and Compressor Division
Docket No. 99900334/83-01

NOTICE OF NONCONFORMANCE

Based on the results of an NRC inspection conducted on July 11-15, 1983, it appears that certain of your activities were not conducted in accordance with NRC requirements as indicated below:

Criterion V of Appendix B to 10 CFR Part 50 states: "Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, of a type appropriate to the circumstances and shall be accomplished in accordance with these instructions, procedures, or drawings. Instructions, procedures, or drawings shall include appropriate quantitative or qualitative acceptance criteria for determining that important activities have been satisfactorily accomplished."

Nonconformances with these requirements are as follows:

- A. Paragraph 4.6.2 of Section 4 of the Quality Assurance Manual (QAM) dated April 30, 1981, states, in part, "when required by Purchase Order material received destined to become a part of the manufactured item must be accompanied by a Certificate of Vendor inspection. The material is then inspected to all applicable specifications utilizing Vendor Certifications" In addition, paragraph 4.1.1 of Quality Control Procedure I.P.200, states, in part, "when it is determined that product deviates from specification, an Inspection Report, Form P-249, will be initiated by the Receiving Inspector describing the nature of the defect."

Contrary to the above, the Transamerica Delaval Incorporated (TDI) receiving inspector accepted material on Purchase Order No. 45333, for which required mill test reports had not been received, without issuing a nonconformance form P-249.

- B. Subparagraphs of II.A and II.B dated January 29, 1976, and November 10, 1969, respectively, of the Drafting Room Practice (DRP) requires: (1) drawing of layouts on tracing paper; and (2) a special title block on layout drawings with ample space for signatures in full of the designer and witnesses along with dates.

~~THIS DOCUMENT HAS NOT BEEN
REPRODUCED FOR THE PUBLIC
UNLESS INDICATED OTHERWISE
ON THIS DOCUMENT~~
SECTION 2.700

Contrary to the above, the following layout drawings for the late 1982 redesign of the emergency diesel generator (EDG) jacket water pump had not been (1) drawn on tracing paper and (2) signed and dated: (a) 101973, (b) 03-426-08-AA, and (c) 03-425-10-AE (lined through).

- C. Paragraphs 2.2 and 2.3 of the Engineering Operating Procedure (EOP) 4, dated April 19, 1979, states, respectively, "The designer shall perform the necessary calculations, if required, and prepare the required design layouts.

"The designer shall sign, date, and submit the calculations which he has checked for completeness and accuracy, along with the design layout as required, and his signed and dated form E-213, to the Manager of Design."

Paragraph II.A.6 dated January 29, 1976, of the Drafting Room Practice, states, "Important calculations should be written in the proper notebook, maintained in the department files."

Contrary to the above, regarding calculations for redesign of defective EDG jacket water pumps located at Shoreham Nuclear Power Station:

1. Calculations for the first occurrence (1979) which are written in the proper notebook had not been signed and dated in the spaces provided.
2. Calculations for the second occurrence (1982) had not been (a) signed, and (b) written in the proper notebook.

- D. Section 6 dated February 27, 1981, of the QAM, contains the following requirements:

1. Paragraph 6.1.1 states, "Documents establishing and defining processes and procedures pertaining to the quality of the product shall be controlled by the subdivision that has the initial responsibility of issue."
2. Paragraph 6.2.1 states, in part, "All documents relating to the quality of the product shall be reviewed by the manager of the issuing section or his representative."
3. Paragraph 6.3.1 states, in part, "All documents such as Engineering drawings . . . must have a mechanism for identification, authority of issuance and revision."

Contrary to the above, "D Sheets" which pertain to quality of the product are issued by the Engineering Department; however, they are not reviewed by the manager as evidenced by the lack of provisions to identify the date, preparer, reviewer, approver, or revision. Examples are D-4986 and D-4956, which are entitled, "Assembly Instructions," and pertain to the EDG jacket water pump. It was noted that the latter document reflected the release date, four revision levels and dates in the lower margin of the affected sheets.

- E. Paragraphs 5.3.2 and 5.3.3 of Section 5 dated February 27, 1981, of the QAM, require that Manufacturing Engineering provide written instructions in the form of route sheets, tooling sheets, or special written instructions, etc., to Manufacturing and Assembly Departments.

Paragraph 16.2.1 of Section 16 dated February 27, 1982, of the QAM states, in part, "Manufacturing and assembly Route Sheets are used as records of in-process inspection of parts, components, and assemblies. All Route Sheets are retained by Quality Control as objective evidence of inspection acceptance."

Contrary to the above, route sheets for the assembly of the EDG jacket water pump reflected on Drawing No. 101973, Revision C, had not been retained by Quality Control as objective evidence of inspection acceptance.

- F. Paragraphs 2.4.1 and 9.1.1 of Quality Control Inspection Procedure No. 300 dated April 1, 1981, requires that the area inspector (1) inspect, (2) stamp and date the Production Routing Sheet (PRS) in the space provided, and (3) stamp and date and enter quantity accepted in the final acceptance block of the PRS.

Contrary to the above, regarding EDG jacket water pump parts that were manufactured during the time period when defective jacket water pumps were being modified:

1. Stamp and date had not been entered at Operation No. 90 and final accept block of PRS No. 03-426-08-AE Water Pump Shaft which was processed in October 1982. Further, the quantity accepted had not been entered in the quantity accepted block.
 2. Stamp had not been entered in the final accept block of PRS No. 101969 Seal Retainer which was processed in September 1982.
- G. Stone and Webster Engineering Corporation Specification No. SHI-89 dated June 24, 1981, provides the bidder with the option of testing or dynamic analysis of mechanical equipment for seismic qualification.

~~THIS DOCUMENT HAS NOT BEEN~~
~~REVIEWED FOR CONFIDENTIALITY~~
~~REASONED THAT IT DOES NOT~~
~~CONTAIN INFORMATION THAT IS~~
~~UNLAWFULLY OBTAINED FROM A~~
~~SECTION 2.750~~

Paragraph 15.3.1 and its subparagraph 5 of EOP 1 dated April 20, 1981, state that the engine driven jacket water pump will be shake tested. The "Qualification Statement for 03-425-04 Jacket Water Cooling Pump Revision" dated October 18, 1982, states, in part, "We submit that these changes do not have any negative effect on the seismic qualification of the subject pump"

Contrary to the above, dynamic analysis or testing had not been conducted on the redesigned EDG jacket water pumps to assure that the seismic qualification had not been compromised.

- H. Paragraph A.1 of EOP 7 dated April 20, 1981, states, in part, "This procedure outlines those steps taken in accomplishing release or revision of . . . purchase specifications." Purchase specifications contain a space for approval.

Contrary to the above, Purchased Material Specification No. RL 019000 dated October 6, 1982, had not been approved as evidenced by the lack of a signature in the approval block.

- I. TDI's 10 CFR Part 21 report letter dated June 23, 1983, concerning a potential problem with the isoprene flexible elements of drive couplings, states, in part, "a copy of this letter will be sent to each of the cognizant parties as listed in paragraph 2, no later than July 15, 1982."

Contrary to the above, the TDI notification letters to 10 affected customer cognizant parties were dated August 18, 1982.

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR PROTECTION
INFORMATION PER 10 CFR~~

REPORT
NO.:

99900334/83-01

INSPECTION
DATE(S)

7/11-15/83

~~SECTION~~ / INSPECTION

ON-SITE HOURS: 81

CORRESPONDENCE ADDRESS: Transamerica Delaval, Incorporated
Engine and Compressor Division
ATTN: Mr. C. Mathews, General Manager
550 25th Avenue
Oakland, California 94261

ORGANIZATIONAL CONTACT: Mr. R. E. Boyer, Manager, Quality Assurance
TELEPHONE NUMBER: (415) 577-7422

PRINCIPAL PRODUCT: Emergency diesel generators.

NUCLEAR INDUSTRY ACTIVITY: Transamerica Delaval, Incorporated (TDI) has no current contracts for domestic nuclear emergency diesel generators (EDGs).

ASSIGNED INSPECTOR:

J. W. Sutton
J. W. Sutton, Reactive and Component Program
Section (R&CPS)

9/26/83
Date

OTHER INSPECTOR(S):

W. E. Foster, R&CPS
R. E. Oiler, R&CPS

APPROVED BY:

I. Barnes
I. Barnes, Chief, R&CPS

7/27/83
Date

INSPECTION BASES AND SCOPE:

A. BASES: 10 CFR Part 50, Appendix B and 10 CFR Part 21.

B. SCOPE: This inspection was made as a result of the issuance of several 10 CFR Part 21 and 50.55(e) reports. The reports pertained to:
(1) incorrectly identified bolt material, (2) failure of high pressure fuel oil injection lines, (3) failure of jacket water pump shafts, (4) failure of a crankcase cover bolt, (5) unqualified isoprene material, and (6) deficient piston skirts. These conditions were observed singly or in combination at one or more nuclear generating stations.

PLANT SITE APPLICABILITY:

Incorrectly identified bolt material: 50-400. Failure of high pressure fuel oil injection lines: 30-322, 50-206, 50-361, 50-362, 50-416, and 50-417.
(cont. on next page)

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR TECHNICAL
INFORMATION PER 10 CFR
SECTION 2.700~~

REPORT NO.: 99900334/B3-D1	INSPECTION RESULTS:	PAGE 2 of 14
----------------------------	---------------------	--------------

PLANT SITE APPLICABILITY: (cont.)

Failure of jacket water pump shafts: 50-322. Failure of a crankcase cover bolt: 50-416. Unqualified isoprene material: 50-416, 50-417, 50-400, 50-413, 50-414, 50-424, and 50-425. Deficient piston skirt: 50-413, 50-414, 50-518, 50-519, 50-553, 50-554, 50-400, 50-401.

A. VIOLATIONS:

Contrary to Section 21.21(b)(1) of 10 CFR Part 21 dated December 30, 1982, a director, responsible officer, or designated person had not notified the Commission in regard to:

1. Jacket water pump shaft failures on EDGs that had been furnished to the Shoreham Nuclear Power Station.
2. A potential defect in the fuel injection line tubing that was used on EDGs furnished to Grand Gulf and San Onofre.

This is a Severity Level IV violation (Supplement VII).

B. NONCONFORMANCES:

1. Contrary to Criterion V of Appendix B to 10 CFR Part 50, paragraph 4.6.2 of Section 4 of the Quality Assurance Manual (QAM) and paragraph 4.1.1 of Quality Control Procedure I.P.200, the receiving inspector accepted material on Purchase Order (PO) 45333, for which required mill test reports had not been received, without issuing a nonconformance form P-249.
2. Contrary to Criterion V of Appendix B to 10 CFR Part 50 and the commitment date of July 15, 1982, in TDI's 10 CFR Part 21 report dated June 23, 1982, concerning unqualified material in flexible drive couplings of EDGs, the notification letters were not sent until August 18, 1982.
3. Contrary to Criterion V of Appendix B to 10 CFR Part 50 and subparagraphs II.A and II.B dated January 29, 1976, and November 10, 1969, respectively, of the Drafting Room Practice, the following layout drawings for the late 1982 redesign of the EDG jacket water pump had not been (1) drawn on tracing paper and (2) signed and dated: (a) 101973, (b) 03-425-08-AA, and (c) 03-425-10-AE (lined through).
4. Contrary to Criterion V of Appendix B to 10 CFR Part 50, paragraphs 2.2 and 2.3 of Engineering Operating Procedure (EOP) 4 dated April 19, 1979, and paragraph II.A.6 dated January 29, 1976, of the

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR FACTUAL
ACCURACY OR COMPLETENESS
BY THE NRC STAFF~~

REPORT NO.:	99900334/83-01	INSPECTION RESULTS:	SECTION 2.700	PAGE 3 of 14
-------------	----------------	---------------------	---------------	--------------

Drafting Room Practice, regarding calculations for the redesign of defective EDG jacket water pumps located at Shoreham Nuclear Power Station:

- a. Calculations for the first occurrence (1979), which are written in the proper notebook, had not been signed and dated in the spaces provided.
 - b. Calculations for the second occurrence (1982) had not been (a) signed, and (b) written in the proper notebook.
5. Contrary to Criterion V of Appendix B to 10 CFR Part 50 and paragraphs 6.1.1, 6.2.1, and 6.3.1 of Section 6 dated February 27, 1981, of the QAM, "D Sheets" which pertain to quality of the product are issued by the Engineering Department; however, they are not reviewed by the manager as evidenced by the lack of provisions to identify the date, preparer, reviewer, approver, or revision. Examples are D-4986 and D-4956 which are entitled, "Assembly Instructions," and pertain to the EDG jacket water pump. It was noted that the latter document reflected the release date, four revision levels, and dates in the lower margin of the affected sheets.
6. Contrary to Criterion V of Appendix B to 10 CFR Part 50 and paragraphs 5.3.2, 5.3.3, and 16.2.1 of Sections 5 and 16, respectively, dated February 27, 1981, of the QAM, route sheets for the assembly of the EDG jacket water pump reflected on Drawing No. 101973, Revision C, had not been retained by Quality Control as objective evidence of inspection acceptance.
7. Contrary to Criterion V of Appendix B to 10 CFR Part 50 and paragraphs 2.4.1 and 9.1.1 of Quality Control Inspection Procedure No. 300 dated April 1, 1981, regarding EDG jacket water pump parts that were manufactured during the time period when defective jacket water pumps were being modified:
- a. Stamp and date had not been entered at Operation No. 90 and final accept block of PRS No. 03-426-08-AE water pump shaft which was processed in October 1982. Further, the quantity accepted had not been entered in the quantity accepted block.
 - b. Stamp had not been entered in the final accept block of PRS No. 101969 seal retainer which was processed in September 1982.

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR PROPRIETARY
INFORMATION PER 10 CFR
SECTION 2.700~~

REPORT
NO.:

99900334/83-01

INSPECTION
RESULTS:

PAGE 4 of 14

8. Contrary to Criterion V of Appendix B to 10 CFR Part 50, Stone and Webster Engineering Corporation Specification No. SHI-89 dated June 24, 1981, paragraph 15.3.1 and its subparagraph 5 of EOP 1 dated April 20, 1981, and the "Qualification Statement for 03-425-04 Jacket Water Cooling Pump Revision" dated October 18, 1982, dynamic analysis or testing had not been conducted on the redesigned EDG jacket water pumps to assure that the seismic qualification had not been compromised.
9. Contrary to Criterion V of Appendix B to 10 CFR Part 50, and paragraph A.1 of EOP 7 dated April 20, 1981, Purchased Material Specification No. RL 019000 dated October 6, 1982, had not been approved as evidenced by the lack of a signature in the approval block.

C. UNRESOLVED ITEMS:

None

D. STATUS OF PREVIOUS INSPECTION FINDINGS:

1. (Closed) Nonconformance A (Report No. S2-02): The Quality Assurance/Quality Control organizational chart had not been updated to reflect changes in the QA/QC organization since January 1, 1982.

The NRC inspector reviewed the current QA/QC organizational chart which was revised on January 15, 1983, showing that the Nondestructive Examination (NDE) Level III examiner is no longer the Manager of Quality Engineering.

2. (Closed) Nonconformance B (Report No. S2-02): Kobe Steel Ltd. had not been surveyed at a minimum of once every three years as required by paragraph 4.4.3 of Section 4 of the QAM.

The NRC inspector reviewed a revision to the QAM, subparagraph 4.4.5, issued April 22, 1983, which indicates that vendors who hold current ASME certificates of authorization or Quality Systems Certificates need not be surveyed or audited. Chemical analysis of subject crankshaft materials were performed and the materials found to be acceptable. The NRC inspector was informed by TDI that they intend to perform a physical inspection at Kobe Steel Ltd. within the next three months.

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR PROPRIETARY
INFORMATION PER 10 CFR~~

REPORT NO.:	99900334/83-01	INSPECTION RESULTS:	SECTION 2.700	PAGE 5 of 14
-------------	----------------	---------------------	--------------------------	--------------

3. (Closed) Nonconformance C (Report No. 82-02): (a) Component drawings released by engineering did not constitute the final instructions to assembly for definition of acceptance criteria for the governor lube oil cooler, and (b) instructions for assembly of the governor lube oil cooler had not been provided in writing from manufacturing engineering to assembly.

The NRC inspector reviewed the lube oil governor assembly drawing and verified that the location of the cooler was not identified. In addition, the parts list for this drawing was reviewed for content. The route sheet now indicates the assembly drawing. TDI's corrective action commitments contained in the January 5, 1983, letter to the NRC have been complied with.

E. OTHER FINDINGS AND COMMENTS:

1. Carolina Power and Light Company's (CPL) 10 CFR Part 50.55(e) notification report, dated January 18, 1983, identified that bolting material for the CPL Shearon Harris, Unit 1, EDG was not properly identified in accordance with design requirements.

The NRC inspector reviewed documents and correspondence between TDI, Ebasco, and CPL pertaining to this subject. It appeared to the NRC inspector that a misunderstanding existed as to whether the bolts and nuts were requested to be fabricated to AISI 4140 or ASTM specifications. The nuts and bolts were bought to the AISI 4140 specification which conforms to ASTM A193 Grade B7 chemical and mechanical property requirements. Specification CAR-SH-E-11, Revision 6, did not require ASTM materials to be purchased. TDI's letter of June 22, 1983, to Ebasco outlines this finding. This is not considered a generic problem.

2. Tennessee Valley Authority (TVA) 10 CFR Part 50.55(e) report to the NRC dated February 10, 1982, addressed the failure of TDI to take corrective action on TVA audit findings described in TVA audit 81V-47, conducted December 1-3, 1981. Documentation and correspondence between TVA and TDI to date was reviewed. Reaudits have been performed by TVA to determine compliance to their findings. TDI had taken action to make sure that proposed corrective actions were implemented before signing off on the corrective action form. Documentation for compliance to this requirement was reviewed.

All outstanding items were closed out by TVA during a TVA reaudit. TVA's letter to TDI dated August 24, 1982, indicated no findings.

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR PROPRIETARY
INFORMATION PER 10 CFR
SECTION 21.700~~

REPORT
NO.:

99900334/83-01

INSPECTION
RESULTS:

PAGE 6 of 14

3. Long Island Lighting Company (LILCO) filed a 10 CFR Part 50.55(e) report on April 20, 1983, with the NRC, Region I. The report stated that failures had occurred in fuel oil injection lines to the EDGs that had been furnished to Shoreham Nuclear Power Station, Unit 1. As a result of the documentation review by the NRC inspector, the following conditions were found to exist:
- a. Three diesel generators were supplied to the Shoreham Nuclear Station for emergency power.
 - b. A failure occurred to the high pressure fuel oil injector line during routine testing of Generator No. 102 on March 3, 1983. The tubing was replaced and on March 5, 1983, a fuel injection line failed on Generator No. 103.
 - c. Both lines were sent to an independent laboratory for failure analysis.
 - d. A failure analysis issued by TDI dated June 24, 1983, concluded that the failure was attributable to the presence of a discontinuity on the inside diameter (I.D.) of the injection tube. This discontinuity acted as a stress riser and combined with the line operating pressures resulted in the fatigue endurance limit of the material being exceeded. The report indicated that the discontinuity was a draw seam that had been created during manufacture of the tubing.
 - e. TDI conducted a 10 CFR Part 21 meeting on June 27, 1983, as required by the Division 10 CFR Policy Procedure, to evaluate the findings and to determine reportability to the NRC. The committee determined that this problem was an isolated case and was not reportable. On July 5, 1983, another meeting was held which still determined the condition to be nonreportable due to the fact that many engines had been and are running with the same type of tubing that had been installed at Shoreham.
 - f. The NRC inspector requested a search be made as to when the tubing used in the Shoreham Units was purchased and if other nuclear sites could have injection lines installed that had been manufactured from the same lot of tubing.

ORGANIZATION: TRANSAMERICA DELVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR PROPRIETARY
INFORMATION PER 10 CFR
SECTION 8300~~

REPORT
NO.:

99900334/83-01

INSPECTION
RESULTS:

PAGE 7 of 14

- g. TDI searched their records and found that the tubing was purchased in 1976. Purchase lots are made in 2000 ft. increments with approximately 200 ft. being used per diesel unit. The record checks indicated that besides the Shoreham nuclear site, EDGs had been furnished to Grand Gulf and San Onofre nuclear sites which had utilized tubing from the same purchase lot.
- h. TDI Design Specification D-266 dated October 2, 1972, and Revisions A and B dated August 18, 1978, and August 15, 1980, contain the applicable requirements required to be followed in regard to tubing manufacturing operations. The supplier was required to furnish material certificates of conformance and test reports with each order. Purchase documentation for this period of time (1976) was not retained by TDI in that the QA program only requires retention for 5 years. The NRC inspector reviewed a recent PO for tubing, No. 45333 dated October 1, 1981, for conformance to purchase requirements. The PO required that mill test reports be furnished. A nonconformance was identified as a result of the acceptance of the material by the receiving inspector, although mill test reports had not been received (see paragraph B.1).
- i. The action to preclude recurrence was contained in the failure analysis report, June 24, 1983, and indicated "more rigid QA procedures were called for. Sections from each length of tubing should be cut off, sawed lengthwise at 90° intervals, and inspected to ensure there are no draw marks on the tubing ID. Since draw seams would run the entire length of the tubing, this inspection measure will ensure that no draw seams are present in any line manufactured from that length of tubing (200 ft.). Such a QA requirement should be called for on any high pressure fuel injection line destined for use on a nuclear stand-by emergency diesel generator."
- j. As a result of the NRC inspector's review of documentation, consistency of drawings, procedures, POs, letters, in-house memos, and reports, it was concluded that this failure may not be an isolated occurrence and that a potential existed for draw seams to be present in fuel injection lines of diesel generators supplied to Grand Gulf and San Onofre. In addition, review of 10 CFR Part 21 evaluation activities concerning the fuel oil line failure consisted of side notes on letters and records, etc., produced by TDI personnel during Delivered Product Trouble (DPT) meetings. These were considered

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR PROPRIETARY
INFORMATION PER 10 CFR
SECTION 2.790~~

REPORT NO.:	99900334/83-01	INSPECTION RESULTS:	10 CFR SECTION 2.790	PAGE 8 of 14
-------------	----------------	---------------------	----------------------	--------------

as inadequate by the NRC inspector to establish the reason for classifying this occurrence as one of a kind. The violation detailed in paragraph A was identified as a result of this review.

- k. Subsequent to the inspection, TDI filed a 10 CFR Part 21 report with NRC, Headquarters. The report is dated July 20, 1983, and identifies the following nuclear generating stations with the potential defect: (1) Shoreham, (2) Grand Gulf, and (3) San Onofre.
- 4. LILCO filed a 10 CFR Part 50.55(e) report on October 15, 1982, with the NRC, Region I. The report stated that jacket water pump shafts had failed on EDGs that had been furnished to Shoreham Nuclear Power Station, Unit 1. Further, the report stated that the failures occurred on jacket water pumps that had been modified to preclude failures that had been experienced in similar units operating overseas.

The following conditions were observed during the course of the inspection:

- a. The Engine and Compressor Division of TDI filed a 10 CFR Part 21 report on September 21, 1979, regarding "a potential failure of the drive shaft for the engine driven jacket water pump which would result in engine nonavailability." The report stated that jacket water pumps of the same design as those that failed had been installed on the three EDGs that had been furnished to Shoreham Nuclear Power Station. The NRC inspector was informed that the jacket water pumps had been modified.
- b. A TDI memo dated October 18, 1982, states, in part, "In the past five months, Lilco [Long Island Lighting Company] has experienced three jacket water pump failures." Information presented as a record of evaluation was included in open areas of a form entitled, "Authorization For No Charge Billings" dated October 7, 1982, and identified LILCO as the customer. The following hand written/printed information was exhibited in the open areas: "Review 10 CFR 21 no-only site conditions at LILCO diff OK other plants not a 10 CFR 21 LILCO unique only site with this problem attendees [list of names dated 10-11-82] LILCO is aware of problem TDI & LILCO will solve [signed, dated 11/11/82]." The information is not sufficiently detailed to enable an adequate evaluation of the decision regarding reportability. The failure of the jacket water pumps had not been reported to the Commission. As a result of the foregoing, the violation detailed in paragraph A was identified.

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN~~
~~REVIEWED FOR PROMINENT~~
~~INFORMATION PER 10 CFR~~
~~SECTION 2.7.50~~

REPORT NO.:	99900334/S3-C1	INSPECTION RESULTS:	PAGE 9 of 14
----------------	----------------	------------------------	--------------

- c. Layouts are created by redlining existing drawings rather than by initiating new drawings. The redlined drawings (layouts) had not been subjected to the required signature/date cycle. Calculations had not been controlled in the manner specified. There was no indication that assembly instructions had been reviewed/approved. Route sheets for assembly of the jacket water pump had not been retained; also, some route sheets for manufacturing activity had not been completed as required. The foregoing, along with other observations, resulted in the nonconformances detailed in paragraph B.3 through B.9.
- d. A TDI memo dated July 16, 1979, which addresses jacket water pumps, identifies Gulf States along with LILCO and a foreign customer. Requested documents were not presented regarding Gulf States; as a result, this issue will remain open in order to determine whether or not Gulf States received suspect jacket water pumps.
- e. TDI identifies the cause as engineering and assembly induced. The NRC inspector concurs; however, in his judgement, the quality organization cannot be excluded. Based upon the observations of this area of the inspection, it is not apparent that adequate corrective actions and preventive measures have been taken. However, the NRC inspector was informed that the pumps at Shoreham Nuclear Power Station have operated past the times of the previous failures.
- f. In an effort to assess the effectiveness of the corrective actions and preventive measures, the following areas were evaluated: (a) change control, (b) manufacturing process control, and (c) records. This area of the inspection was accomplished by evaluating the following documents for requirements and/or implementation of requirements: 12 drawings, 3 specifications, 6 procedures, 3 sections of the QA Manual, 5 memoranda, 7 letters, and 24 other documents identified as: analysis/calculations, packaging/shipping notifications, production routing sheets, qualification statement, material requisitions, authorization for no charge billing, failure analysis report, assembly instructions, and requests for drafting room action. The findings are indicated at other locations of this report.
- g. Subsequent to the inspection, TDI filed a 10 CFR Part 21 report dated July 20, 1983, with NRC, Headquarters.

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR DISCRETIONARY
INFORMATION PER 10 CFR
SECTION 27.99~~

REPORT
NO.:

99900334/83-01

INSPECTION
RESULTS:

PAGE 10 of 14

5. Two 10 CFR Part 50.55(e) reports by Mississippi Power and Light (MP&L) Company to the NRC were filed on March 22, 1982, and April 21, 1982. These reports concerned the shorting of the generator by a sheared crankcase capscrew head of a Unit I, Division II, diesel generator furnished by TDI. This matter was reported in several interim reports by MP&L with the most recent one being Interim Report No. 6.
- a. During a 24-hour performance test, the unit tripped on a "Generator Differential" which was accompanied by electrical arcing inside the generator. Later inspection verified that the stator insulation had been damaged and the head from a 5/8 x 11 threads x 1 3/4" long capscrew was embedded in the stator. It was determined that the capscrew head was from the diesel engine's rear crankcase cover. All of the capscrews were replaced by the utility, and an analysis of the failed capscrew indicated the head broke off due to low-stress fatigue cracking during service. This cracking appeared to have been initiated by over or under torquing of the capscrews.
- b. Findings: Review of the problem with TDI's Grand Gulf site service personnel provided the following information: The source of the capscrew head found in the generator stator was from a top capscrew in the vertical crankcase cover. The screw shank was still in the cover hole. The screws are classed as noncritical service and require torquing of 60 foot pounds (Ft. Lb.). Since the metallurgical analysis indicated a fatigue failure mechanism, the cause appears to have been over or undertorquing coupled with operating stresses. No information was available to indicate when this incorrect torquing may have occurred. TDI service personnel indicated that the site Bechtel craftsman would have had a minimum of two occasions when they would have removed and replaced the crankcase cover for bearing checks after the diesel generator was delivered to the site. In addition, they would have had a TDI instruction manual which showed the required torque value of 60 Ft. Lb. for this size bolt while using a special lubricant. The TDI service personnel also indicated that this incident of a sheared screw head shorting the generator was a first time occurrence for the TDI diesel generators. The matter was discussed between TDI and MP&L personnel, but no meeting notes were made available to the NRC inspector by TDI.

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR PROPRIETARY
INFORMATION~~

REPORT
NO.:

99900334/20-01

INSPECTION
RESULTS:

~~SECTION 2.700~~

PAGE 11 of 14

6. In 10 CFR Part 50.55(e) reports to the NRC by four electric utility companies, a misapplication of unqualified isoprene material in the flexible element of the couplings for diesel generators supplied by TDI was identified. This material was not suitable for use in the high temperature oil atmosphere of the diesel generator and would deteriorate rapidly in service. The couplings were manufactured by Koppers Company. The utilities reporting were: (1) MP&L for Grand Gulf Nuclear Station, Units 1 and 2; (2) CP&L for Shearon Harris Nuclear Power Plant, Unit 1, (3) Duke Power for Catawba Nuclear Station, Units 1 and 2, and (4) Georgia Power for Vogtle Nuclear Plant, Units 1 and 2. This matter was also reported by TDI in 10 CFR Part 21 reports to the NRC on June 23 and July 13, 1982.
- a. The action necessary to correct this deficiency was to change out the existing flexible element in the coupling with one made of neoprene which was suitable material for service. TDI, in their report, identified 10 nuclear power plants which have affected diesel generators, and indicated these cognizant parties would be notified no later than July 15, 1982.
- u. Findings: The NRC inspector verified the following information through observations, discussions, and review of documents:
- (1) The incident which prompted TDI to report on June 23, 1982, was a failure of a coupling flexible element made of isoprene in a nonnuclear diesel generator. The utilities reported subsequent to the above date. The suspect couplings were manufactured by Koppers Company starting in 1977 and purchased as stock items by TDI based on TDI's purchased material specification for "Couplings-Elastomeric, Part No. AK-007-000," dated November 11, 1976. The original version of this specification did not specify the type material of the flexible element. After the above failure, TDI issued Revisions A, B, and C to the specification in 1981, 1982, and 1983, respectively. Change A specified that the flexible element should be neoprene which is a suitable material. Change B specified service in a 175°F oil atmosphere, and Change C specified that the flexible element must have a 1/2 " wide red band on it to distinguish it as neoprene.

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR CONFIDENTIALITY
INFORMATION PER 10 CFR~~

REPORT NO.:	99900334/83-01	INSPECTION RESULTS:	SECTION 2.750	PAGE 12 of 14
-------------	----------------	---------------------	--------------------------	---------------

- (2) Review of TDI notification letters verified that all nuclear order customers with affected diesel generators were notified of the deficiency. However, 10 of the TDI notification letters were dated August 18, 1982. This date was contrary to the TDI commitment date of July 15, 1982, in their 10 CFR Part 21 report and resulted in the nonconformance identified in paragraph B.2.
- (3) Observation of a coupling flexible element in the stores department verified that it did not have a red band on it as required by Revision C of the purchase specification. However, this flexible element was identified only by part number and it could not be traced to specific POs placed with Koppers Company after April 25, 1983.
- (4) Review of receiving inspection cards, "Vendor Inspection Report," for Koppers Company, indicated that the bases for receiving inspection of the couplings was Mil-Std 105 D.
- (5) Review of 10 CFR Part 21 evaluation records concerning the isoprene flexible element established that records were inadequate to establish the cause of the misapplication and the basis for the determination that the item was reportable under 10 CFR Part 21. The only records available were entries dated June 15 and June 22, 1982, in the DPT committee weekly log. The June 15, 1982, entry indicated Product Engineering was to compile a list of engines using Kopper's Elastomer GDV drive couplings, and the June 22, 1982, entry indicated that it was determined that the Kopper's Elastomeric coupling was a 10 CFR Part 21 reportable item and the responsible individuals were to issue the appropriate notification. These DPT committee meeting notes did not provide sufficient information to show the bases for the evaluation (and do not appear to meet the requirements 10 CFR Part 21, paragraph 21.51(a) and (b)).

7. In five 10 CFR Part 50.55(e) reports to the NRC by three electric utility companies, a deficiency in the piston skirt castings of diesel generators was identified. This matter concerned the potential failure of the engine piston skirt castings of diesel generators supplied by TDI. Such failures would result in the unavailability of the diesel generators. The castings were manufactured by TDI between December 1978 and October 1981. The utilities reporting were: (1) Duke Power for the Catawba Nuclear Station, Units 1 and 2; (2) TVA for Hartsville

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REPRODUCED FROM THE
NRC LIBRARY FOR DISTRIBUTION
EXCEPT FOR THE
ORIGINAL PERIODIC
PUBLICATIONS~~

REPORT
NO.:

99900334/S3-01

INSPECTION
RESULTS:

PAGE 13 of 14

Nuclear Plant, Units 1 and 2, and Phipps Bend Nuclear Plant, Units 1 and 2; and (3) CP&L for the Shearon Harris Nuclear Power Plant, Units 1 and 2. This matter was also reported by TDI in a 10 CFR Part 21 report to the NRC on October 28, 1982.

The NRC inspector ascertained the following information by discussions and review of documents:

- a. The incident which prompted TDI to report was a failure of a type "-AN" piston skirt casting in early 1980. The utilities subsequently made their reports to NRC. Subsequently, TDI produced a report entitled, "Failure Analysis No. 152, Piston Skirt, P/N 03-041-02-AN," dated June 20, 1983. This report included a description of events leading up to a change in foundry heat treating practice to include fan cooling of the castings. This cooling method was determined to have resulted in high residual stresses in the castings which, when combined with operating stresses, could result in failure of the castings. The report also provided recommended corrective measures including NDE, stress relieving at 1050°F, and selective grinding of the affected castings.
- b. Review of six TDI notification letters verified that all utility nuclear units with affected diesel generators were accounted for. The letters included a list of foundry shop order numbers and serial numbers of the affected castings to aid the utilities in identifying the suspect castings. The letters also recommended that the castings be returned to TDI for NDE and stress relieving if possible, or replacement with suitable castings, and return for reinstallation. As of this inspection date, only Duke Power Company and Gulf States Utilities have returned skirt castings to TDI.
- c. Review of a current process routing for Job No. 69501 covering reprocessing of returned castings verified that corrective action was being performed under controlled conditions using process travelers, qualified personnel, and procedures. Other records reviewed for Job No. 69501 consisted of: (a) special instruction specification No. 750R; (b) a certificate of compliance; (c) a packaging and shipping notification; (d) a magnetic particle inspection report; (e) an NDE technician's qualification record; and (f) heat treatment records for Iron ASTM A-536, Grade 100/70/03 castings. The review also

ORGANIZATION: TRANSAMERICA DELAVAL, INCORPORATED
ENGINE AND COMPRESSOR DIVISION
OAKLAND, CALIFORNIA

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR CONFIDENTIALITY
INFORMATION PER 10 CFR
SECTION 2.750~~

REPORT NO.:	99900334/83-01	INSPECTION RESULTS:	SECTION 2.750	PAGE 14 of 14
-------------	----------------	---------------------	---------------	---------------

included the original master engine book of records for diesel generator S.N. 75018-2762. Within this area of the inspection, no nonconformances or unresolved items were identified.

F. EXIT INTERVIEW:

During the exit interview, at which time the inspection findings were discussed, the NRC inspectors were informed by TDI's management that they would take exception to all of the violations that had been identified during the inspection. The NRC inspector indicated that this position would be identified in the inspection report. It was determined by staff review subsequent to the inspection to defer issue of one violation which had been identified to TDI management until after performance of further inspection. This violation subject pertained to inadequate evaluation records.

DOCUMENTS EXAMINED ~~THIS DOCUMENT HAS NOT BEEN~~
~~REVIEWED FOR PROPRIETARY~~
~~INFORMATION PER 10 CFR~~
~~SECTION 2.750~~

1	2	TITLE/SUBJECT	3	
1	1	Mo 03-425-06-AG - Shaft, Water Pump	5-1-79	
2		- 03-425-07-AE - ~ ~ ~	~	
3		- 101773 - Water Pump & Bracket Assy	11-12-81	
4		- 03-425-10-AG - Impeller, 10" Dia. R.H. C.C. W	10-6-82	
5		- 03-426-08-AE - Shaft, Water Pump	10-5-82	
6		- 101769 - Retainers, Seal	11-9-79	
7		- 101773 (Layout - 9/23/81)	11-16-89	
8		- 03-426-03-AA ~ - 10/5/82	7-26-79	
9		- 03-425-10-AE (Lined through)	~ ~	
10		- 03-425-01-0F ~	5-2-80	
11		- 03-426-6770 - Water Pump & Bracket Assy	10-12-82	
12	1	PL 03-425-07-04 - Pump in Jkt with Eng. Design	5-11-81	D
13	2	Mo RL 017 000 - Impeller...	6-19-80	1
14		SIW No. S111-89 - DG Side Shanghai NPS Unit 1	10-6-82	
15	2	Mo RL 017 009 (Layout)	6-29-81	1
16	3	Div 10 CFR V P-13y	1-26-81	

Document Types:

- 1. Drawing
- 2. Specification
- 3. Procedure
- 4. QA Manual
- 5. Purchase Order
- 6. Internal Memo
- 7. Letter
- 8. Other (Specify-if necessary)

Columns:

- 1. Sequential Itc
- 2. Type of Document
- 3. Date of Document
- 4. Revision (If

THIS DOCUMENT HAS NOT BEEN

1	2	TITLE/SUBJECT REVIEWED FOR PROPHYLAXIS	3	4
17	1	As. IP 100 - In Progress Inspection	4-1-81	5
18	1	Engng. Proj. Panel 1 - Communication and Responsibility	4-20-81	
19	1	Engng. Proj. Panel 1 - Communication and Responsibility	4-13-79	
20	1	Off. Engng. Panel 1 - Design Group	2-27-81	
21	1	Section of Drafting for Panel - Route Sheet	11-13-81	
22	1	Section of Drafting for Panel - Layout	1-17-79	
23	1	Section - Instructions, Panel, Drafting - 16-00 Panels, 10-1 Panels	2-27-81	
24	6	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	7-16-79	
25	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	11-11-79	
26	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	10-26-82	
27	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	10-13-82	
28	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	15-19-82	
29	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	9-20-77	
30	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	1-28-80	
31	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	2-25-80	
32	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	3-10-80	
33	1	Co. G. C. Inman, Co. G. C. Inman, Lt. Col. G. C. Inman	9-21-81	

THIS DOCUMENT HAS NOT BEEN REVIEWED FOR PROPHYLAXIS

SECTION 7.790

- Document Types:
1. Drawing
 2. Specification
 3. Procedure
 4. Manual
 5. Purchase Order
 6. Internal Memo
 7. Letter
 8. Other (Specify, if necessary)

- Columns:
1. Sequential Item
 2. Type of Document
 3. Date of Document
 4. Revision (If any)

Inspector W. E. Foster

Scope/Module Environmental Response

DOCUMENTS EXAMINED

Deck of No. 11:
Report No. 03-
Page 1 of 2

~~THIS DOCUMENT HAS NOT BEEN
REVIEWED FOR CONFIDENTIALITY~~

	2	TITLE/SUBJECT	3
47	6	Mail Requisition - Ord No. W-11147	11-11-77 11-2-77
52		Certificate of Compliance To LITCO for P.O. # 110552	11-12-77 11-9, 11, 10-11
53		Water Staff Evidence Analysis Report Nov. 11, 76	9-22-82
54		Exp. Costs for DU Pop. Reduction in 1977	
55		Assembly Introduction 10-4756	9-27-87
56		Request for Quoting Action - DU Pop. for LITCO	10-15-82
58	8	Duty Chg. Notice for Arny. Eschbacher, Water Pop.	11-6-79 2-17-82

Document Types:

1. Drawing
2. Specification
3. Procedure
4. Other (Specify-if necessary)

Document Types:

5. Purchase Order
6. Internal Memo
7. Letter
8. Other (Specify-if necessary)

Columns:

1. Sequential No.
2. Type of Document
3. Date of Document
4. Revision (If any)

~~THIS DOCUMENT HAS NOT BEEN REVIEWED FOR PROPRIETARY INFORMATION PER T-19-6HR~~

1	2	TITLE/SUBJECT	3	4
1	4	TDI's SA Manual, Rev. 3, 3rd Edition Sections 4.7, 14 & 15	6-10-83	2
2	7	TDI's Amendment letter to their WCFR Part 21 report dated 6-23-82.	7-18-82	N/A
3	7	TDI's WCFR Part 21 notification letters to 10 customers concerning the generic coupling defect	8-18-82	"
4	8	Minutes of TDI's "APT" committee meeting on June 15 and 22, 1982	-	"
5	3	TDI's "Division WCFR 21 Policy" reporting procedure	1-26-81	"
6	2	TDI's "Purchased Material Specification" for Couplings - Elastomeric for Part No. AK-007-CW	4-25-83	C
7	8	TDI's Change Notices A, B, & C for the above specification	various	N/A
8	8	TDI's "Vendor Inspection Report" receiving inspection record card for Hoppers Company (couplings)	-	"
9	6	Following TDI purchase orders to Hoppers Company for couplings and flexible elements: - P.O. 13185; P.O. 12838; P.O. no. 12244 and P.O. 49263	various	"

- Document Types:
1. Drawing
 2. Specification
 3. Procedure
 4. QA Manual
 5. Purchase Order
 6. Internal Memo
 7. Letter
 8. Other (Specify if necessary)

Columns:

1. Sequential Item No.
2. Type of Document
3. Date of Document
4. Revision (if appl)

scope/Module 2.1's WCFR Part 21 Report
Piston Skirt Casting Stress

REPORT NO. 200-2
 THIS DOCUMENT HAS BEEN REVIEWED FOR PROPRIETARY INFORMATION PER TO CFP. SECTION 2.7.90

DOCUMENTS EXAMINED

1	2	TITLE/SUBJECT	3	4
1	8	TDI's "Failure Analysis No. 152, Piston Skirt" report for P/N 03-341-02-AN.	6-30-83	NA
2	7	TDI's 10 CFR Part 21 notification letters to six electric utility customers concerning diesel generator piston skirt casting potential problem due to stress.	11-18-82	"
3	8	Master Engine Book records for SN 75018-2762		"
4	8	Production Routing traveler for Part 1A-6552, sec. Job No. 69501	various	"
5	8	Nuclear Packaging Shipping Notification, Job No. 69501	6-16-83	"
6	8	Certificate of Compliance, Job No. 69501		"
7	8	Magnetic Particle Inspection Report, Job No. 69501, Part 03-341-02-AN	5-17-83	"
8	2	Special Instruction Specification No. 750A	2-7-83	"
9	8	Heat Treating Record for Iron ASTM A-536, Gr. 10070 f03, Job No. 69501.	5-18-83	"
10	8	Hardness Verification Report, Job No. 69501		"
11	8	Qualification record for NDE Technician AE. Clampett	11-6-81	"

Document Types:

1. Drawing
2. Specification
3. Procedure
4. QA Manual
5. Purchase Order
6. Internal Memo
7. Letter
8. Other (Specify if necessary)

Columns:

1. Sequential Item #
2. Type of Document
3. Date of Document
4. Revision (If appl)

1	2	TITLE/SUBJECT	3	4
1	4	Organizational chart.	1-5-83-	
2	1	Manual Revision 4.4.5	F-22-83	
3	1	NO 102 367	9-17-81	
4	0	Prints Dist 02-415-02-01	1-5-83	Rev 1
5	7	Seller Re: Breaks - Skipt.	Sept 13, 1982	
6	8	Casting Certificates Part No. 03-310-05-AK	" " "	
7	8	Material Test Report. ABS	Oct 11-81	
8	8	Assembly - Test Route Sheet.	2-17-81	
9	4	Section B - Identification / Control of Material.		
10	5	PO 45-333-		
11	4	Section 4. Inspection Section -	8-21-81	
12	3	Procedure 1 P 2.00 Shipping & Receiving MRP-	4-1-81	
13	2	Design Specifications - NO 45-333		
14	8	Audit Report TVA. 81V-49 -	12-1-3-81	
15	4	TVA - TDI.	1-16-82-	
16	7	TVA - TDI	2-2-82	
17	7	TVA - TDI	5-25-83	
18	7	TVA - TDI.	6-25-82-	

Columns:
1. Sequential Item Number
2. Type of Document
3. Date of Document
4. Revision (If applicable)

Document Types:
1. Drawing
2. Specification
3. Procedure
4. QA Manual
5. Purchas Order
6. Internal Memo
7. Letter
8. Other (Specify-If necessary)

ATTACHMENT 8

Delaval Diesel Generator Operation Experience

U. S. Nuclear Experience

In 1974, the Long Island Lighting Company (LILCo) contracted with TDI to purchase three emergency diesel generators for the Shoreham Nuclear Power Station. This was the first order received by TDI to provide an EDG for a commercial nuclear power station. In the next seven years, engines for 14 other plants were ordered from TDI.

San Onofre 1

- ° Two TDI Diesel Engines Installed in 1976 - DSRV-20
- ° Serial No. 75041/42, Rated at 6000KW (nominal)
8800KW (peak)
- ° Engine Run Time to Date - 450 hours per engine

The first plant to actually place a TDI engine into nuclear service was San Onofre Unit 1 (SONGS 1), which purchased two V-20 units to provide emergency power for its feed pumps, which also serve as Emergency Core Cooling System pumps.

The engines at SONGS 1 were installed in 1976, and declared operational in April 1977. Since then, SONGS has experienced some problems with the operation of the engine turbochargers, a lube oil pressure sensing line failure which resulted in a fire, and several other minor problems. Because SONGS did not commit to meet the guidelines of Regulatory Guide 1.108, but rather Regulatory Guide 1.9, the program it used to test the engines before they were placed in service was more abbreviated than for a new plant. A detailed list of problems to date follows.

<u>Date</u>	<u>Problem</u>	<u>Cause/Solution</u>
12/80	Excessive Turbocharger thrust bearing wear.	No lube oil during standby. Lube oil system modified. 10 CFR Part 21 report issued because problem generic.
7/81	Lube oil leak and fire.	Excessive vibration of a lube oil test line which had inadvertently been left installed by the licensee. Line removed.
12/81	Piston modification to prevent crown separation.	Pistons reworked by TDI to respond to Part 21 report. Problem identified at Grand Gulf.
9/83	Unqualified instrument cable.	Replaced in accordance with Part 21 report.

Grand Gulf

- ° Two TDI engines installed - Model DSRV-16
- ° Serial No. 74033/34, Rated at 7000KW
- ° Operating Hours to Date - Division I = 1100 hours; Division II = 700 hours

In 1981, Mississippi Power & Light (MP&L) commenced pre-operational testing of two V-16 engines installed at Grand Gulf Unit 1. They represent the first V-16 units ordered from TDI, and in fact, one of the Grand Gulf engines was used to qualify the entire TDI V-16 line of machines for nuclear applications.

The Grand Gulf engines have experienced significant problems in completing the pre-operational test program, have had several major failures, including a fuel line break which caused a fire, and many minor failures. A detailed list of problems at Grand Gulf follows.

<u>Date</u>	<u>Problem</u>	<u>Cause/Solution</u>
11/81	Piston crown separation during operation.	Holddown studs failed. Pistons returned to TDI for rework. Generic problem.
3/81	Excessive turbocharger thrust bearing wear.	No lube oil during standby. Lube oil system modified.
5/11/82	Air starting valve capscrews replaced. Too long for holes.	Response to Part 21 report.
8/23/82	Flexible drive coupling material incompatible with operating environment.	Replaced with different material.
8/82	Latching relay failed during testing.	Relay replaced.
3/8/82	Air start sensing line not seismically supported.	Sensing line relocated and properly supported.
1/29/82	Governor lube oil cooler located too high. Possibility of trapping air in system.	Lube oil cooler relocated to lower elevation.
3/23/82	Engine pneumatic logic improperly design. Could result in premature engine shutdown.	Pneumatic logic design corrected.

<u>Date</u>	<u>Problem</u>	<u>Cause/Solution</u>
4/29/81	Non-Class 1E motors supplied with EDG auxiliary system pumps.	Motors replaced with Class 1E qualified motors.
3/15/82	Crankcase cover capscrew failed. Head lodged in generator and shorted it out.	Capscrews replaced with higher strength screws. Lock tab washers installed. Generator screens installed.
8/2/83	High pressure fuel injection line failed.	Manufacturing defect in tubing. Tubing replaced.
9/4/83	Fuel oil line failed. Caused major fire.	High cycle fatigue of Swagelock fitting. Additional tubing supports to be installed.
8/11/83	Cracks in connecting push rod welds.	All push rods replaced.
1983	Turbocharger vibration.	Turbocharger replaced.
1983	Cracked jacket water welds.	Excessive turbocharger vibration. Cracks re-welded.
1983	Turbocharger mounting bolt failures.	Excessive turbocharger vibration. Bolts replaced.
7/83	Air start valve failures.	Cause unknown. System cleaned and several valves replaced. More frequent maintenance scheduled.
10/28/83	Fuel oil leak. Cracked push rod weld.	Tubing replaced. Push rod replaced.
During EDG Installation	Cylinder head cracks.	Head replaced.
12/83	Cylinder head cracks.	Two heads replaced.
12/83	Cracks in piston skirts on Division II EDG.	All Division II pistons replaced. Division I pistons to be inspected.
9/83	Unqualified instrument cable.	Replaced in response to Part 21 report.

Shoreham

- Three TDI Diesel Engines installed, Model DSR-48
- Serial No. 74010-12, Rated at 3500KW
- Operating hours at time of crankshaft failure (8/83)
 - #101 = 646 (cracked crankshaft)
 - #102 = 718 (failed crankshaft)
 - #103 = 818 (cracked crankshaft)

The engines at Shoreham are the first straight-8 units to be placed in nuclear service in the U. S. One of the Shoreham engines (#101) was used to qualify the straight-8 series (R48) diesel engine for nuclear service.

Pre-operational testing of the engines at Shoreham started in late 1981 and continued until the major failure of the #102 crankshaft on August 12, 1983. After the performance of extensive tests in late September and early October, which were observed by staff members from NRR and Region I, as well as an NRC consultant, LILCo presented the results of its crankshaft failure investigation in a meeting on November 3, 1983. It reported that the crankshaft had been improperly designed, and had failed because the loading function used in the original design calculations was too small. LILCo also reported that it was investigating four failed connecting rod bearings which were discovered when the EDGs were disassembled. Their preliminary finding was that the failures occurred because the bearing material did not meet specifications, and the bearing loads had not been properly accounted for. A detailed list of the EDG problems at Shoreham follows.

<u>Date</u>	<u>Problem</u>	<u>Cause/Solution</u>
3/81	Excessive turbocharger thrust bearing wear.	No lube oil during standby. Lube oil system modified.
12/81	Piston modifications to prevent crown separation.	Pistons reworked by TDI to respond to Part 21 report. Problem identified at Grand Gulf.
9/82	Engine jacket water pump modifications.	Water pumps reworked by TDI.
6/82	Air starting valve capscrews replaced. Too long for holes.	Response to Part 21 report.
9/82	Engine jacket water pump shaft failed by fatigue.	Pump shafts redesigned and replaced.
Spring/1983	Cracks in engine cylinder heads.	Fabrication flaws. All heads replaced.

<u>Date</u>	<u>Problem</u>	<u>Cause/Solution</u>
3/83	Two fuel oil injection lines ruptured.	Manufacturing defect in tubing. Tubing replaced with shielded design.
3/83	Engine rocker arm shaft bolt failure.	High stress cycle fatigue. Bolts replaced with new design.
8/12/83	Broken crankshaft. Cracks in remaining crankshafts.	Inadequate design. Replaced with larger diameter crankshafts.
9/83	Cracked connecting rod bearings.	Inadequate design and substandard material. Replaced with new design.
10/83	Cracked piston skirts.	Replaced all piston skirts with new design. Generic problem.
11/83	Broken cylinder head stud nuts.	Replaced all head stud nuts.
9/83	Cracked bedplates in area of main journal bearings.	Cracks evaluated by LILCo and determined to not be significant.
9/83	Unqualified instrument cable.	Replaced in response to Part 21 report.

Operating Experience - Non-Nuclear

Marine Applications

Besides being used for stationary electric power generation, TDI diesel engines have been placed in service as propulsion units on commercial cargo vessels. As part of the Shoreham operating license hearing, an intervenor, Suffolk County, requested and was granted by the Licensing Board, subpoenas for the State of Alaska, U. S. Steel, and Titan Navigation, Inc. These three organizations operate vessels which use TDI V-16 diesel engines which are very similar to most of the TDI units installed in nuclear power plants. The responses which were received indicate that the TDI engines in marine service for these organizations have experienced severe reliability problems. Most have related to faulty cylinder heads, but they have also included problems with pistons, cylinder liners, turbochargers, cylinder blocks, connecting rods, connecting rod bearings, main journal bearings, and camshafts. A detailed experience list follows. The staff is reviewing this material to see how much of it is applicable to engines in nuclear service.

Marine Experience with TDI Diesel Generators

State of Alaska, M. V. Columbia

- Vessel fitted with two DMRV-16-4 Engines - Serial No. 72033/34
- Rated at 9200 HP (6900 KW) at 450 RPM
- Vessel and engines placed in service in June 1974.
- Each engine has approximately 30,000 hours of operating time to date.

Document Date

Problem Description

12/76

All cylinder liner seals replaced. All cylinder heads have been removed, reinstalled, or renewed at least three times.

All pistons have been removed and reinstalled at least once.

Turbochargers have been removed, repaired and reinstalled, or renewed 16 times due to leaking oil seals, vibration, rotor damage, or defective bearing seal housing.

Exhaust manifolds have been removed and reinstalled because of frozen expansion joints and resulting cylinder head flange face damage.

Lube oil consumption is excessive.

6/15/78

Rapid deteriorations of fire seal rings causing blowby across gasket surface of cylinder heads.

Very low lube oil filter life (40 hours). Caused by blowby of pistons and valve guides.

Stainless steel exhaust bellows burn out rapidly. Installed backwards by TDI.

11/28/78

(Letter to Alaska from TDI).

Recommends timing changes to improve turbocharger performance.

Document Date

Problem Description

1/31/79

Valve seats and valve guides not concentric. Results in bad valve contact.

Defective piston rings shipped as replacement parts.

Reworked cylinder head received from TDI without all required modifications and with damaged gasket face.

Newly furnished cylinder liners received with incorrect surface finish (twice).

Connecting rod bearings furnished as spare parts were wrong size - 13" vice 12".

Turbocharger exhaust flex section incorrectly furnished by TDI.

2/2/79

Chrome plating failure of piston rings. Caused heavy scoring of cylinder liner. Associated cylinder head found cracked.

Seven cylinder heads replaced during 15 weeks of operation.

Excessive lube oil filter change out rate. Due to piston blowby.

Fuel injector spray tips changed at TDI recommendation to reduce carbon buildup and eliminate washing of liner walls with fuel oil.

Three major overhauls of engines in 5 years of operation.

Carbon accumulations in rocker box areas.

Excessive oil vapor discharge from engine crankcases.

Heavy carbon deposits on valve springs. Suspect valve blowby.

When exhaust valve guides were modified by TDI, they did not follow the procedure outlined in their SIM (Service Information Memo).

Document Date

Problem Description

	Loose piston pin end caps.
	Incorrect piston crown to skirt bolt torque.
	Bad connecting rod bearings. Excessive wear, cracks.
	Damaged connecting rod bolts.
	Valve push rods cracked at weld of ball to pipe. QC problem.
	Crankshaft size changed after engines for ship installed. No notice to owners of reason for change.
	Excessive main bearing wear.
	Camshaft lobe hard facing worn.
	TDI recommended the installation of a new flexible exhaust duct which was too short (new design). Installation attempted at insistence of TDI. Unit damaged by attempt and returned to TDI for repair.
3/19/79	QC or material problems with respect to non-concentricity/out-of-round valve seats, push rods, rod bolts, bearing shells, valve stem plating.
6/14/79	Thermal growth and cracking of exhaust manifold.
12/26/79	Failure of new connecting bearings. Cracks of 25% of connecting rods.

Document Date

Problem Description

1/16/80

Ten (10) new cylinder heads have cracks. This includes 8 that were previously repaired.

Fifteen (15) valves are defective with chrome flaking off the valve stems.

Valve stems are being deformed.

Five additional push rods have cracks.

Turbocharger air cooler inlet housing is cracked for fourth time.

Internal bracing in engine intercoolers is cracked.

2/5/80

Piston rings installed improperly because mistake by TDI in the drawing used by TDI shop.

2/29/80

Piston crown-to-skirt nut torque inconsistent among nuts on various pistons.

Excessive link rod bushing bail wear caused by improperly relieved, drilled oil passages on the matching link rod pins.

3/24/80

Abnormal carbon deposits and formations noted on pistons and cylinder head assemblies.

Fretting of jaw areas of connecting rods.

Insufficient turbo (manifold) air except at near full speed operation.

Cracked exhaust manifold end plates.

Cracking of connecting rod boxes.

Cracking of newly installed connecting rod bearing shells at 4500/hours.

Document Date

Problem Description

Fretting of link rod and link rod pins at their attachment together.

Fretting between link rod bushings and link rod bushing bore.

Galling of link rod bushings in way of link rod pin outer drilled oil passages.

Improper wear/contact pattern on newly installed connecting rod bearings at 4500/hours. Four-point loading.

Insufficient connecting rod bearing wear/contact area to journal wherein it is less than 15% of the total bearing area.

Upsetting of stems in valve keeper area.

Damage to number four piston ring and ring groove on all pistons modified during the 1978-79 engine teardown and rebuilt after 4500/hours operation.

Fretting between piston crown and skirts at 4500/hours since piston modifications.

Variations in piston bolt torque, beyond specified limits, at 4500/hours since piston modifications.

Damage to rod bolts, including cracking, and damage to threads on both the bolt and in the rod boxes.

4/18/80

Exhaust manifold conversion kits received with cuts and grooves in finished surface. Required rework by owner before installation.

5/12/80

New connecting rods received without required code (American Bureau of Shipping) approval. TDI did not have record of which rods were shipped with approval or without approval.

Some new connecting rods shipped with oversize bearings but no note to customer informing of difference.

<u>Document Date</u>	<u>Problem Description</u>
5/14/80	Cylinder head returned to TDI has been lost by TDI. Cannot be located.
5/15/80	Customer received new connecting rod bolt in rusty condition with damaged threads.
5/27/80	Customer received reworked cylinder heads with lip left on exhaust seats which prevents valves from seating. Customer noted that it now was in possession of two cylinder heads with the same serial number. Could not install lockwire in new connecting rod cap screw. Hole drilled partway through with drill broken off in center of hole. Also noted that edges of lockwire holes on other screws had not been rounded to prevent damage to lockwire.
5/29/80	Discovered leaks in newly installed exhaust manifold head plates.
9/4/80	(Meeting Summary) TDI says that all cylinder head problems should be corrected by new design. TDI reports that connecting rod bearing cracks could have resulted from bad bearing alloy makeup by vendors. TDI looking at different bearing materials. TDI stated that they had erred on piston modifications. Effected others besides COLUMBIA.
9/30/80	Eleven remaining master connecting rods to be sent to TDI to have oversize bearings and other modifications installed. Many of the original cylinder heads that were returned to TDI for rework were exchanged for other used heads.

Document Date

Problem Description

11/6/80

Cylinder head changed due to heavy external water leakage.

Severe smoke causing excessive lube oil contamination and engine room atmosphere problems. Engine secured to prevent possible crankcase explosion.

12/10/80

All connecting rods removed. New rod cap screws and washers to be installed because increased torque specified by TDI caused galling.

New connecting rod bearing shell found cracked.

Heavy wear noted on piston side thrust areas. Heavy hard carbon buildup noted in area of compression rings. Fourth ring groove area to be reworked by TDI due to design/machine error by TDI during previous modifications.

Nineteen (19) of 32 cylinder liners exceed spec for out-of-round. TDI to modify limits to permit continued usage.

Twenty-one (21) of 32 liners lost crush. New phenomena. Repairs require machining of engine block.

Fuel injectors removed and to be changed from 140° spray pattern to 135° pattern. Original nozzles had 150° pattern.

1/16/81

Cylinder block bores found to be distorted.

Four new engine camshafts installed.

Document Date

3/13/81

Problem Description

Reworked cylinder heads were returned to the customer without removing the grinding compound from the valves and valve seats.

Two reworked pistons returned to customer without roll pins, which lock the securing nuts in place.

Cylinder liner delivered with wrong surface finish.

Cracks found in cylinder blocks. All replaced.

Main engine blocks found to be cracked and warped. The main block-to-base through bolts appear to have been improperly torqued during initial assembly.

One "new" camshaft found to be a rebuilt unit containing several damaged bearing journal areas.

The threaded head stud holes in the new cylinder blocks were not counterbored deeper, as TDI had indicated they currently do. This was to eliminate cracking of the block near the stud holes. The customer re-machined each of the 256 head studs to accomplish the same intent.

4/9/81

Several reworked pistons were returned without groove pins.

In response to a request for 20 1½" capscrews and washers, TDI supplied 1 7/8" capscrews.

Drawings furnished by TDI for head stud modifications were not applicable to the studs in question.

50% of the fuel pump bases would not fit onto the new cylinder blocks because of slight changes in the design of the blocks.

Document Date

Problem Description

4/29/81

Two new cylinder liners provided with incorrect surface finish.

One new cylinder liner provided with flange thickness larger than manufacturer's maximum tolerance.

New connecting rod capscrews were found to be galled and unfit for use.

Service manual showed incorrect installation of engine camshafts.

2/3 of fuel cam tappet assemblies on one engine could not be installed on one engine because the new cylinder blocks had not been properly counterbored.

Cylinder liner counterbore depths were off to such an extent that difficulty experienced in establishing proper liner crush.

Weld spatter noted on many seating surfaces.

Dirt, sand, and metal showings found in passages and holes which should have been clean.

Cylinder head water port outlet locations varied considerably, causing a water flow restriction.

Air start distributor not properly assembled at factory.

6/1/81

Exhaust manifold head plate developed a leak. Cracks found around 2 of 3 tie rods due to poor initial welding.

11/19/81

Defective valve springs found on one engine.

7/29/82

Valve rotator failed.

Cracks discovered in the intercooler.

Document Date

Problem Description

7/29/82

"In nine years of operation every basic engine component has been modified or replaced with an improved item, at least once, with the exception of the crankshaft (which is obsolete and has not been used for years), the engine base, the fuel pumps and the governor. The last two items are not manufactured by TDI."

10/15/82

Turbochargers replaced.

Exhaust valve lubricating system to be installed.

3/9/83

Cracks discovered in three cylinder heads.

Reworked cylinder returned to customer with tap broken off in threaded hole. Others returned with internal cracks and damaged flange faces.

Titan Navigation, M. V. Pride of Texas

- Vessel fitted with two DMRV-12-4 engines, Serial No. unknown
Rated at 7800 HP at 450 RPM
- Engines installed 1981 - no information on total engine hours to date.

Document Date

Problem Description

7/16/82

Catastrophic piston failure. Due to crack in piston skirt. Engine had 5791 hours of operation.

4/1/82

Cylinder block broken and cracked.

Cylinder head cracked.

Cylinder liner cracked.

Piston skirt fractured.

Suspect that all of above problems caused by water leaking into cylinder from air intake manifold. Leaking tubes found in air intercooler.

8/19/82

Cracks discovered in six piston skirts.

7/22/82

Cracked exhaust valve seats in cylinder heads. Engine had 3000 hours service.

Camshaft lobe design appears to be deficient. Causes excessive stress on fuel cam lobe and roller.

Tappet assembly rollers severely galled. Believed to be due to camshaft and lobe placement and inadequate heat treatment.

Fuel cam lobes have failed twice due to improper heat treatment.

Chrome plating lost from one piston wrist pin.

All four intercoolers have failed because of erosion due to high fluid velocity.

Air start valves have suddenly ceased to function, for no apparent reason.

Document Date

Problem Description

4/1/83

Plugs in crankshaft oil ways may be cracking because improper material used. Under investigation.

Fuel oil return lines have failed. To be replaced with heavier wall tubing.

Exhaust valves fail after about 2000 hours of use. Serious problems with cylinder head cracks.

Turbochargers experiencing difficulty supplying sufficient air.

U. S. Steel, MV E. H. Gott

- Vessel fitted with two DMRV engines (model unknown)
Engine Serial No. 75039-40
- No information on engine hours to date.

<u>Document Date</u>	<u>Problem Description</u>
11/13/80	Cracked cylinder head. Replaced.
11/1/79	Cracked cylinder head. Replaced.
6/1/80	Cracked cylinder head. Replaced.
10/8/81	Cracked cylinder head. Replaced.

Note: This information was summarized from documents provided by U. S. Steel in response to a subpoena which asked specifically for information about cylinder head failures. Many other portions of the documents were deleted by U. S. Steel, and it appears that the deleted portions referred to problems with other engine parts.

Other Applications

The staff understands that other TDI engines are in service as stationary electric power generators. The operating history of these engines will be taken into consideration during the staff assessment of TDI engines.

Reference List

Shoreham

Letter dated 1/6/84 from B. McCaffrey (LILCo) to H. Denton (NRC)
Board Notification 83-160 dated 10/21/83
Board Notification 83-160 dated 11/17/83
Letter dated 12/9/83 from J. Smith (LILCo) to T. Muley (NRC)
Letter dated 12/9/83 from A. Schwencer (NRC) to M. Pollock (LILCo)
Letter dated 12/29/83 from A. Schwencer (NRC) to M. Pollock (LILCo)
Letter dated 12/16/83 from C. Matthews (TDI) to T. Novak (NRC)
Letter dated 12/16/83 from J. Smith (LILCo) to T. Murley (NRC)
Letter dated 12/16/83 from A. Dynner (Suffolk County) to A. Earley (LILCo)
Letter dated 10/20/83 from A. Earley (LILCo) to L. Brenner (NRC)
Letter dated 10/16/83 from R. Boyer (TDI) to NRC
Letter dated 11/17/83 from A. Earley (LILCo) to L. Brenner (NRC)
IE Information Notice 83-51, dated 8/5/83
IE Inspection Report 99900334/83-01, dated 10/3/83
IE Information Notice 83-58, dated 8/30/83

Grand Gulf

Letter dated 11/15/83 from L. Dale (MP&L) to H. Denton (NRC)
Letter dated 10/19/83 from L. Dale (MP&L) to H. Denton (NRC)
LER 50-416/83-171/03L-0 dated 11/28/83
Letter dated 10/26/83 from L. Dale (MP&L) to H. Denton (NRC)
LER 50-416/83-082/01T-0
LER 50-416/83-126/01T-0

San Onofre Unit 1

LER 50-206/81-017 dated 8/12/81

Letter dated 9/15/81 from H. Ray (SCE) to R. Engelken (NRC)

LER 50-206/80-039 dated 12/23/80

Letter dated 6/8/81 from J. Haynes (SCE) to R. Engelken (NRC)

Marine Applications

Letter dated 12/21/83 from A. Dynner (Suffolk County) to A. Earley (LILCo)

Includes many other individual documents.

ATTACHMENT 9

Vendor Inspection History

To date, the Region IV Vendor Inspection program has inspected the TDI facility in Oakland, California, nine times. The following inspection reports have been published in the PDR regarding these inspections:

1. Docket No. 99900334/79-1, dated 3/20/79
2. Docket No. 99900334/80-01, dated 1/22/81
3. Docket No. 99900334/81-01, dated 5/27/81
4. Docket No. 99900334/81-02, dated 9/18/81
5. Docket No. 99900334/82-01, dated 4/15/82
6. Docket No. 99900334/82-02, dated 12/8/82
7. Docket No. 99900334/83-01, dated 10/3/83

Attached is a summary by the Vendor Inspection Branch of the TDI inspection history. The history includes some results from the last two inspections, which are being reviewed for proprietary information, and which will be published when that review is complete.

TRANSAMERICA DELAVAL INSPECTION HISTORY
VENDOR PROGRAM BRANCH FINDINGS 1979-1983MANUFACTURING PROCESS CONTROL:

1. Performance of required inspections for completed operations on Shop Engine No. 2931 Tank Lube Oil Sump Inlet Compartment could not be verified, in that neither inspection acceptance stamps were present on the route sheets for the completed operations nor were inspection reports available to indicate rejectable conditions had been found upon inspection.
2. Route sheets were not available to confirm required inspection acceptance of assembly operations for the emergency diesel generator (EDG) jacket water pump reflected on Drawing No. 101973, Revision C.
3. Absence of evidence of inspection acceptance for components manufactured during jacket water pump modifications performed in September and October 1982.
4.
 - a. Acceptance signoff by QC inspectors was made on route sheets in regard to installation of rocker arm hold down bolts. These bolts were subsequently found to be missing on inspection at the Shoreham Nuclear Power Station (SNPS).
 - b. Shipment of reworked pistons to San Onofre, Unit 1, prior to dates indicated on route sheets by QC inspectors that various manufacturing operations were accepted.
5.
 - a. Route sheets not issued for rework of 92 pistons from SNPS and Grand Gulf EDGs and there is, thus, no evidence of inspection acceptance of the various manufacturing operations.
 - b. No records of quality activities for rework activities on Grand Gulf EDG pistons which was a specific requirement of the procurement specification.
6. Absence of required NDE reports for SNPS replacement cylinder head castings.
7. Apparent use of unqualified personnel for performance of NDE operations on SNPS replacement cylinder head assemblies.
8. Improper signoffs and dates for acceptance of SNPS replacement cylinder heads with respect to personnel identity and use of a surrendered inspection stamp prior to expiration of the minimum 6-month period.
9. Use of a different hard facing welding procedure specification to that specified on the route sheets for valve seats in SNPS replacement cylinder head assemblies.
10. Requirements not provided for welding of and acceptance of Shearon Harris EDG fuel oil line clamps.

11. Prior to October 1981, manufacture of piston skirt castings did not comply with engineering component drawing instructions with respect to performance of specified stress relief heat treatment.
12. Route sheets for Job No. 02933 did not provide instructions in regard to swaging operations performed on crankshaft oil plugs.
13. No assembly route sheets available for SNPS replacement cylinder head assemblies.

CONTROL OF SPECIAL PROCESSES:

1. Absence of procedures for examination of Level III NDE personnel and failure to qualify personnel performing visual examinations in accordance with ASME Code requirements.
2. a. Performance of vertical up position welding on ASME Section III piping (Shop Engine No. 2931, Shop Order No. 94302) by welder qualified only for flat position welding.
b. Welding of a 2-inch ASME Section III piping assembly by unqualified welder.
3. Observations during three different inspections of failure to return unused welding electrodes in required 4-hour issuance period.
4. Identification of welders used for certain operations on Shop Engine Nos. 2931 and 2959 could not be verified.
5. Unacceptable fillet weld size in Shop Engine No. 2931 Tank Lube Oil Sump Inlet Compartment due to bad fitup of tank roof and sidewall resulting in almost flush condition.
6. Use of welding electrode sizes that were not permitted by applicable welding procedure specifications on Job Nos. 94922 and 96632.
7. Use of Job No. 95395 of welding amperage and voltage in excess of welding procedure specification requirements.
8. Performance of welding on Job Order No. 97-485-3085 without specified revision of welding procedure specification being in welder's possession.
9. Certification records for nondestructive examination personnel did not indicate the use of ten checkpoints by the examiner during the practical examination as required by SNT-TC-1A and internal procedures.

PROCUREMENT CONTROL:

1. Failure of Quality Engineering to both update Qualified Suppliers List every 3 months and to provide a monthly summary of vendor quality ratings to QC and Purchasing.

2. Evidence not available to assure that the seller of auxiliary lube oil and jacket water pump motors complied with the requirements of the purchase order.
3. Betts Spring Company, a supplier of critical valve springs, had not been surveyed every 3 years. The available evidence showed it was approximately 5 years since a survey had been made.
4. Associated Spring Company (Barnes Group) was placed on the Approved Suppliers List and used for procurement without completion of a survey or audit.
5. Kobe Steel Ltd., a supplier of crankshaft, was not surveyed every 3 years as required by the quality assurance program. The only available record was a self-evaluation survey form completed by Kobe Steel's American representative.
6. Fuel oil tubing for Purchase Order No. 45333 was accepted by receiving inspection without issue of a nonconformance report, although required mill test reports had not been received.
7. Purchased Material Specification No. RL 019000 dated October 6, 1982, was not approved as required by Engineering Operating Procedure 7.
8. A QA program was not imposed on the manufacturer of exhaust silencers for EDGs furnished to Perry, Units 1 and 2, as required by Perry Specification Nos. SP-750-4549-00 and SP-706-4549-00.
9. Purchased material specifications for engine mounted electrical control cables required only commercial grades of cable and did not invoke applicable customer specification requirements.
10.
 - a. No available evidence to indicate that materials which were used to fabricate EDG ASME Section III Code Class 3 component supports (Midland) and fuel oil systems (Midland and Grand Gulf) were procured from vendors who were either identified on the Approved Suppliers List or had been subject to audits.
 - b. Prior to 1982, ASME Section III Code fasteners were procured from vendors who had neither been audited nor were identified on the Approved Suppliers List as being approved for supply of this product.
11. Acceptance by receiving inspection of ASME Section III Code fastener certifications which did not comply with purchase order requirements with respect to: (a) conformance of chemical composition to material specification requirements, (b) completeness of mechanical test data, and (c) compliance with ASME Section III Code requirements for reporting of material heat treatment.

12. Failure to comply with testing requirements of paragraph NCA-3867.4(e) in the ASME Section III Code when purchasing stock materials from unsurveyed vendors.

MATERIAL IDENTITY AND CONTROL:

Eleven discrepancies in material identity observed in a sample of 45 between the identity of material issued and that recorded as being used for Midland EDG S/N 77002 piping system component supports.

DESIGN AND DOCUMENT CONTROL:

1. Failure to comply with Division Standard Practice Nos. 4.101 and 4.201 requirements with respect to:
 - a. Release of a drawing revision to the shop without receiving approval of the applicable Engineering Change Notice from Industrial Engineering.
 - b. Maintenance of the Engineering Change Log, classification of changes as major or minor, and initiation of required forms.
2. Parts list and component drawings released by Engineering did not define acceptance criteria for installation of crankshaft oil plugs.
3. Absence of any instructions in regard to installation location of governor lube oil cooler to engine.
4. Failure to comply with Drafting Room Practice during 1982 redesign of the EDG jacket water pump in regard to certain layout drawings not being either drawn on tracing paper or signed and dated.
5. Dynamic analysis or testing not performed in accordance with Stone & Webster Specification No. SHI-89 after redesign of the SNPS EDG jacket water pumps.
6. Failure to comply with Engineering Operating Procedure 4 and Drafting Room Practice requirements with respect to signing and dating of calculations by the designer for the SNPS jacket water pump redesign.
7. No evidence of required approval of "D Sheets" by the applicable Engineering manager. Examples noted were D-4986 and D-4956 which were entitled, "Assembly Instructions," and pertained to the EDG jacket water pump.
8. Jacket water pump analyses dated September 24 and October 4, 1982, and July 15, 1983, for SNPS had not received required certification from the staff Registered Professional Engineer.

NONCONFORMANCES AND CORRECTIVE ACTION:

1. No evidence to indicate that required quarterly submittal of completed corrective action activity to the Division General Manager had ever been accomplished.
2. Failure of Quality Engineering to process a required Corrective Action Request Form after customer identification of TDI failure to meet weld quality requirements in ASME Section III Code Class 3 diesel generator piping.
3.
 - a. Removal and replacement of a defective weld in Shop Engine No. 2931, Part No. 02-717-02YR, without required rejection and documentation on an Inspection Report.
 - b. Disposition of a dimensional nonconformance on Shop Engine No. 2931, Part No. 02-540-07-B7, made by QC supervision without required submission of the Inspection Report to the Material Review Board for review.
4. Failure to comply with ASME QA Manual requirements with respect to immediate identification of nonconforming items on Inspection Reports and segregation of the items.
5. Weld shop audit not performed in the fall of 1981 in accordance with corrective action commitments made to the NRC.

EQUIPMENT CALIBRATION:

1. Actual calibration measurements for micrometers and a pressure gage were not recorded as required by Quality Control Procedure No. IP-100.
2. Gage used to measure, accept/reject the diameter and depth of the link rod dowel counterbore had not been identified in accordance with QA program requirements for calibration equipment.
3. Measures were not established to assure that tools used in crankshaft oil plug installation were properly controlled and adjusted at specified periods to maintain accuracy within necessary limits.
4.
 - a. A welding machine in Weld Area No. 3 (Foundry) was observed in September 1983 to have calibration stickers showing a calibration due date of August 30, 1980. The QA program calibration frequency requirement for this equipment is 12 months.
 - b. A heat treat furnace was observed in September 1983 to have calibration stickers on the meters and temperature recorder showing a calibration due date of March 13, 1983.

INTERNAL AUDITS:

Failure to perform required semiannual audits of the Foundry, Manufacturing and support activities.

10 CFR PART 21 PRACTICES:

1. Records were not available with respect to fractured thermostatic control valves in Grand Gulf, Unit 1, EDGs to indicate either that an evaluation had been conducted in accordance with 10 CFR Part 21 requirements or that actions had been taken to determine whether the product deviation contributing to the valve fractures (i.e., improper use of raised face flanges in connecting piping) was present in equipment supplied to other customers.
2. Notification to affected parties in regard to a potential problem with isoprene flexible elements of drive couplings was made after the committed date in the 10 CFR Part 21 report.
3. Failure to notify the NRC in regard to:
 - a. Jacket water pump shaft failures at SNPS.
 - b. Potential defect in fuel injection line tubing that was used on EDGs furnished to Grand Gulf and San Onofre, Unit 1.

QA RECORDS:

1. Records not available to demonstrate environmental qualification of auxiliary lube oil and jacket water pump motors with respect to Bechtel Specification Nos. 9645-M-018.0 and 9645-G-QA-1.
2. Failure to protect records against fire in accordance with QA Manual requirements noted during two separate inspections.

MISCELLANEOUS:

Failure to have Certificate of Compliance for SNPS replacement cylinder head assemblies notarized in accordance with customer specification requirements.

TRANSAMERICA DELAVAL, INCORPORATED
VENDOR PROGRAM BRANCH INSPECTION HISTORY SUMMARY
OF NINE INSPECTIONS DURING 1979-1983

<u>Subject</u>	<u>Number of Nonconformances/Violations</u>
Manufacturing Process Control	13
Control of Special Processes	11
Procurement Control	12
Material Identity and Control	1
Design and Document Control	8
Nonconformances and Corrective Action	5
Equipment Calibration	4
Internal Audits	1
10 CFR Part 21 Practices	3 (Violations)
QA Records	3
Miscellaneous	1

SC 4P-35

ATTACHMENT 10

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25

A Meeting on TDI DIESEL GENERATORS

Phillips Building
Bethesda, Maryland
Thursday, January 26, 1984

A meeting on TDI Diesel Generators convened
at 3:04 p.m., Harold Denton presided.

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25

APPEARANCES:

(Attendance List will be Generated.)

1 MR. DENTON: Good afternoon. My name is
2 Harold Denton. What we are going to discuss today is
3 the results of the staff review of the reliability of
4 the Delaval diesel.

5 We started looking intensively in this area
6 when problems began to develop at San Onofre, Grand Gulf,
7 and at Shoreham. Since that time, our review has ex-
8 panded.

9 We are prepared today to discuss with you in
10 detail the results of all the information that has come
11 to our attention regarding the operating performance of
12 these diesels.

13 We also have with us today the Regional Ad-
14 ministrator from Region IV, John Collins, who conducts
15 our vendor inspection program. He will describe the
16 results of his vendor inspections at the factory of
17 Delaval Diesels.

18 I understand that the Owner's Group has
19 been informed of the utilities who own these diesels,
20 and they are represented today by Jim McGaughy, who is
21 the Chairman of the Owner's Group. I understand that
22 the Chief Executive of Delaval Diesel Corporation is
23 also present, and that his representatives will be
24 making a presentation.

25 Let me discuss a few ground rules to begin

1 with, to make the meeting go smoother. We are taking a
2 transcript of this meeting. The issue is in contention,
3 as you know, at several proceedings. And this makes it
4 easier for us to provide the Hearing Boards a complete
5 and accurate record of what information is made available
6 today. Because of this transcript, it's very important
7 that anyone who has questions or comments be sure to
8 identify themselves for the record when they ask questions.

9 The way I would like to walk through this pro-
10 cess is to have the staff first describe in some de-
11 tail the information that has become available in the
12 last few months on the performance of these diesels in
13 the field. This is mainly at nuclear power plants, but
14 we also collected data from some non-nuclear sources.

15 Then, we will cover the vendor inspection, as
16 I mentioned. Then, we turn the meeting over to the
17 utility Owner's Group, who I understand is prepared to
18 describe their remedial program to try to establish the
19 reliability of these diesels.

20 I understand, Jim, that you may have an open-
21 ing -- opening remarks to say before we begin. Why don't
22 you do that now?

23 MR. McGAUGHY: Good afternoon. My name is
24 Jim McGaughy. I am Vice-President of Mississippi Power
25 and Light Company. I am speaking to you today as Chairman

1 of the Delaval Diesel Owner's Group.

2 The issues that will be presented here, we
3 feel the problems that have been found in our pre-operational
4 testing program and our subsequent research and reported
5 to the NRC, as they've been found, using the proper pre-
6 scribed methods. For some time, all the owner's of these
7 engines have bound together putting the best minds avail-
8 able in the world on these issues in the one effort to
9 study and correct these issues.

10 Our goals and the goals of the NRC are the
11 same. We are committed to provide our plant to reliable
12 emergency backup power supplies. We feel this comprehen-
13 sive program we have in place, in place now, working now,
14 will do just that.

15 We are here today to tell you about what it
16 is that we have been doing. The elements of our program
17 are four. The first element is resolve the known problems,
18 both generic problems and problems in the specific engines
19 themselves, to design and find fixes to these problems.

20 In addition, we will take -- and are in the
21 process of taking each engine from the ground up, review-
22 ing its design, its construction, its procurement and
23 doing a quality revalidation on each and every engine.
24 From the results of the quality revalidation, then we
25 go into testing, and the testing involves non-destructive

1 testing, destructive testing, operational testing of
2 components, operational testing of the engines. This
3 work is in progress now.

4 And also then we will, through this group,
5 respond to the questions, of course, that the NRC will
6 put to us. The participants in our program are as
7 follows. We have the eleven owners, and I will have a
8 list of those for you later. Eleven utilities. FaAA
9 Associates, who are renown in doing failure analysis work.
10 We have the wholehearted support of Delaval in this
11 effort, both in gathering of information and gathering
12 of design data, and in review of this data. Stone and
13 Webster Engineering is supporting this effort. And also
14 several diesel generator consultants from around the
15 world.

16 The organization the Owner's Group has set up
17 has me as Chairman, Mr. Joe George of Texas Utilities as
18 Vice-Chairman. Executive Committee made up of the eleven
19 utilities. The Technical Director of the program is Mr.
20 Bill Museler of LILCO. We have taken the program that
21 LILCO has started on their site, adding to it. The work
22 is being done at the LILCO site.

23 As you see, in resolving the known failures and
24 determining solutions to those problems, FaAA is taking
25 the lead; that is their speciality. In terms of design

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25

review and quality revalidation, we have FaAA, Stone and Webster, our various consultations, and we have engineers from each utility working in this effort. The testing program definition and carrying out the testing program will be done, of course, by the utilities who own the engines and operate them, and by FaAA who will assist us in that effort.

To give you an idea of the extent of this program, I would like to put this chart up. This is the organization that is in place. We have over a hundred and twenty people full-time working on this effort, working on this effort now. This is in progress. We are confident that when we complete this program, that we will have reliable engines to provide backup power supplies for these plants.

Thank you.

MR. DENTON: As those of you know, who own these diesels, this is a very important safety issue for the NRC. There are about fifty-seven engines made by Transamerica Delaval that are in this, owned by the sixteen utilities that are on our list. None of the Delaval diesels are at operating plants, which means it's not an imminent safety problem today, but certainly it has profound implications for schedules for some of the utilities if the problem is not adequately addressed.

1 I did want to mention my perspective on the
2 safety side to be sure it's well understood. The only
3 plants that are operating that have Delaval diesels are
4 San Onofre Unit 1. That plant is shut down for a seismic
5 modification. Grand Gulf, which is limited to a five
6 percent power license and is presently shut down. And,
7 Rancho Seco, which is using other diesels, but I under-
8 stand has ordered, or has in place, several Delaval diesels
9 which they have intended to install.

10 We view this as a very serious problem for the
11 industry. It is unique to have a problem in what I will
12 call a convention component of American technology. You
13 wouldn't think that diesel generators would get on the
14 critical path of the nuclear power reactors, but that's
15 very likely what has happened.

16 And just so there is no doubt about where the
17 staff stands on this issue, we are not prepared to go
18 forth and recommend the issuance of new licenses on any
19 plant that has Delaval diesels until the issues that are
20 raised here today are adequately addressed. It sounds
21 like we have a very ambitious program. What I want to do
22 is make sure you have all the information we have.

23 And if we come to an understanding about the
24 factual basis that we are working with, so we can move
25 to a discussion of the information we have been able to

1 gather, and if everyone would hold their questions to the
2 extent they can, we can get through the presentations
3 faster.

4 We will provide ample opportunity for discus-
5 sion after we have gotten the factual basis on the table.
6 Then, we will turn to a detailed presentation of your
7 program. And I plan to provide a break somewhere in the
8 meeting. But we will probably go until about six o'clock.

9 The first presentation will be made by Frank
10 Miraglia and assisted by Carl Berlinger. Carl Berlinger
11 is a Senior Manager on the NRC staff. We designated him
12 as the person responsible for ultimately reviewing your
13 program and making sure that it is an acceptable, adequate
14 program.

15 So, Frank, why don't I turn over to you to
16 cover what we know about the operating experience.

17 MR. MIRAGLIA: My name is Frank Miraglia. I
18 am the Assistant Director of the Safety Assessment Division
19 of Licensing.

20 The first view graph is a list -- the first
21 view graph indicates the fifty-seven Delaval diesels that
22 have been procured for use at sixteen different nuclear
23 power plant sites. May I have the second view graph?

24 We are going to discuss the U.S. experience
25 with these diesels in the operating stations to date.

1 The next slide is a brief summary of the operat-
2 ing experience with San Onofre 1 station. The informa-
3 tion on this view-graph is in a very summarized fashion.
4 We have a more detailed handout that will be available
5 at the end of the meeting that has additional details
6 about the operating experience and chronology with some
7 of these machines at the various nuclear power stations.

8 There are two Delaval diesels at San Onofre 1.
9 They were installed in 1976. They are Delaval V-20
10 engines. They were declared operational in 1977. The
11 operating time on each engine at San Onofre is approximate-
12 ly 450 hours. These are actually the first Delaval diesels
13 to enter nuclear service.

14 Problems to date are indicated on the slide.
15 They've had turbocharger thrust bearing problems. This
16 event resulted in a Part 21 report, was issued and pro-
17 blem was considered to be of a generic nature.

18 They've had a lube oil leak and fire, which
19 was a result of a fuel line failure, test line off a lube
20 oil line which failed because of vibration. And it was a
21 small fire.

22 The pistons have been modified at San Onofre 1
23 to correct a problem that is noted at Grand Gulf and
24 resulted in a Part 21 notification there, to prevent crown
25 separation.

1 They've had an unqualified instrument cable,
2 which also was replaced in conformance with reported
3 Part 21 occurrence. And just recently in another Part 21
4 report, there is potentially defective coupling material.
5 That Part 21 report was filed earlier this month.

6 The next slide is a summary of the experience
7 on the -- of the Grand Gulf diesels. They have Delaval
8 diesels. They are the V-16. The operational hours on
9 the diesels are 1100 hours on the Division I diesels,
10 and seven hundred hours on the Division II diesels.

11 These are the first V-16 Delaval diesels to
12 enter nuclear service. The problems to date are the --
13 Number one is the pistol crown separation. That was a
14 generic problem and identified this particular problem
15 as a Part 21 for the Delaval diesels.

16 They have experienced piston skirt cracks,
17 and piston skirts have been replaced on the Division II
18 diesels.

19 They've had a fuel line failure, which resulted
20 in a fire. And the fuel line failure was due to fatigue.
21 They have experienced cylinder head cracking on these
22 diesels. The heads have been replaced.

23 In addition to those, they've had the turbo-
24 charger problems. I believe three different instances of
25 turbocharger problems. And, again, you can see commonality

1 between this experience and the San Onofre experience.

2 They have experienced push rod cracking pro-
3 blems. In addition, they've had the generator short due
4 to an engine fastener. This was a crankcase capscrew
5 failed and had lodged in the generator and shorted the
6 generator out.

7 In addition, Grand Gulf has also experienced
8 problems with their air starting valves which has resulted
9 in failure of the generators to start.

10 This summarizes the experience with the San
11 Onofre and the Grand Gulf units. I would like to have
12 Ralph Caruso summarize for you the experience to date
13 on the Shoreham machines and also to present a brief
14 summary of the information that we have been able to
15 gather from non-nuclear marine experience with similar
16 type diesels.

17 Ralph Caruso.

18 MR. CARUSO: The engines installed at Shoreham
19 are Model DSR-48, straight-8 engines. They are rated at
20 3500 kilowatts and ~~have~~ ^{had} approximately 700 hours roughly *LC*
21 on each engine at the time of a major failure of crank-
22 shaft in August of 1983.

23 These engines were the first straight-8 engines ✓
24 to be installed in the United States in service. Shoreham
25 has had a number of minor problems and one major problem.

1 To date, they've had problems with jacket water
2 pump propellers. This problem occurred twice. Two fuel
3 oil lines have ruptured due to manufacturing defects.
4 Those two ruptures resulted in Part 21 reports being is-
5 sued for San Onofre and Grand Gulf.

6 In August they had the failure of the crank-
7 shaft in the Number 102 diesel generator. Subsequent
8 inspections of Number 101 and 103 engines revealed cracks
9 in the crankshafts of those engines, and in approximately
10 the same location as the failure of the 102 engine.

11 Upon disassembly of the engine to repair the
12 crankshaft problems, connecting rod ^{bearing} failures were dis- *RC*
13 covered, not just on the engine with the failed crank-
14 shaft but also on another engine. Subsequent inspection
15 revealed problems with piston skirts, with cracks in the
16 piston skirts. Those piston skirts have been replaced at
17 Shoreham.

18 And, in addition, over the life of the plant
19 they have experienced several problems with different
20 types of fasteners used to attach critical components to-
21 gether in the engine.

22 The staff has received a considerable amount
23 of information regarding marine experience from three
24 different operators of marine engines. ^{The} Marine engines we *RC*
25 are talking about, ^{are} ~~is~~ the V-16 and V-12 engines. They are *RC*

1 very similar, if not identical, to engines that are being
2 installed in nuclear power plants in the United States.

3 The operating experience for these engines is
4 varied at this time, with engine operating hours varying
5 from 3000 to 30,000 hours. To date, all three operators
6 have reported cylinder head cracking to various different
7 extents.

8 Two operators have reported piston cracking.
9 One operator reported the complete failure of two pistons.

10 Problems have also been noted with excessive
11 bearing wear, turbocharger instability, and turbocharger
12 vibration. Cracks have been noted in push rods, valves. *EC*
13 Cracks have been noted in connecting rods.

14 In addition, cylinder blocks have been replaced
15 by one of the operators.

16 This is a summary of the marine experience to
17 date.

18 MR. DENTON: We have given you a very quick
19 summary, but there is extensive information available in
20 what we will hand out later in the presentation.

21 And just because we have gone through it quickly,
22 I don't want you to think that this is all there is. There ✓
23 is really quite a bit of poor operating history with this
24 piece of equipment in the time that we have been able to
25 assemble it.

1 I think some of the reasons for this poor
2 performance will be obvious when you hear from our next
3 speaker, John Collins, who I mentioned heads up the
4 vendor inspection program. John.

5 MR. COLLINS: Thank you, Harold. Now, we are
6 passing out the view-graphs which cover a summary of the
7 major findings that we've had of the inspection.

8 Since 1979, we have made nine inspections of
9 Delaval. Seven of those inspection reports are identified
10 in handout material. They are available in the PDR. If
11 you would like copies and you cannot get copies, contact
12 myself in Arlington or Ian Barnes of our Vendor Branch,
13 we will be very happy to see that copies of these reports
14 are sent to you.

15 The remaining two reports have been forwarded
16 to the Company for proprietary review. That review
17 period should be up tomorrow. If there are not any pro-
18 prietary problems, they will be placed in the PDR and they
19 will be available, too. So, if you want to contact me,
20 my number in Arlington is Area Code 817-860-8225. Or,
21 Mr. Barnes, same area code, 860-8176.

22 We have -- as I hope everybody has the slides
23 now, our finding of deficiencies covered just about every
24 subject. They included areas on manufacturing process
25 control, control of special processes, procurement control,

1 material identity and control, design and document control,
2 equipment calibration, lack of internal audits or improper
3 or not sufficient disposition of audit findings, and then
4 deficiencies in QA records.

5 At this time, I am going to ask Ian Barnes,
6 who is the Chief of the Reactor Section for the Vendor
7 Program to go through some of the highlights of the
8 inspection findings with you. We are not going to read
9 them to you. You have them, but I think it's important
10 we at least identify some of them.

11 The other handout material has a more complete
12 summary of all of the findings that were made or documented
13 in the nine reports. So, Ian, why don't you walk us
14 through some of the significant findings?

15 MR. BARNES: Good afternoon. The first slide
16 that is on now shows a categorization of the vendor
17 program branch inspection findings by subject area. It
18 represents a total of sixty-two non-conformances and
19 violations that were issued as a result of the nine in-
20 spections.

21 As John has just indicated, a description of
22 all of the findings in that particular slide are in-
23 cluded in a handout that is being passed around. From
24 this inspection history summary, we have extracted
25 examples of inspection findings that raise concerns with

1 regard to the adequacy of implementation and the effective-
2 ness of the Transamerica Delaval program.

3 The next slide, please. The first subject I
4 am going to address is manufacturing process control.
5 We have put specific examples of inspection findings in
6 a subject area, but bringing the question of implementa-
7 tion effectiveness, manufacturing process controls, and
8 the performance of quality function of Transamerica
9 Delaval.

10 As you will note from this slide, instances
11 were noted where route sheets were not available to
12 the Vendor Branch review. For example, the first item on
13 the slide, jacket water pump. Reworked operations for
14 ninety-two pistons that were supplied to Shoreham and Grand
15 Gulf, that's the fifth item. Replacements of cylinder
16 head assemblies for Shoreham, that's the final item on
17 the slide.

18 Route sheets from Transamerica Delaval provide
19 the primary basis for verifying that the inspection opera-
20 tions have been performed. The absence of those route
21 sheets did not allow us to verify that required inspections
22 of manufacturing operations had, in fact, been accomplished.

23 Examples of findings which address the per-
24 formance of the quality control function is shown in the
25 second, third and fourth items, i.e. there was no evidence

1 of acceptance of certain operations on components for
2 jacket water pumps pertaining to modification efforts.

3 As Ralph indicated earlier, there had been
4 two successive problems involving jacket water pump pro-
5 blems at Shoreham. And, so evidence of sign-off to
6 installation of rocker arm hold down bolts were found
7 subsequent at Shoreham, were found subsequent to be mis-
8 sing.

9 In regard to San Onofre, piston reworked, with
10 the date of sign-off for manufacturer operations occurring
11 actually two to three weeks after the pistons had been
12 returned to San Onofre.

13 If you look, in regard to the seventh item on
14 this list, is the apparent use as indicated by the route
15 sheets of unqualified personnel performing non-descriptive
16 examinations on SNPs replacement cylinder head.

17 The eighth item, which is an absence of any
18 documented provisions for control of installation of
19 fuel oil line clamps in regard to Shearon Harris. We
20 believe that's generic to all of the engines, in that one
21 of the fuel oil line failures at Grand Gulf has been
22 attributed in part to the absence of required line clamp.
23 We believe this finding is quite significant.

24 It has been mentioned earlier about cracking
25 problems in piston skirts. Review of engineering drawings

1 for the various designs of piston skirts show, in fact,
2 that there was an engineering requirement to perform
3 stress relief heat treatment after normalizing of the
4 castings. The corrective action that, in part, is being
5 carried out for piston skirts is to perform stress relief.
6 There was an initial requirement always in effect to do
7 that very thing.

8 The next slide. This slide shows a few
9 examples of inspection findings in regard to procurement
10 document control deficiencies, use of vendors, the materials
11 that without performing any service or audits of those
12 vendors to establish adequacy of their own programs, and
13 inadequate receiving inspection.

14 In the more comprehensive handout that is being
15 distributed, you will find additional examples of inade-
16 quate receiving inspection and using other vendors without
17 performing required service or audits.

18 Next slide. In the area of material identity
19 and control, an inspection of this subject showed eleven
20 discrepancies were observed in a sample of forty-five,
21 I believe, in material identity between that recorded at
22 the time of the misuse of the material to a given job and
23 the identity of the material that was recorded on the
24 finished engine.

25 Next slide. We have included the next slide

1 to show examples of the failure of the quality issuance
2 function to comply with both QA program requirements for
3 corrective action and non-conformance conditions to be
4 identified and the specific instance of failure to comply
5 with corrective action commitments made to the NRC in
6 regard to the performance of their ASME weld shop.
7 In the same context, their ASME weld shop, recurring ex-
8 amples were noted during successive inspections for
9 failure to enforce program commitments with respect to
10 control of welding electrodes in regard to that console
11 moisture.

12 Next slide. The next slide is an additional
13 example of the failure of the QA function to comply with
14 program requirements for audits of their manufacturing
15 activities.

16 The final slide, John. We have included this
17 to illustrate that we have certain concerns in regard to
18 the adequacy of the Delaval evaluation and reporting
19 practices in regard to 10 CFR Part 21.

20 MR. COLLINS: As we indicated at the beginning,
21 we have summarized in these slides the findings. But,
22 as I also indicated, I think there is a lot more that's
23 of interest. If you carefully review the findings that
24 were handed to you that were documented in the handout to
25 you, one thing it says to me, in my opinion, is that

1 not only has there been problems at the manufacturing
2 shop but also, in my opinion, calls into question the
3 adequacy of the vendor programs or surveillance programs
4 that are being conducted by the utilities. Had some of
5 these been identified up front by utilities on-site
6 inspection programs, or receiving inspection programs, or
7 procurement programs, I think they could have been identi-
8 fied even sooner than now.

9 So, it really calls into question your own
10 programs. Darrell.

11 MR. EISENHUT: Well, let's see, we went through
12 the two aspects in such a short summary fashion, the
13 operating experience and the inspection findings, that one
14 might draw connections that they infer, or might leave it
15 to the operating experience, these were meant to be short
16 summaries. We certainly are going to be, on the staff,
17 undertaking a more detailed look at all these aspects,
18 in both the experience, the inspection results.

19 As mentioned earlier, Carl Berlinger is heading
20 a major review effort. But I guess you have to sit back
21 and say: Where does this leave us right now?

22 And right now, our preliminary conclusion --
23 and that conclusion is based on these limited looks -- is
24 that certainly our level of confidence in the overall
25 reliability of TDI diesels in general is significantly

1 reduced. We've got to say that from the front end.

2 And, secondly, as Harold Denton mentioned in
3 the beginning, is that before we undertake the licensing
4 of any plants with TDI diesels at this time, these issues
5 clearly are going to have to be addressed. These issues
6 are clearly the quality aspect from both the design, the
7 construction, the operating experience is going to have
8 to be factored in, and the overall ability of these diesels
9 to reliably perform their function is going to have to
10 be demonstrated.

11 That's basically where we are today. As we
12 said early, and Jim McGaughy pointed out, there is a
13 major industry undertaking, a major program has been laid
14 out, that we hope is going to address all of these issues.
15 And, obviously they are going to have to address them to
16 the staff's satisfaction.

17 With that as a short summary, I guess I would
18 like to open it up to the staff presentation for any
19 questions before we go to the second part this afternoon
20 on either piece, the operating experience piece, or on
21 the inspection results found today. Any questions?

22 (No reply.) Can't get off that easy.

23 Well, if there are no questions, why don't
24 I suggest it would probably be easier, Jim, on your
25 presentation if we took a short break now rather than

CERTIFICATE OF PROCEEDING

1
2 This is to certify that the attached proceeding before
3 the NRC Staff

4 In the matter of: Meeting on TDI Diesel
Generators

5 Date of Proceeding: January 26, 1984

6 Place of Proceeding: Phillips Building,
7 Bethesda, Maryland

8 was held as herein appears, and that this is the original
9 transcript for the file of the Commission.

10
11
12 MYRTLE H. TRAYLOR
13 Official Reporter - Typed

14
15 Official Reporter - Signed
16
17
18
19
20
21
22
23
24
25

ATTACHMENT 4

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

Before the Atomic Safety and Licensing Board

In the Matter of)
)

LONG ISLAND LIGHTING COMPANY)

Shoreham Nuclear Power Station,)
Unit 1))
_____)

Docket No. 50-322-OL-4
(Low Power)

TESTIMONY OF ROBERT WEATHERWAX,
MOHAMED EL CASSEIR AND GREGORY MINOR
ON BEHALF OF SUFFOLK COUNTY

Q. Please state your names and professional affiliations.

A. My name is Robert K. Weatherwax, Jr. I am the president of Sierra Energy and Risk Assessment, Inc., of Sacramento, California. I have had 15 years experience in matters relating to nuclear safety analysis of commercial power generation, including work related to developing elements of fault tree, sequence tree, and event tree analyses. A statement of my qualifications and educational background is set forth in Attachment A.

Corrections made
by witnesses.

~~My name is Mohamed M. El Casseir. I am a senior staff scientist with Sierra Energy and Risk Assessment, Inc. I hold a B.S. degree in chemical engineering from the University of California, Berkeley and a M.S. degree~~

~~in the same field from the University of Rochester. I am a doctoral candidate of Berkeley in the field of energy and resources. My recent work at Sierra has focused on probabilistic assessments. A statement of my qualifications is set forth in Attachment B.~~

My name is Gregory Minor. I am founder and vice president of MHB Technical Associates. I have 24 years of experience in the nuclear industry, including 16 years with the General Electric Nuclear Energy Division and 8 years as a consultant with MHB. A copy of my qualifications has been submitted with other testimony.

My educational background is in electrical engineering in which I received a B.S. degree at the University of California, Berkeley and a M.S. degree from Stanford.

My work with General Electric included the design, testing, qualification and pre-operational testing of safety equipment and control rooms for use in nuclear power plants.

As a consultant for MHB Technical Associates I have participated in numerous technical reviews and analyses of nuclear plant safety for government, public interest, and

private organizations. My work has included project coordination for a PRA study on the Barseback Nuclear Plant in Sweden, and involvement in the performance or analysis of several probabilistic consequence models related to emergency planning for nuclear plants in the United States. In addition, I have participated through review, analyses, and testifying in many licensing hearings for nuclear power plants in the United States and abroad.

Q. What is the purpose of this testimony?

A. The purpose of this testimony is to address the question whether operation of the Shoreham plant at up to 5 percent power, under the AC power system proposed by LILCO in its Supplemental Motion for Low Power Operating License (the "alternate" system), would be as safe as operation at up to 5 percent power with three fully qualified on-site emergency diesel generators, as described in the Shoreham FSAR (a "normal" system). In our opinion, operation with LILCO's alternate proposed system would not be as safe as operation with a normal system.

Q. Generally, on what do you base your opinion?

A. We have assembled and reviewed documentation that enabled us to compare the proposed LILCO alternate AC power system and its components, with the qualified on-site AC power system described in the Shoreham FSAR and its components, in particular, those systems which affect their capability to deliver, and sustain the delivery of, AC power to essential emergency loads. ~~A description of the two systems is contained in Attachment C hereto.~~ We then performed a quantitative comparison of the probability of Shoreham reaching a state of core vulnerability (as defined by LILCO's contractor Science Applications, Inc. in Probabilistic Risk Assessments for the Shoreham plant) due to loss of offsite power, during operation at five percent power, assuming operation with the alternate system and assuming operation with the originally proposed qualified on-site power system.

Q. How does the quantitative comparison you just described relate to the relative safety of the two systems?

A. The comparison of calculated frequencies of the Shoreham plant reaching a state of core vulnerability due to a loss of offsite power, given each of the two AC power systems, provides a quantitative measure of the two systems'

relative safety in terms of the overall operation of the plant at up to five percent power. The fact that the calculated probability of core vulnerability given operation with the alternate system is substantially greater than the corresponding probability given the normal system demonstrates that operation with the alternate system is quantifiably less safe than operation with the normal system.

Q. Please describe briefly the two AC power systems you compared.

A. The proposed alternate system's major components include four General Motors EMD, mobile outdoor-type diesel repowered generators ("EMDs"), and a 20-MW refurbished Pratt and Whitney gas turbine. The EMDs as well as the gas turbine were used (prior to their relocation to Shoreham) as peaking units for several years. ~~Technical details of this generation equipment and of the supporting electric devices can be found in Table C1 of Attachment C. The proposed configuration is depicted by the line diagram in Figure C2 of Attachment C. The geographical layout of the major equipment is shown in Figure C1. The procedures for restoring power via the gas turbine and the EMDs are described in Section 2.1.1.2. of Attachment C.~~

The normal system consists of a set of three self-contained and operationally independent diesel generators manufactured by Transamerica DeLaval Inc. ("TDIs"). ~~Technical details of the TDIs can be found in Section 2.1.2.1 of Attachment C and in Testimony of G. Dennis Eley et al. on behalf of Suffolk County regarding EMD diesel generators and the 20 MW gas turbine. Specifications for other components related to operation of the TDIs are also listed in Table C1. The configuration of the normal system is shown in Figure C4 of Attachment C. The operation of the TDIs is automatic.~~

- Q. Please describe the process you used in analyzing the probability of Shoreham reaching a state of core vulnerability during operation at five percent power under each system.
- A. Recently,, at LILCO's request, Science Applications, Incorporated ("SAI") and Delian Corporation performed a Probabilistic Risk Assessment for Shoreham operation at 5 percent power. "Probabilistic Risk Assessment, Shoreham Nuclear Power Station, Low Power Operation up to 5% of Full Power," by Delian Corporation and Science Applications, Incorporated, Draft, May 1984 (hereinafter, "SAI

Low Power PRA"). Our basic approach in performing our quantitative analysis of core vulnerability probabilities was to use the structure and methodology used by SAI in performing its assessment for LILCO. We used that methodology to produce two estimates of the probability of reaching core vulnerability due to a loss of offsite power transient at Shoreham for operation at 5 percent power. One estimate assumed that the TDIs, as described in the FSAR, were fully operational; and the other assumed that the EMDs and the gas turbine were operational in place of the TDIs. We decided to produce these two estimates for purposes of comparison, because the potential for reaching a state of core vulnerability is a key measure of whether operation of the Shoreham plant at 5 percent power with the alternate AC power configuration proposed by LILCO would be as safe as 5 percent power operation with fully qualified onsite diesel generators.

Our principal data sources in deriving these two estimates of core vulnerable probability were the SAI Low Power PRA and information from the Probabilistic Risk Assessment dated June 24, 1983, also performed by SAI for LILCO. "Final Report, Probabilistic Risk Assessment, Shoreham Nuclear Power Station," Science Application

Incorporated, June 24, 1984 (hereinafter, "SAI 1983 PRA"). The latter source was used primarily to derive reliability figures relating to the operation of the TDIs.

We used the SAI data in performing our analysis for several reasons. First, we did not have sufficient time to derive all the necessary data independently. Second, the approach and methodology used by SAI in its PRAs seemed generally reasonable, and in our professional judgment, the SAI analyses were competently performed and its results, in general, were reasonable and accurate. Third, we believe that since SAI acquired much of the data it used in its analysis from LILCO, it is reasonable to assume that the underlying factual data are likely acceptable to LILCO, thus reducing the chance of controversy regarding such underlying data. We used the SAI data, however, recognizing that in our opinion, not all the assumptions incorporated into the SAI analyses were as conservative or as appropriate as they should have been. Attachment E sets forth certain adjustments that we believe would make SAI's estimates of core vulnerability probabilities at Shoreham more realistic.

Core vulnerability can be produced by a number of initiating events. We limited our analysis to core vulnerability following loss of offsite power because, in the SAI analysis, that was the only source of core vulnerability affected by the differing AC power configurations now at issue.

In its Low Power PRA, SAI assumed that the EMDs and the gas turbine comprised the onsite emergency AC power system, and then investigated five types of accident sequences, each involving a unique time within which core vulnerability was reached after a loss of offsite power. The probabilities of core vulnerability derived by SAI are contained in Table 3.1.3 of the SAI Low Power PRA. We performed a comparable analysis, using the same methodology as SAI, but assuming that the emergency onsite AC power system was comprised solely of operational TDIs. We obtained the necessary data to perform the TDI event tree analysis from the SAI 1983 PRA. The result of SAI's calculations assuming the EMDs and the gas turbine provided emergency power, and of our calculations assuming the TDIs provided emergency power, are set forth in Table 1.^{1/} The

^{1/} We believe, based on our review of the SAI Low Power PRA, that SAI did not consider the possibility of repairing the

(Footnote cont'd next page)

TABLE 1

COMPARISON OF CORE VULNERABILITY FREQUENCY
FOR LOSS OF OFFSITE POWER TRANSIENT FOR NORMAL
AND ALTERNATE AC POWER SOURCES

Loss of Off-site Power Sequence Type	Time to Core Vulnerable	Frequency (per Rx Yr); using EMD diesels and gas turbine	Frequency (per RX Yr.); using TDI diesels
Type 1	2 days	1.0E-7	5.1E-9
Type 2	30 hours	3.2E-7	2.8E-8
Type 3	3 hours	8.1E-7	1.3E-7
Type 4	10 hours	5.9E-7	7.0E-8
Type 5	7.5 hours	1.5E-6	2.1E-7
	TOTAL	3.3E-6	0.44E-6

Note: Column totals may not exactly equal the sum of the figures in each column due to rounding.

event trees which form the bases for the frequencies in Table 1 are Attachment D.

Q. What were your conclusions?

A. As shown on Table 1, the calculated probability of core vulnerability due to loss of offsite power, assuming LILCO's alternate AC power configuration is in place (EMDs and gas turbine) is 3.3 E-6 ; assuming the normal configuration (TDIs) is in place, it is 0.44 E-6 . This means that assuming there is a loss of offsite power during operation of the Shoreham plant at 5 percent power, it is more than seven times as likely that such an event would lead to core vulnerability under the alternate system than under the normal system. It also means that the likelihood of the Shoreham plant reaching a core vulnerable condition due to loss of offsite power is over seven times greater under the alternate configuration than under the

(Footnote cont'd from previous page)

EMDs or gas turbine if they failed. Accordingly, in deriving the frequencies in Table 1, we used values for the TDIs that also assumed no repairs if they failed. Because there is a possibility, however, that either the TDIs or the EMDs and gas turbine could be repaired following a failure, we also performed a sensitivity study and compared calculated core vulnerable frequencies assuming such repairs. See Attachment E.

normal configuration. Furthermore, assuming the accuracy of SAI's estimate of $1.6 \text{ E-}6$ for the annual frequency of core vulnerability from all other initiating events during 5 percent operation (SAI Low Power PRA at Table 4-4-1), the likelihood that the Shoreham plant would experience an event leading to core vulnerability during 5 percent operation is approximately 2-1/2 times greater under the alternate configuration than it is under the normal configuration.

We recognize that uncertainties exist in each of the core vulnerability estimates set forth in Table 1. However, we believe that the uncertainties are comparable in the two estimates and that the existence of the uncertainties does not invalidate either the comparison or our conclusions. In our opinion the comparison set forth in Table 1 demonstrates that operation of the Shoreham plant with the alternate AC power configuration is not as safe as operation with a fully qualified source of emergency power.

Q. Did you perform any additional analyses or sensitivity studies?

(Weatherwax)

A. A Yes. We performed a sensitivity study to assess the reduction in core vulnerability attributable to the possibility of repairing the TDI diesels and the EMDs and gas turbine following their failure. We also analyzed the effect of certain adjustments to the SAI probabilities of offsite power restoration and the frequency of loss of offsite power events at Shoreham, which we believe make those probabilities more realistic. These analyses are described in Attachment E.

Q. Do the results of your sensitivity studies cause you to modify your conclusions regarding the relative probability of core vulnerability due to loss of offsite power given the alternate as compared to the normal Shoreham emergency power system?

(Weatherwax)

A. A No. Our sensitivity studies confirm our conclusion that the probability of core vulnerability due to loss of offsite power transient, assuming use of the alternate system, is higher than with the use of the normal configuration. The precise difference in probability, though uncertain, is sufficiently large to conclude that low power operation with the alternate configuration would not be as safe as with the normal configuration.

ATTACHMENT A


SERA

Sierra Energy and Risk Assessment, Inc.

ROBERT K. WEATHERWAX, JR.

EXPERIENCE:

Jan. 1981 - Present	President, Sierra Energy and Risk Assessment, Inc. Sacramento, California
July 1980 - June 1981	Visiting Scientist, Energy and Resources Group, University of California, Berkeley
July 1977 - December 1980	Chief Energy Forecaster, California Energy Commission, Sacramento, California
Jan. 1977 - June 1977	Staff Scientist, Science Applications, Inc. Palo Alto, California
May 1974 - Jan. 1977	Staff Scientist, School of Engineering Princeton University, Princeton, New Jersey
Jan. 1969 - April 1974	System Safety Supervisor, McDonnell Douglas Aeronautics Company, Huntington Beach, California

As the founder and Chief Executive Officer of Sierra Energy & Risk Assessment, Inc. (SERA), Mr. Weatherwax is presently involved in the twin topics of (1) risk assessment and comparison, and associated cost benefit analysis, and (2) energy demand and supply assessment, and policy evaluation.

He has had fifteen years of experience in nuclear safety analysis of commercial power generation and isotope power systems for space application. He has worked broadly in the area of nuclear fuel cycle risk assessment, and in reliability and failure mode assessment of complex systems. He has contributed to the original development of elements of fault tree, sequence tree (i.e., FAST), and event tree analyses; and has applied these methods to light-water nuclear power plants, nuclear fuel cycles, radioisotope thermal generators, strategic weapons systems and launch vehicles. In an American Physical Society meeting, Mr. Weatherwax debated Dr. Norman Rasmussen on the merits of the Reactor Safety Study, WASH-1400 (to which he was the major contributor). He is an engineer by formal education with a minor in economics and has applied these disciplines in numerous systems engineering and evaluation efforts, particularly related to energy demand forecasting and policy assessment during the last several years.

As a McDonnell Douglas Astronautics Company (MDAC) employee, Mr. Weatherwax was principal author of a PSAR for the NASA 50 kWe space station power system. He later was manager for Environmental Impact and Risk Assessment on the MDAC team selected by the Air Force Weapons Laboratory (AFWL) to perform safety analyses of LES 8/9 and Viking missions. After leaving MDAC he continued as a consultant to MDAC, and subsequently became a consultant to Teledyne Energy Systems in their support of the AFWL's space nuclear safety responsibilities.



SERA

Sierra Energy and Risk Assessment, Inc.

Robert K. Weatherwax, Jr.
Resume Continued

Mr. Weatherwax has performed energy and risk analysis of fusion systems and nuclear reactor designs. At Princeton University, he modeled performance and cost properties of TOKAMAK fusion reactor concepts and associated power conversion technologies CIRCA 2000. Mr. Weatherwax managed the risk analysis of the Hanford (nuclear) Reservation Purex plant. He also managed the initiation of the risk analysis of a Swedish PWR under Swedish Government sponsorship. More recently, he has reviewed and evaluated the probabilistic risk assessments of the Indian Point and proposed Limerick light-water reactor power plants for the Union of Concerned Scientists and the Limerick Ecology Action Committee, respectively. In 1983, Mr. Weatherwax testified before the Indian Point Atomic Safety and Licensing Board regarding the probabilistic risk assessment of the Indian Point power plant.

Mr. Weatherwax's current research and development interests in the area of probabilistic risk assessment focus on the adequacy of existing fault-tree and event-tree methodologies for estimating low-probability events and representation of uncertainties in risk/benefit analysis. He is now involved in an AFWL project reviewing the probabilistic risk assessment of the space shuttle/Galileo - International Solar Polar missions. A list of risk assessment studies authored or contributed to by Mr. Weatherwax is appended to this resume.

Mr. Weatherwax's experience in energy forecasting includes work done at Princeton University, UC Berkeley and as Chief Energy Forecaster for the CEC. During this time, he performed research involving end-use, microeconomic energy demand forecasting models and implementation of data bases to various end-use forecasting models. He developed the first utility service area version of a residential end-use energy demand forecasting model and associated load shape forecasting model. As the Chief Energy Forecaster, he was responsible for forecasting electricity and natural gas requirements and peak loads for utility service areas for use in determining the need for power plants within California. Duties included technical direction of others in performing development and implementation of state-of-the-art microeconomic end-use models of energy consumption by fuel type and electric peak load by economic sector by utility service area. Other duties involved evaluation of cost effectiveness of conservation and alternative energy options and their potential energy impact, and management of twenty-five post-graduate level professionals.



SERA

Sierra Energy and Risk Assessment, Inc.

ROBERT K. WEATHERWAX

BIBLIOGRAPHY

Selected reports and analyses authored or coauthored by Mr. Weatherwax in the field of risk assessment include:

(With E. William Colglazier) Review of Shuttle/Centaur Failure Probability Estimates for Space Nuclear Mission Applications, Sierra Energy and Risk Assessment, Inc., Draft Report for Teledyne Energy Systems, SERA No. 83-57, June 1983.

(With E. W. Colglazier) "The 236U92 Penalty for Recycled Uranium", under publication review, Annals of Nuclear Energy.

Probabilistic Investment Decision Analysis Model, Sierra Energy and Risk Assessment, Inc., Report for the MCR Geothermal Corporation, SERA No. 82-13, April 1982.

"Comments on Assessment of Accidental Pathways, Subtask D Report (Draft), A. D. Little Inc. dated February 1978", for Office of Radiation Programs, EPA, July 12, 1978.

Nuclear Safety Analysis Methodology for RTG Equipped Satellite Launches, MDC G6751, McDonnell Douglas Astronautics Company, Huntington Beach, California, May 1976.

Nuclear Fusion Systems Analysis Research, AMS Report No. 1250, Princeton University, October 1975.

"Probabilistic Fission Power Plant Risk Analysis: Its Virtues and Limitations", presented as an invited paper at the American Physical Society General Meeting, April 1975, and published in Bulletin of the Atomic Scientists, September 1975.

Probabilistic Risk Analysis of Nuclear Systems, Princeton University Seminar, May 1975.

(With C. Wildon, et al.) Launch Vehicle Reliability Considerations for Nuclear Safety Assessment, MDC G5983, McDonnell Douglas Astronautics Company, Huntington Beach, California, April 1975.

(With R. Luna, et al.) Site Defense Safety Analysis and Hazard Evaluation Report, MDC G4885, McDonnell Douglas Astronautics Company, Huntington Beach, California, October 1973.


"Applications of Multi-Phase Fault Tree Analysis", presented as part of industry course entitled RISK ANALYSIS given at Flow Research, Inc., Kent, Washington, February 1973.

"A Comparison of Fault Tree Quantification Techniques", presented to System Safety Society Symposium, University of Southern California, April 1972.

(With R. L. Gervais, et al.) Preliminary Safety Analysis Report, Volumes 1, 3, and 5 (NASA Space Station 50 KW isotope and reactor power supplies), MDC G0744, McDonnell Douglas Astronautics Company, Huntington Beach, California, January 1971.


SC LP-61

ATTACHMENT D




Entry Conditions Sequence Type 1: LOSP; Isolation; Reactor Scrammed; Primary System Intact; Coolant Injection Available through 10 hours via HPCI/RCIC; reactor may be depressurized to 150 psia.

EVENT TREE D-1
(Table 1, Column 3)



Entry Conditions Sequence Type 2: LOSP; Isolation; Reactor Scrammed;
 Reactor Integrity Intact; Coolant
 Makeup Available 0-4 Hours; Reactor
 may be depressurized to 150 psia.


EVENT TREE D-2
 (Table 1, Column 3)



Total Cumulative Value = 8.1E-7


Entry Conditions Sequence Type 3: LOSP; Isolation; Reactor Scrammed; SORV, LOCA or ADS; no Coolant Makeup Available; Reactor Depressurized to Less than 65 psia.

EVENT TREE D-3
(Table 1, Column 3)



Entry Conditions Sequence Type 4: LOSP; Isolation; SORV,
Coolant Injection Available
Initially.


EVENT TREE D-4
(Table 1, Column 3)



Total Cumulative Value = 1.5E-

Entry Conditions for Sequence Type 5: LOSP; Isolation; no initial Coolant Makeup; Procedural Depressurization


EVENT TREE D-5
(Table 1, Column 3)



Total Cumulative Value = 5.1E-9

Entry Conditions Sequence Type 1: LOSP, Isolation; Reactor Scrammed; Primary System Intact; Coolant Injection Available through 10 hours via HPCI/RCIC; reactor may be depressurized to 150 psia.

* Does not reflect repair.




Total Cumulative Value = 2.8E-8

Entry Conditions Sequence Type 2: LOSP; Isolation; Reactor Scrammed; Reactor Integrity Intact; Coolant Makeup Available 0-4 Hours; Reactor may be depressurized to 150 psia.

* Does not reflect repair


EVENT TREE D-7
(Table 1, Column 4)



Entry Conditions Sequence Type 3: LOSP; Isolation; Reactor Scrammed; SORV, LOCA or ADS; no coolant Makeup Available; Reactor Depressurized to Less than 65 psia.

* Does not reflect repair


EVENT TREE D-8
(Table 1, Column 4)



Entry Conditions Sequence Type 4: LOSP; Isolation; SORV; Coolant Injection Available Initially.

*Does not reflect repair

EVENT TREE D-9
(Table 1, Column 4)



Entry Conditions for Sequence Type 5: LOSP; Isolation; no initial
Coolant Makeup; Procedural
Depressurization.

* Does not reflect repair

EVENT TREE D-10

SC LP-62

ATTACHMENT E

SENSITIVITY STUDIES AND ADJUSTMENTS
TO SAI METHODOLOGY AND DATA

Some of the data and assumptions used by SAI in performing its Low Power PRA for LILCO could be improved or made more accurate. The two most significant items are (1) the frequency of occurrence of the loss of offsite power transient at the Shoreham facility, and (2) the assumed means of restoring offsite power via the 69 KV switchyard. It also appears that slight changes are necessary in the probability of restoring power following a loss of offsite power and in the conditional availability of the 138 KV switchyard following the occurrence of a loss of offsite power. We have recalculated the frequencies of core vulnerable conditions due to loss of offsite power, as set forth in Table 1 of our testimony, using corrected data as described below.

First, we used a loss of offsite power frequency of 0.25 events per year instead of .082 events per year as was used by SAI in both the Low Power PRA and its 1983

PRA. SAI's loss of offsite power frequency value is based on data concerning only the LILCO grid. (SAI 1983 PRA, page 3-102). Thus, its value of .082/year does not take into account the probability of failures within the Shoreham switchyard resulting in loss of offsite power. In our opinion, the failure to account for such failures makes the SAI value unrealistically low.

The .25/year frequency of loss of offsite power, which we believe is more realistic, is from a Brookhaven National Laboratory assessment of the frequency of loss of offsite power for the nuclear reactors found in the Reliability Council region to which LILCO belongs. See Table E-1. We consider this figure to be conservative, but more realistic than SAI's, because it takes into account the contribution to losses of offsite power from failures in the switchyards of nuclear power plants. Such failures are a major contributor to loss of offsite power events. Although we believe that a value even higher than the .25 figure might be appropriate for a plant such as Shoreham which will be operated at low power by relatively inexperienced operating staff using equipment subject to break-in type failures, we did not increase the Brookhaven frequency in performing our calculation.

Second, our recalculation also corrected what we believe to be an error in the SAI model for offsite power availability. The SAI low power event tree for the loss of offsite power transient takes into account the possibility that offsite power will be restored at different times after the transient, with varying probabilities. SAI also assumes, however, availability of offsite 69 KV power with a probability of 0.99985, after the occurrence of the loss of offsite power transient. We believe this second assumption is improper, and amounts to double counting, because the probability of restoring offsite 69 KV power is already included in the event tree in the time varying probabilities for restoring offsite power. We have eliminated this double counting in our recalculation.

The final major change we made was to consider the possibility of repairing the gas turbine and the EMDs following a failure. The SAI Low Power PRA did not discuss the possibility of repairing the EMDs and gas turbine. Thus, to the best of our knowledge, the values in Table 1 of our testimony reflect comparable assumptions of no repairs for both the EMDs and gas turbine, and the TDIs. If the SAI Low Power PRA did include repairs of the EMDs and gas turbine, then the difference between the core

vulnerable frequencies for the TDIs and the EMDs and gas turbine is understated in Table 1 to our testimony, because adding the repairability assumption to the TDI values would further reduce the probability of reaching a core vulnerable condition.

We took values from the SAI 1983 PRA to determine the core vulnerable frequencies assuming the TDIs could be repaired. To be conservative, we used the same TDI repair values used by SAI in our EMD and gas turbine event trees to determine core vulnerable frequencies for the alternate system.

The results of our recalculations are summarized in Table E-2. Increasing the frequency of loss of offsite power increases the estimated frequency of core vulnerability due to loss of offsite power by an equal factor of about 3 for both the alternate and the normal AC power systems. Thus, the impact of this adjustment is only in the overall core vulnerable frequency, and the adjustment does not affect the frequency for one system relative to the other. The elimination of redundant consideration of offsite power restoration results in a greater increase in the probability of core vulnerability for the alternate configuration than for the normal configuration. This

would reflect the greater dependency of the alternative system on the 69 KV switchyard availability.

Explicitly considering repair of the gas turbine and EMDs reduces the estimated probability of core vulnerability due to loss of offsite power for the alternate system. The TDI analysis showed a comparable reduction in core vulnerable frequency when repairability was included. This is expected because the system components might be returned to operation even though they may have initially failed to operate.

Combining the corrections in data and methodology described above, and assuming the possibility of repair for both the alternate and normal systems, the probability of core vulnerability due to loss of offsite power, is still about a factor of 4 higher for the alternate system. Furthermore, assuming the accuracy of SAI's estimate of 1.6×10^{-6} for the annual frequency of core vulnerability from all other initiating events during 5 percent operation (SAI 1983 PRA at Table 4-4-1), the likelihood that the Shoreham plant would experience an event leading to core vulnerability during 5 percent operation is approximately 2.8 times greater under the alternate configuration than it is under the normal configuration.

TABLE E-1

PLANT-SPECIFIC POSTERIOR PROBABILITY
FOR THE FREQUENCY OF THE LOOP
(Events Per Year)

RELIABILITY COUNCIL - NPCC

PLANTS IN SITE	N	T	MEAN	5 PERC	50 PERC	95 PERC
1. Fitzpatrick	2	5.55	2.6E-01	9.6E-02	2.4E-01	5.4E-01
2. Ginna	3	10.57	2.6E-01	1.0E-01	2.2E-01	4.6E-01
3. Haddam Neck	5	13.72	3.0E-01	1.3E-01	2.7E-01	5.0E-01
4. Indian Point 2 & 3	4	7.94	3.5E-01	1.4E-01	3.0E-01	6.2E-01
5. Main Yankee	1	7.62	2.0E-01	5.3E-02	1.7E-01	3.8E-01
6. Millstone 1 & 2	1	10.47	1.7E-01	4.5E-02	1.5E-01	3.2E-01
7. Nine Mile Point	1	11.32	1.6E-01	4.3E-02	1.4E-01	3.1E-01
8. Pilgrim	4	7.96	3.5E-01	1.4E-01	3.0E-01	6.2E-01
9. Vermont Yankee	1	8.19	1.9E-01	5.1E-02	1.6E-01	3.7E-01
10. Yankee Rowe	1	20.70	1.2E-01	2.9E-02	1.0E-01	2.2E-01
AGGREGATE	23	104.04	2.5E-01	4.4E-02	1.9E-01	5.8E-01

Source: I. A. Papazoglou et al, Bayes Analysis Under Population Variability With An Application to the Frequency of Loss of Offsite Power in Nuclear Plants, BNL Report, Feb., 1983.

TABLE E-2

REQUANTIFICATION OF SAI EVENT
 TREE FOR CORE VULNERABILITY DUE
 TO LOSS OF OFFSITE POWER TRANSIENT
(Frequency Per Reactor Year)

Type	<u>Gas Turbine/EMD Diesels</u>		<u>TDI Diesels</u>	
	Non-Repairable	Repairable	Non-Repairable	Repairable
1	2.3E-5	1.0E-6	1.4E-6	6.4E-8
2	1.9E-5	1.7E-6	1.2E-5	1.1E-6
3	4.0E-6	2.0E-6	7.0E-7	3.5E-7
4	5.6E-6	1.3E-6	6.8E-7	1.6E-7
5	8.7E-6	2.6E-6	1.2E-6	3.6E-7
Sum	6.0E-5	.87E-5	1.6E-5	.21E-5

Note: Column totals may not exactly equal the sum of the figures in each column due to rounding.