

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Palo Verde Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 5 2 8	PAGE (3) 1 OF 0 2
----------------------------------------	--------------------------------------	----------------------

TITLE (4)  
Automatic Actuation of Balance of Plant Engineered Safety Feature System

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	2	0	8	5	-	0	3	0			0 5 0 0 0
											0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §. (Check one or more of the following) (11)

OPERATING MODE (9) 5	20.402(b)	20.406(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 0 0 0	20.406(a)(1)(i)	50.36(c)(1)	<input type="checkbox"/>	50.73(a)(2)(v)	73.71(c)
	20.406(a)(1)(ii)	50.36(c)(2)	<input type="checkbox"/>	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.406(a)(1)(iii)	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)	
	20.406(a)(1)(iv)	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)	
	20.406(a)(1)(v)	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME William F. Quinn (Extension 6087)	TELEPHONE NUMBER 6 0 2 9 4 3 1 - 7 2 0 1 0
-------------------------------------------	-----------------------------------------------

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH 0 6	DAY 3	YEAR 0 8 5
-------------------------------------------------------------------------------------	-----------------------------	-------------------------------	--------------	----------	---------------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

Automatic actuation of the Control Room Essential Filtration Actuation Signal occurred due to a spurious high radiation alarm on the radiation monitoring unit. All attendant equipment actuated satisfactorily. Spurious actuation was verified by sampling.

The root cause and final corrective action regarding this event are still under investigation and will be addressed in a supplement to this report.

8503180270 850308  
PDR ADOCK 05000528  
S PDR

TE 22  
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Palo Verde Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 5 2 8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 5	- 0 1 1	- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On February 6, 1985, at 2035 Palo Verde Unit 1 was in Mode 5. Train "A" of Shutdown Cooling was in operation when the Control Room Essential Filtration unit was automatically operated by a spurious alarm/actuation from the control room ventilation radiation monitor. All attendant equipment operated satisfactorily.

The Control Room Essential Filtration unit is actuated from the Balance of Plant Engineered Safety Features Actuation System which receives a signal from the control room ventilation radiation monitoring unit. The signal will operate from either a high radiation signal or an equipment failure signal. The system computer identified that high radiation caused the trip; the radiation level indicated 2.19E-06 microcuries per milliliter with a setpoint of 2.20E-06 after the trip. The duration of the alarm was less than 18 seconds.

During investigation it was identified that the radiation alarm setpoint was greater than allowed by the Technical Specifications. The setpoint that was in effect was the default value which is stored in the radiation monitor's microcomputer software. The radiation monitor restores the default value for setpoints after a loss of power. The plant's redundant radiation monitor was operable with setpoints consistent with the Technical Specifications and the minimum channels needed to be operable per the Technical Specifications was satisfied.

The following action was taken: the high radiation alarm setpoint was adjusted to be conservative with the Technical Specifications and a plant change request has been generated to modify the microcomputer software default values to be consistent with the Technical Specifications. Plant procedures are in effect to verify that setpoints are in compliance with the Technical Specifications.

The cause of the high radiation signal was not identified. The range of the instrument is 1E-06 to 1E-01 microcuries per milliliter. The setpoint of 2E-06 is near the lower end of the range of the detector. Subsequent random spikes of indicated radiation levels have been observed on this monitor. Routine radiological surveys have not detected airborne radiation above naturally occurring background levels. It is, therefore, believed that these random spikes of radiation levels are due to electronic circuit noise. Although none of the spikes have been of sufficient magnitude to cause a high alarm/actuation, this actuation is considered random and has not occurred since February 6, 1985.

LER 85-003-00 was also concerned with the automatic actuation of the Control Room Essential Filtration Actuation Signal due to a spurious high radiation alarm on the radiation monitoring unit.

The root cause and final corrective action regarding this event are still under investigation and will be addressed in a supplement to this report.



## Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

ANPP-32098-EEVB/WFQ/GEC

March 8, 1985

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Palo Verde Nuclear Generating Station (PVNGS)  
Unit 1  
Docket No. STN 50-528, License No. NPF-34  
Licensee Event Report  
File: 85-056-026; G.1.01.10

Dear Sirs:

Attached please find Licensee Event Report (LER) No. 85-011-00 prepared and submitted pursuant to 10 CFR 50.73. By copy of this letter we are also forwarding a copy of the LER to the Regional Administrator of the Region V Office.

If you have any questions or concerns, please contact me.

Very truly yours,

E. E. Van Brunt, Jr.  
Executive Vice President  
Project Director

EEVB/GEC/mb  
Attachment

cc: J. B. Martin  
R. P. Zimmerman  
E. A. Licitra  
A. C. Gehr  
INPO Records Center

IE22  
/1