

LICENSEE EVENT REPORT (LER)

| | | |
|---|---|-----------------------------|
| FACILITY NAME (1) BEAVER VALLEY, UNIT I | DOCKET NUMBER (2) 0 5 0 0 0 3 3 4 | PAGE (3) 1 OF 0 2 |
|---|---|-----------------------------|

TITLE (4)
SEISMIC MONITOR INOPERABLE MORE THAN 30 DAYS

| EVENT DATE (5) | | | LER NUMBER (6) | | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | | | | | | | | | | | | | | | |
|----------------|----------|----------|----------------|-------------------|-----------------|-----------------|----------|----------|-------------------------------|----------|------------------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAMES | | DOCKET NUMBER(S) | | | | | | | | | | | | | |
| 1 | 0 | 2 | 7 | 8 | 4 | 8 | 4 | 0 | 0 | 1 | 6 | 0 | 0 | 1 | 2 | 2 | 0 | 8 | 4 | 0 | 5 | 0 | 0 | 0 |

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

| | | | | |
|--------------------------------|--|---|---|--|
| OPERATING MODE (9) 5 | <input type="checkbox"/> 20.402(b) | <input type="checkbox"/> 20.406(c) | <input type="checkbox"/> 50.73(a)(2)(iv) | <input type="checkbox"/> 73.71(b) |
| | <input type="checkbox"/> 20.406(a)(1)(i) | <input type="checkbox"/> 50.36(e)(1) | <input type="checkbox"/> 50.73(a)(2)(v) | <input type="checkbox"/> 73.71(c) |
| | <input type="checkbox"/> 20.406(a)(1)(ii) | <input type="checkbox"/> 50.36(e)(2) | <input type="checkbox"/> 50.73(a)(2)(vii) | <input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A) |
| | <input type="checkbox"/> 20.406(a)(1)(iii) | <input type="checkbox"/> 50.73(a)(2)(i) | <input type="checkbox"/> 50.73(a)(2)(viii)(A) | |
| | <input type="checkbox"/> 20.406(a)(1)(iv) | <input type="checkbox"/> 50.73(a)(2)(ii) | <input type="checkbox"/> 50.73(a)(2)(viii)(B) | |
| | <input type="checkbox"/> 20.406(a)(1)(v) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input type="checkbox"/> 50.73(a)(2)(ix) | |

LICENSEE CONTACT FOR THIS LER (12)

| | |
|--|--|
| NAME ROBERT J. DRUGA, Manager Technical Services | TELEPHONE NUMBER 4 1 2 6 4 3 - 5 3 0 8 |
|--|--|

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPRDS | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPRDS |
|----------|----------|-----------|--------------|---------------------|----------|----------|-----------|--------------|---------------------|
| X | I | N | M | O | N | T | 1 | 3 | 9 |

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

| | | | |
|-------------------------------|-------|-----|------|
| EXPECTED SUBMISSION DATE (15) | MONTH | DAY | YEAR |
| | | | |

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

The unit was in operational Mode 5 during a scheduled refueling shutdown. During the performance of a refueling frequency test, metal filings were found in one (1) of the seismic sensors. The filings could not be cleaned out enough for reuse, so a spare sensor was obtained from the storeroom. It was found that the spare sensor had a sensitivity range of ±2g rather than the ±1g required by Beaver Valley Technical Specification (Tech. Spec.) 3.3.3.3. The sensor was returned to the vendor to be reworked.

When the transmitter did not return from the vendor within the requested ninety (90) days, the report date was not flagged. Therefore this submittal of a late report. Personnel involved in the reporting have been counseled on the necessity for thorough and timely reporting.

8501170258 841220
PDR ADOCK 05000334
S PDR

LE22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | | |
|--|--|----------------|-------------------|-----------------|----------|----|-----|
| FACILITY NAME (1) BEAVER VALLEY, UNIT I | DOCKET NUMBER (2) 0 5 0 0 0 3 3 4 8 4 | LER NUMBER (8) | | | PAGE (3) | | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| | | 8 4 | 0 1 6 | 0 0 0 | 2 | OF | 0 2 |

TEXT (If more space is required, use additional NRC Form 365A's) (17)

Beaver Valley had been operating in operational Mode 5 during a scheduled refueling outage. On October 27, 1984, Maintenance Surveillance Procedure (MSP) 45.04, "Peak Recording Accelerometer Calibration," was being performed. During the test metal filings were found in the seismic sensor located on top of the Recirculation Spray Cooler. The filings could not be cleaned out enough for reuse of the sensor so a spare sensor was obtained from spare parts. It was found, however, that the sensitivity range of the spare was rated at $\pm 2g$ as opposed to the $\pm 1g$ as required by Beaver Valley Tech. Specs. The vendor was notified and recommended that the spare sensor be returned in order to be reworked for a rating of $\pm 1g$.

During the first part of December the reworked sensor had not yet been returned to Beaver Valley. On December 8, 1984, a similar sensor located at the Primary Plant Component Cooling Water (CCW) Heat Exchanger, which was to be retubed, was removed and placed on the Recirculation Spray Heat Exchanger. On December 14, 1984, the recalibrated sensor was received back at the station and is currently scheduled to be placed at the Primary Plant CCW Heat Exchanger as soon as the retubing is complete.

The cause of the sensor failure was due to the metal filings. However, it is presently unknown where the filings had originated from. The delay in the sensor's return from the vendor was abnormal. Delays at the vendor and return delivery delays contributed to the sensor being out at the vendor for more than thirty (30) days. Human error was the cause of missing the reporting requirement because of the dependence on vendor deliveries which are normally reliable.

There were no safety implications due to the incident. The health and safety of plant personnel and the general public were not jeopardized at any time. No seismic events occurred during the period that the sensor was not operable and all remaining sensors remained operable throughout the entire time.



Duquesne Light

Nuclear Division
P. O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 393-6000

December 28, 1984
NDISS1:2309

Beaver Valley Power Station, Unit No. 1
Docket No. 50-334, License No. DPR-66
LER 84-016


Dr. Thomas E. Murley
Regional Administrator
United States Nuclear Regulatory Commission
Region I
Park Avenue
King of Prussia, Pennsylvania 19046

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 84-016, information report on "Seismic Instrumentation," related to Technical Specification 3.3.3.3.

Very truly yours,


Wm. S. Lacey
Plant Manager

WSL:mh

Attachment

IB22
//

T. E. Murley
December 28, 1984
ND1SS1:2309
Page two

cc: Director of Management & Program Analysis
United States Nuclear Regulatory Commission
Washington, D.C. 20555

C. A. Roteck, Ohio Edison

Director, Office of Inspection and Enforcement Headquarters
United States Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Peter Tam, BVPS Licensing Project Manager
United States Nuclear Regulatory Commission
Washington, D.C. 20555

W. Troskoski, Nuclear Regulatory Commission, BVPS Site Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator, Toledo Edison

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Mr. J. A. Triggiani, Operating Plant Projects Manager
Mid Atlantic Area
Westinghouse Electric Corporation
Nuclear Services Integration Division
Box 2728
Pittsburgh, PA 15230

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CN 06032