19-43)	w n 264					CENS	EE EVE	NT R	EPORT	(LER)	U.S. N	APPROVED C	OHE NO. 216					
L	142	ick			g Stati			it 1			0 6 0 0		2 1 0	F 01				
R	eact	or v	late	clear	nup Iso	olat:	ion											
EVENT DATE (8) LER NUMBER (6)						-	PORT DAT	£ 177		OTHER	FACILITIES INVOLVED IN							
HUNTI	DAY	YEAR	YEAR	NUMBE	AL MEVER	MONTH	DAY	YEAR		PACILITY NAM	Lo	DOCKET NUMBERIE						
												0 5 0	0101					
1/2	2 1 1 8 4 8 4 0 3 2 0 0				0 0 1	10	8 5		uz. zode	6.0	0.5.0.0							
00	ERATING	4	THIS REP	ORT IS BUSMIT	TEO PURBUANT	TO THE A	COUREM	NTS OF 1	0 CFR \$. 1	Check one or more of	f the fallowing) (1)	1)	101					
20,406(a)(1)(a) 20,406(a)(1)(a) 20,406(a)(1)(a) 20,406(a)(1)(a) 20,406(a)(1)(a)				50,34(a) 50,34(a) 50,73(a) 50,73(a) 50,73(a)	(2) (2)(i) (2)(ii) (2)(iii)	POR THIS	150 (12)	80.73(a)(2)(iv) 80.73(a)(2)(v) 80.73(a)(2)(vii) 80.73(a)(2)(viii)(A) 80.73(a)(2)(viii)(B) 80.73(a)(2)(a)		72.71(a) 72.71(a) OTHER IS Delegated	rivact C Farm							
JC	hn (c. N	agle	, Engi	neer/S	uper	viso	ry			AREA CODE	8 4 1 -	. 5. 1.	. 8,4				
				COMPLET	ONE LINE FOR	EACH CO	MPONENT	FAILURE	DESCRIBE	O IN THIS REPORT	(13)							
LAUSE	SYSTEM	TEM COMPONENT		MANUFAC TURER	TO NPROS				SYSTEM	COMPONENT	MANUFAC TURER	MEPORTABLE TO MPROS						
		11	,	111		***				111	111							
	1	11		111		(A.A.)				111	111							
				SUPPLEM	ENTAL REPORT	EXPLOTED	114)					MONTH	CAY	YEAR				
_	(11			UBMISSION DAT		×	1 40				SUBMISSIO DATE (16)	N						

Abstract: 84-032

On December 11, 1984, the Reactor Water Cleanup (RWCU) inboard suction valve closed to the isolation position upon receiving a high ambient temperature trip signal. Cause of the event was personnel error. After the trip signal was cleared, the RWCU system was returned to service.

En

A-1

NAC Form 344A 15-831	LICENSEE EVENT REPORT II ERI TEXT CONTINUATION													-	PLATORY COMMISSION NO. 3150-0104							
	Generating Station			DOCKET NUMBER (2)						YEAR	-	1110	QUENTIAL AEVISION					PAGE (3)				
Unit 1			0	1:	5	0	0	0	13	15	12	814	_	0	3	2	_	010	0	2	OF	013
TEXT III more word is requi	ed, use additional NRC Form	3664 (17)		_		-	_		-	-	-	-	_	-	-	-	-	-	-	-	-	

Description of the Event:

On December 11, 1984, at 3:40 p.m., prior to initial criticality, the Reactor Water Cleanup (RWCU) system inboard suction valve, HV-44-IF001, received an inadvertent high ambient temperature trip isolation signal. HV-44-IF001 isolated properly to the closed position. After the isolation signal was cleared, the RWCU system was returned to normal operation.

Consequences of the Event:

The portion of the RWCU system affected by the high ambient temperature signal isolated properly. There were no adverse consequences.

Cause of the Event:

At the time of the event, instrument and controls technicians were performing a surveillance test on a RWCU outboard logic high ambient temperature isolation switch. Since actuation of any one of these temperature switches causes the RWCU outboard suction valve, HV-44-IF004, to isolate closed, the surveillance test requires blocking HV-44-IF004 in the open position if RWCU is in service at the time of the test. HV-44-IF004 was blocked in the open position with its feed removed as required by the surveillance test.

Concurrent with the performance of the surveillance test referenced above, a second group of instrument and controls technicians was attempting to resolve a problem with another RWCU high ambient temperature isolation switch, TDTS-44-IN602N. This group believed that TDTS-44-IN602N was also in the outboard RWCU isolation logic, and the group verified that HV-44-IF004 was blocked open prior to start of work. However, TDTS-44-IN602N is actually in the inboard RWCU isolation logic. As a result, the inboard RWCU suction valve, HV-44-IF001, isolated to the closed position when TDTS-44-IN602N was actuated during checkout.

NRC form 3n4A 15 431	LICENSEE	ULATORY COMMISSION US NO. 3150-0104 AS										
FACILITY NAME (1)			DOCKET NUMBER (2)			-	1		PAGE IN			
	Generating	Station		TEAR		SIGULATIAL		ALVISION NUMBER		T	T	
Unit 1			0 15 10 10 10 13 15 12	81 4	_	01312	_	010	01	3 01	0	13

TEXT (III more space is required, and additional NAC Form 3660 (17)

Corrective Actions:

The instrument and controls personnel involved with actuating the inboard logic isolation switch were reminded of the importance of reviewing the proper electrical schematics prior to starting work on safety-related systems.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

January 10, 1985

Docket No. 50-352

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

SUBJECT:

Licensee Event Report Limerick Generating Station - Unit 1

This LER deals with the automatic isolation of the Reactor Water Cleanup system. This event occurred prior to initial criticality.

Reference:

Docket No. 352

Report Number:

84-032 00

Revision Number:

Event Date: Report Date: Facility:

December 11, 1984 January 10, 1985

Limerick Generating Station

P.O. Box A, Sanatoga, PA 19464

This LER is submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(iv).

Very truly yours,

mullenl

W. T. Ullrich Superintendent

Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator, Region I, USNRC J. T. Wiggins, Senior Site Inspector See Service List

Judge Helen F. Hoyt cc: Judge Jerry Harbour Judge Richard F. Cole Judge Christine N. Kohl Judge Gary J. Edles Judge Reginald L. Gotchy Troy B. Conner, Jr., Esq. Ann P. Hodgdon, Esq. Mr. Frank R. Romano Mr. Robert L. Anthony Ms. Phyllis Zitzer Charles W. Elliott, Esq. Zori G. Ferkin, Esq. Mr. Thomas Gerusky Director, Penna. Emergency Management Agency Angus Love, Esq. David Wersan, Esq. Robert J. Sugarman, Esq. Martha W. Bush, Esq. Spence W. Perry, Esq. Jay M. Gutierrez, Esq. Atomic Safety & Licensing Appeal Board Atomic Safety & Licensing Board Panel Docket & Service Section (3 Copies) James Wiggins Timothy R. S. Campbell