

South Carolina Electric & Gas Company P.O. Box 88 Jenkinsville, SC 29065 (803) 345-4344 Gary J. Taylor Vice President Nuclear Operations

June 13, 1996 RC-96-0143

Document Control Desk U. S. Nuclear Regulatory Commission Washington, DC 20555

Gentlemen:

Subject: VIRGIL C. SUMMER NUCLEAR STATION DOCKET NO. 50/395 OPERATING LICENSE NO. NPF-12 LICENSEE EVENT REPORT (LER 960004)

Attached is Licensee Event Report No. 96-004 for the Virgil C. Summer Nuclear Station. This report is submitted pursuant to the requirements of 10CFR50.73(a)(2)(ii).

Should you have questions, please call Mr. Jim Turkett at (803) 345-4047.

Gary Tawor You

JWT/GJT/nkk Attachment

c: J. L. Skolds W. F. Conway R. R. Mahan (w/o attachment) R. J. White S. D. Ebneter A. R. Johnson S. R. Hunt S. F. Fipps A. R. Koon G. E. Williams

K. R. Jackson D. L. Abstance NRC Resident Inspector J. B. Knotts Jr. INPO Records Center Marsh & McLennan NSRC RTS (TSP 960002) Files (818.07) DMS (RC-96-0143)

180025

9606190164 960613 PDR ADOCK 05000395 S PDR

TEU



NUCLEAR EXCELLENCE - A SUMMER TRADITION!

Document Control Desk LER 960004 RC-96-0143 Page 2 of 2

STATE OF SOUTH CAROLINA

TO WIT :

COUNTY OF FAIRFIELD

I hereby certify that on the 13^{-74} day of $5c \sim e$ 19.76, before me, the subscriber, a Notary Public of the State of South Carolina personally appeared Gary J. Taylor, being duly sworn, and states that he is Vice President, Nuclear Operations of the South Carolina Electric & Gas Company, a corporation of the State of South Carolina, that he provides the foregoing response for the purposes therein set forth, that the statements made are true and correct to the best of his knowledge, information, and belief, and that he was authorized to provide the response on behalf of said Corporation.

1

-

WITNESS my Hand and Notarial Seal

Notary Public

My Commission Expires

July 26, 2005 Date

M

	U.S. NUCLEAR REGULATORY COMMISSION (4-95) LICENSEE EVENT REPORT (LER)						APPROVED BY OMB NO. 3150-0104 EXPIRES 04/30/98 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THI MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO TH LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARI COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATIO AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAN REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TI THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE O								
FACILITY NAM	E (1)							mention sector and	MANAGE	ME	NT AND BUDGET,	WASHINGT	ON, DC	20503	MARCE C
	- 117								DOURETI	UNI	DCH (2)			PAGE	(3)
Virgil C. Summer Nuclear Station						1.1			05000395			1 OF	7 5		
Unanalyz	ed C	ondit	ion Re	garding Rea	ctor Bu	ilding Li	ine Bi	reak Ar	nalyses	5					
MONTH	DATE	YEAR	YEAR	SEQUENTIAL	(6)	REPO	TDAY	TE (7)	FACILITY	VALE	OTHER FAC	ILITIES IN	OLVEL	(8)	
		TERMI	TEAT	NUMBER	NUMBE	A	DAT	TEAR	PAULIT NAME				05000		
0.5	12	06	0.6	0.4	0		10	0	FACILITY NAME				DOCKET NUMBER		
OPERATI	13	96	90	04 -	- 01	0 06	13	96	No. of Concession, Name	-		and the party of the second	and the second second	0500	00
MODE))	5	120	2201(b)	MITED P	20 2203	(a)(2)/	TEQUI	HEMENT	50	73(a)(2)(0)	heck one or	more)	11)	A CHIN
POWER	POWER 20.2203(a)(1)			20 2203	20.2203(a)(3)(i)			¥ 50.73(a)(2)(ii)			50.73(a)(2)(vil)				
LEVEL (1	LEVEL (10) 0 20.2203(a)(2)()		20.2203	20.2203(a)(3)(ii)			50.73(a)(2)(iii)		73.71		//*/				
deset of the second second	ion a company the s		20. 20. 20.	2203(a)(2)(ii) 2203(a)(2)(iii) 2203(a)(2)(iv)		20.2203 50.36(c) 50.36(c)	(a)(4) (1) (2)		50.73(a)(2)(iv) 50.73(a)(2)(v) 50.73(a)(2)(v)		OTHER Specify in Abstract below or in NRC Form 366A				
	RANSON DECTOR	ane na manada	and an and a second		LICE	NSEE CON	TACT	FOR THE	S LER (1	2)			-	NOBUCININAL	
George A Manager, CAUSE SV	Nucl	pard, lear L	III Licensi COM	ng & Operat	ing Ex For Ex Urier	perience CH COMPC	ONENT	CAUSE	E DESCI	THE PHO	(8 0 3 COMPONENT	e Area Code)) 3 4 5 - ORT (13) MANUFAI	- 4 8 1		OHTABLE
		-				TO NPHD	2							TO	NPADS
x	BA					N									
remetation in case of a survey		SI		ENTAL REDAR	FYDE	ED AA				cacesa a	EVDEATED	LEPCT			1 1 1 1 1 1
(If yes, co	omplete	e EXPE	CTED S	UBMISSION DA	TE).		x	NO			SUBMISSION	MON		UAY	TEAR

motor-driven Emergency Feedwater (EF) pumps in operation, even though the EF flow control valves (FCVs) were closed. On May 13, 1996, it was determined that this condition was not covered by the Emergency Operating Procedures (EOPs) and may not be addressed in the safety analysis report.

The EF FCV leakage could impact the safety analysis in three areas: 1) the reactor building (RB) flood level for a steamline break (SLB) inside containment, 2) long term RB pressure response for a postulated SLB inside containment and 3) EF flow diversion from the intact SGs during a postulated feedwater line break.

Any potential adverse effect to the plant would have been restricted to an event requiring EF isolation. The cause of this condition is attributed to normal degradation of the valve seats. Engineering analysis has determined that, with operator action by 30 minutes into the event, manual isolation of the EF FCV leakage will assure the established safety criteria are met. Applicable EOPs have been revised to require operator action to close manual valves located upstream and downstream of the FCVs to assure EF flow to a faulted SG is terminated. The leaking valves will be reworked by the end of the next refueling currently planned for the Fall of 1997.

NRC FORM 366 (4-95)

NRC ÉORM 366A			U.S. NU	CLEAR REGUL	ATORY
(5-92)			APPF	OVED BY OMB	NO. 3150-0104
LICENSEE EVENT REPOR	T (LER) TEXT (CONTIN	JUATION	EXPIR	IES 5/31/95
FACILITY NAME (1)	DOCKET NUMBER		PAGE (2)		
		YEAR	NUMBER	NUMBER	
Virgil C. Summer Nuclear Station	05000395	96	04	00	2 OF 5
TEXT (If more space is required, use additional copies of NRC	Form 366A) (17)	dia mana managana		ALL DE LE	
PLANT IDENTIFICATION:					
Westinghouse - Pressurized Water Peactor					
Westinghouse - Hessinized Water Reactor					
DOUTED AT THE THE PRESENCE THE PARTY OF THE					
EQUIPMENT IDENTIFICATION:					
Motor Driven Emergency, Peedwater Dump El	Control Males III	10050	EE 100.00	1 55 15100	
Motor-Driven Emergency Feedwater Pump Fig	ow Control Valves IP	VU3531	I-EF, IFV0354	1-EF, 1FV03.	551-EF
Turbine-Driven Emergency Feedwater Pump F	low Control Valves I	FV0353	36-EF, IFV035	46-EF, IFV0	3556-EF
EIIS System Code - BA					
IDENTIFICATION OF EVENT:					
During Integrated Safeguards Testing, steam ge	enerator levels were o	observed	increasing as	a result of lea	kage past
the Motor-Driven Emergency Feedwater Pump	Flow Control Valve	s. Upor	n further invest	igation on Ma	ay 13,
					-
1996, it was determined that flow past these va	lves may result in an	unanalyz	zed condition a	ssociated with	h the
1996, it was determined that flow past these va reactor building line break analyses. This conce	lves may result in an ern was expanded to i	unanalyz include t	zed condition a the Turbine-Dr	ssociated with	h the hcy

EVENT DATE:

May 13, 1996

REPORT DATE:

June 13, 1996

This report was generated by Off-Normal Occurrence Report 960243.

CONDITIONS PRIOR TO THE EVENT

MODE 5 0% Reactor Power

NRC FORM 366A (5-92)

NRC FORM 366A COMMISSION				U.S. NUC	LEAR REGUL	ATORY	
(5-92)	LICENSEE EVENT REPORT	(LER) TEXT C	APPROVED BY OMB NO. 3150-010 CONTINUATION EXPIRES 5/31/95				
	DOCKET NUMBER	LER NUMBER (6)			PAGE (3)		
			YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Virgil C	05000395	96	04	00	3 OF 5		

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

DESCRIPTION OF EVENT

On May 13, 1996, plant personnel determined that leakage past the flow control valves of the Emergency Feedwater (EF) Pumps has the potential for placing the plant in an unanalyzed condition in regards to the Reactor Building line break analyses. The plant was in a refueling outage (Mode 5) conducting Integrated Safeguards Testing when the leakage was detected through observation of increasing steam generator water levels.

CAUSE OF EVENT:

The cause of the event is attributed to normal degradation of the valve seats. The valves are used to adjust feedwater flow to the steam generators during start-up and shutdown. These valves have been in service since the system was contructed and have not required any work to be performed on their seats prior to the event.

Additionally, valve operator air pressure was determined to have an influence on the amount of leakage by not maximizing seating thrust during valve closure. Air operator pressure for the valves was adjusted, as necessary, to provide additional seat loading. Additional testing of the motor-driven EF pump lines was performed to further quantify leakage through the flow control valves when closed and to determine if flow leakage could be isolated by closing the upstream or downstream manual isolation valves associated with the flow control valves. This additional testing confirmed the flow control valves were still leaking in the closed position, but that flow was terminated when either manual isolation valve was closed.

ANALYSIS OF EVENT:

The EF flow control system is designed to isolate flow to a faulted steam generator to limit the mass input to containment, and to terminate the diversion of flow from the intact steam generators. Under certain specific single failure scenarios, the analysis did not address the potential for leakage past a closed EF flow control valve.

NRC FORM 366A COMMISSION (5-92)	LICENSEE EVENT REPORT	(LER) TEXT C	U.S. NUCLEAR REG APPROVED BY O TEXT CONTINUATION				
	DOCKET NUMBER	[LER NUMBER	(6)	PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Virgil C	05000395	96	04	00	4 OF 5		

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

ANALYSIS OF EVENT: (Cont'd)

A leaking flow control valve could impact the plant safety analyses in three areas: 1) the reactor building flood level for a steam line break inside containment, 2) long term reactor building pressure response for a postulated steam line break inside containment and 3) emergency feedwater flow diversion from the intact steam generators during a postulated line break. Supplemental analyses of these three areas had to address the leakage from initiation of the event until the operator manually isolates emergency feedwater flow to the faulted steam generator within 30 minutes. To assure that these additional analyses encompassed any additional leakage, a conservative value of 50 GPM was established as the maximum leakrate through any flow control valve.

The conclusions of these analyses are that an additional 50 GPM emergency feedwater flow control valve leakage is acceptable to assure that the plant is maintained within its design basis provided that flow control valve leakage is terminated within 30 minutes from the start of the event.

IMMEDIATE CORRECTIVE ACTIONS:

Following identification of the concern on May 13, 1996, additional testing was performed to further quantify the worst case leakage and to establish if closure of the upstream and/or downstream manual isolation valves would stop the leakage. The leakage was terminated successfully by manual isolation, so the applicable Emergency Operating Procedures (EOPs) were revised to require operator action to manually close the emergency feedwater isolation valves to a faulted steam generator. Validation of the EOPs was performed on the Control Room Simulator and through in-plant walkdown. Engineering reviews were performed on the leakage rate data to confirm that the leakage was much less t¹ 50 GPM and would meet analysis assumptions provided appropriate operator action was taken.

Based on the conclusions of the engineering analyses and the revisions to the applicable emergency operating procedures, continued operation does not present an adverse impact on safety.

NRC FORM 366A COMMISSION			di hulo da invandar ondar	U.S. NUC	LEAR REGUL	ATORY
(5-92)	LICENSEE EVENT REPORT	(LER) TEXT C	APPROVED BY OMB NO. 3150-010 CONTINUATION EXPIRES 5/31/95			
	DOCKET NUMBER		LER NUMBER	(6)	PAGE (3)	
			YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Virgil C.	05000395	96	04	00	5 OF 5	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

ADDITIONAL CORRECTIVE ACTIONS

The following additional action is planned:

 Rework leaking EF flow control valves prior to restart from the next refueling (RF10) currently scheduled for Fall 1997.

PRIOR OCCURRENCES:

None