

PERRY NUCLEAR POWER PLANT

10 CENTER ROAD PERRY, OHIO 44081 (216) 259-3737 Mail Address: PO. BOX 97 PERRY, OHIO 44081

September 19, 1996 PY-CEI/NRR-2095L

United States Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Perry Nuclear Power Plant Docket No. 50-440 LER 96-007-00

Gentlemen:

Enclosed is Licensee Event Report 96-007-00, Design Modification Program Weakness Results in Missed Surveillance Requirements and Technical Specification Violations.

If you have questions or require additional information, please contact Mr. James D. Kloosterman, Manager - Regulatory Affairs at (216) 280-5833.

Terr

Very truly yours,

L. W. Myers

L. W. Myers Vice President - Nuclear

CRE:SC

Enclosure: LER 96-007-00

cc: NRC Region III Administrator NRC Resident Inspector NRC Project Manager



240032 Operating Companies Cleveland Electric Illuminating Toledo Edison

FACILITY NAME (1) Perry Nuclea Title (4)	(S	ee reverse	LICENSEE EV CAL REPORT (LER)								N APPROVED BY OMB NO. 3150-0104 EXPIRES 04/30/98 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATI COLLECTION REQUEST: 50.0 HRS. KEPORTED LESSONS LEARNED ARE INCORPORATED IN THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARD BURDEN ESTIMATE TO THE INFORMATION AND SECOND AND SECOND					
FACILITY NAME (1) Perry Nuclea	STALL OF A DESIGNATION OF A	digits/chara	(See reverse for sig and number of digits/charactics (or each block)						U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT / WASHINGTON, DC 20503.							
TITLE (4)	Perry Nuclear Power Plant, Unit 1						DOCKE	O50	000440		1	AGE (3) OF 8				
Design Modi Violations	ication	Program \	Weakness	Results i	n Misse	d Surv	eilland	ce Re	quiremer	nts and Tech	nnical S	pecific	ation			
EVENT DAT	E (5)	LE LE		6)	I REPO	RTDAT	E (7)	-	0	THER FACILITI	ES INVO	LVED (8)	REAL COLOR OF COLOR OF COLOR			
MONTH DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION	MOWTH	DAY	YEAR	FACILI	FACILITY NAME			OSOOO				
08 21	96	96	007 -	- 00	09	19	96	FACILI	TY NAME		1	OCKET NO	MBER 5000			
OPERATING MODE (9)		THIS REPO	RT IS SUBMI	TTED PUR	SUANT T	O THE P	EQUIRI	EMENT	S OF 10 C	R : (Check o	ne or mo	ore) (11)				
POWER		20.22	03(a)(1)		20.2203	203(a)(2)(v)			X 50.73(a	i)(2)(i)		50.7	3(a)(2)(viii)			
LEVEL (10)	100	20.22	03(a)(2)(i)		20.2203	3(a)(3)(ii)			50.73(2	(2)(1)		73.71				
WANTED IN A LOSS BUT OF SHERE	Contrast Contrasts of Contrasts	20.22	03(a)(2)(ii)		20.2203	3(a)(4)			50.73(a)(2)(iv)			X OTHER				
		20.22	03(a)(2)(iii)		50.36(c)(1)			50.73(a	a)(2)(v)	1	Specify in Abstract below or in NRC Form 366A				
Charmed by an a strange of the strange	TO DATA NEW COLD	20.22	03(a)(2)(iv)	ILEPPE	50.36(c))(2)			50.73(a	a)(2)(vii)						
NAME				LICEN	ISEE CON	TACT F	OR THIS	S LER (12) TELEPHONE NO	JMBER (Include Are	a Code)					
Keith E. Jury	, Super	visor-Com	pliance							(216)	280-5	594				
ananan (5), (5), (6), 70, 7	946 ··· 200000	COMPL	ETE ONE LIN	E FOR EAC	HCOMP	ONENT P	AILURI	E DESC	RIBED IN T	HIS REPORT (3)					
CAUSE	STSTEM	COMPONENT	MANUFACT	URER RE	PORTABLE O NPRDS		CAU	JSE	SYSTEM	COMPONENT	MANUF	ACTURER	REPURTABLE TO NPRDS			
		TIDDI EMEN	TAL PERART	EVECTET	577.81				FV	PATER	LICETU		VPAR			
VES (If yes, corr	plete EXP	ECTED SUB	MISSION DA	TE).		XNC)	SUBMISSION			MUNT	JAT	TEAN			

instructions (SVIs) resulted in a condition prohibited by the plant TS. A complex modification to Leak Detection system instrumentation was installed during the last refueling outage; however, associated SVIs were not properly revised to account for the complete logic system functional and channel calibration TS surveillance requirements (SRs). As a result, the two SVIs were inadequate to demonstrate that the applicable TS SRs were met. Performance of applicable sections of revised SVIs to verify the relay contacts in question was successfully completed in accordance with the 24 hour time period allowed by TS SR 3.0.3. This event is being reported in accordance with 10CFR50.73(a)(2)(i)(B) and the Perry Nuclear Power Plant, Unit No. 1 Facility Operating License, Section 2.F.

The cause of this event is a weakness in the design modification process. The process does not include sufficient detail to ensure critical functional testing and performance requirements are identified for post-modification testing.

The design modification process is being revised to provide detailed requirements for prescribing functional testing and performance requirements.

Characteristic and the second se		THE PROPERTY AND ADDRESS OF ADDRE	
NRC FORM 366A		U.S. NUCLEAR REGULATORY	COMMISSION
(4-30)	LICENCEE EVENT DEPOST (LED)		
	LICENSEE EVENT REPORT (LER)		

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET	The second second	LER NUMBER (PAGE (3)			
	05000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF	8
Perry Nuclear Power Plant, Unit 1	440	96	007	00			

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

I. Introduction

On August 21, 1996, at approximately 1500 hours, it was determined that the omission of isolation logic verification within two Technical Specification (TS) surveillance instructions (SVIs) resulted in a condition prohibited by the plant TS. On August 22, at 1305 hours, a 24-hour non-emergency notification No. 30911 was made to the NRC as required by the Perry Nuclear Power Plant, Unit No. 1 Facility Operating License, Section 2.F. This event is being reported in accordance with 10CFR50.73(a)(2)(i)(B) and the Facility Operating License, Section 2.F.

At the time of the event, the plant was in Mode 1 at 100 percent of rated thermal power. The reactor pressure vessel pressure was at approximately 1024 psig with reactor coolant at saturated conditions.

II. Event Description

In February and March 1996, during Refueling Outage 5, Design Change Package (DCP) 87-725 was installed in the plant to replace selected Riley Temperature Modules with Nuclear Measurement Analysis and Control (NUMAC) Leak Detection Monitors (LDMs) in the Leak Detection system (E31). As part of the design change process, the associated TS SVIs were revised to accommodate testing of the modified instrument channels. SVI-E31-T0086-A, "NUMAC LDM Calibration for 1E31-N700A," and SVI-E31-T0086-B, "NUMAC LDM Calibration for 1E31-N700B," were utilized for the post-modification testing of the work orders that installed the NUMAC LDMs.

Performance of these SVIs is intended to fully meet the channel calibration TS Surveillance Requirements (SR) 3.3.6.1.4, and partially meet the logic system functional test TS SR 3.3.6.1.5, for the Primary Containment and Drywell Isolation Instrumentation channels listed in TS SR Table 3.3.6.1-1. The specific items affected are 1.e., 3.e., 3.f., 3.g., 3.h., 4.c., 4.d., 4.e., 4.f., 4.g., 4.h., 4.i., and 5.a. SVI-E31-T0086-A verifies calibration for LDM 1E31-N700A and verifies operability for relay output unit 1E31-N702A. SVI-E31-T0086-B verifies calibration for LDM 1E31-N700B and verifies operability for relay output unit 1E31-N702B. SVI-E31-T0086-A was completed February 25, 1996, and SVI-E31-T0086-B was completed March 10, 1996. Both SVIs are required to be performed on an 18-month frequency.

On August 20, 1996, at 1500 hours, during surveillance/drawing review activities for SVI-E31-T0086-A and B, it was discovered that the following relay contacts had been omitted from testing for the Reactor Core Isolation Cooling (RCIC)[BN], Reactor Water Cleanup (RWCU)[CE], and Residual Heat Removal (RHR)[BO] systems' respective isolation logic. The specific contacts and their system function(s) are delineated below.

Relay	1E31-N702A-K5	Contacts	5	and	9	Division	1	RCIC	Isolation	Logic
Relay	1E31-N702B-K5	Contacts	5	and	9	Divisic	2	RCIC	Isolation	Logic

NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

1.1	TEXT	CONTINUATION	

FACILITY NAME (1)	DOCKET		LER NUMBER	3 (6)	1	PAGE (3)
	05000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF	8
Perry Nuclear Power Plant, Unit 1	440	96	007	00			

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Relay	1E31-N702A-K6	Contacts	5	and	9	Division	1	RWCU Isolation Logic
Relay	1E31-N702B-K6	Contacts	5	and	9	Division	2	RWCU Isolation Logic
Relay	1E31-N702A-K7	Contacts	5	and	9	Division	1	RHR Isolation Logic
Relay	1E31-N702B-K7	Contacts	5	and	9	Division	2	RHR Isolation Logic

As a result of the deficiencies identified with the surveillance tests, at 1630 hours on August 20, 1996, the provisions of TS SR 3.0.3 were invoked for TS Limiting Condition for Operations (LCOs) 3.3.6.1 Primary Containment and Drywell Isolation Instrumentation, Table 3.3.6.1-1 Items 3.f., 4.i., and 5.a. SR 3.0.3 specifies that if it is discovered that a surveillance was not performed within its specified frequency, then compliance with the requirement to declare the LCO not met may be delayed, from the time of discovery, up to 24 hours or up to the limit of the specified frequency, whichever is less. This delay period is permitted to allow performance of the surveillance. For the case of this situation, the surveillance requirements not met for the instrument channels were SR 3.3.6.1.4 (Channel Calibration) and SR 3.3.6.1.5 (Logic System Functional Test), which both have an 18 month frequency. The 24 hour time provision was invoked due to it being less than the frequency of the missed SRs.

SVIs-E31-T0086-A and B were revised to include the checking of the omitted contacts. Performance of applicable sections of the SVIs to verify the relay contacts in question was successfully completed on August 21, 1996, at 1241 hours. At 1500 hours, review of the issue determined that, due to the length of time between installation of the NUMAC modification and the discovery of the omission of TS SR verifications, the required actions were not taken in accordance with TS LCO 3.3.6.1. completion times, which is a condition prohibited by the plant's technical specifications and reportable as required by 10CFR50.73(a)(2)(i)(B) and the Facility Operating License, Section 2.F.

III. Cause of Event

The cause of this event is a weakness in the design modification process, in that, the modification procedure does not clarify post-modification testing requirements. Nuclear Engineering Instruction (NEI)-0373, "Initiating, Developing, and Processing Design Modifications," describes the initiation and review of design modifications; however, it does not include sufficient detail to ensure critical function, design, functional testing, and performance requirements are identified in the modification packages. There is no specific direction to confirm existing testing requirements for components or functions presently tested. Additionally, there is no direction or requirement to describe, in detail, how a new design is to be tested, nor is there any required comparison from the existing design to the new design, to ensure that such new designs are verified to meet their specified (e.g., Technical Specification, In-Service Inspection, Motor-Operated Valve program, etc.) requirements.

NRC FORM 366A		U.S. NUCLEAR REGULATORY COMMISSION
	LICENSEE EVENT REPORT (LER)	

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET		LER NUMBER (PAGE (3)			
	05000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	OF	8
Perry Nuclear Power Plant, Unit 1	440	96	007	00			

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

DCP 87-725 replaced 52 Riley Temperature Modules (which include actuation logic relays) with two NUMAC LDMs (each with an associated relay output unit). This modification resulted in reconfiguration of the isolation actuation logic and in the reduction in the number of channel functional and channel calibration instructions from 48 to 4. The technical preparation of SVI-E31-T0086-A and B was incomplete and inadequate; the magnitude of the changes adversely impacted the thorough preparation and self-checking of the preparer. During the development of the SVIs in response to DCP 87-725, a structured process to verify testing methodology and completeness was not in place. Without such a structured process, the in-depth technical review was also ineffective in detecting the omissions. The omissions were not discovered until a non-proceduralized review process was performed to identify which respective SVI verified proper operation of the contacts shown on the electrical elementary drawings.

A contributing factor is that the non-proceduralized method utilized to ensure the adequacy of surveillance testing was not performed in a timely manner. This method prescribes review of the test methodology, by the Instrumentation and Controls (I&C) procedure writers, against the electrical elementary/logic drawings to ensure the appropriate circuits and components are tested; however, there is not a time requirement in which the review must be performed. Had this review been performed prior to approval of the BVIs, the omissions could have been detected and corrected prior to the post-modification performance of the SVIs.

IV. Safety Analysis

Primary containment isolation instrumentation automatically initiates closure of primary containment isolation valves (PCIVs). The function of PCIVs, in combination with other accident mitigation systems, is to limit fission product release during and following postulated Design Basis Accidents (DBAs). Primary containment isolation within the time limits specified for those isolation valves designed to close automatically, ensures that the release of radioactive material to the environment is consistent with the assumptions used in the analyses for a DBA.

The isolation instrumentation includes the sensors, relays, and switches that are necessary to cause initiation of primary containment and reactor coolant pressure boundary isolation. The channels include electronic equipment (e.g., trip units) that compares the measured input signals with pre-established setpoints. When the setpoint is exceeded, the channel output relay actuates, which then outputs a primary containment isolation signal to the isolation logic.

The NCIC System Isolation, Main Steam Line Pipe Tunnel Temperature-High Instrumentation (TS Table 3.3.6.1-1 Item 3.f.) provides containment isolation signals to Division 1 (i.e., outboard) and Division 2 (i.e., inboard) RCIC System isolation logic when ambient temperature in the Main Steam Line Pipe Tunnel exceeds approximately 152 degrees Fahrenheit (F). Additionally, the late verification of the associated relay contacts resulted in not meeting the

NRC FORM 266A		U.S. NUCLEAR REGULATORY COMMISSION
	LICENSEE EVENT REPORT (LER)	
a second second second second second	TEXT CONTINUATION	

FACILITY NAME (1)	DOCKET	T		(6)		DACE /2	
	05000	YEAR	SEQUENTIAL	REVISION	5	OF	8
Perry Nuclear Power Plant, Unit 1	440	96	007 -	00			

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Operational Requirements Manual (ORM) channel calibration and logic system functional test requirements 6.2.16.3 and 6.2.16.4 for Isolation Actuation Instrumentation Operational Requirement Table 6.2.16-1.3 RCIC System Isolation, Item a. Main Steam Line Tunnel Differential Temperature - High. These instrumentation channels utilize the same relay contacts to provide containment isolation signals when differential temperature between two locations in the Main Steam Line Pipe Tunnel exceeds approximately 103 degrees F.

The RWCU System Isolation, Main Steam Line Pipe Tunnel Temperature-High Instrumentation (TS Table 3.3.6.1-1 Item 4.i.) provides containment isolation signals to Division 1 and Division 2 RWCU System isolation logic when ambient temperature in the Main Steam Line Pipe Tunnel exceeds approximately 152 degrees F. Additionally, the late verification of the associated relay contacts resulted in not meeting ORM channel calibration and logic system functional test requirements 6.2.16.3 and 6.2.16.4 for Isolation Actuation Instrumentation Operational Requirement Table 6.2.16-1.2 RWCU System Isolation, Item b. Main Steam Line Tunnel Differential Temperature - High. These instrumentation channels utilize the same relay contacts to provide containment isolation signals when differential temperature between two locations in the Main Steam Line Pipe Tunnel exceeds approximately 103 degrees F.

The RHR System Isolation, RHR Equipment Area Ambient Temperature-High Instrumentation (TS Table 3.3.6.1-1 Item 5.a.) provides isolation signals to Division 1 and Division 2 RHR system isolation logic when ambient temperature in RHR equipment areas exceeds approximately 153 degrees F. Additionally, the late verification of the associated relay contacts resulted in not meeting ORM channel calibration and logic system functional test requirements 6.2.16.3 and 6.2.16.4 for Isolation Actuation Instrumentation Operational Requirement Table 6.2.16-1.4 RHR System Isolation, Item a. RHR Equipment Room Differential Temperature - High. These instrumentation channels utilize the same relay contacts to provide containment isolation signals when differential temperature between two locations in RHR equipment areas exceeds approximately 49 degrees F.

Although the specific relay contacts were not checked before the NUMAC LDMs were placed into service, other contacts on the relays were verified as part of the associated post-modification testing. The relay contacts in question were verified to successfully perform their intended function when tested on August 21, 1996, and it can be assumed that these contacts would have performed successfully, if required, between the time the equipment was placed into service and the time the contacts were verified. Therefore, this event is not considered to be safety significant.

V. Similar Events

LERs 93-016-01, 93-017, 94-016, 94-022, and 96-003 address events in which TS SRs were not performed within time requirements. LERs 93-016-01 and 94-022 documented events in which programmatic controls for scheduling performance of SVIs were not

Construction and the second second and the submersion of the second second second second second second second s		
NRC FORM 366A		U.S. NUCLEAR REGULATORY COMMISSION
(4-95)		
	the second se	

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET LER NUMBER (6)				PAGE (3)			
	05000		SEDUENTIAL REVIS NUMBER NUME		6	OF	8	
Perry Nuclear Power Plant, Unit 1	440	96	007	00				

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

effective in meeting time requirements for ventilation system charcoal sampling, and for testing diesel generators utilizing a staggered test basis, respectively. LER 93-017 documented an event in which containment penetrations were not properly tested in accordance with 10CFR50 Appendix J requirements, which resulted in not meeting containment leak rate TS SRs. LERS 94-016 and 96-003 documented events in which TS SRs were not performed within time requirements due to personnel errors. None of the corrective actions associated with these five LERs could reasonably be expected to have prevented the issue documented by this LER from occurring, since the root cause for this issue primarily involved weaknesses in the modification process.

LER 94-011-01 documented an event in which a combination of design program weaknesses and failure to follow procedure resulted in an inadvertent Engineered Safety Feature actuation when the modified equipment was returned to service. Corrective actions included extensive revision to the design change program and development of a post-maintenance test manual to provide a consistent set of requirements for post-maintenance/modification testing of equipment and components. However, these actions did not prevent the occurrence of the event documented by LER 96-007. The modification discussed in LER 94-011-01 involved replacing a non-regulating transformer with a regulating type. Part of the problem perceived at the time was that test requirements were not consistent. Even though there were other regulating type transformers in the plant, the test requirements were not reflected in a consistent manner. Efforts were focused on development of a post-maintenance test manual to provide consistent test requirements for like components. The revision to the design change program at that time, provided additional guidance for functional testing and performance requirements; however, the guidance did not provide sufficient detail to ensure that specified requirements adequately tested the functional operation and performance intended by the design.

VI. Corrective Actions

The following corrective actions have been taken or are in progress:

- SVIs-E31-T0086-A and B were revised to include the proper contact verifications; the appropriate portions of the SVIs were subsequently performed to meet TS surveillance requirements.
- 2. An extent of condition review was performed for other recent design changes to the plant to verify the completeness of design change implementation with regard to TS surveillance requirements and testing. No other conditions similar to the ones reported under this LER were identified.
- 3. An engineering review determined that no complex modifications similar to DCP 87-725 are scheduled for installation prior to the next refueling outage. This action provides additional confidence that the situation should not recur prior to implementation of future corrective actions.

Desarran annexemption experience index and a second s	A REAL PROPERTY AND ADDRESS OF A DREAM AND ADDRESS OF A DREAM AND ADDRESS ADDRES	CONTRACTOR AND	IN INCOMENDATION AND ADDRESS	A MARTIN PROPERTY AND INCOME.	International Action of the Action	NAME AND ADDRESS OF TAXABLE PARTY.
NRC FORM 366A						
(4-95)						

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET	LER NUMBER (6)				PAGE (3)		
	05000		YEAR SEQUENTIAL REVISION NUMBER NUMBER		7 OF		8	
Perry Nuclear Power Plant, Unit 1	440	96	007	00				

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

- 4. The I&C surveillance writers have been counseled on this event and are aware of the importance of timely verification of surveillance testing adequacy against the applicable elementary drawings to ensure the proper fulfillment of SRs.
- 5. The Design Engineering section will discuss expectations for post-modification test requirements at a section meeting scheduled to be held by October 4, 1996.
- 6. Procedure NEI-0373 is being revised to provide additional detailed requirements for prescribing functional testing and performance requirements for design modifications. These detailed requirements will include at a minimum, a detailed explanation of:
 - current testing and performance requirements,
 - components tested and by what existing documents present testing is performed,
 - the new design and identification of any new tests or required changes to tests.
- 7. A Maintenance Administrative Instruction is being developed to formalize the non-proceduralized method of verifying surveillance test methodology against the electrical elementary/logic drawings to ensure the appropriate circuits and components are tested. This instruction will require that the verification be performed prior to incorporating any SVI changes created due to design modifications.

Energy Industry Identification System (EIIS) codes are identified in the text as [XX].

NRC FC	DRM 3 66A		and the product of the second second	U.S. NUCLE	AR REGULAT	ORY	COMMIS	SION
	LICENSEE EVE TEXT CO	NT REPORT (I	.ER)					
	FACILITY NAME (1)	DOCKET	T	LER NUMBER	3 (6)	PAGE (3)		
		05000	YEAR	SEQUENTIAL	REVISION	8	OF	8
Perry	Nuclear Power Plant, Unit 1	440	96	007	00			
TEXT (If more space is required, use additional copies of NRC Form 366A)	(17)	L		Next Line Providence and			
	The following table identifies those a commitments. Any other actions discus planned actions, are described for the commitments. Please notify the Manage Power Plant of any questions regarding commitments.	ctions which sed in this NRC's infor r-Regulatory this docume	are condition mation Affai: nt or a	onsidered nt repres , and are rs at the any assoc	to be n sent inte not reg Perry 1 ciated re	regu ende gula Nucl egul	lator d or tory ear atory	У
		*******						a.,
	Commit	ments						
	编制引行的法则和资格和保证证据和实施和考试和保证的资源和实际的法律和考虑					****	*****	22
1.	The Design Engineering section will di test requirements at a section meeting	scuss expect scheduled t	ations o be h	for post eld by Oc	-modific tober 4	cati , 19	on 96.	
		**********						=
2.	NEI-0373 is being revised to provide a prescribing functional testing and per modifications. The procedure revision 1997.	dditional de formance req is schedule	tailed uireme d to b	requiren nts for d e complet	nents fo: lesign ted by Ja	r anua	ry 15	,
	***************************************			*******				=
3.	A Maintenance Administrative Instructi non-proceduralized method of verifying electrical elementary/logic drawings t components are tested. This instructi performed prior to incorporating any S modifications. The instruction is sch	on is being surveillanc o ensure the on will requ VI changes c heduled to be	develo e test appro ire th reated devel	ped to fo methodol priate c at the ve due to o oped by d	ormalize logy aga ircuits erificat design January	the inst and ion 15, ====	the be 1997.	-

.....