

Southern Nuclear Operating Company
Post Office Box 1295
Birmingham, Alabama 35201
Telephone (205) 868-5131



Southern Nuclear Operating Company
the southern electric system

Dave Morey
Vice President
Farley Project

September 20, 1996

Docket No.: 50-348

10 CFR 50.73

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Joseph M. Farley Nuclear Plant - Unit 1
Licensee Event Report Number 96-005-00
Valve Misalignment Due To
Personnel Error Results in Missed Surveillance

Ladies and Gentlemen:

Joseph M. Farley Nuclear Plant Licensee Event Report No. 96-005-00 (Unit 1) is being submitted in accordance with 10 CFR 50.36(c)(2) and 50.73(a)(2)(i). If you have any questions, please advise.

Respectfully submitted,

Dave Morey

EFB/clt:LER96-05.doc

Enclosure

cc: Mr. S. D. Ebnetter, Region II Administrator
Mr. J. I. Zimmerman, NRR Project Manager
Mr. T. M. Ross, Plant Sr. Resident Inspector

9609270195 960920
PDR ADDCK 05000348
S PDR

IE 22
|
|

070013

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-8 F33) U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555-0001 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104) OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) Joseph M. Farley Nuclear Plant - Unit 1 DOCKET NUMBER (2) 05000348 PAGE (3) 1 OF 4

TITLE (4) Valve Misalignment Due to Personnel Error Results in Missed Surveillance

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME			
08	27	96	96	005	000	08	27	96				

OPERATING MODE (9) 1

POWER LEVEL (10) 100

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 1: (Check one or more) (11)

<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input checked="" type="checkbox"/> 50.3(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(vii)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(x)
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(iii)	73.71
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(iv)	OTHER
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	Specify in Abstract below
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input checked="" type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	or in NRC Form 366A

LICENSEE CONTACT FOR THIS LER (12)

NAME R.D. Hill, General Manager - Nuclear Plant TELEPHONE NUMBER 334899-5156

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (if yes, complete EXPECTED SUBMISSION DATE) NO DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-space typewritten lines) (16)

At approximately 0805 on August 27, 1996, with Unit 1 in Mode 1 operating at 100 percent reactor power it was determined that Unit 1 had been operating in a condition prohibited by Technical Specifications (TS). TS 4.8.1.1.2.a.3 requires that each emergency diesel generator set be demonstrated operable by verifying the fuel transfer pump can transfer fuel from the storage system to the day tank. TS 3.8.1.1 requires that with one emergency diesel generator set inoperable, demonstrate the operability of the remaining A.C. sources and remaining emergency diesel generator set. However, it was determined the 1B diesel generator fuel transfer system (which consists of two transfer pumps in parallel) was not capable of adequately transferring fuel from the 1B diesel generator fuel oil storage tank to the 1B diesel generator day tank due to the misalignment of two valves. The improperly positioned valves had been open since approximately 1820 on August 23, 1996 and the remaining A.C. sources and emergency diesel generator set had not been demonstrated operable in accordance with TS 3.8.1.1. The valves were restored to the required position at the time of discovery.

The cause of this event was cognitive personnel error due to a system operator failing to ensure two valves were closed. The individual involved in this event has been disciplined.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Joseph M. Farley Nuclear Plant - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 8	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL YEAR	REVISION NUMBER			
		9 6	- 0 0 5	- 0 0	2	OF	4

TEXT (if more space is required, use additional NRC Form 366) (17)

Plant and System Identification

Westinghouse -- Pressurized Water Reactor

Energy Industry Identification System codes are identified in the text as [XX].

Description of Event

At approximately 0805 on August 27, 1996, with Unit 1 in Mode 1 operating at 100 percent reactor power it was determined that Unit 1 had been operating in a condition prohibited by Technical Specifications (TS). TS 4.8.1.1.2.a.3 requires that each emergency diesel generator[EK] set be demonstrated operable by verifying the fuel transfer pump can transfer fuel from the storage system to the day tank. TS 3.8.1.1 requires that with one emergency diesel generator set inoperable, demonstrate the operability of the remaining A.C. sources and remaining emergency diesel generator set. However, it was determined the 1B diesel generator fuel transfer system[DC] (which consists of two transfer pumps in parallel) was not capable of adequately transferring fuel from the 1B diesel generator fuel oil storage tank to the 1B diesel generator day tank due to the misalignment of two valves. TS 3.8.1.1 requires that with one emergency diesel generator set inoperable, demonstrate the operability of the remaining A.C. sources and remaining emergency diesel generator set. The improperly positioned valves had been open since approximately 1820 on August 23, 1996 and the remaining A.C. sources and emergency diesel generator set had not been demonstrated operable in accordance with TS 3.8.1.1. The valves were restored to the required position at the time of discovery.

The 1B diesel generator fuel oil transfer system was not capable of adequately transferring fuel from the 1B diesel generator fuel oil storage tank to the 1B diesel generator day tank due to the misalignment of two valves. The valves had not been realigned to the closed position following the transfer of fuel oil from the auxiliary fuel oil storage tank to the 1B diesel generator fuel oil storage tank on August 23, 1996. The system operator responsible for the positioning of the valves failed to utilize existing guidance and inappropriately concluded the two valves were located in the responsible area of another individual standing a separate on-duty position. Furthermore, he failed to ensure the valves were properly positioned by the other individual.

Although the misalignment of valves did not isolate the flowpath between the 1B diesel generator fuel oil storage tank and the 1B diesel generator day tank, the valve configuration created an additional flow path which would have resulted in negligible flow reaching the 1B diesel generator day tank upon demand. Even though an adequate fuel supply would not have been provided to the day tank as a result of the improperly opened valves, the design of the day tank alarm system

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST, 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Joseph M. Farley Nuclear Plant - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 8	LER NUMBER (5)			PAGE (3)	
		YEAR	SEQUENTIAL YEAR	REVISION NUMBER		
		9 6	- 0 0 5	- 0 0	3	OF 4

TEXT (If more space is required, use additional NRC Form 366) (17)

provides two alarms (low and low-low level) which would provide approximately 2 hours to investigate and correct the problem in the event of required diesel generator operation. Without any operator intervention the diesel generator would be expected to run at full load for approximately 4 hours.

All diesel generators were subsequently run satisfactorily and all A.C. sources were verified operable. Furthermore, during the event, all other diesel generators were operable.

Cause of Event

The cause of this event was cognitive personnel error due to a system operator failing to ensure the two valves were closed.

Safety Assessment

There was no other ESF equipment in the affected train made inoperable by this event. All ESF equipment in the redundant train remained operable during this event.

The health and safety of the public was not affected by this event.

Based on the above, no safety concerns exist.

Corrective Action

The individual involved in this event has been disciplined. A summary of this event, along with management expectations, will be provided to appropriate operations personnel. This will be completed by November 15, 1996.

Additional Information

The following recent LERs have been submitted due to personnel inappropriately concluding that tasks had been properly completed:

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-8 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Joseph M. Farley Nuclear Plant - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 8	LER NUMBER (6)			PAGE (3)	
		YEAR 9 6	SEQUENTIAL YEAR - 0 0 5	REVISION NUMBER - 0 0	4	OF 4

TEXT (if more space is required, use additional NRC Form 366) (17)

96-002-00 (Shared) - Technical Specification Surveillance Requirements Not Met and Common Cause Failure Identified

95-002-00 (Unit 1) - Missed Surveillance for Inoperable Axial Flux Difference Monitor Alarm