AVERAGE DAILY UNIT POWER LEVEL

Unit Name Salem # 1 Date April 10,1985 Completed by J. P. Ronafalvy Telephone609-935-6000 Extension 4455 Month March 1985 Day Average Daily Power Level Day Average Daily Power Level (MWe-NET) (MWe VET)

P. 8,1-7 R1

8504220317 850331 PDR ADOCK 05000272 R PDR

IEZ

Docket No.

50-272

OPERATING DATA REPORT Docket No.50-272 Date April 10, 1985 Telephone 935-6000 Completed by J. P. Ronafalvy Extension 4455 Operating Status 1. Unit Name Salem No. 1 Notes 2. Reporting Period March 1985 3. Licensed Thermal Power (MWt) 3338 4. Nameplate Rating (Gross MWe) 1170 5. Design Electrical Rating (Net MWe) 1090 Maximum Dependable Capacity (Gross MWe) 1124 6. 7. Maximum Dependable Capacity (Net MWe) 1079 8. If Changes Occur in Capacity Ratings (items 3 through 7) since Last Report, Give Reason 9. Power Level to Which Restricted, if any (Net MWe) N/A 10. Reasons for Restrictions, if any N/A This Month Year to Date Cumulative 11. Hours in Reporting Period 744 2160 67969 12. No. of Hrs. Reactor was Critical 744 2142.6 37966.1 13. Reactor Reserve Shutdown Hrs. 0 0 3088.4 14. Hours Generator On-Line 744 2139.7 36298.3 15. Unit Reserve Shutdown Hours 0 16. Gross Thermal Energy Generated (MWH) 2480827 7082904 109850901 17. Gross Elec. Energy Generated 848600 (MWH) 2425140 36341190 18. Net Elec. Energy Generated (MWH) 816628 2331205 34429187 19. Unit Service Factor 100 99.1 53.4 20. Unit Availability Factor 100 99.1 53.4 21. Unit Capacity Factor (using MDC Net) 101.7 100.0 46.9 22. Unit Capacity Factor (using DER Net) 100.7 99.0 46.5 23. Unit Forced Outage Rate 0 31.9 24. Shutdowns scheduled over next 6 months (type, date and duration of each) N/A 25. If shutdown at end of Report Period, Estimated Date of Startup: 26. Units in Test Status (Prior to Commercial Operation): Forecast Achieved Initial Criticality 9/30/76 12/11/76 Initial Electricity 11/1/76

Commercial Operation

12/25/76

6/30/77

12/20/76

8-1-7.R2 Page of

UNIT SHUTDOWN AND POWER REDUCTIONS REPORT MONTH March 1985

Docket No.50-272 Unit Name Salem No.1 April 10,1985 Date Telephone 609-935-6000 Extension 4455

Completed by J.P. Ronafalvy

No.	Date	Туре	Duration Hours	Reason 2	Method of Shutting Down Reactor	License Event Report	System Code 4	Component Code 5	Cause and Corrective Action to Prevent Recurrence
85-182	3-07	F	8.5	A	5		нв	VALVEX	Intercept Valves Turbine

F: Forced S: Scheduled 2 Reason A-Equipment Failure-explain B-Maintenance or Test C-Refueling D-Regulatory Restriction E-Operator Training & Licensing Exam F-Administrative G-Operational Error-explain H-Other-explain

3 Method 1-Manual 2-Manual Scram. 3-Automatic Scram. tion of Data 4-Continuation of Previous Outage 5-Load Reduction 9-Other

4 Exhibit G Instructions Salem as for Prepara- Source . Entry Sheets for Licensee Event Report (LER) File (NUREG 0161)

5 Exhibit 1

MAJOR PLANT MODIFICATIONS REPORT MONTH MARCH 1985

DOCKET NO.: 50-272

UNIT NAME: Salem 1

DATE: April 10, 1985

COMPLETED BY: J. Ronafalvy

TELEPHONE: 609/339-4455

*DCR NO.	PRINCIPLE SYSTEM	SUBJECT
1EC-1304	Chemical & Volume	Buttwelding of valves (associated with the test, vent and drain connections along the centrifugal and reciprocating charging pump suction and discharge lines and CVC letdown Lines) to the header making each of them a "one piece connection"
1EC-1588	Cable Trays	Retag, repull various cables throughout the plant to match changes made to wiring diagrams prior to implementation of the DCR system.
1EC-1676A	Reactor Coolant	Replace reactor coolant narrow range RTD's with environmentally qualified elements. Also relocate solenoid valves associated with MS7 and MS18 valves.
1EC-1698A	Circulating Water- Traveling Screens	Install a 316 stainless steel traveling screen in place of 138 screen. Install one set of 316 stainless steel baskets in 11A traveling screen. Install flexible line from inlet screen wash piping to screen wash spray hdeader piping.
1EC-1775	Circulating Water	Replace the inlet expansion joints of Unit 1 Main Condensers, additionally replace the remaining outlet expansion joints not changed during the main condenser retubing in 1980.

*DCR NO.	PRINCIPLE SYSTEM	SUBJECT
1EC-1816	Safeguards Equipment Controller R130	Install new Lambda power supplies and new Potter Brumfield relays in the Unit 1 SEC's.
1EC-1830	Generator Protective Relay	Upgrade generator stator ground fault relay protection.
1EX-1836	Reactor Coolant	Revise setpoints of #12 RCP locked rotor protection relaying.
1EC-1874A	Service Water	Revise 8" Service Water emergenc; supply line to Aux Feedwater from #12 Service Water nuclear header. Revise 4" SW supply line to room and oil coolers from #12 Service Water nuclear header. Line or replace stainless steel service water supply and return piping to #12 CC Hx. Add break flanges in service water supply and return piping to #12 CC Hx.
1EC-1950	Containment Cooling Fan Coolers	Machine stator core, rotor and roll file to remove eccentricity between stator and core and obtain uniform air-gap. Also increase air gap from 39 mils to 44 mils. Drill ports (3/4") which can be plugged, on end bell - 4 each on each end.
1EC-1988	Steam Generator Feed Pump and Turbine Lube and Control Oil	Change the SGFP No. 11 and 12 thrust bearing wear alarm and trip setpoints from 8 and 12 psi to 13 and 17 psi respectively.
1ET-1996	Chilled/Service Water	Test application of Garlock "Turbo-Star" cartridge type mechanical seal in chiller condenser recirc pumps No. 11, 12, 13.

PRINCIPLE SYSTEM	SUBJECT
Service Water Pump Motors (#15)	Vent the oil level columns in the bearing oil lubrication system on No. 15 Service Water Pump Motor.
Containment Personnel Hatch	Install a mechanical stop valve at the hatch flowmeter-air supply line. Separate valve to be installed on El. 100' and El. 130' hatches.
Security (Barriers)	Make additions and modifications to provide security barriers on three air vents in the 122' El. hallway between the Aux Building and the "A" Building.
	Service Water Pump Motors (#15) Containment Personnel Hatch

MAJOR PLANT MODIFICATIONS REPORT MONTH MARCH 1985 DOCKET NO.: 50

50-272

UNIT NAME:

Salem 1

DATE:

April 10, 1985 J. Ronafalvy

COMPLETED BY: TELEPHONE:

609/339-4455

*DCR NO. SAF

SAFETY EVALUATION 10 CFR 50.59

- This change addresses the intent to increase conservatism and thereby reduce the possibility of a future occurrence of cracks/breaks at the test, vent, and drain connections. In addition, the section modulus of the connection will be significantly increased which will improve resistance to heretofore undetected shock load. No unreviewed safety or environmental questions are involved.
- 1EC-1588 The work to be done with this DCR will not change the actual design of any system nor will it affect any safety related system. No unreviewed safety or environmental questions are involved.
- This change involves a substitution of existing equipment. The system response time will increase and the over temperature delta T (Table 3.3.2 of the Tech. Specs.) will increase but by an amount less than that allowed in Table 15.1-3 of the FSAR accident analysis. No unreviewed safety or environmental questions are involved.
- This change involves the upgrading of the traveling screen material. This system does not affect the presently performed safety analysis nor does it create any new hazards. No unreviewed safety or environmental questions are involved.
- 1EC-1775 The work to be done with this DCR will not change the actual design of any system nor will it affect any safety related system. No unreviewed safety or environmental questions are involved.
- This change replaces components with components manufactured by a different vendor. All replacement components have been qualified to equal to or greater requirements than the original equipment. This includes seismic qualification to IEEE 344. All failure modes are identified to the originally installed equipment. No unreviewed safety or environmental questions are involved.

- This change increases protection of the Main Generator stator from ground faults. The change is non-safety related and does not add any generator trips which are not already possible through various electrical faults. No unreviewed safety or environmental questions are involved.
- This change verifies the #12 RCP locked motor protection relay set points to determine if the motor is acceptable to remain in service or must be removed for further inspection. No unreviewed safety or environmental questions are involved.
- 1EC-1874A This change replaces the Service Water unlined stainless steel supply and return piping with polyethylene lined carbon steel. The new piping will prevent the buildup of marine growth on the pipe wall and will prevent pipe corrosion. The new polyethylene piping will stand up to the Service Water conditions. It will not affect the effluent to the river and will prevent the release of Service Water to the atmosphere. Also, the 8" emergency supply to the Auxiliary Feedwater System and the 4" supply to the Room Coolers are being revised to allow the line to be isolated thereby eliminating the build-up of marine growth and silt. It will also allow the supply line to the Room Coolers to operate more efficiently. addition of break flanges will allow for future inspections to verify the integrity of the system. No unreviewed safety or environmental questions are involved.
- 1EC-1950 These changes result in a uniform air gap in the electrical motor and provides a means to verify the uniformity. These features only add to the reliability and availability of the motor. No unreviewed safety or environmental questions are involved.
- The intended function of the system remains unaffected. The change is in conformance with the manufacturer's recommendation. This is a non-safety related system. No unreviewed safety or environmental guestions are involved.
- The test applicatins of a "Garlock Turbostar" cartridge type mechanical seal in the Chiller Condenser Recirc.

 Pumps do not affect any presently performed safety analysis nor does it create any new hazards. No unreviewed safety or environmental questions are involved.

^{*}DCR - Design Change Request

*DCR NO.	SAFETY EVALUATION 10 CFR 50.59
1sc-0605	The modification of the oil sight gauge vent will improve the accuracy of the oil level indication. No unreviewed safety or environmental questions are involved.
1SC-0892	The controls changes do not affect the operation of installed equipment and will not deduct from the margin of safety of presently installed equipment. This change does not affect the safe shutdown of the plant. No unreviewed safety or environmental questions are involved.
1SC-1306	This change involves the structural work required to restrict unauthorized access through a roof opening by welding bars to the roof opening frame. The work area is the hallway between the Aux. Building and the A Building (122' elevation). This hallway is not in a safety related area of the plant. No unreviewed safety or environmental questions are involved.

^{*}DCR - Design Change Request

PSE&G SALEM GENERATING STATION SAFETY RELATED WORK ORDER LOG

SALEM UNIT 1

WO NO	DEPT	UNIT	EQUIPMENT IDENTIFICAT	ION		
8503191008 SMD		1	13 FAN COIL UNIT			
			FAILURE DESCRIPTION:	SERVICE WATER LINE BROKEN OFF UPSTREAM OF 13SW243 PLEASE REPAIR		
			CORRECTIVE ACTION:	WELDED NIPPLE PERFORMED AN ACCEPTABLE PT & IN SERV ICE LEAK EXAM		
8503120	950 SMD	1	11BF19			
			FAILURE DESCRIPTION:	REPAIR 11BF19 PACKING LEAK USING FURMANITE PROCESS.		
			CORRECTIVE ACTION:	VALVE FURMANITED		
8503121	964 SIC	1	SOLENOID VALVE			
			FAILURE DESCRIPTION:	THE INLET VALVE TO THE RIGHT CHAMBER IS BLOWING AIR. POSSIBLE DIAPHRAGM LEAK. VALVE LOCATED UNDER CHAMBER.		
			CORRECTIVE ACTION:	REPLACED VALVE AND MOISTURE INDICATOR.		
8503070	359 SIC	1	AFD MONITOR			
			FAILURE DESCRIPTION:	AFD RECORDER IS SPIKING LOW INTO ALARM. I&C DEPT PLEASE REPAIR.		
			CORRECTIVE ACTION:	SWITCH #1 WAS REMOVED CONTACTS CLEANED AND RETURNED TO SERVICE. PROCEDURE 1PD-16.1.007 WAS USED TO REMOVE SWITCH FROM SERVICE TO WORK ON IT.		

SALEM UNIT 1

NO NO	DEPT	UNIT	EQUIPMENT IDENTIFICAT	ION
8503070	0600 SIC	1		SOLENOID VALVE IS CONTINUOUSLY VENTING REBUILD SV-601 WITH ASCO SOLENOID REPAIR KIT.
0099160501 SMD		1	12SW24 12 STRNR. BK/W	ASH 12SW24 12SWP STRNR. BACKWASH VALVE, HAS BLOWN DIAPHRAGM
			CORRECTIVE ACTION:	FOUND VALVE DIAPHRAGM BLOWN, AND INTERNALS DISTROYED REPLACED WITH A NEW COMPLETE VALVE. NEW NUTS AND SUTDS. CLEANED AREA.
		1	VCT FAILURE DESCRIPTION:	A SWAGELOCK FITTING ON LEVEL POT BOTTOM BELLOWS IS BLOWING CAUSING A RADIATION PROBLEM. PLEASE REPAIR
			CORRECTIVE ACTION:	REPLACED FITTING SENSING LINE FOR LEVEL BELLOWS ON VCT.
009916	0714 SMD	1	#13 CFCU MOTOR COOLER FAILURE DESCRIPTION: CORRECTIVE ACTION:	SERVICE WATER LEAK IN MOTOR COOLER, PLEASE REPAIR. REPLACED MOTOR COOLER
009916	50480 SMD	1	16 SW PMP STRNR. FAILURE DESCRIPTION: CORRECTIVE ACTION:	16 SW PMP. STRNR. HAS A PACKING LEAK. REPACKED STRAINER

SALEM UNIT 1

WO NO DI	EPT	UNIT	EQUIPMENT IDENTIFICAT	ION
009900525	5 SMD	1	12 BF19	
			FAILURE DESCRIPTION:	PACKING GLAND LEAKING BADLY. PACKING HAS BEEN TIGHTENED AS MUCH AS POSSIBLE WORK ORDER TO COVER TEMP. REPAIRS, FURMANITE
			CORRECTIVE ACTION:	DRILLED TRAPPED AND INSERTED FURMANITE FITTINGS INJECTED FURNMANITE COMPOUND ASSURED VALVE STEM MOVEMENT NEW WO ISSUED FOR PERMANENT REPAIR IS 8502280201

SALEM GENERATING STATION MONTHLY OPERATING SUMMARY - UNIT NO. 1 MARCH 1985

SALEM NO. 1

The Unit began the period operating at full power. On 3/07/85 at 0420 hours Unit power was reduced to 79% as a result of 12E Intercept valve failing to reopen after completion of a routine turbine valve surveillance test. The valve failed to reopen as a result of a cut seat on the hydraulic dump valve. At 1657 hours, with the completion of repairs, the Unit was returned to 100% power where it remained for the rest of the period. On March 31, 1985, No. 1 Unit's consecutive days in operation exceeded its previous record of 88 days.

REFUELING INFORMATION

COMPLETED BY:	J. Ronafalvy	DOCKET NO.: UNIT NAME: DATE: TELEPHONE: EXTENSION:	50-272 Salem 1 April 10, 1985 609/935-6000 4455
Month March	1985		
1. Refuelin	g information has char YES	nged from last m	onth:
2. Schedule	d date for next refue	ling: Februar	y 22, 1986
3. Schedule	d date for restart for	llowing refuelin	g: May 4,1986
	l Technical Specificate ndments be required? YES NOT DETERMINED	NO	other license
	the reload fuel designating Review Committee YES If no, when is		
5. Schedule	d date(s) for submitt: January 1986	ing proposed lic 6 if required	ensing action:
6. Importan	t licensing considerat	tions associated	with refueling:
7. Number o	f Fuel Assemblies:		
A) Inco	ore		193
B) In	Spent Fuel Storage		296
8. Present	licensed spent fuel st	torage capacity:	1170
Future s	pent fuel storage capa	acity:	1170
to spent	last refueling that ca fuel pool assuming th capacity:		September 2001



Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

April 10, 1985

Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

Dear Sir:

MONTHLY OPERATING REPORT SALEM NO. 1 DOCKET NO. 50-272

In Compliance with Section 6.9, Reporting Requirements for the Salem Technical Specifications, 10 copies of the following monthly operating reports for the month of March 1985 are being sent to you.

Average Daily Unit Power Level
Operating Data Report
Unit Shutdowns and Power Reductions
Major Plant Modification
Safety Related Work Orders
Operating Summary
Refueling Information

Sincerely yours,

J. M. Zupko, Jr.

General Manager - Salem Operations

JR:sbh

cc: Dr. Thomas E. Murley
Regional Administrator USNRC
Region I
631 Park Avenue
King of Prussia, PA 19406

Director, Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Enclosures Page of 8-1-7.R4

TEZA