No: theast **U**alities System Millstone Offices . Rope Ferry Rd., Waterford, CT

P.O. Box 128 Waterford, CT 06385-0128 (203) 447-1791

July 29, 1996 Docket No. 50-245 B15820

Re: 10CFR50.73(a)(2)(i)

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

This letter forwards Licensee Event Report (LER) 96-046-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 1 on June 27, 1996. This LER is submitted pursuant to 10CFR50.73(a)(2)(i).

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

For Director - Millstone Unit No. 1

By

W. J. Riffer

Sau Assistant Director - Millstone Unit No. 1

Attachment: LER 96-046-00

cc: T. T. Martin, Region I Administrator

T. A. Easlick, Senior Resident Inspector, Millstone Unit No. 1

J. W. Andersen, NRC Project Manager, Millstone Unit No. 1

9608060240 960729 PDR ADOCK 05000245 PDR

OS3422-9 REV. 1-95

NRC FORM 366

(4-35)

FACILITY NAME (1)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104 EXPIRES 04/30/98 EXTINES 04/30/36 EXTINES 04/30/36 EXTINATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST. 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FEE BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH IT 6 F331, U.S. NUCLEAR REGULATORY COMMISSION. WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104) OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

	DOCKET NUMBER (2)	PAGE (3)
Millstone Nuclear Power Station Unit 1	05000245	1 of 4

TITLE (4)

Failure to Perform Applicable 10CFR50 Appendix J Tests to Satisfy Technical Specifications

EVEN	T DATE	(5)	T	LER NU	MBER	(6)	REPO	RT DAT	E (7)	1	OTHER	FACILITIES I	INVOLVED (8)																																											
MONTH	DAY	YEAR	YEAR	SEQUE	NTIAL	REVISION	MONTH	DAY	YEAR	FACI	LITY NAME		DOC	KET NUMBER																																										
06	27	96	96	04	6	00	07	29	96	FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		FACILITY NAME		PACILITY NAME		PACILITY NAME		FACILITY NAME			DOC	KET NUMBER										
OPERA	TING	N	THIS	REPORT IS	SUBM	ITTED PURS	UANT TO	THE REC	UIREME	INTS	OF 10 CFR §	: (Check one	or m	ore) (11)																																										
MODE	: (9)	19	20).2201(b)			20.2203	(a)(2)(v)			× 50.73(a)	(2)(i)	50.73(a)(2																																											
POW	ER	000	20).2203(a)()		20.2203	(a)(3)(i)			50.73(a)(2)(ii)		50.73(a)(2)(ii) 50.73		50.73(a)(2)(x)																																									
LEVEL	(10)	000	20).2203(a)(?)(i)		20.2203	(a)(3)(ii)			50.73(a)(2)(iii)			73.71																																										
			20).2203(a)(!)(ii)		20.2203	(a)(4)			50.73(a)(2)(iv)			OTHER																																										
20		20.2203(a)(2)(iii)			50.36(c)(1)				50.73(a)	(2)(v)	Specify in Abstract below																																													
			20	20.2203(a)(2)(iv)			50.36(c)(2)			50.73(a)(2)(vii)			or in NHC Form 366A																																											
						LICENSEE	CONTACT	FOR TH	IS LER (12)	water and a second s																																													
NAME	R	obert	W. Wa	lpole, Nu	clear	Licensing	Supervis	sor			TELEPHONE NUN	(860)440 (100)440	Code))-21	91																																										
	C	OMPL	ETE O	VE LINE	ORI	EACH CON	PONEN	T FAIL	URE D	ESC	RIBED IN T	HIS REPOR	T (1	13)																																										
CAUSE	CAUSE SYSTEM COMPONENT		MANUFA	TURER	REPORTABLE TO NPRDS		CAUS	E SY	STEM	COMPONENT	MANUFACTU	RER	REPORTABLE TO NPRDS																																											

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED	MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE).	NO	SUBMISSION	11	15	96

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On June 27, 1996, with the plant shut down and the reactor in the COLD SHUTDOWN condition, a self assessment program review determined that several containment penetrations did not have adequate local leak rate tests (LLRTs) performed pursuant to the requirements of 10CFR50 Appendix J. Not all testable connections were tested on ten 18" atmospheric control system valves, and there are no testable flanges on two 2" atmospheric control system valves. Additionally, a piping flange in the head spray system is not appropriately tested.

The failure to perform individual Type B leakage tests in accordance with the requirements of 10CFR50 Appendix J results in the inability to adequately demonstrate primary containment integrity, which is required to be maintained by Millstone Unit 1 Technical Specification 3.7.A 3. This event is reportable pursuant to 10CFR50.73(a)(2)(i)(B) as a condition prohibited by the plant's Technical Specifications.

Modifications to make the penetrations testable and subsequent testing will be completed prior to startup from the current refueling outage. All penetrations have been tested as part of the Type A integrated leak rate testing (ILRT) program. There were no safety consequences as a result of this event.

1

NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)					
Millstone Nuclear Power Station Unit 1	stone Nuclear Power Station Unit 1 05000245 YEAR SEQUENTIAL R NUMBER 1 96 046		REVISION NUMBER	2 of 4				
				046	**	00	2 01 4	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

I. Description of Event

On June 27, 1996, with the plant shut down and the reactor in the COLD SHUTDOWN condition, a self assessment program review determined that several containment penetrations did not have adequate LLRTs performed pursuant to the requirements of 10CFR50 Appendix J. Not all testable connections were tested on ten 18" atmospheric control system valves, and there are no testable flanges on two 2" atmospheric control system valves. Additionally, a piping flange in the head spray system is not appropriately tested.

The failure to perform individual Type B leakage tests in accordance with the requirements of 10CFR50 Appendix J results in the inability to adequately demonstrate primary containment integrity, which is required to be maintained by Millstone Unit 1 Technical Specification 3.7.A.3. This event is reportable pursuant to 10CFR50.73(a)(2)(i)(B) as a condition prohibited by the plant's Technical Specifications.

Modifications to make the valves testable and subsequent testing will be complete prior to startup from the current refueling outage. All penetrations have been tested as part of the ILRT program. There were no safety consequences as a result of this event.

II. Cause of Event

The cause of this event is personnel error, in that the "as-built" systems and equipment configuration were not identified as needing modification when the 10CFR50 Appendix J criteria were implemented at Millstone Unit No. 1. Construction of Millstone Unit No. 1 and the plant's initial criticality pre-date 10CFR50 Appendix J. These deficiencies were discovered during a self assessment of the Appendix J program, and a walkdown of the containment penetrations conducted during an extended refuel outage. The Systematic Evaluation Program (SEP) and other reviews failed to identify the penetrations as not meeting Appendix J criteria.

III. Analysis of Event

Atmospheric Control Vacuum Breakers 1-AC-1A- J; Penetration X-202A - H

The self actuated check valves (vacuum breakers) of the drywell to torus penetrations form a part of the atmospheric control system and the valve components are part of the reactor building boundary. Five testable gasketed joints exist on each of the valves, namely the flanged body cover, and the shaft packing gland and the stuffing box located at both ends of the disc shaft. Each of these containment boundaries is testable and should receive a Type B LLRT in accordance with Appendix J. However, only the double gasketed flanged body cover was appropriately tested per Appendix J. The shaft packing gland and stuffing box (at each shaft end) utilize pipe plugs to communicate between the inner and outer barrier at the lantern gland and between the o-rings respectively. These boundaries have not been LLRT tested. When the pipe plugs are removed, a Type B test can be performed to verify the leak tightness of these potential leak paths. This configuration exists on all ten of the Atwood & Morrill Co., 18 inch Vacuum Breakers used in the Torus to drywell penetrations.

Overall containment integrity has been demonstrated during the Type A ILRT, on numerous occasions. A review of these test results has not shown that the lack of performing a Type B test adversely affected the results of the Type A test. Since the Type B test is performed on static seals, both the shaft packing and oring seals, it is unlikely that degradation of the leak tightness would result in a failed test. The review of the historical data of Type B test results of the body flange for all vacuum breakers has shown consistent leak

NRC FORM 366A (4-95)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)		FAGE (3)				
Millstone Nuclear Power Station Unit 1	05000245	YEAR	SEQUENTIAL REVISION NUMBER NUMBER		3 of 4		
	00000240	96	**	046	**	00	0014

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

tightness. The flange seals have shown continued LLRT performance and have not degraded during subsequent refuel outages. Vacuum breakers are manually exercised quarterly to confirm operability and no significant changes have been observed in the unseating torque values. Since the unseating torque is unchanged, it is inferred that there is no change in the shaft seal characteristics, and hence no change in the shaft sealing capability. Furthermore, two vacuum breakers are overhauled each refueling outage. The overhaul includes replacement of the packing and o-rings, and a complete inspection of all internal parts.

Torus Exhaust Bypass Valve 1-AC-9 & 1-AC-12 (X-25/202D)

The torus exhaust bypass valves are 2" air operated containment isolation valves located on a branch line from drywell vent penetration X-25/202D. Valves 1-AC-9 & 1-AC-12 exhibit standard fiber gasket material on both the upstream and down stream flange connections and do not exhibit testable flanges in either the upstream or downstream direction. The gaskets in the downstream direction (outside of containment) are tested during Type C testing of the system valves; however the inboard gaskets are only tested during the Type A ILRT of the overall containment. Consecutive ILRTs have been performed during 1991 (RFO13), 1994 (RFO14) and is scheduled for current RFO15. No leakage has been observed at these locations. The ILRT "as-left" results of .4077 wt.%/day and .3143 wt.%/day have shown acceptable (1.2 wt.%/day Technical Specification limit) and improved containment integrity performance.

Head Spray System Flange X-17

A piping system flange exists between the inboard containment isolation check valve 1-HS-5 and the outboard motor operated containment isolation valve 1-HS-4 to allow removal of the head spray piping when removing the reactor head cover. The flange only receives a leak test during Type A ILRT of the overall containment. The configuration does not provide for an appropriate Type B LLRT of this flange.

The failure to adequately perform Appendix J testing on these penetrations calls into question the ability to demonstrate the operability of the primary containment during the past operating cycles. Since Millstone has failed to adequately demonstrate primary containment integrity, as required by Technical Specification 3.7.A.3, this event is reportable pursuant to 10CFR50.73(a)(2)(i)(B) as a condition prohibited by the plant's Technical Specifications.

IV. Corrective Action

The qualifications and experience of the individual currently responsible for the Millstone Unit No. 1 Appendix J program has been reviewed and has been verified to be satisfactory. The individuals responsible for Appendix J are now part of the Condition Based Maintenance (CBM) group. The CBM group has been organized to include personnel from the same discipline to work together across all five units on areas such as the Appendix J program. The Appendix J group, as part of the IST organization, now reports to one manager. Therefore, the individuals are able to establish uniformity among the Appendix J programs and specialize in the area of leak rate testing.

The Appendix J program review is ongoing. Any additional discrepancies which affect the LLRT will be included in a supplement to this LER. In addition, it will be investigated as to whether any of the issues would have impacted the ILRTs. This self-assessment will be completed and the final results reported to the NRC via a supplement to this LER.

NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)					
Millstone Nuclear Power Station Unit 1	05000245	YEAR	SEQUEN GAL NUMBER			REVISION NUMBER	A of A	
		96		046		00	4014	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Modifications will be made to the procedure for performing the local leak rate test on the vacuum breakers to include testing of the shaft packing and stuffing box. LLRTs will be performed before the overall containment Type A ILRT, and prior to startup for operating cycle 16.

Modifications will be made to the containment side bolting flange of valves 1-AC-9 & 1-AC-12, as well as to the bolted flange between valves 1-HS-4 and 1-HS-5 during refueling outage 15. LLRTs will be performed before the overall containment Type A ILRT, and prior to startup for operating cycle 16.

V. Additional Information

The following are Northeast Nuclear Energy Company's (NNECO's) commitments contained within this letter. All other statements contained within this letter are for information only.

- B15820-1 NNECO commits to modify the procedure for performing the LLRT on the vacuum breaker to include testing of the shaft packing and stuffing box. LLRTs will be performed before the overall containment Type A ILRT prior to startup for operating cycle 16.
- B15820-2 NNECO commits to modify the containment side bolting flange of valves 1-AC-9 & 1-AC-12 during refueling outage 15. LLRTs will be performed before the overall containment Type A ILRT prior to startup for operating cycle 16.
- B15820-3 NNECO commits to modify the bolted flange between valves 1-HS-4 and 1-HS-5 during refueling outage 15. LLRTs will be performed before the overall containment Type A ILRT prior to startup for operating cycle 16.
- B15820-4 NNECO commits that the self-assessment of the Appendix J program will be completed and the final results reported to the NRC via a supplement to this LER by November 15, 1996.

Similar Events

LER 96-026-00

Manufacturer Data

None.