

**RADIOLOGIC AND ENGINEERING ASSESSMENT**

FOR

DOE ID NO.: GJ-07784-RS  
ADDRESS: 2696 MILO DRIVE

APRIL 1985

FOR

URANIUM MILL TAILINGS REMEDIAL ACTION PROJECT OFFICE

ALBUQUERQUE OPERATIONS OFFICE

DEPARTMENT OF ENERGY

BY

BENDIX FIELD ENGINEERING CORPORATION  
P.O. Box 1569  
Grand Junction, Colorado 81502

APPROVED BY

*Michael K. Tucker*  
M. TUCKER  
DOE PROJECT ENGINEER

DATE

*April 16, 1985*

REA07784:REA-312

8505020119 850416  
PDR WASTE  
WM-54 PDR

## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
1.0 EXECUTIVE SUMMARY . . . . .	1
1.1 Introduction . . . . .	1
1.2 Evaluation and Recommendation . . . . .	1
2.0 PROPERTY DESCRIPTION . . . . .	2
2.1 General Description . . . . .	2
2.2 Existing Facilities and Structures . . . . .	2
3.0 RADIOLOGIC SURVEY . . . . .	4
3.1 Introduction . . . . .	4
3.2 Gamma Exposure-Rate Surveys . . . . .	4
3.2.1 Exterior Findings . . . . .	4
3.2.2 Interior Findings . . . . .	4
3.3 Boreholes, Soil Samples, and Other Measurements . . . . .	4
3.4 Radon/Radon Daughter Concentration . . . . .	5
3.5 Extent of Contamination . . . . .	5
4.0 RECOMMENDED REMEDIAL ACTION . . . . .	6
4.1 Decontamination and Restoration . . . . .	6
4.2 Evaluation of Recommended Remedial Action . . . . .	6
5.0 REFERENCES . . . . .	7
6.0 APPENDIX . . . . .	8

## 1.0 EXECUTIVE SUMMARY

### 1.1 Introduction

The location, DOE ID No. GJ-07784-RS, is a single-family residence located at 2696 Milo Drive, Grand Junction, Colorado.

The purpose of this assessment is to evaluate the extent of uranium millsite contamination at this property. This assessment includes recommended remedial action, estimated volume of contaminated material to be removed, and estimated cost of the proposed action.

### 1.2 Evaluation and Recommendation

The action recommended is the removal of contaminated material and restoration of the property to its original condition. The identified residual radioactive material found on this property is tailings; the estimated volume is: exterior, 16 cu. yd.; interior, 0 cu. yd.

Approximately 10 days are required for completion of design work. Estimated cost to perform remedial action, including dislocation when applicable, is \$1,988. Remedial action on this property will take approximately 7 days to complete.

## 2.0 PROPERTY DESCRIPTION

### 2.1 General Description

Address: 2696 Milo Drive, Grand Junction, Colorado

Zoning: Residential (RMF)

Lot Size: Approximately 12,375 sf (0.28 acre)

Legal Description: Lot 12, Munfrada Subdivision, Section 26, T. 1S., R. 1W, City of Grand Junction, County of Mesa, State of Colorado.

Point of Reference: This property is located approximately 1 mile southwest of the State of Colorado Tailings Repository. Appendix Figure 2.1 shows the property location relative to its surroundings.

Utilities: Utility locations are shown in Appendix Figure 2.2.

Electrical:	Overhead
Gas:	Underground
Telephone:	Overhead
Sewer:	Underground
Water:	Underground
Cable TV:	Overhead

Bordering Properties:

North:	Commercial complex
South:	Milo Drive
East:	Single-family residence
West:	Single-family residence

### 2.2 Existing Facilities and Structures

Primary Structure:

Type:	Single-family residence
Size:	Approx. 1,279 sf
Construction Date:	1957
Construction:	Wood-frame with brick veneer on front
Foundation:	Concrete stemwall on spread footing
Footing Depth:	Approximately 12" to bottom of footing from grade
Basement:	None
Crawl Space:	Yes; full
Condition:	Fair



Other Structures:

Type:	Metal shed
Size:	Approximately 43 sf
Construction:	Metal
Foundation:	Not determined
Condition:	Good

Improvements or Attachments to Structure:

Additions:	None
Porches:	None
Patios:	None
Driveways:	
Type:	Gravel
Location:	Milo Drive to the house
Sidewalks:	
Type:	Concrete
Location:	Driveway to front door
Fences:	
Type:	Chain link and woven wire
Location:	Around perimeter of yard except south side
General Remarks:	The property is well landscaped; the house is in fair condition. Structures, utilities, landscaping, and other special features of this property are included in Appendix Figure 2.2.

Historical Data:

This structure is not over 50 years old. Therefore, it does not meet the eligibility criteria for consideration of inclusion on the National Register of Historic Places.

### 3.0 RADIOLOGIC SURVEY

#### 3.1 Introduction

Radiologic data were collected by Bendix at DOE ID No. GJ-07784-RS on January 28, 1985. Data collection methods were performed in accordance with procedures fully described in the Radiologic Support Operations Procedures Manual GJ-07(84) (Bendix Field Engineering Corporation, 1984). These data were evaluated to determine the areal and vertical extent of uranium mill tailings contamination at this property as well as any other contaminated material that may have originated from the millsite.

A review of historical information from the files of the Colorado Department of Health (CDH) and the inclusion data from Oak Ridge National Laboratory (ORNL) was conducted. These records indicate that contamination is located along the total length of the west property line and in two small areas in the north yard.

The Bendix radiologic survey was designed to investigate the entire property, with emphasis on previously identified areas of contamination. Conclusions based upon data analyses are discussed in Section 3.5, Extent of Contamination. Photocopies of the Official Survey Report, Memo of Understanding, team leader notes, and deconvolution graphs are included in the Appendix (Section 6.0).

#### 3.2 Gamma Exposure-Rate Surveys

##### 3.2.1 Exterior Findings

Background Readings: 13 to 15 uR/h  
Highest Outside Gamma Reading (HOG): 32 uR/h

Exterior radium-concentration measurements are presented in Appendix Table 3.1. Grid-point survey results are shown in Appendix Figure 3.1. Appendix Figure 3.2 presents the ranges of elevated gamma readings and indicates areas of possible contamination.

##### 3.2.2 Interior Findings

Background Readings: 11 to 14 uR/h  
Highest Inside Gamma Reading (HIG): 14 uR/h

Interior gamma exposure-rate measurements are summarized in Appendix Table 3.2. Appendix Figure 3.3 shows interior exposure rates and locations of these measurements.

#### 3.3 Boreholes, Soil Samples, and Other Measurements

Areas which displayed elevated gamma levels were further investigated; these areas are shown in Appendix Figure 3.4. Data from these investigations are included in Appendix Table 3.1.

### 3.4 Radon/Radon Daughter Concentration (RDC)

The working level was not assessed by CDH. No RDC measurements were taken by Bendix.

### 3.5 Extent of Contamination

Appendix Figure 3.5 shows identified areas and estimated depths of contamination on this property, based on assessments of all measurements taken. As noted in this figure, areas recommended for remedial action that contain identified residual radioactive materials are:

- (AREA A) Along the fence, southwest of the primary structure, there is contamination to a depth of 24 inches (approximately 88 sf).
- (AREA B) Along the fence, west of the primary structure, there is contamination to a depth of 9 inches (approximately 60 sf).
- (AREA C) North of the primary structure there is contamination to a depth of 12 inches (approximately 42 sf).
- (AREA D) Two deposits along the west property line are contaminated to a depth of 12 inches (approximately 104 sf).
- (AREA E) There is a deposit of contamination northeast of the primary structure. The depth of contamination is 18 inches (approximately 40 sf).

#### 4.0 RECOMMENDED REMEDIAL ACTION

##### 4.1 Decontamination and Restoration

The recommended remedial action for this property, DOE ID No. GJ-07784-RS, includes removal of all areas identified as containing radioactive material (as discussed in Section 3.5 and shown in Appendix Figure 3.5) and transport of removed material to the disposal site.

After remedial action is completed, the areas involved will be restored to original condition in accordance with the Bendix drawings, Vicinity Properties General Construction Specification (Bendix Field Engineering Corporation, 1984), and Statement of Work for Construction Subcontractor.

Dislocation of the occupants will not be required for this remedial action.

##### 4.2 Evaluation of Recommended Remedial Action

Volume calculations of the areas included for remedial action are presented in Appendix Table 4.1. Cost estimates are presented in Appendix Table 4.2.

Estimated cost of remedial action is \$1,988.

This remedial action will result in removal of the identified residual radioactive materials.

Owner preference is to have the remedial action done in late fall.

No legal or other complications are foreseen at this time.

## 5.0 REFERENCES

ARIX, A Professional Corporation, Procedures Manual for the Grand Junction Remedial Action Program, for Colorado Department of Health, Radiation Control Division, and the U.S. Department of Energy, 1983.

Bendix Field Engineering Corporation, Procedures Manual Radiologic Support Operations Grand Junction Vicinity Properties, (GJ-07), for U.S. Department of Energy, UMTRA Project Office, Albuquerque Operations Office, Albuquerque, New Mexico, 1984.

Bendix Field Engineering Corporation, Engineering, Construction, and Land Support Manual Grand Junction Vicinity Properties Project, (GJ-08), for U.S. Department of Energy, UMTRA Project Office, Albuquerque Operations Office, Albuquerque, New Mexico, 1984.

Bendix Field Engineering Corporation, Grand Junction Vicinity Properties Operating Manual, (GJ-16) for U.S. Department of Energy, Nuclear Energy Programs, Division of Remedial Action Projects, UMTRA, 1984.

Bendix Field Engineering Corporation, Vicinity Properties General Construction Specification, for U.S. Department of Energy, Nuclear Energy Programs, Division of Remedial Action Projects, UMTRA, 1984.

Bendix Field Engineering Corporation, Environmental Assessment of Preliminary Cleanup Activities at Offsite Properties Contaminated by Tailings from the Grand Junction Inactive Uranium Millsite, (GJ-04), for U.S. Department of Energy, UMTRA Project Office, Albuquerque Operations, Albuquerque, New Mexico, 1983.

U.S. Department of Energy, Programmatic Memorandum of Agreement (DOE No. DE-GMD4-84AL28460) between the U.S. Department of Energy, the Advisory Council on Historic Preservation, and the Colorado State Historic Preservation Officer, for UMTRA Project Office, Albuquerque Operations Office, Albuquerque, New Mexico, 1984.

U.S. Department of Energy, Vicinity Properties Management and Implementation Manual, for UMTRA Project Office, Albuquerque Operations Office, Albuquerque, New Mexico, 1984.

U.S. Environmental Protection Agency, Standards for Remedial Action at Inactive Uranium Processing Sites (40 CFR Part 192), Washington, D.C., 1983.

## 6.0 APPENDIX

This Appendix contains the following:

Appendix Tables:

Table 3.1	Radium Concentrations at Exterior Locations
Table 3.2	Summary of Interior Gamma Exposure Rates
Table 4.1	Contaminated Material Calculations
Table 4.2	Estimated Cost of Decontamination and Restoration

Appendix Figures:

Figure 2.1	Vicinity Map
Figure 2.2	Site Plan
Figure 3.1	Exterior Grid-Point Exposure Rates
Figure 3.2	Exterior Gamma Scan
Figure 3.3	Interior Gamma Exposure Rates
Figure 3.4	Sample Locations
Figure 3.5	Exterior Estimated Extent of Contamination

Official Survey Report

Memo of Understanding

Team Leader Notes

Deconvolution Graphs (Apparent Radium-226 Concentration)

## Radium Concentrations at Exterior Locations

DOE ID No. GJ-07784-RS

2696 Milo Drive

Page 1 of 4

Loc #	Grid Location	Depth (in.)	Meas. Type	In Situ Ra-226 (pCi/g)		Chem Ra-226 (pCi/g)	Comments
				Tot. Ct	Spectr.		
1	204217	03	TC	4.8		*	North yard near fence line
		06	TC	4.7		*	
		09	TC	4.6		*	
		12	TC	4.2		*	DC = 12 inches Based on the deconvolution graph
		15	TC	3.9		*	
		18	TC	3.5		*	
		21	TC	3.2		*	
2	214243	03	TC	3.4		*	In leach field
		06	TC	3.6		*	
		09	TC	3.7		*	
		12	TC	3.7		*	DC = 0 inches
		15	TC	3.7		*	
		18	TC	3.6		*	
		21	TC	3.5		*	
3	224246	03	TC	4.0		*	In leach field
		06	TC	4.3		*	
		09	TC	4.4		*	
		12	TC	4.4		*	DC = 0 inches
		15	TC	4.3		*	
		18	TC	4.3		*	
		21	TC	4.1		*	
		24	TC	4.1		*	
		27	TC	3.9		*	
4	240270	03	TC	8.0		*	North of house
		06	BH	6.7	5.2	*	
		09	TC	5.9		*	
		12	BH	5.2	2.9	*	DC = 12 inches Based on the deconvolution graph
		15	TC	4.9		*	
		18	BH	4.4	1.8	*	
		21	TC	4.1		*	
		24	TC	3.6		*	
		27	TC	3.4		*	
		30	TC	3.1		*	
5	243267	03	TC	4.5		*	North of house
		06	TC	4.9		*	
		09	TC	4.9		*	DC = 0 inches
		12	TC	4.9		*	
		15	TC	4.9		*	



## Radium Concentrations at Exterior Locations

DOE ID No. GJ-07784-RS

2696 Milo Drive

Page 2 of 4

Loc #	Grid Location	Depth (in.)	Meas. Type	In Situ Ra-226 (pCi/g)		Chem Ra-226 (pCi/g)	Comments
				Tot. Ct	Spectr.		
5	243267	18	TC	4.8		*	
		21	TC	4.4		*	
		24	TC	4.0		*	
6	252287	03	TC	10.7		*	Northeast of house
		06	BH	9.6	8.4	*	
		09	TC	7.9		*	
		12	BH	6.5	4.5	*	
		15	TC	5.5		*	
		18	BH	4.7	2.4	*	DC = 18 inches
		21	TC	4.1		*	Based on the
		24	BH	3.6	1.2	*	deconvolution graph
		27	TC	3.3		*	
		30	TC	3.2		*	
		33	TC	3.2		*	
7	258243	03	TC	3.9		*	Near sewer line
		06	TC	4.1		*	
		09	TC	4.4		*	
		12	TC	4.5		*	DC = 0 inches
		15	TC	4.4		*	
		18	TC	4.3		*	
		21	TC	4.0		*	
8	270217	03	TC	5.1		*	West of house
		06	TC	5.2		*	Next to fence line
		09	TC	4.9		*	
		12	TC	4.6		*	
		15	TC	4.5		*	
		18	TC	4.1		*	DC = 9 inches
		21	TC	3.7		*	Based on the
		24	TC	3.3		*	deconvolution graph
		27	TC	3.1		*	
		30	TC	3.0		*	
		33	TC	3.0		*	
9	280229	03	TC	3.8		*	West side of house
		06	TC	4.1		*	Auger refusal
		09	TC	4.3		*	
		12	TC	4.4		*	DC = 0 inches
		15	TC	4.3		*	
		18	TC	4.1		*	
		21	TC	3.9		*	



## Radium Concentrations at Exterior Locations

DOE ID No. GJ-07784-RS

2696 Milo Drive

Page 3 of 4

Loc #	Grid Location	Depth (in.)	Meas. Type	In Situ Ra-226 (pCi/g)		Chem Ra-226 (pCi/g)	Comments
				Tot. Ct	Spectr.		
10	289267	03	TC	3.6		*	Near water line
		06	TC	3.7		*	
		09	TC	3.9		*	
		12	TC	4.2		*	
		15	TC	4.3		*	
		18	TC	4.4		*	
		21	TC	4.3		*	
		24	TC	4.2		*	
		27	TC	4.0		*	
		30	TC	4.0		*	
		33	TC	3.9		*	DC = 0 inches
		36	TC	3.9		*	
		39	TC	3.7		*	
		42	TC	3.7		*	
		45	TC	3.7		*	
		48	TC	3.7		*	
		51	TC	3.7		*	
		54	TC	3.7		*	
		57	TC	3.8		*	
		60	TC	3.6		*	
		63	TC	3.7		*	
		66	TC	3.7		*	
11	290217	00	DS	20.4		*	Southwest of house
		06	DS	12.4		*	
		12	DS	5.5		*	
		18	DS	3.1		*	
		24	DS	1.0		*	
		03-09	SS			75.7	DC = 24 inches
		12-16	SS			14.8	
		16-20	SS			3.4	
12	290230	00	DS	1.8		*	Above gas line
		24	DS	1.3		*	DC = 0 inches
13	290242	00	DS	<1.0		*	Background
		00-06	SS			2.6	Wet moist soil
		03	TC	3.4		*	
		06	TC	3.7		*	
		09	TC	3.9		*	
		12	BH	4.0	1.3	*	DC = 0 inches
		15	TC	4.0		*	

## Radium Concentrations at Exterior Locations

DOE ID No. GJ-07784-RS

2696 Milo Drive

Page 4 of 4

Loc #	Grid Location	Depth (in.)	Meas. Type	In Situ Ra-226 (pCi/g)		Chem Ra-226 (pCi/g)	Comments
				Tot. Ct	Spectr.		
13	290242	18	BH	3.9	1.1	*	
		21	TC	3.9		*	
		24	TC	3.9		*	
		27	TC	3.8		*	

Tool Types: GB = GAD-6 Borehole  
GS = GAD-6 Surface  
DS = Delta Scintillometer  
TC = Total Count Borehole  
SS = Soil Sample  
BH = Combined GAD-6 and  
Total Count Borehole

Notes: DC = Depth of Contamination  
\* = No Soil Sample Taken

Date of Survey = 01-28-85  
Team Leader = R2

Location *	Number of Readings Taken at Waist Level	Range at Waist Level (uR/h)	Mean at Waist Level (uR/h)	Number of Readings Taken at Surface	Range at Surface (uR/h)	Mean Surface (uR/h)
GROUND FLOOR	*	*	*	*	11-14	*
SHED	05	10-11	11	05	11-11	11

---

\* The CDH and ORNL data indicated the absence of interior contamination at this property. This information was investigated by performing a walking gamma scan. These areas and the ranges of gamma measurements are shown in Appendix Figure 3.3. Exposure rates in the shed are shown in Appendix Figure 3.3.

Table 4.1  
Contaminated Material Calculations  
DOE ID No. GJ-07784-RS

Page 1 of 1

<u>AREA</u>	<u>CALCULATIONS(ft)</u>		<u>SF</u>	<u>DEPTH(ft)</u>		<u>CF</u>		<u>CUBIC YARDS</u>
EXTERIOR								
A	22 x 4	=	88	x	2.0	=	176	
B	15 x 4	=	60	x	0.8	=	48	
C	7 x 6	=	42	x	1.0	=	42	
D	26 x 4	=	104	x	1.0	=	104	
E	10 x 4	=	40	x	1.5	=	60	
							<hr/>	
TOTAL VOLUME - EXTERIOR						=	430	= 430/27 = 16

See Appendix Figure 3.5 For Areas

=====

Table 4.2  
Estimated Cost of Decontamination and Restoration  
DOE ID No. GJ-07784-RS

Page 1 of 1

---

EXTERIOR

Remove identified residual radioactive material (manual) 16 cy @ \$44.00/cy	\$ 704
Replace roadbase 4 cy @ \$11.50/cy	46
Replace topsoil 12 cy @ \$9.50/cy	114
Replace sod 334 sf @ \$0.30/sf	100
Remove/replace sprinkler system 192 sf @ \$0.40/sf	77
	<hr/>
TOTAL EXTERIOR	\$ 1,041
TOTAL INTERIOR	0
ACCESS CONTROL	250
	<hr/>
SUBTOTAL	\$ 1,291
CONTINGENCY @ 10%	129
	<hr/>
SUBTOTAL	\$ 1,420
CONTRACTOR OVERHEAD & PROFIT @ 40%	568
	<hr/>
GRAND TOTAL	\$ 1,988

=====

LR850308  
REA07784/REA-312/MJP


LOCATION #  
07784

2696 MILO DR.


Tailings Pile

Z. PROPERTY  
LOCATION

FIGURE 2.1 VICINITY MAP









LOT 12, MUNFRADE SUBDIVISION,  
SECTION 26 T13, R1W,  
CITY OF GRAND JUNCTION,  
MESA COUNTY, COLORADO




FEB 1997

This drawing, prepared for the Uranium Mill Tailings Remedial Action Project, is for the sole use of the U.S. Department of Energy and its contractors. It is not a survey plot or an improvement survey plot and is not to be relied upon for the establishment of fence, building, or other future improvement lines.


U.S. DEPARTMENT OF ENERGY GRAND JUNCTION AREA OFFICE, COLORADO	LOCATION NO C30724 25
ADDRESS 2496 MILD DRIVE GRAND JUNCTION, COLORADO	 Purdue Engineering Corporation Grand Junction Office
OWNER	TELE
TENANT	TELE
SURV. MAP 12285	CR. 22
DRAWING NO. 3-C-503-F1	SHEET 1 OF 1
















U.S. DEPARTMENT OF ENERGY  
URANIUM MILL TAILINGS REMEDIAL ACTION PROJECT  
GRAND JUNCTION VICINITY PROPERTIES

Official Survey Report

Property Address 2696 Milo Drive

Property Owner Randy A. and Cynthia J. Hoit

Address of Owner (if different from above) \_\_\_\_\_

Report Prepared By R. Ryan

I. PRESENCE/ABSENCE OF RESIDUAL RADIOACTIVE MATERIALS

1 1 No evidence of residual radioactive material on surveyed property.

1 XXX 1 Residual radioactive materials found at the following locations:

1 XXX 1 In open areas.

1 1 Under or around exterior improvements.

1 1 Under or around a typically nonoccupied structure.

1 1 Under or around a typically occupied structure.

II. RESULTS OF RADIOLOGIC ASSESSMENT

1 1 Levels of radiation from residual radioactive materials, if any, do not exceed EPA Standards and no action is required under the Uranium Mill Tailings Remedial Action Project.

1 XXX 1 Levels of radiation from residual radioactive materials exceed EPA Standards such that Remedial Action is recommended and will be accomplished, with your consent, as soon as budget and schedule permit.

cc:

G. A. Franz, III, GJ/CDH

J. Themelis, Mgr. UMTRA Proj. Off.

HIG = 14 uR/h  
HOG = 32 uR/h

**Bendix**

**Field Engineering  
Corporation**

Environmental Operations

P O Box 1569  
Grand Junction, CO 81502  
Tel (303) 242-8621

A Subsidiary of  
The Bendix Corporation

March 8, 1985

Colorado Department of Health  
222 South 6th Street  
Grand Junction, Colorado 81501

ATTN: Jon Luellen

Dear Jon:

This letter is a follow-up of the Department of Energy (DOE) Identification (ID) number GJ-00784-RS (2696 Milo Drive), conducted on 28 January 1985. The areas requiring additional work or commentary are as follows:

1. Gridpoint measurements shown in Figure 3.1, locations 300280 and 270230, were a computer error that has been corrected. A corrected gridpoint map is enclosed.
2. To include location number 6, Area 'E' with a depth of 18 inches has been added to the Estimated Extent of Contamination map.

Thank you for your time and cooperation. If you have any questions or additional comments, please contact me at 242-8621, extension 433.

Yours very truly,

*Terry Coulson*

Terry Coulson  
Radiologic Survey Team

TC:pr

**INTERNAL  
MEMORANDUM**

**Bendix Field Engineering Corporation  
Grand Junction Projects Office**

**Date:** January 28, 1985

**To:** Files

**From:** Rick Ryan *RR*

**Subject:** GJ-07784-RS

---

Weather

Sunny

Occupancy

Three, two adults, and one child.

Crew

I. Caley  
J. Garcia

C. Adams  
B. Beltz

P. Tuhey  
V. Young

Waterline was investigated with an auger next to the house.

The sewer line and leach field was investigated with augers to check for possible contamination involvement.

The gas line was investigated with a delta on the surface and a depth delta on top of the line.

A low spot in the north section of the lawn was found and augered to see if there was fill in this area. The owner said that this was once a fish pond that had been filled in.

The entire yard has river rock fill and the augers were not as deep because of the difficulty in augering through the large rock.

Contamination on the west side of the property extends over the property line. This adjoining property has been gamma surveyed this summer.

A walking scan of the interior showed no contamination. Since Oak Ridge National Laboratory (ORNL) and Colorado Department of Health (CDH) files indicate no interior contamination, the crawlspace was not gamma surveyed. Because of the difficulty in augering due to the river rock fill, depth deltas were used to find the depth of contamination west of the house near the fence.

All personnel were frisked before leaving the site.




# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

1

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 1

LOCATION: 204217



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	4.8	4.3
6	4.7	4.7
9	4.6	5.1
12	4.2	4.0
15	3.9	4.1
18	3.5	3.3
21	3.2	3.2


# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

2

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 2

LOCATION: 214243



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	3.4	3.4
6	3.6	3.3
9	3.7	3.9
12	3.7	3.7
15	3.7	3.9
18	3.6	3.6
21	3.5	3.5
24	3.4	3.4


# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

3

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 3

LOCATION: 224246



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	4.0	4.0
6	4.3	4.7
9	4.4	4.6
12	4.4	4.6
15	4.3	4.1
18	4.3	4.7
21	4.1	3.7
24	4.1	4.5
27	3.9	3.9


# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

4

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 4

LOCATION: 240270



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	8.0	8.0
6	6.7	5.8
9	5.9	5.7
12	5.2	4.5
15	4.9	5.3
18	4.4	4.0
21	4.1	4.5
24	3.6	3.1
27	3.4	3.6
30	3.1	3.1


# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

5

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 5

LOCATION: 243267



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	4.5	4.5
6	4.9	5.6
9	4.9	4.9
12	4.9	4.9
15	4.9	5.1
18	4.8	5.3
21	4.4	4.4
24	4.0	4.0


# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

6

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 6

LOCATION: 252287



Depth (in)	Apparent Radium-226 (pCi/g)	Apparent Radium-226 (pCi/g)
	Undeconvolved	Deconvolved
3	10.7	10.7
6	9.6	10.7
9	7.9	7.4
12	6.5	5.8
15	5.5	5.1
18	4.7	4.3
21	4.1	3.9
24	3.6	3.2
27	3.3	2.9
30	3.2	3.0
33	3.2	3.2


# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

7

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 7

LOCATION: 258243



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	3.9	3.9
6	4.1	3.9
9	4.4	4.3
12	4.5	4.9
15	4.4	4.4
18	4.3	4.7
21	4.0	4.0


# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

8

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 8

LOCATION: 270217



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	5.1	5.1
6	5.2	5.9
9	4.9	4.9
12	4.6	4.2
15	4.5	5.0
18	4.1	4.1
21	3.7	3.7
24	3.3	2.9
27	3.1	2.9
30	3.0	2.8
33	3.0	3.0




# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

9

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 9

LOCATION: 280229



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	3.8	3.8
6	4.1	4.3
9	4.3	4.5
12	4.4	4.8
15	4.3	4.5
18	4.1	4.1
21	3.9	3.9


# APPARENT RADIUM-226 CONCENTRATION DECONVOLUTION GRAPH

10

PROPERTY NUMBER: GJ-07784-RS

HOLE NUMBER: 10

LOCATION: 299267



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	3.6	3.6
6	3.7	3.5
9	3.9	3.7
12	4.2	4.6
15	4.3	4.3
18	4.4	4.8
21	4.3	4.3
24	4.2	4.4
27	4.0	3.6
30	4.0	4.2
33	3.9	3.7
36	3.9	4.3
39	3.7	3.3
42	3.7	3.7
45	3.7	3.7
48	3.7	3.7


51  
54  
57  
60  
63  
66

3.7  
3.7  
3.8  
3.6  
3.7  
3.7

3.7  
3.5  
4.3  
3.1  
3.9  
3.7

# APPARENT RADIUM-226 CONCENTRATION 13 DECONVOLUTION GRAPH

PROPERTY NUMBER: GJ-07784-RS  
HOLE NUMBER: 13  
LOCATION: 290242



Depth (in)	Apparent Radium-226 (pCi/g) Undeconvolved	Apparent Radium-226 (pCi/g) Deconvolved
3	3.4	3.4
6	3.7	3.9
9	3.9	4.1
12	4.0	4.2
15	4.0	4.2
18	3.9	3.7
21	3.9	3.9
24	3.9	4.1
27	3.8	3.8