Report

. on

Defective Type SB12
Auxiliary Switches

on

General Electric
Metalclad Switchgear

7908200 294

Table of Contents

- I. Introduction
- II. Material Description
- III. Material Deficiency and Safety Implications
- IV. Investigation at the Callaway Jobsite
- V. Corrective Action

Attachments

A. Summary of Callaway Jobsite Class IE Type SB12 Auxiliary Switches

I. Introduction

In accordance with the requirements of 10 CFR 50.55e, this final report is submitted relative to the deficiency in General Electric Type SB12 auxiliary switches.

General Electric advised us by letter dated July 6, 1979, of a potential 10 CFR 21 incident related to auxiliary switches used in metalclad switchgear. Action was immediately taken to determine if defective switches were in existence at the Callaway jobsite. General Electric was advised by Bechtel that the defective switches constituted a reportable deficiency and they were requested to take corrective action. General Electric subsequently instructed their local Installation and Service Engineering Division representative to coordinate an inspection and replacement program.

II. Material Description

Type SB12 auxiliary switches form an integral part of the circuit breaker trip coil circuit. The trip coil and switch "a" contacts are monitored on the front door of the switchgear by a red light which is illuminated when the breaker is closed. The illuminated red light signifies trip circuit continuity and that a trip signal will open the breaker.

In addition, Type SB12 auxiliary switches are provided as stationary contacts in the switchgear cubicle for interlocking and annunciation.

III. Material Deficiency and Safety Implications

Factory tests by General Electric revealed that some Type SB12 switches on circuit breakers were found to have intermittent continuity through the switch "a" contacts in the trip coil circuit.

Investigation by General Electric revealed that a die used to form a hole in the contact arms of the switch had worn resulting in elongated holes. This condition could permit the contact bridge member to move laterally relative to the contact arm resulting in occasionally improper contact wipe.

Failure of this auxiliary switch contact to close prevents electrical tripping of the circuit breaker, and, if undetected, the ability to provide reliable power to Class IE loads could be significantly degraded.

IV. Investigation at the Callaway Jobsite

An inspection program was undertaken at the Callaway jobsite to identify Type SB12 switches in the 4.16KV Class IE metalclad switchgear supplied by General Electric. The identification was performed using the Quality Control Acceptance Number on each switch. This QC number consists of a date code which is unique to the date of switch manufacture. The results of this inspection are contained in Attachment A. This information has been communicated to General Electric.

It was determined by GE that all Type SB12 switches in Class IE applications at the Callaway jobsite with the exception of those with QC Acceptance Number 30FM were defective.

V. Corrective Action

Nonconformance report No. 2SN-0822-E was issued on July 17, 1979, to document the Type SB12 auxiliary switches that have been received at the Callaway jobsite. "QC Hold" tags have been placed on all Type SB12 switches. GE will replace the defective switches when replacements become available.

Attachment A

Summary of Callaway Jobsite Class IE Type SB12 Auxiliary Switches

Circuit Breaker Serial Number	General Electric Drawing Number	Acceptance No.
26226311 - 011	226A9287-G1	31AR
269A5311 - 011 - 012		31AR
- 001		31ER
- 002	경기에 지난 후 그러워 시작되었다.	31ER
- 003		31ER
- 004		31ER ·
- 005		31ER
- 006	•	31ER
- 007		31ER
- 008	• • • • • • • • • • • • • • • • • • • •	31ER
- 009		31ER
- 010		31ER
- 015	•	31ER
269A6000 - 001	•	31ER
- 020		31ER
	General Electric	Quality Control
Metalclad Switchgear Equipment Number	Drawing Number	Acceptance No.
NB0101	6353570-G12	30PM
02		30JM
03		30JM
.04		30JM
05		30JM
.06	이 강점하다면 보고 있는 사실이다	30JM
07		30JM
08	불합하다 이 교육에는 12 대통 하고	30FM
09	네. 그리는 이번 이번 이번 이번 없는데?	30FM
10		30JM
11	선생님 아내를 하는 것이 되었다.	30JM
12		30JM
13		30JM
14		30JM
15		30HM
16	[발하다] [[[하다 하다 하다 [[[[[[[[[[[[[[[[[[[[[[[[30HM
17		30JM
NB0201		30HM
02		30JM
03		30HM
04		30HM
05		30HM
06		30HM
		30JM

Summary of Callaway Jobsite Class IE Type SB12 Auxiliary Switches (cont'd)

Metalclad Switchgear Equipment Number	General Electric Drawing Number	Quality Control Acceptance No.
NB0208	6353570-G12	30HM
09		30JM
10		30HM
11		30JM
12		30HM
		30HM
13		30HM
14	게게 보고 하셨습니다 맛이 되었다.	30HM
15		3 CHM
16		
17		30HM.