



Crystal River Urit 3 Docket No. 50-302

> December 9, 1992 3F1292-07

U. S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, D. C. 20555

Subject: Licensee Event Report (LER) 92-023

Dear Sir:

Enclosed is Licensee Event Report (LER) 92-023 which is submitted in accordance with 10 CFR 50.73.

Sincerely,

My Boldt

G. L. Boldt Vice President Nuclear Production

EEF:mag

Enclosure

xc: Regional Administrator, Region II Project Manager, NRR Senior Resident Inspector

140050

9212150049 921209 PDR ADDCK 05000302 S PDR

JEZZ !

POST OFFICE BOX 219 • CRYSTAL RIVER, FLORIDA 32623-0219 • (904) 795-6486 A Florida Progress Company

U.S. NUCLEAR REGULATORY COMMISSION											ION	APPROVED OMB NO. 2150-0104 EXPIRES 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 50.0 HOURS. FORV ARD COMMENTS REGARDING BURDEN ESTIMATE TO THE REC JADS AND REPORTS MANAGEMENT BRANCH (P-550). U.S. NUT LEAR REGULATORY COMMISSION WASHINGTON, DC 20555. ND TO THE PAPERWORK REDUCTION PROJECT (0150-0104). FFICE OF MANAGEMENT AND BUDGET, WASHINGTON DC 2° JS.												
FACIL	FACILITY NAME (1) CRYSTAL RIVER UNIT 3 (CR-3)												D	DOKET NUN	IBER	(2)		Ĩ,	PAG	E (3)				
TITLE (	6)	CF	YSTAL	RI	VER UNIT	3 (	CR-3)						(	5 0	0	0	3 5	1	1 OF	0 3				
		ersight	In Origi	nal	Appendix F	A An	alysis P	lesults	In Ope	ration Ou	tside D	esi	gn Basis											
EVE	NT DATE (	(5)		t	ER NUMBER (	3)		REP	ORT DAT	E (7)			01	THER FACIL	ITIES	S INVOLVED (8)								
MONTH	MONTH DAY YEAR				SEQUENTIAL NUMBER		REVISION NUMBER		DAY	YEAR		FACI	ILITY NAMES			0	S 0	1	(S)					
a ( 4	1 0	9 2	9 2		0 2 3		0 0	1 2	0 9	9 2		N/A.				0	5 0	0	0					
	RATING		THIS RE	POF	I IS SUBMITTE	D PUP	SUANT TO	O THE RE	QUIREMA	NTS OF 10	CFR §:	(CHE	OK ONE OR MORE O	OF THE FOLLO	WING		(11)							
M	DDE (9)		20	402(	(b)			20.405(c) 50					73(a)(2)(iv)				73.71(b)							
POWER 20.405(a)(1)()					50.36(c)(1)					73(a)(2)(v)	- 1	-	73.71(c)											
(10		0 0	20	.405(	(a)(1)(ii)	-	50.36(c)(2)				50.7	73(a)(2)(vii)			OTHER (Specify in Abelract below and in Text, NRC Form									
			20	405(	(a)(1)(0)			50.73(a)(2)(l)					73(a)(2)(viii)(A)			366A)								
			20	405	(a)(1)(iv)		X	50.73(a)(2)(ii) 50.73(a)(2)(vii												19				
		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	20	.405(	a)(1)(v)			50.73(a)	a second a second as				73(a)(2)(x)											
NAME	-		-	-				LICENSE	E CONTA	CT FOR THE	S LER (12	0	ومعرفة معادرته	-		TELE	PHONE NU	MBE	R					
					W. A. Step	hen	son, Nu	iclear S	afety S	luperviso				AREA C	ODE	7			6 4	0 0				
5			-	-	COMPLE	TEON	NE LINE FO	OR EACH	COMPON	ENT FAILUR	E IN THIS	S FRE	PORT (13)	1 9 1 4			0 0 -	-	0 4	0 0				
CAUSE	SYSTEM	COMP	ONENT		MANUFAC- TURER		OFTABLE NPRDS			CAUS	E SYST	EM	COMPONENT		IUFAC		REPORTAB TO NPRDS							
		Ĺ									1	-	i i i	1		-								
												111												
					SUPPLE	MENT	AL REPOR	T EXPEC	TED (14)					100	ECTE		MONT	н	DAY	YEAR				
YES (If yes, complete EXPECTED SUBMISSION DATE)							X	NO	_		MISS E (15)		1			1								
ABSTR					unit				as o	perat	ing	at	: 100% c	of RA'	TEI		THERM	AI						

POWER on November 10, 1992. At 1400, contractor personnel determined that a discrepancy in the assumptions of the 10CFR50 Appendix R analysis constituted a condition outside the plant's design basis. The discrepancy concerned normal makeup valve, MUV-31, which functions to control makeup flow to the Reactor Coolant System (RCS) such that a predetermined level is maintained in the pressurizer. The design of MUV-31 is to fail "as-is" if fire damage results in a loss of air and/or power to the valve. The CR-3 Appendix R analysis assumed that such a failure would occur with the valve in its normal open position. During research of Appendix R background data, contractor personnel realized a scenario in which MUV-31 could close automatically following a manual isolation of RCS letdown flow. Assuming that subsequent fire damage resulted in MUV-31 failing "as-is," the valve would not be available for RCS inventory control. As a result of this event, the MUV-31 scenario will be reanalyzed to take credit for the bypass flow around the valve. Plant operations will be provided with specific options to use in the event of fire damage disabling MUV-31.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION								APPROVED OMB NO. 3150-0104 EXPIRES 4/30/92													
								ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 50.0 HOURS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON DC 20503.										RD DS AR TO			
FACILITY NAME (1)	DOG	DOCKET NUMBER (2)							LER NUMBER								PAGE (3)				
CRYSTAL RIVER UNIT 3 (CR-3)						Y	EAR		SEQUENTIAL				VISION								
열렸다. 김 씨는 것은 것을 많이 없다.		0	5   (	0 0	0	3	0	2	9	2		0	2	3	- 0	0	0	2	OF	0	3

TEXT (If more space a required, Use additional NRC Form 366A a (17)

## EVENT DESCRIPTION

On November 10, 1992, Crystal River Unit 3 was operating in MODE 1 (POWER OPERATION) at 100% of RATED THERMAL POWER. At 1400 hours, contractor personnel determined that a discrepancy in the assumptions of the plant's 10CFR50 Appendix R fire analysis constituted a condition outside the plant design basis. The event was reported to the Nuclear Regulatory Commission at 1445 via the Emergency Notification System per 10CFR50.72(b)(1)(ii)(B).

The Makeup and Purification (MU) system [CB] functions primarily to maintain chemistry and inventory control in the Reactor Coolant System (RCS) [AB], provide seal injection flow to the Reactor Coolant Pumps (RCPs) [AB,P], and to provide High Pressure Injection flow. During normal power operations, the MU system continuously removes a portion of the fluid from the RCS and directs it to purification equipment. The MU system returns fluid to the RCS via the normal makeup valve, MUV-31 [CB,LCV], and via RCP seal injection flow. Valve MUV-31 controls makeup flow to the RCS as necessary to maintain the desired level in the pressurizer [AB,PZR]. The valve provides a flow path separate from the High Pressure Injection valves [BQ,FCV]. A bypass line around MUV-31 provides approximately 15 gallons per minute (gpm) flow to the RCS via MUV-30 which is independent of the MUV-31 position.

The design of MUV-31 is such that the valve will fail "as-is" if fire damage results in a loss of air and/or control power to the valve. The plant Appendix R analysis assumed that such failure would occur while the valve was open, thus allowing the valve to provide a makeup flow path despite fire damage. During research of background data for the Appendix R analysis, contractor personnel realized that a scenario existed in which MUV-31 could fail in the closed position. The specific scenario postulated that the effects of a fire could cause operators to isolate letdown flow from the RCS before MUV-31 failed due to a loss of air and/or power. With letdown flow isolated, pressurizer level would increase. Valve MUV-31 would close in response to this increase. If MUV-31 failed "as-is" following closure, the valve would not be available for RCS inventory control. However, makeup flow would still exist via the bypass around MUV-31.

This report is being submitted in accordance with 10CFR50.73(a)(2)(ii)(B).

NRC FORM 366A U.S. NUCLEAR REGULATORY 20 (559)							NON APPROVED CMB NO. 8150-0104 EXPIRES 4/30/92															
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION								ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 50.0 HOURS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), UFFICE OF MANAGEMENT AND BUDGET WASHINGTON DC 20503.														
FACILITY NAME (1)	DOCKET NUMBER (2)										U	ER N	NUMBER (6)					1)				
CRYST				YE	RAR			UNBER		REVI												
		0	5	0	0	0	3	0	2	9	2		0	2 3	-	0	0	0	3  OF	10	3	

TEXT (If more space a required, Uav additional NRC Form 386A a (17)

# EVENT ANALYSIS

Following failure of MUV-31, makeup flow to the RCS would still be available through the MUV-31 bypass line. Analysis of this bypass flow has determined that the flow would provide sufficient RCS inventory control provided existing RCS leakage did not exceed nine gpm.

Plant Technical Specifications discuss limits on RCS IDENTIFIED, UNIDENTIFIED, PRESSURE BOUNDARY, primary-to-secondary, and CONTROLLED LEAKAGE. Technical Specifications allow a combined total leakage of 24 gpm. However, Crystal River 3 operates well below these limits. Of the allowable 24 gpm, up to 12 gpm may be attributed to CONTROLLED This leakage is defined by Technical Specifications as LEAKAGE. "seal water flow from the Reactor Coolant Pump Seals." CONTROLLED LEAKAGE is controlled at approximately 6 gpm by flow orifices. Technical Specifications limit UNIDENTIFIED LEAKAGE to one gpm. Primary-to-secondary leakage is typically zero. IDENTIFIED LEAKAGE is typically less that one gpm. Therefore, with normal amounts of IDENTIFIED, CONTROLLED, and primary-to-secondary leakage, and with the maximum allowed amount of UNIDENTIFIED LEAKAGE, controlled plant cooldown would still be possible with MUV-31 closed.

# CAUSE

The discrepancy in the Appendix R analysis was caused by an oversight in the original analysis. The analysis failed to realize that a scenario existed in which MUV-31 could fail while closed. The analysis also failed to consider the adequacy of bypass flow around MUV-31 for RCS inventory control.

#### CORRECTIVE ACTIONS

As a result of this event, the MUV-31 scenario will be reanalyzed to take credit for bypass flow and to address RCS makeup needs versus allowed leakage. Plant operations will be advised of the aforementioned scenario and will be provided with specific options to use in the event of fire damage disabling MUV-31 while it is serving as the primary flow path into the RCS. Additionally, FPC will incorporate the ability to shut down using only MUV-30 into the Appendix R Technical Design Basis Document.

### PREVIOUS SIMILAR EVENTS

This is the first report concerning Appendix R analysis deficiencies related to MUV-31.