

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 8 9 G A E I H Z 2 0 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 57 CAT 58 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0 1 8 60 L 6 0 5 0 0 0 3 6 6 7 1 2 2 4 7 9 8 0 1 0 8 8 0 9

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing procedure HNP-2-1050, Surveillance checks, during steady-state
0 3 | operation, plant operators observed the Drywell and Torus Temperature Recorder,
0 4 | 2T47-R626, printing erratic temperatures. All other drywell and torus temperature
0 5 | indications appeared normal. There was no effect on the environs. This is a
0 6 | non-repetitive event.
0 7 |
0 8 |
7 8 9

SYSTEM CODE S A 11		CAUSE CODE B 12		CAUSE SUBCODE B 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE R 15		VALVE SUBCODE Z 16			
7 8		9 10		11 12		13 14 15 16 17 18				19 20		21 22			
17 LER/RO REPORT NUMBER		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 1 3 7		OCCURRENCE CODE 0 3				REPORT TYPE L		REVISION NO. 0			
21 22		23 24		25 26		27 28 29				30 31		32			
ACTION TAKEN B 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22				ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. N 24	
33 34		35 36		37 38		39 40				41 42		43 44			
PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER L 1 3 0 26													
45 46		47 48		49 50		51 52 53 54				55 56		57 58			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Investigation revealed a cold solder joint on a transistor lead causing the pen to

1 1 be erratic. The transistor pins were resoldered to the card which eliminated the

1 2 problem, and the recorder was returned to service.

1 3

1 4

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	E	28	0	9	9	29	NA				B	31	Operator Observation					
ACTIVITY CONTENT				AMOUNT OF ACTIVITY				LOCATION OF RELEASE											
1	6	Z	33	0	9	9	34	NA				NA							
PERSONNEL EXPOSURES				DESCRIPTION				90017252											
1	7	0	37	0	0	0	38	NA											
PERSONNEL INJURIES				DESCRIPTION				NA											
1	8	0	40					NA											
LOSS OF OR DAMAGE TO FACILITY				DESCRIPTION				NA											
1	9	Z	42					NA											
PUBLICITY ISSUED				DESCRIPTION				NA											
2	0	N	44					NA											

POOR ORIGINAL

NAME OF PREPARER R. T. Nix

PHONE: 912-367-7781

8001140337

NARRATIVE REPORT

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-366/1979-137.

While performing procedure HNP-2-1050, Surveillance Checks, during steady-state operation at 99% power, plant operators observed the Drywell and Torus Temperature recorder, 2T47-R626, printing erratic temperatures. There was no effect on the environs. This is a non-repetitive event. Investigation revealed a cold solder joint on a transistor lead causing the pen to respond erratically. The transistor leads were resoldered which eliminated the problem. This is not a generic problem and therefore has no effect on any other systems or on Unit I.

90017253