

LICENSEE EVENT REPORT

POOR ORIGINAL

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

13	2	2	0	0	-	0	0	0	-	0	0	3	4	1	1	1	1	4	5
LICENSEE CODE					LICENSE NUMBER					LICENSE TYPE					ST. CAT. NO.				

REPORT SOURCE	60	L	61	5	0	5	0	0	0	2	3	7	7	1	2	1	8	7	9	8	0	1	0	7	8	0	9
DOCKET NUMBER													EVENT DATE					REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During surveillance testing of 2/3 D/G, pinion gears engaged, starting the D/G. At 200 RPM pinion gears remained engaged, but they eventually disengaged prior to D/G reaching full speed. Failure to start alarm was received. D/G was immediately de-energized to prevent pinion gears from being damaged. Health and safety of public were not affected because redundant systems were verified operable by required testing. This event is the first of its kind.

SYSTEM CODE	3	E	E	11	COMPONENT CODE	13	X	X	X	X	X	14	COMP SUBCODE	19	X	15	VALVE SUBCODE	23	Z	16
EVENT YEAR	21	7	9	OCCURRENCE CODE	28	0	3	29	REPORT TYPE	32	L	REVISION NO.	33	0						

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (37)

Probable cause was bad connection in speed sensing circuit, preventing deenergizing start solenoid and disengaging gears. A suspected bad capacitor was replaced, but removed capacitor subsequently tested satisfactorily. D/G was successfully started and loaded to full power. No further corrective action deemed necessary.

POWER	10	0	8	2	22	OTHER STATUS	41	N/A	METHOD OF RECOVERY	45	B	31	DISCOVERY DESCRIPTION	46	Routine Surveillance Testing
BASED ON RELEASE	12	Z	22	13	AMOUNT OF ACTIVITY	44	N/A	LOCATION OF RELEASE	45	N/A					
PERSONNEL INVOLVED NUMBER	9	0	0	0	DESCRIPTION	11	N/A								
PERSONNEL INVOLVED NUMBER	9	0	0	0	DESCRIPTION	11	N/A								
TYPE	10	Z	42	DESCRIPTION	11	N/A									

90022233

8001150634

NAME OF PREPARER: Atif A. Ammar