

# The Light company

Houston Lighting & Power

South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483


December 31, 1992  
ST-HL-AE-4293  
File No.: G26  
10CFR50.73

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

South Texas Project  
Unit 1  
Docket No. STN 50-498  
Licensee Event Report 92-019  
Calculation Errors in the  
Setpoint Curves for the Cold Overpressure Mitigation System

Pursuant to 10CFR50.73, Houston Lighting & Power Company (HL&P) submits the attached Unit 1 Licensee Event Report (LER 92-019) regarding Calculation Errors in the Setpoint Curves for the Cold Overpressure Mitigation System (COMS). This event did not have an adverse effect on the health and safety of the public.

If you should have any questions on this matter, please contact Mr. C. A. Ayala at (512) 972-8628 or me at (512) 972-7138.



S. L. Rosen  
Vice President,  
Nuclear Engineering

MAC/ag

Attachment: LER 92-019 (South Texas, Unit 1)

050007

LER\92356001.U1

A Subsidiary of Houston Industries Incorporated

9301050273 921231  
PDR ADOCK 05000498  
S PDR

JE22

Houston Lighting & Power Company  
South Texas Project Electric Generating Station

ST-HL-AE-4293  
File No.: G26  
Page 2

CC:

Regional Administrator, Region IV  
Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

George Dick, Project Manager  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

J. I. Tapia  
Senior Resident Inspector  
c/o U. S. Nuclear Regulatory  
Commission  
P. O. Box 910  
Bay City, TX 77414

J. R. Newman, Esquire  
Newman & Holtzinger, P.C., STE 1000  
1615 L Street, N.W.  
Washington, DC 20036

D. E. Ward/T. M. Puckett  
Central Power and Light Company  
P. O. Box 2121  
Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee  
City of Austin  
Electric Utility Department  
P.O. Box 1088  
Austin, TX 78767

K. J. Fiedler/M. T. Hardt  
City Public Service Board  
P. O. Box 1771  
San Antonio, TX 78296

Rufus S. Scott  
Associate General Counsel  
Houston Lighting & Power Company  
P. O. Box 61867  
Houston, TX 77208

INPO  
Records Center  
1100 Circle 75 Parkway  
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, NY 11713

D. K. Lacker  
Bureau of Radiation Control  
Texas Department of Health  
1100 West 49th Street  
Austin, TX 78756-3189

Revised 10/11/91

L4/NRC/

## LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.8 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

South Texas, Unit 1

DOCKET NUMBER (2)

05000498

PAGE (3)

1 OF 05

TITLE (4)

Calculation Errors in the Setpoint Curves for the Cold Overpressure Mitigation System

| EVENT DATE (5)     |     |      | LER NUMBER (6)  |                   |                 | REPORT NUMBER (7) |     |      | OTHER FACILITIES INVOLVED (8) |               |  |   |   |   |   |   |   |   |                    |           |
|--------------------|-----|------|---|-------------------|-----------------|-------------------|-----|------|-------------------------------|---------------|--|---|---|---|---|---|---|---|--------------------|-----------|
| MONTH              | DAY | YEAR | YEAR  | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH             | DAY | YEAR | FACILITY NAME                 | DOCKET NUMBER |  |   |   |   |   |   |   |   |                    |           |
| 1                  | 2   | 0    | 2   | 9                 | 2               | 9                 | 2   | 0    | 1                             | 9             | 0  | 0 | 1 | 2 | 3 | 1 | 9 | 2 | South Texas Unit 2 | 05000 499 |
|                    |     |      |   |                   |                 |                   |     |      | FACILITY NAME                 |               | DOCKET NUMBER  |   |   |   |   |   |   |   |                    |           |
|                    |     |      |   |                   |                 |                   |     |      | South Texas Unit 2            |               | 05000  |   |   |   |   |   |   |   |                    |           |
|                    |     |      |   |                   |                 |                   |     |      | FACILITY NAME                 |               | DOCKET NUMBER  |   |   |   |   |   |   |   |                    |           |
|                    |     |      |   |                   |                 |                   |     |      |                               |               | 05000  |   |   |   |   |   |   |   |                    |           |
| OPERATING MODE (9) |     | 5    | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 4: (Check one or more) (11) |                   |                 |                   |     |      |                               |               |  |   |   |   |   |   |   |   |                    |           |
| POWER LEVEL (10)   |     | 000  | 20.402(b)   |                   |                 | 20.405(c)         |     |      | 50.73(a)(2)(iv)               |               | 73.71(b)   |   |   |   |   |   |   |   |                    |           |
|                    |     |      | 20.405(a)(1)(i)   |                   |                 | 50.36(c)(1)       |     |      | 50.73(a)(2)(v)                |               | 73.71(c)   |   |   |   |   |   |   |   |                    |           |
|                    |     |      | 20.405(a)(1)(ii)  |                   |                 | 50.36(c)(2)       |     |      | 50.73(a)(2)(vi)               |               | OTHER  |   |   |   |   |   |   |   |                    |           |
|                    |     |      | 20.405(a)(1)(iii)   |                   |                 | X 50.73(a)(2)(i)  |     |      | 50.73(a)(2)(vii)(A)           |               | (Specify in Abstract below and in Text, NRC Form 366A) |   |   |   |   |   |   |   |                    |           |
|                    |     |      | 20.405(a)(1)(iv)  |                   |                 | X 50.73(a)(2)(ii) |     |      | 50.73(a)(2)(vii)(B)           |               |  |   |   |   |   |   |   |   |                    |           |
|                    |     |      | 20.405(a)(1)(v)   |                   |                 | 50.73(a)(2)(iii)  |     |      | 50.73(a)(2)(x)                |               |  |   |   |   |   |   |   |   |                    |           |

## LICENSEE CONTACT FOR THIS LER (12)

NAME

Charles Ayala - Supervising Licensing Engineer

TELEPHONE NUMBER (include Area Code)

(5 1 2) 9 7 2 - 8 6 2 8

## COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NRC | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NRC |
|-------|--------|-----------|--------------|-------------------|-------|--------|-----------|--------------|-------------------|
|       |        |           |              |                   |       |        |           |              |                   |
|       |        |           |              |                   |       |        |           |              |                   |
|       |        |           |              |                   |       |        |           |              |                   |

## SUPPLEMENTAL REPORT EXPECTED (14)

| YES   | NO                       | EXPECTED SUBMISSION DATE (15) | MONTH | DAY | YEAR |
|---|--------------------------|-------------------------------|-------|-----|------|
| <input checked="" type="checkbox"/> If yes, complete EXPECTED SUBMISSION DATE | <input type="checkbox"/> |                               |       |     |      |

## ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On December 2, 1992, Unit 1 was in Mode 5 during a refueling outage and Unit 2 was in Mode 1 at 100% power. At 1500 hrs, while reviewing a Nuclear Network item regarding a calculation error affecting the Power Operated Relief Valve (PORV) setpoint curves for the Cold Overpressure Mitigation System (COMS), it was determined that the same condition existed at South Texas Project. The analysis performed by Westinghouse for the COMS setpoint neglected the pressure loss of the reactor coolant flow through the reactor core. This resulted in a higher pressure at the reactor core midplane elevation than the pressure at the sensing point in the RCS hot leg. Because of the error, COMS has been technically inoperable since the startup of each unit. Corrective actions for this event include issuing a Justification for Continued Operation (JCO), resetting the high PORV COMS setpoint curves to meet the JCO limit and requesting Westinghouse to revise the COMS Safety Analysis as well as providing a root cause analysis on this event to determine the generic implication and corrective actions.

REQUIRED NUMBER OF DIGITS/CHARACTERS  
FOR EACH BLOCK

| BLOCK NUMBER | NUMBER OF DIGITS/CHARACTERS   | TITLE                        |
|--------------|---|------------------------------|
| 1            | UP TO 46  | FACILITY NAME                |
| 2            | 8 TOTAL<br>3 IN ADDITION TO 05000   | DOCKET NUMBER                |
| 3            | VARIES  | PAGE NUMBER                  |
| 4            | UP TO 76  | TITLE                        |
| 5            | 6 TOTAL<br>2 PER BLOCK  | EVENT DATE                   |
| 6            | 7 TOTAL<br>2 FOR YEAR<br>3 FOR SEQUENTIAL NUMBER<br>2 FOR REVISION NUMBER             | LER NUMBER                   |
| 7            | 6 TOTAL<br>2 PER BLOCK  | REPORT DATE                  |
| 8            | UP TO 18 -- FACILITY NAME<br><br>8 TOTAL -- DOCKET NUMBER<br>3 IN ADDITION TO 05000   | OTHER FACILITIES INVOLVED    |
| 9            | 1   | OPERATING MODE               |
| 10           | 3   | POWER LEVEL                  |
| 11           | 1<br>CHECK BOX THAT APPLIES   | REQUIREMENTS OF 10 CFR       |
| 12           | UP TO 50 FOR NAME<br>14 FOR TELEPHONE   | LICENSEE CONTACT             |
| 13           | CAUSE VARIES<br>2 FOR SYSTEM<br>4 FOR COMPONENT<br>4 FOR MANUFACTURER<br>NPRDS VARIES | EACH COMPONENT FAILURE       |
| 14           | 1<br>CHECK BOX THAT APPLIES   | SUPPLEMENTAL REPORT EXPECTED |
| 15           | 6 TOTAL<br>2 PER BLOCK  | EXPECTED SUBMISSION DATE     |

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 80.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

**LICENSEE EVENT REPORT (LER)**  
**TEXT CONTINUATION**

| FACILITY NAME (1)   | DOCKET NUMBER (2) | LER NUMBER (6) |                      |                    | PAGE (3) |
|---------------------|-------------------|----------------|----------------------|--------------------|----------|
| South Texas, Unit 1 | 05000 498         | YEAR           | SEQUENTIAL<br>NUMBER | REVISION<br>NUMBER | 02 OF 05 |
|                     |                   | 9 2            | - 0 1 9 -            | 0 0                |          |

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**DESCRIPTION OF EVENT:**

On December 2, 1992 Unit 1 was in Mode 5 during a refueling outage and Unit 2 was in Mode 1 at 100% power. At 1500 hours, while reviewing a Nuclear Network item regarding a calculation error affecting maximum Power Operated Relief Valve (PORV) setpoint curves for the Cold Overpressure Mitigation System (COMS), it was determined that the same conditions existed at the South Texas Project Electric Generating Station (STPEGS). The Reactor Coolant System (RCS) COMS analysis by Westinghouse indicated that the setpoint curve in Technical Specification 3.4.9.3, Figure 3.4-4 was non-conservative.

The Network entry described a condition where two discrepancies were noted which affect the heatup and cooldown curve shown in the Technical Specification and also the maximum PORV setpoint curves for the COMS. First, it was determined that the pressure difference between the RCS wide range pressure sensing location and the region of interest for the heatup/cooldown curves (typically, the core midplane elevation) had not been considered. Secondly, the dynamic pressure (which varies, depending on the number of operating reactor coolant pumps and which wide range pressure transmitter is used) had been neglected. These discrepancies result in a higher pressure at the reactor core midplane elevation than the pressure at the sensing point in the RCS hot leg. STPEGS uses the wide range pressure transmitters located on the hot legs of three of the four coolant loops for indication to ensure compliance with the heatup/cooldown pressure/temperature curves. Transmitters sensing pressure at two of these same locations are used for the automatic operation of the COMS. It has been determined that the static and dynamic pressure differences between wide range pressure indication location and the region of interest for the heatup/cooldown curves had not been considered in the safety analysis for STPEGS.

COMS is designed to provide protection by monitoring RCS pressure and temperature and opening the Pressurizer PORVs if the COMS setpoint curve is exceeded.

LER\92356001.U1



LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (INBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| FACILITY NAME (1)   | DOCKET NUMBER (2) | LER NUMBER (4) |                   |                 | PAGE (3) |
|---------------------|-------------------|----------------|-------------------|-----------------|----------|
|                     |                   | YEAR           | SEQUENTIAL NUMBER | REVISION NUMBER |          |
| South Texas, Unit 1 | 05000 498         | 9 2            | - 0 1 9 -         | 0 0             | 03 OF 05 |

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

DESCRIPTION OF EVENT: (Con't)

Both PORVs in Units 1 and 2 have always been set within the Technical Specification setpoint curve. The error in the safety analysis has caused the COMS to be technically inoperable since the startup of each unit. However, one of the two COMS setpoint curves is low enough to have provided adequate overpressure protection even considering the calculation error.

The NRC was notified on December 3, 1992 at 1438 hours that this event was a violation of the Plant Operating License No. NPF-76(2G) Section 2.C(2). A Justification for Continued Operation (JCO) was completed on December 4, 1992.

CAUSE OF EVENT:

The Westinghouse analysis which was used to determine the COMS setpoint curves and the Licensing Basis neglected to allow for the differential pressure between the reactor vessel cold legs and the pressure transmitter instrument taps on the RCS hot leg piping.

ANALYSIS OF EVENT:

STPEGS has reviewed the PORV COMS setpoint curves and the Technical Specification limits and determined that there is margin in the low PORV (PCV-656A) setpoint curve. The PCV-656A setpoint is approximately 70 PSIG below the Technical Specification limit throughout the curve. A maximum differential pressure of 35 PSID across the core has been calculated for two Reactor Coolant Pump (RCP) operation. This calculation represents a conservative, worst-case maximum for the given conditions. Even with a 35 PSID differential across the core, PCV-656A will open approximately 35 PSIG prior to exceeding the COMS Technical Specification limit for any operating temperature. Therefore, PCV-656A will perform its intended function during two RCP operation with no change to its setpoint curve.

LER\92356001.U1

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THE INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNRB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| FACILITY NAME (1)   |  | DOCKET NUMBER (2) |  | LER NUMBER (4) |                   |                 | PAGE (3) |
|---------------------|--|-------------------|--|----------------|-------------------|-----------------|----------|
| South Texas, Unit 1 |  | 05000 498         |  | YEAR           | SEQUENTIAL NUMBER | REVISION NUMBER | 04 OF 05 |
|                     |  |                   |  | 9 2            | - 0 1 9 -         | 0 0             |          |

TEXT (if more space is required, use additional copies of NRC Form 366A) (17)

ANALYSIS OF EVENT: (Con't)

The high PORV (PCV-655A) COMS setpoint curve is only 10 PSIG below the Technical Specification limit. In order to provide a conservative margin to the Technical Specification limit, the PCV-655A COMS setpoint curve had to be lowered by 35 PSIG, the maximum core differential pressure. Following this temporary change, even with a 35 PSID differential across the core, PCV-655A will open approximately 10 PSIG prior to exceeding the COMS Technical Specification limit, per the original design intent. This still assumes a maximum of two RCPs operating.

Requirements addressing overpressure protection are given in the Technical Specification Limiting Condition for Operation (LCO) 3.4.9.3. This LCO requires that two PORVs be operable during Modes 4, 5, and 6 with the reactor vessel head on; or that the RCS be depressurized and a 2.0 square inch or greater vent be provided. Since COMS was technically inoperable since plant startup for each unit, this event is reportable pursuant to 10CFR50.73(a)(ii)(B) and 10CFR50.73(a)(i)(B).

CORRECTIVE ACTIONS:

1. A JCO has been issued for both units, limiting Reactor Coolant Pump operation to two (2) RCPs when RCS temperature is below 245°F and lowering the high PORV COMS setpoint curve by 35 PSIG. These actions insure the operability of COMS within the existing Technical Specification limitations and Licensing Basis.
2. The high PORV COMS setpoint has been reset to meet the limits provided in the JCO.
3. Westinghouse will be requested to revise the COMS Safety Analysis. Upon receipt of the revised analysis, a Technical Specification change request will be submitted to correct the COMS curve. Approval of that Technical Specification change will initiate recalibration of the PORV COMS setpoint curves and eliminate the need for the JCO.
4. In an effort to determine the generic implications of this event, STPEGS will request that Westinghouse perform a root cause analysis and develop any necessary corrective actions.

LER\92356001.U1

**LICENSEE EVENT REPORT (LER)**  
**TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THE INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| FACILITY NAME (1)   | DOCKET NUMBER (2) | LER NUMBER (4) |                   |                 | PAGE (3) |
|---------------------|-------------------|----------------|-------------------|-----------------|----------|
| South Texas, Unit 1 | 05000 498         | YEAR           | SEQUENTIAL NUMBER | REVISION NUMBER | 05 OF 05 |
|                     |                   | 9 2            | - 0 1 9 -         | 0 0             |          |

TEXT (If more space is required, use additional copies of NRC Form 365A) (17)

ADDITIONAL INFORMATION:

A similar event has been reported regarding the NSSS Vendor having discrepancies in their safety analysis which led to a reportable event: LER 91-024 (Unit 1 and 2) "A Safety Analysis Deficiency concerning the Pressurizer Safety Relief Valve (SRV) Loop Seal Delay Time."

LER\92356001.U1