NMP-12058

185

NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

300 ERIE BOULEVARD. WEST SYRACUSE, N. Y. 13202

June 5, 1985

Dr. Thomas E. Murley Regional Administrator United States Nuclear Regulatory Commission Region 1 631 Park Avenue King of Prussia, PA 19406

RE: Docket No. 50-220 SPECIAL REPORT

Gentlemen:

In accordance with Technical Specification 3.6.10.1, we hereby submit the following Special Report concerning fire barrier penetrations.

Very truly yours,

Thomas & Lampges

Thomas E. Lempges Vice President Nuclear Generation

TEL/PC/10 attachments cc: Document Control Desk

> 8506210409 8 PDR ADOCK

U. LICENSEE EVENT REPORT (LER)										U.S.	NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85												
FACILITY NAME (1) DOCK										OCK	CKET NUMBER (2)					PAGE (3)							
PACIEITY			E POI	NT	INTT	T										5 1 0 1		and I	210	10	F012		
TITLE (4)		PEAK			ONT	-								-	-	1-1-	-		- 1-		1-1-		
		INC	ΓIONA	L F	IRE I	BAR	RIE	R PE	NETR/	TIO	NS												
EVE	NT DATE		T	_	ER NUM	-				PORTO	the second s	T	071	-	ACIL	THES INS	OLVE	0 (8)					
MONTH DAY YEAR			YEAR	YEAR SEQUENTIAL NUMBER				EVISION UMBER	ION MONTH DAY YEAP			FACILITY NAMES				00	DOCKET NUMBERIS						
			+			NUMBER		UMBEN	+		+	1					0	151	010	101	1.1		
	1.11		1			. 1											1	-					
0 5	0 8	8 5	1.1	-			-		0 6	0 5	8 5	1					0	151	0 10	101	1.1		
	in second second	-	THIS A	EPORT	IS SUBN	ITTE	PURS	UANT	TO THE R	EQUIRE	MENTS OF	10 CFR 5	Check one or n	078 0	t the	lallowing)	(11)			aller secolaria			
MODE (0)			20.402(b)					20.406(c)				50.73(a)(2)(iv)					73.71(b)						
POWE	20	20.406(a)(1)(i)					50.38(c)(1)				50.73(a)(2)(v)					73.71(c)							
(10) 11010			20	20.406(a)(1)(#)					50.38(c)(2)				50.73(a)(2)(vii)			X	X OTHER (Specify in Abstract						
			20	4061	1(1)(6)				60.734	0(2)(1)			50.73(a)(2))	AHIII	3			366			2		
1.		24	20.406(a)(1)(iv)				50.73(e)(2)(u)					50.73(a)(2)(v(i))(8)			12	SPECIAL REPORT							
			20	20.406(a)(1)(v)					50.73(s)(2)(iii)				50.73(a)(2)(x)				1						
								1	ICENSEE	CONTA	CT FOR TH	(S LEA (12)		_									
NAME															-	REA COD	-	LEPHO	VE NUM	BER			
ROBERT RANDALL, SUPERVISOR, T						, TE	CHNICAL SUPPORT						1	HER COR									
													311 5 314 9 1-12 1414										
		_		-	COMP	ETE	ONE LI	NE FOR	EACH C	OMPONE	NT FAILU	RE DESCRIB	IED IN THIS RE	PORT	(13)				-				
CAUSE	SYSTEM	COM	ONENT	NENT MANUFA				1.1		CAU	SE SYSTEN	COMPONENT		MANUFAC			REPORTABLE TO NPROS						
				-	UNER	_									-		-						
												1.1											
		_	11	+	1	1						-	+	-	-	_		-	-+				
											1	1.	111			E 1		5.4			114		
	_		1	1		-			EXPECT									1	MONTH	DAY	YEAR		
	-			-	80.99	CEME	ATAL I	ALFOR I	EAPEGI	E.M. 1 1 M						EXPEC SUBMIS	SIGN				-		
- Ver	tit on a	0/10/814	EXPECTED	sum	NOISSIN	DATE	F.		-	NO						DATE	(16)		1	1			
_				_		-	-			A.L									_	deren deren			

ABSTRACT

It was identified on May 8, 1985, that a ventilation duct fire penetration in the Reactor Bldg. Track Bay wall is not equipped with a fire damper. The penetration was declared inoperable in compliance with Tech. Spec. 3.6.10.1 (Fire Barrier Penetrations). Fire watch patrols have been established in accordance with the Tech. Spec. to perform hourly inspections until the situation is corrected. Tech. Spec. 3.6.10.1.d requires that a special report be submitted to the NRC for fire barrier penetrations which are non-functional for more than 14 days.

A Fire Protection Design Package is being formulated to address various technical deficiencies in the fire protection features at Nine Mile Unit 1. The design package will include this fire damper for installation.

NAC Form 366A (9-83)	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED OM EXPIRES 8/31/										
FACILITY NAME (1)	DOCKET NUMBER (2)	L	ER NUMBER (6)		PAGE (3)						
NINE MILE POINT UNIT I		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER							
Carlos and the second	0 5 0 0 0 2 2 0	-	- 11	-	0 12	OF	0	12			

TEXT III more space is required, use additional NRC Form 366A's/ (17)

TEXT

On May 8, 1985 it was discovered that a duct penetration through a fire rated wall in the Reactor Bldg. Track Bay is not equipped with a fire damper. The penetration was declared inoperable in accordance with Tech. Spec. 3.6.10.1, which requires that nonfunctional fire barrier penetrations are restored to functional status within 14 days, or a report shall be prepared and submitted in accordance with 6.9.2.b.

CORRECTIVE ACTIONS

According to the NMPC Fire Protection Engineer, a Fire Protection Design Package is being formulated to address various technical deficiencies in the fire protection features at Nine Mile Unit 1. The design package will include this fire damper for installation. The new damper installation is presently scheduled for completion in late 1985. In accordance with Tech. Spec. 3.6.10.1.c, hourly fire watch patrol was established for the identified duct penetrations not equipped with fire dampers. The fire watch patrol will be maintained until the dampers are installed.

ASSESSMENT OF SAFETY CONSEQUENCES

Because fire watch patrols have been established and will be maintained in accordance with Tech. Spec., no safety consequences have arisen as a result of this event. The fire watch patrols perform hourly inspections guarding against fire while the penetration is non-functional. The watches shall continue until the new damper is installed.