UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555



JUN 1 9 1985

Docket No. 50-322

MEMORANDUM	FOR:	Chairman Palladino	
		Commissioner	Roberts
		Commissioner	Asselstine
		Commissioner	Bernthal
		Commissioner	Zech

FROM: Hugh L. Thompson, Jr., Director Division of Licensing

SUBJECT: BOARD NOTIFICATION 85-063 TDI DIESEL AIR START CHECK VALVE CRACKS AT SHOREHAM

In accordance with the procedures for Board Notification, the following information is being provided directly to the Commission. The appropriate boards and parties, for all facilities with TDI diesel generators, are being informed by a copy of this memorandum. This information is relevant to all facilities that have diesel generators manufactured by TDI, including Shoreham, which is currently before the Commission.

Enclosure 1 is a memo from Richard Starostecki of Region I to the Director, Division of Licensing which describes problems with cracks in, and failures of, certain check valves used in TDI diesel generators. As noted in the Enclosure, problems were first identified at Grand Gulf, and then subsequently at Shoreham. Although these check valves may be used in all TDI engines, problems have only been identified in valves associated with air start systems, and only the TDI engines at Shoreham, Catawba, Midland, San Onofre, Rancho Seco, and River Bend have these particular check valves installed in their air start systems. All engines may have Williams-Gauge check valves installed in their lube oil and/or jacket cooling water systems.

Replacement check valves manufactured by a different vendor as recommended by TDI have either been ordered or are on hand at all sites where the valves are

Contact: R. Caruso X28392

8506260018

installed in air start systems. The staff believes that the problems with these valves are due to a combination of high cycle and low cycle fatigue. Because the valves in the lube oil and jacket water systems operate in a medium with a much higher viscosity, and because they are not subjected to the rapid cycling motion of the air start check valves, we do not believe that there is an immediate problem in those systems.

Hugh L. Thompson, Jr., Director Division of Licensing

Enclosure: Memo from Richard Starostecki (Region I) to Hugh L. Thompson (DL) dated 4/19/85

cc: SECY (2) OPE

OGC EDO Parties to the Proceeding ACRS (10) See next page Midland ASLBs for: Shoreham Shearon Harris

Comanche Peak Perry Vogtle WNP-1 Shoreham

Catawba

ASLABs for: