



GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775
AREA CODE 504 635-6094 346-8651

May 3, 1985
RBG- 20,891
File Code G9.5

Mr. Harold R. Denton, Director
Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Denton:

River Bend Station-Unit 1
Docket No. 50-458

Enclosed for your review is the Gulf States Utilities Company (GSU) Total Inspection Report (Attachment 1) and Owners Group Modification Report (Attachment 2) for the River Bend Station (RBS) Transamerica Delaval, Inc. (TDI) Standby Diesel Generators. The Total Inspection Report lists each diesel generator part by component number as identified in the Design Review and Quality Revalidation (DR/QR) Report through Revision 1 (see the letter from J. C. Deddens (GSU) to H. R. Denton (NRC) dated March 7, 1985 with a GSU Letter No. RBG-20351). The governing work document, remaining scope of work, scheduled completion date and status as of April 26, 1985 are also provided. Finally, the type of inspection being performed is indicated with PTI standing for post-test inspection and INS standing for the TDI Owners Group Inspections. Notes are provided at the end of Attachment 1 to clarify points made in the Total Inspection Report.

Attachment 2 contains the Owners Group Modification Report which when cross-referenced by component number to the DR/QR Report, Revision 1 provides a discussion, schedule and status (through April 26, 1985) of each modification recommended by the TDI Owners Group. Notes are provided at the end of Attachment 2 to clarify points made in the Owners Group Modification Report.

Sincerely,

J. E. Booker

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

8505210598 850503
PDR ADOCK 05000458
Q PDR

JEL
JEB/WJR/JWL/amg
Attachments (2)

8031
140

RIVER BLVD. SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK - ENGINE	DATE	STATUS
F-068	Intercooler	M5000290	Visual for leakage and security	P11-A&B	Fuel Load	Complete
		C-27188		P11-A&B		
		M5000296	Retorque bolts	P11-A&B	Fuel Load	Complete
MF-020	Turbocharger	M4000592	VT thrust bearings	INS-A&B	Fuel Load	Open
		RUM79384		INS-A&B		
		RUM7908		INS-A&B		
MF-020	Turbocharger	C-27125	VT core plug according to STM 360	INS-A&B	Fuel Load	Open
			Perform LP test on weld of nuts	INS-A&B	Fuel Load	Open
		C-27188	LP stationary nozzle ring for cracks	P11-A&B	Fuel Load	Open
			VT stationary nozzle ring for missing blades	P11-A&B	Fuel Load	Open
			Measure axial thrust clearance	P11-A&B	Fuel Load	Open
		C-27188	VT thrust bearings	P11-A&B	Fuel Load	Open
			Turbocharger tube oil pressure readings during engine run at 100%	P11-A&B	Fuel Load	Open
			Bolt torque verification per STM 360	P11-A&B	Fuel Load	Open
			Oil analysis (See 93-8206)	P11-A	Fuel Load	Open
			Oil analysis (See 93-8206)	P11-B	Fuel Load	Complete
00-494	Air Inlet Adapter	M5000275	Visual for security	P11-A&B	Fuel Load	Complete
		C-27188		P11-A&B		

FIVE SEABEE
TRANSAMERICA DELVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 20 1982

UNIT/ITEM #	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK - ENGINE	SUB-DAILY COMPLETION DATE	STATUS
00-400	Exhaust Duct Adapter	n5900276 C-27138	Visual for security	PTI-000 PTI-000	Fuel Load Fuel Load	Complete Complete
03-305ACB	Main Bearing Caps	C-27237 n5900150 RCFM50416 RCFM50435 RCFM50443	VI of 25 main bearing cap mating surface for evidence of fretting Verify preload bearing cap & stud nuts for torque Verify preload bearing cap & stud nuts for torque	INS-B INS-B INS-A INS-A INS-B INS-B	Fuel Load Fuel Load Fuel Load Fuel Load Fuel Load Fuel Load	Complete Complete Complete Complete Complete Complete
03-305ACB	Main Bearing Caps	n5900236 n5900336 C-27138 RCM50600	VI of outside bearing caps for absence of discoloration. Inspect 7 of 7 VI of cotter pin security of nuts (1002 of bearing caps between connector rods) Main bearing caps (mating state with heat gun. (Inspect main) between connector rod bearings). Inspect 7 of 7 Oil analysis (See 03-00000) Oil analysis (See 03-00000)	PTI-000 PTI-000 PTI-000 PTI-000	Fuel Load Fuel Load Fuel Load 5% Power	Complete Complete Complete Upset
03-305E	Main Bearing Rodding	C-27325	Dimensional verification of uniform washer thickness on accessible washer (P/H 03-305-02-00)	INS-000 INS-000 INS-000	Fuel Load Fuel Load Fuel Load	Complete Complete Complete

APRIL 22 1994

COMPONENT IDENTIFICATION	TEST DESCRIPTION	WORK LOG, DUTY HOURS	REMAINING SCORE IN WORK	TIME WORK - ENDED	TIME WORK - STARTED	STATUS
03-3076	Lube Oil Filings - Internal	05000237	VI accessible internal lube oil fittings	PTI-ABB	Fuel Load	Good Lot 6
03-3106	Crankshaft	04000276 04000841	VI crankpin journal surfaces	IMS-ABB IMS-ABB	Fuel Load	Complete
03-3106	Crankshaft	020-2347	Crankshaft web deflection - After 8 hrs. @ 3000 rpm	PTI-ABB PTI-ABB	Fuel Load	Good
03-3106	Crankshaft	0-27468	Dimensional check of crankshaft thrust bearing clearance, use feeler gauges & dial indicators.	PTI-ABB PTI-ABB	Fuel Load	Good
03-3106	Main Bearings	006-20708	Perform oil analysis (See 03-3200)	IMS-B	Fuel Load	Complete
03-3106	Main Bearings		Perform oil analysis (See 03-3200)	IMS-A	Fuel Load	Good
03-3106	Main Bearings		Dimensional check of bearing shells	IMS-ABB	Fuel Load	Complete
03-3156	Cylinder Block	04000841	Dimensional check on cylinder liners area	IMS-B IMS-B	Fuel Load	Complete
03-3156	Cylinder Block	04000823	Liquid penetrant test on cylinder block liner landings	IMS-B IMS-B	Fuel Load	Good Lot 6
03-3156	Cylinder Block	05000345	Visual for normal wear of liners Visual for cleanliness, water leakage in area of block-top	PTI-ABB PTI-ABB PTI-ABB	Fuel Load	Good Lot 6

ATTACHMENT 1

RIVIER BEND STILL TRANSAMERICA DELAVAL DIESEL GENERATOR TOTAL INSPECTION REPORT APRIL 22 1985

COMPLETION NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	START DATE COMPLETION DATE	STATUS
F-068	Intercooler	W5000290 C-27188	Visual for leakage and security	PTI-ABB Fuel Load		Complete
		C-27188		PTI-ABB Fuel Load		Complete
		W5000296	Retorque bolts	PTI-ABB Fuel Load		Complete
MP-020	Turbocharger	W4000592 RCF W59384 RCF W708 C-27325	VI thrust bearings	INS-ABB Fuel Load		Open
			VI core plugs according to N16 300	INS-ABB Fuel Load		Open
			Portion LP test on weld of bolts	INS-ABB Fuel Load		Open
			LP stationary nozzle ring for crack	PTI-ABB Fuel Load		Open
			VI stationary nozzle ring for missing blades	PTI-ABB Fuel Load		Open
			Measure axial thrust clearance	PTI-ABB Fuel Load		Open
			VI thrust bearings	PTI-ABB Fuel Load		Open
			Turbocharger lube oil pressure readings during engine run at 100%	PTI-ABB Fuel Load		Open
			Bolt torque verification per N16 300	PTI-ABB Fuel Load		Open
			Oil analysis (See 03-8290)	PTI-ABB Fuel Load		Open
			Oil analysis (See 03-8290)	PTI-ABB Fuel Load		Complete
00-491	Air Inlet Adapter	W5000275 C-27188	Visual for security	PTI-ABB Fuel Load		Complete
				PTI-ABB Fuel Load		Complete

FIVE SEAB EEE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1988

COMPARISON #1 NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK ENGINE	SUB-DAILY COMPLETION DATE	STATUS
03-305	Exhaust Outlet Adapter	MS000276 C-27188	Visual for security	P11-ADR P11-ADR	Fuel Load	Complete
03-305A20	Main Bearing Caps	C-27237 MS000150 RCFM50446 RCFM50443 RCFM50443	VI of 25 main bearing cap mating surface for evidence of fretting Verify preload bearing cap & stud nuts torque Verify preload bearing cap & stud nuts torque	INS-B INS-B INS-A INS-A INS-B INS-B	Fuel Load	Complete
03-305A20	Main Bearing Caps	MS000236 MS000236 C-27188 RCM202068	VI of outside bearing cap for absence of discoloration. Inspect 2 of 2 VI of cotter pin security of nuts. (100% of bearing caps between connector rods) Main bearing caps temperature within heat gun. (Inspect main bearing connector rod bearings). Inspect 2 of 2 Oil analysis (See 03-305-07-00) Oil analysis (See 03-305-07-00)	P11-ADR P11-ADR P11-ADR P11-ADR P11-ADR P11-ADR P11-ADR	Fuel Load Fuel Load 5% Power Fuel Load Fuel Load	Complete Complete Upset Complete
03-305A	Main Bearing Bolting	C-27325	Dimensional verification of uniform washer thickness on accessible washer (P/P 03-305-07-00)	INS-ADR INS-ADR INS-ADR	First Outage First Outage First Outage	Open

RIVER BEND STN
 TRANSAMERICA DELAVAL DIESEL REFRIGERATOR
 TOTAL INSPECTION LOG SHEET
 APRIL 22, 1988

COMPLETION DATE	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-307A	Lube Oil Fittings - Internal	M5000237	VT accessible internal lube oil fittings	PTI-ABB	Fuel Load	Load Test
03-310A	Crankshaft	M45000876	VT crankpin journal surfaces	INS-ABB	Fuel Load	Complete
		M46000841		INS-ABB		
03-310B	Crankshaft	M50003317	Crankshaft web deflection - After 8 hrs @ 3.50 kw	PTI-ABB	Fuel Load	Open
		C-27188	Dimensional check of crankshaft thrust bearing clearance. Use feeler gauges & dial indicators.	PTI-ABB	Fuel Load	Open
03-310B	Main Bearings	M4620708	Perform oil analysis (See 03-329A)	INS-B	Fuel Load	Complete
			Perform oil analysis (See 03-329A)	INS-A	Fuel Load	Open
03-310B	Main Bearings		Dimensional check of bearing shells	INS-ABB	Fuel Load	Complete
				INS-ABB	See Note 1	
03-315A	Cylinder Block	M46000841	Dimensional check on cylinder liners area	INS-B	Fuel Load	Complete
		M46000823	Liquid penetrant test on cylinder block inner landings	INS-B	Fuel Load	Complete
03-315A	Cylinder Block	M50003315	Visual for normal wear of liners	PTI-ABB	Fuel Load	Open
			Visual for clearest of water leakage in area of block-top	PTI-ABB	Fuel Load	Complete

RIVER BEND SITE
TRANSMISSION - LOVAL DIESEL GENERATOR
T0100 - INSPECTION REPORT
11/22/1985

COMPLETION NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-3450	Cylinder Liner	M5000343 M4000357 M4000335 M4000499 C-27188	Material comparison for test on liner Verify liner dimensions VI liners over zone of piston travel VI liners outside pilot diameters Visual for normal wear of liners. Use Endoscope for combustion chamber inspection. Use side door for lower liner inspection. (Take photos)	INS-B INS-ABB INS-ABB INS-ABB FIT-ABB FIT-ABB FIT-ABB FIT-ABB	Fuel Load Fuel Load Fuel Load Fuel Load Fuel Load Fuel Load Fuel Load Fuel Load	Complete Complete Complete Complete Open
03-3450	Water Manifold (L/R)	C-27237 M5000182 C-27217 M5000182	Flange bolting to be (Grade 5) or better Torque verification	INS-ABB INS-ABB INS-ABB INS-ABB	Fuel Load Fuel Load Fuel Load Fuel Load	Complete Complete
03-3450	Cylinder Block Studs	M4000834 M4000856	VI head studs for stress Verify head studs torque	INS-B INS-B	Fuel Load Fuel Load	Complete Complete
03-3450	Cylinder Head Nuts	M4000835 M4000963	VI head nuts for ID marks & for turning mark Verify head nuts proper installation & torque	INS-B INS-B INS-B	Fuel Load Fuel Load Fuel Load	Complete Complete Complete
03-3450	Cylinder Liner Seals	C-27210 M5000191	Verify proper cylinder liner "D" ring seals were installed	INS-ABB INS-ABB	Fuel Load Fuel Load	Complete

RIVER BL
TRANSAMERICA DELAVAL
TOTAL INSPEL
APRIL 2

11 GENERATOR
PORT

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-317A&B	Jacket Water Discharge (LB)		Visual for security and leak tightness	PTI-A&B	5% Power	Complete
		C-27237	Verify bolt material	INS-A&B	Fuel Load	Complete
		M5000184		INS-A&B		
		C-27237	Verify bolt torque	INS-A&B	Fuel Load	Complete
		M5000186		INS-A&B		
03-330B	Flywheel Bolting	C-27325	Verify IBI Installation Procedures were	INS-A&B	Fuel Load	Complete
		M3000453-B	used at engine assembly & precautions	INS-A&B		
		M3000209	were used to keep flywheel, generator,	INS-A&B		
		(A&B)	shaft, & crankshaft flanges dry &	INS-A&B		
		M3000462-A	clean of lubricants during assembly	INS-A&B		
03-330B	Flywheel Bolting	M5000367	Verify cotter pin security	INS-A&B	5% Power	Complete
			Verify installation bolt torque	INS-A&B	Fuel Load	Complete
03-331A	Flywheel Guard	C-27188	VI of flywheel guard for security	PTI-A&B	Fuel Load	Complete
03-332A	Gear Case	C-27188	VI of gear case for security	PTI-A&B	Fuel Load	Complete
		C-27188	Verify bolt torques	PTI-A&B	Fuel Load	Complete
		M5000291		PTI-A&B		
03-340A	Connecting Rods	C-27188	Visual, for normal wear and absence of	PTI-A&B	Fuel Load	Complete
		M5000238	discoloration 8 of 8	PTI-A&B		
		M4000423		PTI-A&B		

RIVER BED SITE
TRANSMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPONENT IDENT	PART DESCRIPTION	WORKING COMMENTS	REMAINING SCOPE OF WORK	TYPE UNIT - ENGINE	ENGINE COMPLETION DATE	STATUS
03-140E	Con Rod Bearing Shells		Oil analysis (See 03-820A)	P11-B	Fuel Load	Complete
			Oil analysis (See 03-820A)	P11-A	Fuel Load	Open
			Connection rod cap temperature with heat P11-A&B	P11-A&B	Fuel Load	Open
			Run B of B (during web deflection ck)	P11-A&B	Fuel Load	Complete
			Verify connecting rod bolt torques	INS-A	Fuel Load	Complete
			Verify connec. and rod bolt torques	INS-B	Fuel Load	Complete
			X-ray replacement bearing shells (separ)	INS-A&B	First Outage	Open
03-341A	Pistons		Perform visual inspection of piston crown outside diameter for scuffing and the combustion bowl in the crown for pitting	INS-E	Fuel Load	Complete
				INS-B	See Note 2	
				INS-E		
				INS-E		
03-341A	Pistons		VI piston for normal wear from crankcase P11-A&B	P11-A&B	Fuel Load	Complete
			Bore scope inspection of piston crown and combustion chamber	P11-A&B	Fuel Load	Open
				P11-A&B		
			Oil analysis (See 03-820A)	P11-E	Fuel Load	Complete
			Oil analysis (See 03-820A)	P11-A	Fuel Load	Open
03-341E	Piston Rings		Piston rings installed in compliance with TBI assembly requirements	INS-A	Fuel Load	Complete
			Piston rings inspection for wear verified	INS-A	Fuel Load	Complete
				INS-A		
				INS-A		

RIVER BEND SITE
TRANS-ALBERTA BELVAL DIESEL GENERATOR
INSPECTION REPORT
JAN 27 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMARKS SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-341C	Piston Pin Assembly	M4000595	Verify new package. Piston rings	INS-A	Fuel Load	Complete
			VI piston ring for wear	INS-B	Fuel Load	Complete
				INS-B	See Note 3	
			VI piston rings for carbon buildup	INS-B	Fuel Load	Complete
				INS-B	See Note 3	
03-341C	Piston Pin Assembly	M4000892	Wrist pins 100% LP tested before	INS-AAB	Fuel Load	Complete
		M4000557	installation into engines	INS-AAB		
		M4000556		INS-AAB		
		M4000400		INS-AAB		
		M5000335	Perform material comparator and hardness test on one satisfactorily inspected wrist pin and one rejectable wrist pin	INS-AAB	Fuel Load	Complete
03-345A	Tappets and Guides	M4000896	Comparator sample to be AIST-8630	INS-AAB		
			Dimensional check on one spare wrist pin	INS-AAB	Fuel Load	Complete
		M5000335		INS-AAB		
		M5000665	VI of tappet roller for severity and normal wear	PTI-AAB	Fuel Load	Complete
				PTI-AAB		
03-345A	Tappets and Guides	M5000265	Check for excessive valve leak during engine barring	PTI-AAB	Fuel Load	Complete
		M5000265	Check tappet roller clearances by using	PTI-AAB	Fuel Load	Complete

SILVER STAR
TRANSMISSION DELIVERY CHECK SHEET
TOTAL DELIVERY REPORT
REF: 1985

COMPLETION NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	TESTING SCOPE OF WORK	TYPE WORK ENGINE	SCHEDULE COMPLETION DATE	STATUS
Bump test						
03-3500	Camshaft Assembly	M40000870	Inspect cam lobes before and after	INS-B	Fuel Load	Complete
		M40001017	engine VR performance run	INS-B		
03-3500	Camshaft Assembly	M40000449	Determine the material of the cam lobes	INS-ASB	Fuel Load	Complete
		M40000822	by use of a comparator.	INS-ASB	See Note 4	
			Perform a hardness test on the cam lobes	INS-B	Fuel Load	Complete
			on engine VR.	INS-B	See Note 4	
03-3500	Camshaft Assembly	M40001019	Where accessible, VI camshaft gasket	PTI-ASB	Fuel Load	Complete
		M50000297	for cracks.	PTI-ASB		
		M50000297	Verify valve timing by assembling	PTI-ASB	Fuel Load	Complete
			Pyrometer data and comparing to	PTI-ASB		
			adjacent cylinders.	PTI-ASB		
VI cam gear for stops of wear						
03-3500	Camshaft Support & Gear	M40000819	VI cam gear for stops of wear	INS-A	Fuel Load	Complete
		M40001020	VI cam gear for stops of wear	INS-B	Fuel Load	Complete
03-3500	Camshaft - Support & Gear	M40000319	Verify support bolts are secured & lock	INS-A	Fuel Load	Complete
		M50000330	tabs are in place	INS-A	See Note 5	
		M40000822	Verify support bolts are secured and	INS-B	Fuel Load	Complete
		M50000330	lock tabs are in place	INS-B	See Note 5	
		M40001019	VI crank to pump gear	INS-ASB	Fuel Load	Complete
VI of crank to pump gear (take photos)						
03-3500	Crank to Pump Gear	M40001019	VI of crank to pump gear (take photos)	INS-B	Fuel Load	Complete
			Hardness test deleted. Ref. Owners Group	INS-ASB	Fuel Load	Complete

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPLETION NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-355A	Crank to Pump Gear	C-27188	Revision 1 Report	INS-ABB		
		M5000339	Where accessible, VI crank to pump gear	FII-ABB	Fuel Load	Complete
			for normal gear & security. Take photo FII-ABB			
03-355B	Idle Gear	M4000448	VI idler gear test engine 1A	INS-A	Fuel Load	Open
		M4001919	VI idler gear test engine 1B	INS-B	Fuel Load	Complete
		M4600871		INS-B		
			Material and hardness test of gear	INS-ABB	Fuel Load	Open
03-359	Air Start Valves	M&D 2616	Verify copper gaskets	INS-ABB	Fuel Load	Complete
		M&D 2616	Verify proper cap screws & torque	INS-ABB	Fuel Load	Complete
		M4000953	Engine 1A hot torque per SIB 360	INS-A	Fuel Load	Complete
		M4000954	Engine 1B initial torque	INS-B	Fuel Load	Complete
		M4000954	Engine 1B dimensional check	INS-E	Fuel Load	Complete
		M4000954	Engine 1B locking pins check	INS-B	Fuel Load	Complete
		C-27237	Perform a visual inspection to verify no carbon deposits exist on valve intervals. Use differential temperature measurements	INS-ABB	Fuel Load	Complete
					See Note 5	
03-359	Air Start Valves	C-27237	Perform a material comparison test on the nitrogen cap screws	INS-ABB	Fuel Load	Complete
		M5000356		INS-ABB		
		C-27237	Perform a visual inspection on the air start valve for wear and corrosion.	INS-ABB	Fuel Load	Complete
				INS-ABB	See Note 6	

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
			Use differential temp. measurements.	INS-A&B		
		C-27237	Hot torque verification of hold down	INS-A&B	Fuel Load	Complete
		M5000356	capscrews per SIM 360	INS-A&B		
03-359	Air Start Valves	C-27188	Borescope VI inspect. of air start vlvs.	PTI-A&B	Fuel Load	Open
			from combustion chamber for security.	PTI-A&B		
		C-27188	VI air start supply filter for foreign	PTI-A&B	Fuel Load	Complete
		M5000266	contaminants.	PTI-A&B		
03-360A	Cylinder Heads	C-27188	Borescope inspection of combustion	PTI-A&B	Fuel Load	Open
			chamber and valves. Take photos	PTI-A&B		
		M5000338	Inspect gaskets for leak tightness	PTI-A&B	Fuel Load	Complete
			during engine run	PTI-A&B		
		M5000338	Bar engine with cylinder cocks open	PTI-A&B	Fuel Load	Complete
			for leakage	PTI-A&B		
03-360B	Cylinder Head Valves	C-27237	VI of valve and valve ring for	INS-B	Fuel Load	Complete
		M4000502	scuffing and erosion. Valves were	INS-B		
		M4000916	all blue-checked into valve seats.	INS-B		
		M4000923		INS-B		
		M5000324		INS-B		
		C-27237	Remove subcover bonnet and inspect	INS-A	Fuel Load	Complete
		M5000185	internal for soot blowby	INS-A		
		M4000483		INS-A		

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
		M5000203	Remove subcover bonnet and inspect internals for soot blowby	INS-B INS-B	Fuel Load	Complete
03-369C	Cylinder Head-Bolts & Gaskets	M4000952	Verify proper gaskets installed	INS-B	Fuel Load	Complete
		M4001021	VI engine block to head mating surface during run to determine if any gasket leaks	INS-B INS-B INS-B	Fuel Load	Complete
03-362A	Subcovers		Perform a liquid penetrant test of the subcovers on the machined surfaces of rocker shaft assembly bolt boss pedestal for evidence of linear indications. Repeat at five-year intervals (B)	INS-B INS-B INS-B INS-B INS-B	First Outage See Note 7	Open
		M4000629	VI engine subcovers	INS-B	Fuel Load	Complete
		M4000415	VI and LF engine subcovers	INS-A	Fuel Load	Complete
03-365B	Fuel Injection Tips	C-27188	Visual on tips for normal firing, roundness	PTI-A&B PTI-A&B	5% Power	Open
03-365C	Fuel Injection Tubes	C-27325	VI or fuel injection equipment for leaks during operation. Check outside of shrouds during/after operation	INS-A&B INS-A&B INS-A&B	Fuel Load	Complete

4/26/85 - 1:27 PM

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-3710	Fuel Pump Linkage	M40000996	All high pressure fuel lines examined by	INS-A&B	Fuel Load	Open
			Eddy Current on both ends of the tube	INS-A&B	See Note 8	
			Autofrettaged fuel oil lines installed	INS-A&B	Fuel Load	Open
03-3710	Fuel Pump Linkage	M40000996	Verify fuel pump linkage is free to move & proper lubrication used in each bearing cup prior to operation	INS-B	Fuel Load	Complete
				INS-B		
				INS-B		
03-3710	Fuel Pump Linkage	C-27188 M5000267 M4000443	Visual for security and free movement	PTI-A&B	Fuel Load	Complete
				PTI-A&B		
				PTI-A&B		
03-375	Intake Manifold	M40000949 RUF-M-440	VI intake manifold elbow flanges	INS-E	Fuel Load	Complete
			Verify bolt torque on bottom rectangular flange of the intercooler	INS-A&B	Fuel Load	Complete
			Verify bolt torque	INS-A&B		
03-545	Intake Manifold	C-27188 M5000292 M5000292	Verify bolt torque	PTI-A&B	Fuel Load	Complete
				PTI-A&B		
			VI of intake manifold elbows for corner cracks. (3 of 8)	PTI-A&B	Fuel Load	Complete
03-580A	Exhaust Manifold	M5000292	VI of intake manifold for leaks during engine run	PTI-A&B	Fuel Load	Complete
				PTI-A&B		
			VI of exhaust manifold for leaks and	PTI-A&B	Fuel Load	Complete

RIVER BEND SITE
TRANSCONTINENTAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPLETION NUMBER	PART DESCRIPTION	WORK LOG DOCUMENTS	REMARKS, SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
		#5000298	security during engine run	PTI-A&B		
03-308	Exhaust Manifold Gasket/Bolt	#4001092	Verify exhaust pipe flange cap screws torque	INS-A&B	Fuel Load	Complete
		#4001092	Verify no binding on exhaust manifold	INS-B	Fuel Load	Complete
			% proper gasket & bolting installed	INS-B		
		#4007299	Perform dimensional check of cap screws	INS-A&B	Fuel Load	Complete
		#4001092	VI manifold flange fillets	INS-B	Fuel Load	Complete
03-309	Block Cover Gaskets and Bolts	C-27188	Verify bolt torque	PTI-A&B	Fuel Load	Complete
		#5000278		PTI-A&B		
03-309B	Block Cover Gaskets and Bolts	#4001037	Verify proper bolting & torque applied	INS-B	Fuel Load	Complete
		#4001037	VI block cover gaskets for deterioration	INS-A	Fuel Load	Complete
03-307A	Crankcase Ventilator	C-27188	VI outside case for oil buildup and security	PTI-A&B	Fuel Load	Complete
		#5000268		PTI-A&B		
03-308A	Rocke Arms and Pushrods	C-27188	Visual for normal wear	PTI-A&B	Fuel Load	Complete
		#5000269		PTI-A&B		
		#5000269	Verify valve lash and clearance	PTI-A&B	Fuel Load	Complete
			Verify lubrication (see pre-tube pump)	PTI-A&B	Fuel Load	Done

RIVER HEAD SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22, 1985

Component Number	Part Description	Working Documents	Remaining Scope of Work	Type Work -Engine	Schedule Completion Date	Status
03-2806240 Pushrods			Perform a liquid penetrant test on a	INS-A&B Fuel Load	See Note 9	Complete
			visual inspection of the friction	INS-A&B		
			welded main and intermediate connector	INS-A&B		
			pushrods. No surface cracks allowed	INS-A&B		
			Verify friction welded pushrods are	INS-A Fuel Load		Complete
04-4000953 Rocker Arm Bolting			installed	INS-A		
			Verify friction welded pushrods are	INS-B Fuel Load		Complete
			installed	INS-B		
			Spare pushrods to specify destructive	INS-A&B Commercial		Open
			verification of weld quality	INS-A&B		
03-40270 Governor Drive			Verify engine 18 rocker arm Cap screw	INS-B Fuel Load		Complete
			torque	INS-B		
			Material comparison of governor drive	INS-A Fuel Load		Open
			gear and governor driven gear	INS-A		
			Material to be AISI 4142	INS-A		
			LP of governor drive	INS-A&B Fuel Load		Complete
			a. Gear/shaft contact surface	INS-A&B See Note 10		
			b. Gear pin and bores	INS-A&B		
			c. Vertical shaft/gear keyway	INS-A&B		
			d. Reduced shaft diameter at coupling	INS-A&B		

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-402B	Governor Drive Coupling	C-27188	VT security of governor drive coupling	FTI-A&B	Fuel Load	Open
		M4001018	VT coupling on engine 1B	INS-B	Fuel Load	Complete
		M4001018	Verify set screw & drive pin properly installed on engine 1B	INS-B INS-B	Fuel Load	Complete
03-410A	Overspeed Trip Governor		Verify proper installation & calibration of overspeed trip in accordance "The Installation and Oil Supply Topic of Woodward Documentation"	INS-A&B INS-A&B INS-A&B	Fuel Load See Note 11	Complete
		M4000985	Overspeed trip governor inspected & test by Woodward governor vendor engine 1B	INS-B INS-B	Fuel Load	Complete
		M5000331	After setting overspeed governor, the adjustment screw position should be marked with torque seal	INS-A&B INS-A&B INS-A&B	Fuel Load	Complete
03-410A	Overspeed Trip Governor	C-27188	VT security of governor drive coupling	FTI-A&B	Fuel Load	Complete
		M5000342		FTI-A&B		
03-410B	Overspeed Trip Drive	M5000329	Material comparator test of gear	INS-A	Fuel Load	Complete
		M4000866	Shaft/bearing clearances Sat. in accordance with TDI manual	INS-A INS-A	Fuel Load	Complete
		M4000884	Shaft/bearing clearances Sat. in accordance with TDI manual	INS-B INS-B	Fuel Load	Complete
		M4000866	VT gear for wear, spalling cracks	INS-A	Fuel Load	Complete

RIVER BEND SITE
TRANSMERICA DELAVER DISTRICT HEADQUARTERS
FINAL INSPECTION REPORT
APRIL 27 1985

COMPARISON NUMBER	FACT DESCRIPTION	WORK LOG DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK - ERM, LINE	SCHEMATIC COMPLETION DATE	STATUS
03-430C	Over-speed Trip Coupling	M4000867 M4000883	VT coupling for deterioration VT coupling for deterioration	INS-A INS-B	Fuel Load Fuel Load	Complete Complete
03-433	Governor Linkage	M4000726 M4000986	VT of governor linkage for strength of distress VT of governor linkage for strength of distress	INS-A INS-A INS-B INS-B	Fuel Load Fuel Load Fuel Load Fuel Load	Complete Complete Complete Complete
03-433	Governor Linkage	C-27483 M5000270	VT governor linkage for security and free movement	FTI-A&B FTI-A&B	Fuel Load Fuel Load	Complete Complete
03-435A	Goodward Governor		Review site instruction to ensure detail and clarity exists in order to properly set governor	INS-A&B INS-A&B INS-A&B	Fuel Load	Open
03-435E	Governor Boost	C-27237 M5000133 M5000183	Booster servomotor is mounted lower than governor Inlet booster line is 3/8 inch and outlet booster line is at least 1/4 inch	INS-A&B INS-A&B INS-A&B INS-A&B INS-A&B INS-A&B	Fuel Load Fuel Load Fuel Load Fuel Load Fuel Load Fuel Load	Complete Complete Complete Complete Complete Complete
03-435F	Governor Boost	M5000183	Oil line should slope upward from the booster to the governor and should have minimum number of loops or bends	INS-A&B INS-A&B	Fuel Load Fuel Load	Complete Complete

RIVER BEND SITE
TRANSMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22, 1985

CONFIDENTIAL	DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK - ENGINE	THE DATE COMPLETION	STATUS
03-4256	Tube Driven Engine Driven	C-27188 M5000304	Verify pump performance	P11-ADB	Fuel Load	Complete
03-4256	Engine-Driven Water Pump	C-27188	Pump shaft hardness Pump shaft material VI pump shaft photograph VI pump gear photograph LE gear tooth and transition area VI wear ring Verify new pump performance	INS-A INS-A INS-A INS-A INS-A INS-A P11-ADB	Fuel Load	Open
03-4256	Engine-Driven Water Pump	C-27188	VI jacket water fittings for security and leaks	P11-ADB P11-ADB	Fuel Load	Open
03-4376	Turbo Water Fittings	C-27188 M5000310	VI water fittings for security & leaks	P11-ADB P11-ADB	Fuel Load	Complete
03-4416	Starting Air Lines	C-27188 M5000309 M5000266	VI starting air lines security & leaks Air supply filter cleanliness (See 93-359)	P11-ADB P11-ADB P11-ADB P11-ADB	Fuel Load	Complete
03-4416	Start Air Manifold (LR)	C-27188	Bolting is to be Grade 5 or better	INS-ADB	Fuel Load	Complete

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
		M5000187	on flanges	INS-A&B		
		M5000187	torque verification	INS-A&B	Fuel Load	Complete
93-442A	Start Air Distributor		Verify the proper timing of the air	INS-A&B	Fuel Load	Open
			start distributor as described in the	INS-A&B	See Note 12	
			TBI manual	INS-A&B		
			After verifying the correct timing of	INS-A&B	Fuel Load	Complete
			each starting air distributor, the	INS-A&B	See Note 12	
			evaluation of wear on the cam and	INS-A&B		
			valve contacts should be performed as	INS-A&B		
			follows:	INS-A&B		
			a. Remove the distributor from engine	INS-A&B		
			b. Visually inspect the wear marks on	INS-A&B		
			the cam lobes. Note the position	INS-A&B		
			and orientation of the lube oil jet	INS-A&B		
			Oil flow from the jet should cover	INS-A&B		
			the wear mark region on the cam	INS-A&B		
			lobe	INS-A&B		
			c. Visually inspect the wear marks on	INS-A&B		
			the end of each valve spool where	INS-A&B		
			it slides on the cam. Measure the	INS-A&B		
			average diameter of the "flat" worn	INS-A&B		
			area on the end of each spool to	INS-A&B		

RIVER BIRD SITE
Hondamerica DELVAL DIESEL GENERATOR
TUGBOAT INSPECTION REPORT
APRIL 27, 1985

Component Number	Part Description	Work Log Documents	Remaining, Scope of Work	Type Work - ENG, IRE	Work Log Complete Date	Status
03-4426	Start Air Distributor	C-27188 M5000271	the nearest 1/64 inch. If the	INS-ABB		
			request of those measurements is	INS-ABB		
			more than 1.5 times the smallest,	INS-ABB		
			an engineering evaluation of the	INS-ABB		
			observed wear should be performed	INS-ABB		
03-4456	Fuel Booster Pump	C-27188 M5000279	and a superficial hardness measure-	INS-ABB		
			ment should be made on the end	INS-ABB		
			wear flat of each valve spool.	INS-ABB		
			If the hardness of any spool end is	INS-ABB		
			significantly below 50 Rc, it	INS-ABB		
03-4506	Fuel Oil Filter	C-27188 M4000875	should be replaced.	INS-ABB	Fuel Load	Complete
			Verify the installation of the follower	INS-ABB	See Note 12	
			tube on the camshaft (y engine only)	INS-ABB		
			VI security & leaks during dry roll	PII-ABB	Fuel Load	Complete
				PII-ABB		
03-4508	Porter Tube Oil Strainer	C-27188	Visual for security and leaks	PII-ABB	Fuel Load	Complete
				PII-ABB		
			Verify torque on filter attach bolts	INS-B	Fuel Load	Complete
			D.P. gauges installed on panel	INS-ABB	Fuel Load	Complete
4/26/85 - 1:27 PM		C-27188	VI cleanliness of strainer element	PII-ABB	Fuel Load	Complete

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

Component Number	Part Description	Working Documents	Remaining Scope of Work	Type Work -ENGINE	Schedule Completion Date	Status
03-4250	Turbo Inlet External (LB)	C-27188 MS000272	Visual for leaks & security	PTI-ABB	Fuel Load	Open
03-4670	Turbo Inlet Fittings (LB)	C-27188 MS000307	Visual for leaks & security	PTI-ABB	Fuel Load	Complete
03-4750A	Turbo Inlet Bracket/Bolting	M40001023 RCFMS0384 C-27237 MS000489	Verify bolt torque at installation Verify bolt torque at installation Retorque bolts	INS-B INS-A INS-ABB INS-ABB	Fuel Load Fuel Load Fuel Load	Complete Complete Complete
03-4750B	Turbo Bracket/Bolting	C-27188 MS000280 MS000280	Temperature measurements to verify temperature differential between start & engine block Visual for integrity of welds, security	INS-ABB INS-ABB PTI-ABB PTI-ABB	Fuel Load Fuel Load Fuel Load Fuel Load	Open Complete Complete Complete
03-475B	Turbo Butterfly Assembly	C-27225 MS000336	Hardness test on the shaft (F/P 92-475- 15A)	INS-A INS-A	Fuel Load	Complete
03-475C	Turbo Intake Pipe	C-27247 MS000481	Verify bolt material (Grade 5) between intercooler and butterfly valve	INS-ABB INS-ABB	Fuel Load Fuel Load	Complete Complete

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-500N	Control Panel Terminal Boards	C-27210	Verify no Multi-Amp. states division terminal blocks, manufactured between 1974 and 1976 are installed	INS-A&B INS-A&B INS-A&B	Fuel Load	Open
03-515	Water Thermostatic Valve	C-27210 M5000190	Verify valve body material is cast steel	INS-A&B INS-A&B	Fuel Load	Complete
03-530	Engine	C-27188	VI ladder for security	PTI-A&B	Fuel Load	Open
03-531	Platform Ladder	C-27188 M5000284	VI ladder for security	PTI-A&B PTI-A&B	Fuel Load	Complete
03-540A-C	Lube Sump Tank	C-27325 M5000334	Verify the lube oil sump tank mounting bolts (skid mounting) torque values.	INS-A&B INS-A&B	Fuel Load	Complete
		C-27188	VI sump tank for leaks	PTI-A&B	Fuel Load	Complete
03-540A-C	Lube Sump Tank	REG20700	Oil analysis (See 03-820A)	PTI-B	Fuel Load	Complete
			Oil analysis (See 03-820A)	PTI-A	Fuel Load	Open
03-550	Foundation Bolts	N&D-3592	Hardness test of bolts missing "stamp" be checked to verify proper heat treatment	INS-A&B INS-A&B INS-A&B	Fuel Load	Complete
03-550	Foundation Bolts	C-27188	Verify foundation bolt torque	PTI-A&B	Fuel Load	Open

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

Component Number	Part Description	Working Documents	Remaining Scope of Work	Type Work - Engine	Schedule Completion Date	Status
03-630	Conduit Supports	C-27188	VI pyrometry conduit security	PTI-A&B	Fuel Load	Open
03-650	Generator	C-27188	Visual of slip rings and brushes for wear and adjustment	PTI-A&B	5% Power	Open
			VI security of pedestal & fod bolts	PTI-A&B	5% Power	Open
			Pedestal bearing oil analysis	PTI-A&B	Fuel Load	Open
			Grounding straps are intact	PTI-A&B	5% Power	Open
03-650B	Generator Controls	C-27325	Verify no installation of Porter CT P/N A-01616-4 used in assembling the exciter. Document installed part no.	INS-A&B	Fuel Load	Complete
03-688	Electrical Wiring	C-27188	Check terminations and junction box covers for security	PTI-A&B	5% Power	Open
			Flex conduit for security (visual)	PTI-A&B	5% Power	Open
03-699	Off Engine Wiring	C-27188	Check terminations	PTI-A&B	5% Power	Open
			Check conduit and flex fittings	PTI-A&B	5% Power	Open
03-700A	Standpipe	C-27188	VI for security and leaks	PTI-A&B	Fuel Load	Complete
		N5000283		PTI-A&B		
		N5000284		PTI-A&B		

RIVER BEND SITE
TRANSCAMERICA DELTAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
April 22, 1985

CONTRACT # NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK -ENGINE	SCHEDULE COMPLETION DATE	STATUS
03-700R	Standpipe Valves	C-27325 M5000333	Verify proper jacket water valve is installed (standpipe drain valve) Proper installation of jacket water valve	INS-ABB INS-ABB INS-ABB INS-ABB	Fuel Load Fuel Load	Complete Open
03-700F	Standpipe Misc. Bolting	H-5 Report	Verify as-built condition of installed bolting material to the IDI drawing.	INS-ABB INS-ABB	Fuel Load	Open
03-715A	Sub-Base	C-27210 M5000389	VT about for cracks or voids under skid framing	INS-ABB INS-ABB	Fuel Load	Complete
03-715B	Sub-Base Bolting	C-27325	Monitor turbocharger for excessive vibration using IRB's. If excessive then torque verify when engine comes up to engine standby temperature Replace bolts with correct torque values	INS-ABB INS-ABB INS-ABB INS-ABB INS-ABB	5% Power	Open
03-717A	Auxiliary Skid	C-27188 H-5 Report	VT of auxiliary skid rising for leaks Verify bolt torques via ACME documentation	PII-ABB PII-ABB PII-ABB	Fuel Load Fuel Load	Open Open
03-717I	Sub-Base Lube Valves	C-27210	Verify relief valves installed per manufacturer's recommendation	INS-ABB INS-ABB	Fuel Load	Open

RIVER BLVD 211E
TRANSCAMERICA DELAVAL DIESEL GENERATOR
TOTAL INSPECTION REPORT
APRIL 22 1985

COMPLAINT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	TYPE WORK ENGINE	SCHEDULE COMPLETION DATE	
					Fuel Load	Complete
03-27170	Sub-Base Fuel Valves	C-27216 MS000189	Verify proper valve orientation	INS-ASB INS-ASB		Complete
03-2006	Water Heater	C-27188 MS000287	VF for leaks & security	PTI-ASB PTI-ASB	Fuel Load	Complete
03-2006ASB	Intake and Exhaust Equipment	C-27188	VF security of exhaust elbows and slotted feet	PTI-ASB PTI-ASB	5% Power	Open
		MS000383	Verify clean inlet filter	PTI-ASB	Fuel Load	Complete
03-2102E	Jacket Water Equipment	C-27188 MS000317	VI jacket water equip for leaks & security	PTI-ASB PTI-ASB	Fuel Load	Complete
03-2006	Lube Oil Equipment	C-27188 KB020703	Visual for leakage and security Oil Analysis	PTI-ASB PTI-ASB	Fuel Load	Open
			Oil analysis	PTI-ASB	Fuel Load	Open
03-2006	Fuel Oil Equipment	C-27188	VF fuel oil equip for leaks & security	PTI-ASB	Fuel Load	Open

NOTES TO THE TOTAL INSPECTION REPORT

1. The recommendation is to perform a dimensional check of the bearing shells to verify that the thickness is within TDI specifications. An alternate method of compliance is proposed.

GSU inspected a sample of three bearings on standby diesel generator A, which were found to be satisfactory. All the bearings were functionally tested by measuring the temperature of the bearing cap immediately after shutdown during break-in. No abnormal temperatures were present. Trending of oil analysis results will also be performed in service to indicate any signs of distress. We believe these measures indicate that the bearings are satisfactory as installed, and the preventive maintenance program will detect distress in the unlikely event that latent problems should occur.

2. The recommendation is for additional LP inspection of the piston skirts and visual inspection of the piston crown outside diameter for scuffing. GSU will perform the LP inspections either during the next major overhaul or the next time the pistons are removed, whichever comes first. The piston crowns were removed during rebuilding, reworked by TDI factory to the latest configuration and installed with new AE piston skirts. This together with the post test inspection of cylinder liners (see 03-315C) meets the intent of the recommendation.

3. New Muskegon piston rings were installed in both TDI diesel-generators before performance testing. These piston rings were installed under the supervision of a TDI service representative. Trending of oil analysis results will be performed in service in indicate any signs of distress.

A boroscope inspection of the cylinder liners (see 03-315C) reveal signs of distress showing on the cylinder liners.

4. The recommendation is to perform material comparator and hardness tests on the cam lobes. We propose to substitute visual inspections of the cam lobes for signs of abnormal wear, at each refueling outage.
5. The recommendation is to verify camshaft support bolt torque values. We propose to verify support bolts are secure and lock tabs are in place.
6. The recommendation is to perform visual inspections for adequate seating between the valve and the valve ring and that no carbon deposits exist on the valve internals. An alternate position is proposed. The concern is possible leakage from the combustion chamber back to the air start manifold, and starting air distributor. This leakage can be detected during engine operation by abnormally high temperature in the air start piping to each

cylinder, or by exhaust particulates on the engine side of the air start filter. No such leakage has been observed to date.

7. The recommendation is to perform a liquid penetrant inspection of the diesel B subcover pedestals. This inspection was performed on diesel A with satisfactory results. At that time, their recommendation was for inspection of one engine only. We propose to inspect the diesel B subcovers at the first refueling outage.
8. The recommendation is to eddy current inspect both ends of the high pressure fuel tubes. Autofrettaged and shrouded high pressure tubes which have significantly greater resistance to fatigue cracking will be installed. Eddy current inspection of the autofrettaged tubing is not required.
9. The recommendation is for 100% liquid penetrant inspection of the pushrods. At the time of the inspection, the recommendation was for inspection of a sample of the pushrods, and this was satisfactorily completed. We believe that no further inspection is necessary in view of the satisfactory experience with friction welded pushrods.
10. The recommendation is for liquid penetrant inspections of the governor drive. During rebuilding, the gears were visually inspected. Disassembly for LP inspection was found to be possible, only by destructive methods. Visual inspection of the assembly showed no signs of distress. We believe these inspections, together with the commitment to perform visual inspections at the first refueling outage provides adequate assurance.
11. The recommendation is installation of the overspeed trip in accordance with certain Woodward documents. We installed and calibrated the overspeed trip governor under the supervision of the TDI and Woodward governor service representatives.
12. A disassembly inspection for wear and proper lubrication is recommended. An alternate method of verification is proposed. The starting air distributor will be verified for proper operation and timing. We believe that most problems with the distributor are result of corrosion from exhaust gases leaking past the air start valves. Leaking air start valves have not been experienced, therefore, we do not believe a disassembly inspection is appropriate. If problems should develop with the starting air distributor, we would most likely replace the complete assembly. Any problems which might develop with the distributor would be detected during surveillance testing.

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
03-CFR	Turbo Drip Lube	C-27260	Support at bypass shutoff Support at Riser	Fuel Load	Open
03-375	Intake Manifold		Add seven ribs to bottom of intake manifold	First Outage	Open
03-425A	Engine-Driven Water Pump		Replace existing water pump with latest revised water pump	Fuel Load	Open
03-435B	Jacket Water (SB)	C-27260	Two directional restraint from jacket water return line to turbocharger support brace	Fuel Load	Complete
			Two directional restraint to replace existing rubber grommet support	Fuel Load	Open
03-437B	Turbo Water Supports (SB)	C-27413	Two directional restraint using 3/8 inch diameter	Fuel Load	Open
			Two directional restraint	Fuel Load	Open
03-441ALB	Start Air Manifold (LB)		Supports running parallel to the length of the engine require reinforcement of support members and bolt hole elongation in the East-West direction	Fuel Load	Open

4/26/85 - 1:26 PM

ATTACHMENT 2

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22 1995

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	PLANNING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
			to allow for thermal expansion		
03-441A	Start Air Manifold (LB)		Free flowing drains installed at the air Fuel Load air distributor filters by TDI		Open
03-441C	Start Air Supports (SB)	C-27260	The 1/4" diameter tubes across the generator end of the engine from the air distributor to the belt head are not adequately supported. The existing tubing spacers should be provided with cover plates and the assemblies attached rigidly to engine A (A)	Fuel Load	Open
		C-27260	The two 3/4" diameter tubes from the starting air headers to the inlet of the distributors' air filter should be provided with two-directional restraints on the risers at the platform elevation (A)	Fuel Load	Open
		C-27260	The 1/4" diameter tubing from the air start header to the combustion air cooler should be provided with two- directional restraints at 4'0" max.	Fuel Load	Open

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
			span intervals. Location of the supports should allow for flexibility by providing a 6-inch minimum offset around bends (A)		
		C-27260	A two-directional restraint should be added on the 1/4 inch diameter air start tubing on the left side of cylinder No. 8, approx. 6 inches below the horizontal run along the cylinder cover (A)	Fuel Load	Open
		C-27260	The two 3/4 inch diameter tubes from the starting air headers to the inlet of the distributor air filters should be provided with two-directional restraints on the risers approx. 12 inches down from the horizontal run (at the platform) (B)	Fuel Load	Open
		C-27260	The U-bolts around the air filter bodies are to be secured (B)	Fuel Load	Open
		C-27260	The 1/4 inch diameter tubing risers to each cylinder (16 locations) should be provided with an additional two-directional restraint approx. 12 inches up	Fuel Load	Open

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
			from the horizontal tubing runs along the left side of the engine (B)		
03-441C	Start Air Supports (SB)		NOTE: It is recommended that the tubing and supports including the above modifications be installed so that both installations on engines A and B are similar		
03-450B	Fuel Oil Header Supports	C-27260	Engine driven fuel oil pump to filter Fuel oil filter to supply header a. increase support stiffener b. add riser support Fuel oil supply and recirculation header a. cylinder #1 restraint modified to three-directional b. two-directional restraints to be shimmed	Fuel Load Fuel Load	Open Open
		C-27413	Fuel oil drip return header a. cylinder #8 to be a 3-way restraint b. remaining restraints to be a 2-way, using 3/8" diameter V-bolts	Fuel Load	Open
03-465B	Lube Oil External (SB)	RCFI50660	Lube oil to cam shaft bearing	Fuel Load	Complete

4/26/85 - 1:26 PM

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
			Replace crimped tubing across cam shaft bearing cover	Fuel Load	Complete
		C-27260	Two directional restraint on riser	Fuel Load	Open
		C-27260	Lube oil to rocker arm supply header	Fuel Load	Open
		C-27260	Replace one-bolt clip supports with two-directional restraints	Fuel Load	Open
		C-27260	Nylon tube block support near header be modified to increase lateral and vertical stiffness	Fuel Load	Open
		C-27260	Rocker arm supply header	Fuel Load	Open
		C-27260	Three-way restraint to restrict axial motion	Fuel Load	Open
		C-27260	Shim remaining two-directional restraints for proper sliding fit	Fuel Load	Open
03-467A	Turbo Lube Fittings (LB)	C-26008A	Remove the single tie-rod assembly surrounding the coupling.	Fuel Load	Complete
03-467B	Turbo Lube Fittings Support	C-27260	Add two directional restraint to the 3/4" lube tubing riser	Fuel Load	Open
03-475B	Turbo Butterfly Assembly	RCFM50416	Addition of grease fittings for SIM 322	Fuel Load	Complete

RIVER BEND STEEL
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
03-475C	Turbo Intake Pipe		Remove pipe supports	Fuel Load	Open
03-475E	Turbo Bracket Supports		Remove all subject pipe supports	Fuel Load	Open
03-530A	Conduit Supports	C-60970	Provide an additional support at about three feet from terminal point for conduit coming out of the governor box on left	Fuel Load	Open
03-650A	Generator	N&D 3545	Verify status of N&D 3545	Fuel Load	Complete
		N&D 3545	Verify status of N&D 3545	Fuel Load	Complete
03-650B	Generator Controls		Replace field flash contactor with an enclosed type	Fuel Load See Plot 2	Complete
			Provide additional ventilation for the generator control cabinet	Fuel Load	Open
		C-60962	Put temperature sensitive label on rectifier assembly diodes. Inspect.	Fuel Load	Open
		C-60962	Put temperature sensitive label on SCR's. Monitor periodically. (Rectifier assembly)	Fuel Load	Open
		C-60957	Coat diodes and SCR's of the bridge rectifier assembly with alkytol.	Fuel Load	Open

4/26/85 - 1 26 PM

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
			inspect to determine if they have moved.		
		C-60957	Voltage regulator boards-coat one side of the adjustment screw for the adjustable potentiometers. inspect for movement.	Fuel Load	Open
			Provide additional ventilation for the exciter cabinet	Fuel Load	Open
			Change the diode mounting configuration in the bridge rectifier assembly	First Outage	Open
			Change the SCR mounting configuration in the bridge rectifier assembly	First Outage	Open
			Redesign, bolted-on lug arrangement such that there is a max. of two lugs on each bolt	First Outage	Open
			Install a power supply bypass capacitor on integrated circuits in voltage regulator	ILSP See Note #4	Plant Betterment
			Add large value capacitor to amp U1 in the voltage regulator	ILSP See Note #4	Plant Betterment
			Install shielded signal leads between the motor operated pot and the voltage regulator	ILSP See Note #4	Plant Betterment

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22, 1985

EQUIPMENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
			Install a bypass capacitor on the feed-back circuit	ILSP See Note #4	Plant Betterment
			Run SCR gate signals in separate bundles	ILSP See Note #4	Plant Betterment
			Voltage regulator-direct solder 2 I.C. to the PC board and delete I.C. sockets	ILSP See Note #4	Plant Betterment
			Voltage regulator-replace R4 and R5 with multi-turn MIL style potentiometers	ILSP See Note #4	Plant Betterment
			Voltage regulator-replace single sided PC boards with double sided PC boards	ILSP See Note #4	Plant Betterment
			Voltage regulator-direct solder components to PC board or provide retaining mechanism	ILSP See Note #4	Plant Betterment
93-495a	Shutdown Tubing (SB)	C-27260	Add two-directional restraints to line E19, high temperature bearing type tubing, between each engine casing connection similar to installation on engine B (A)	Fuel Load	Open
			Add three-directional restraints to lines E23H and E24 within 12 inches of the turbo mounted vibra switch (A)	Fuel Load	Open

4/26/85 - 1:26 PM

RIVER BEND SITE
TRANSAMERICA DELAVAL DIESEL GENERATOR
OWNER'S GROUP MODIFICATION REPORT
APRIL 22 1985

COMPONENT NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
			All instrument tubing routed along the face of the governor and along sides of engine should have two-directional supports mounted to the engine. Multi-tube support should be designed with spacers and cover plates.	Fuel Load	Open
03-717K	Sub-Base Lube Supports	C-27260	Lube oil filter vents (1/4" vent) band type restraint be replaced with two-directional restraints	Fuel Load	Open
		C-23790A	Pipe support on lube oil booster pump discharge to allow axial pipe expansion	See Note 2	Open
		C-23790A	3/8" line to engine driven lube oil pump to have two-directional restraints at 4'-6" spans	Fuel Load	Complete
		C-27290A	Add two-directional restraint to 1" drain line	Fuel Load	Open
03-717W	Sub-Base Fuel Oil Supports		Modify support 03-717-01-UX to allow axial pipe expansion	See Note 2	Open
			Modify support 03-717-01-UI to allow axial pipe expansion	See Note 2	Open

4/26/85 - 1:26 PM

RIVER BEND SITE
 TRANSAMERICA DELAVAL DIESEL GENERATOR
 UPPER'S GROUP MODIFICATION REPORT
 APRIL 22 1985

COMPLETION NUMBER	PART DESCRIPTION	WORKING DOCUMENTS	REMAINING SCOPE OF WORK	SCHEDULE COMPLETION DATE	STATUS
			After 33-717-01-UX for adjacent pipe clearance	See Note 2	Open

NOTES TO MODIFICATION REPORT

1. Under review by GSU, Impell and TDI. The intake manifold has ribs welded to the inside surface, which may not have been recognized by the Impell review.
2. TDI concurrence has been requested prior to implementing this modification.
3. Efforts to purchase a safety related enclosed contactor complying with the recommendation have been unsuccessful. GSU proposes to implement a preventive maintenance action to clean the contactor quarterly. This meets the intent of the recommendation, which resulted from concern that dust or dirt might reduce the reliability of the contactor.
4. The Integrated Living Schedule Program provides an integrated process for budgeting, managing, and scheduling activities for plant improvement or modification (plant betterment). Items in this category will be provided with other proposed improvements or modifications. Items in this category would most likely be scheduled after the first refueling outage.