

itory

FILE BY:

NSP

PDR

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

October 8, 1973

Mr. J F O'Leary, Director
Directorate of Licensing
Office of Regulation
U S Atomic Energy Commission
Washington, D C 20545



Dear Mr. O'Leary:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Malfunction of the "B" SPGT System Heater

A condition occurred at the Monticello Nuclear Generating Plant which we are reporting to your office in accordance with Section 6.7.B.1, Abnormal Occurrence Reports, of Appendix A, Technical Specifications, of Provisional Operating License DPR-22.

On September 29, 1973, while deinerting the primary containment during a scheduled reactor shutdown, the "B" Standby Gas Treatment (SBGT) System LOW HEAT alarm was received and indication of low differential temperature was observed. The redundant SBGT train was immediately placed in operation.

Subsequent investigation revealed failure of the 30 amp-600 volt fuse block assembly in the heater circuit. It was determined that a loose fuse clip on the fuse block had created a high resistance path resulting in overheating of the assembly to the point of failure. The fuse block assembly was replaced. Physical inspection and electrical testing of the heater revealed it to be undamaged. An operability test of the "B" SBGT System was satisfactorily performed on October 2, 1973, prior to reactor startup.

This occurrence did not affect safe operation since the redundant train was fully operable and within minutes the plant conditions were such that SBGT operability was not required.

No similar failures have occurred at Monticello. An inspection of the redundant SBGT train heater circuit was performed and no abnormal conditions noted. It is felt that the measures taken were sufficient to prevent repetition.

Yours very truly,

L. O. Mayer / 11.4.0

L O Mayer, PE
Director of Nuclear Support Services

cc: J G Keppler 9211200454 731008
G Charnoff PDR ADOCK 05000263
S PDR
Minnesota Pollution Control Agency
Attn. Ken Dzugan

7530