

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

Regulatory Docket File
JPD

July 23, 1975

Mr A Giambusso, Director
Division of Reactor Licensing
U S Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr Giambusso:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Inoperable Reactor Water Level Sensor

The Licensee Event Report for this occurrence is reproduced on the back of this letter.

Yours very truly,

L. O. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/ak

cc: J G Keppler
G Charnoff
MPCA
Attn: J W Ferman

7-25
407

7909

-over-

9211230493 750723
PDR ADOCK 05070263
S PDR

LICENSEE EVENT REPORT

CONTROL BLOCK 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 M N M N P I 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 0 1

CATEGORY 01 CONT P O T L 0 5 0 - 0 2 6 3 0 7 1 3 7 5 0 7 2 3 7 5

EVENT DESCRIPTION

02 During normal operation a small leak developed in a Reactor Pressure Gauge. The
03 leak lowered the reference leg level for the scram and ECCS initiating Yarway
04 Level instruments connected to the same process tap causing incorrect level
05 indication. Redundant Yarways were operable. No previous similar occurrences.
06 Pressure Gauge isolated. (AO 50-263/75-12)

SYSTEM CODE 07 I A E I N S T R U N X 9 9 9 N

CAUSE DESCRIPTION

08 A leak developed in the Bourdon Tube of Heise Model CMM 7646 0-1500 psig
09 pressure Gauge. Cause of leak unknown. Gauge to be replaced.
10

FACILITY STATUS 11 E 0 6 7 NA A Received Level Alarms

FORM OF ACTIVITY RELEASED 12 Z Z NA NA NA

PERSONNEL EXPOSURES

13 0 0 0 Z NA

PERSONNEL INJURIES

14 0 0 0 NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16 Z NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 Occurrence also affected system IB

19

NAME W J Hill

PHONE 612-295-5151