NRC Form 300 (9-83) LICENSEE EVENT REPORT (LER)			U.S. NUCLEAR REGULATORY COMMISSION APPROVED ONB NO. 3150-0104 EXPIRES: 8/31/85						
FACILITY NAME (1)			DOCKET NUMBER	(2)	PAGE (3)				
TITLE (4)			0 15 0 10	0121/15	1 OF 0 2				
REACTOR TRIP AND SAFETY INJECTION	N		<u> () () () () () () () () () (</u>						
EVENT DATE (5) LER NUMBER (6)	REPORT DATE (7)	FACILITY NA	FACILITIES INVO	R(S)					
NUMBER NUMBER				0 15 10 10	101 1 1				
0 5 2 0 8 5 8 5 0 1 5 0 0 0	0 6 1 8 8 5			0 15 10 10	101 1 1				
OPERATING	THE REQUIREMENTS OF 10	CFR §: /Check one or more	of the following) (1	1)					
POWER 20.402(b) 2 LEVEL 0 5 5 20.405(a)(1)(i) 6 20.405(a)(1)(ii) 20.405(a)(1)(ii) 6 6 6 20.405(a)(1)(iii) 20.405(a)(1)(iii) 6 6 6 20.405(a)(1)(iii) 20.405(a)(1)(iii) 6 <td< td=""><td>20.406(c) 50.38(c)(1) 50.38(c)(2) 50.73(a)(2)(i) 50.73(a)(2)(ii) 50.73(a)(2)(iii)</td><td>A 50.73(a)(2)(iv) 50.73(a)(2)(v) 50.73(a)(2)(vii) 50.73(a)(2)(viii) 50.73(a)(2)(viii) 50.73(a)(2)(viii) 50.73(a)(2)(viii)</td><td>(A) (8)</td><td>73,71(b) 73,71(e) X OTHER (Sp Derow and in 366A) Special</td><td>ectly in ALStreet Text. NRC Form Report</td></td<>	20.406(c) 50.38(c)(1) 50.38(c)(2) 50.73(a)(2)(i) 50.73(a)(2)(ii) 50.73(a)(2)(iii)	A 50.73(a)(2)(iv) 50.73(a)(2)(v) 50.73(a)(2)(vii) 50.73(a)(2)(viii) 50.73(a)(2)(viii) 50.73(a)(2)(viii) 50.73(a)(2)(viii)	(A) (8)	73,71(b) 73,71(e) X OTHER (Sp Derow and in 366A) Special	ectly in ALStreet Text. NRC Form Report				
LICE	ENSEE CONTACT FOR THIS	LER (12)							
DAVID P. SISK, REGULATORY COMPLIAN	CE ENGINEER		AREA CODE	519151-	17 13 1511				
CAUSE SYSTEM COMPONENT MANUFAC. TO NPROS	CAUSE	SYSTEM COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	*				
		1 111	111						
			111						
SUPPLEMENTAL REPORT EX	PECTED (14)		EXPECTE	ED MONTH	DAY YEAR				
YES III yes complete EXPECTED SUBMISSION DATE	X NO		DATE (1	5)					
At 0520 PDT, May 20, 1985, with U followed by a safety injection oc designed. The plant was stabiliz procedures. All systems and equi normal operation. This event was caused by a loose instrument inverter IY-1-2. This reactor coolant pump breaker posi (Loss of Flow Permissive), only o reactor trip signal. The connect returned to normal operation. To prevent recurrence, the output 30 days and again quarterly until method of making terminations. This was the seventh emergency co that has resulted in the discharg	nit 1 in Mode curred. All a ed in Mode 3 pment affected connection to resulted in t tion trip sign ne breaker ope ions were rete circuit break the connection re cooling syste of water int	1 (power oper automatic equi (hot standby) d by this ever the output ci the breaker tr nal. Since th en signal was erminated and ter connection ons are replace tem (ECCS) ac	ration), a ipment res in accord it were re ircuit bre ripping op ne unit wa required the inver as will be ced with a ctuation c	a reactor ponded as lance with turned to eaker for ben products above P to initia ter was rechecked in improve system.	trip ing a -8 te a d in d				
8507010102 850618 PDR ADOCK 050002 S PD	75 R				LEZZ				

4

LICENSEE EVENT REPORT (LE	R) TEXT	CONTINUATION
---------------------------	---------	--------------

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

EXPIRES 8/31/86

							Contraction (Sector				
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)					PAGE (3)				
DIABLO CANYON UNIT 1		YEAR		SEQUENTIAL		REVISIO			T		
	0 15 10 10 10 12 17	815	_	0111	5	_	010	012	OF	01	12
TEXT IN more space is required, use additional NRC Form 366A's) (17)					-				-		-

At 0520 PDT, May 20, 1985, with Unit 1 in Mode 1 (power operation), a reactor trip followed by a safety injection occurred. All automatic equipment responded as designed. The plant was stabilized in Mode 3 (hot standby) in accordance with procedures. All systems and equipment affected by this event were returned to normal operation.

A loose connection to the output circuit breaker for instrument invertar IY-1-2 (EE)(BU) caused the breaker to trip open. This resulted in the loss of power to the Reactor Coolant Pump (RCP) breaker position indicator (JC)(ZI), which produced an RCP breaker (AB)(BKR) open signal. Since the unit was above P-8 (Loss of Flow Permissive), only 1 RCP breaker open signal was required to produce the reactor trip signal. The safety injection signal resulted from a lo-lo Tavg signal for all four loops, due to cooldown after the reactor trip, coincident with the high steam flow signals (produced from all four steam lines when bistables in Reactor Protection Set 2 were deenergized on loss of inverter IY-1-2).

The connections were reterminated and the inverter was returned to normal operation. To prevent recurrence, the output circuit breaker connections will be rechecked in 30 days and again quarterly until the connections are replaced with an improved method of making terminations.

This was the seventh emergency core cooling system (ECCS) actuation cycle to date that has resulted in the discharge of water into the reactor coolant system.

NRC Form 366A

PACIFIC GAS AND ELECTRIC COMPANY

TP C + 77 BEALE STREET · SAN FRANCISCO, CALIFORNIA 94106 · (415) 781-4211 · TWX 910-372-6587

JAMES D. SHIFFER VICE PRESIDENT NUCLEAR POWER GENERATION

June 18, 1985

PGandE Letter No.: DCL-85-219

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-80 Diablo Canyon Unit 1 Licensee Event Report 85-015-00 Reactor Trip and Safety Injection

Gentlemen:

Pursuant to 10 CFR 50.73(a)(2)(iv) and as required by Diablo Canyon Unit 1 Technical Specification 6.9.2 and Action Statement b of Technical Specification 3.5.2, PGandE is submitting the enclosed Licensee Event Report/ Special Report concerning the inadvertent actuations of Engineered Safety Features (ESF), a reactor trip followed by a safety injection.

This event has in no way affected the public's health and safety.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerel J. D. Shiffer

Enclosure

cc: J. B. Martin Service List