

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Beaver Valley Power Station, Unit 1DOCKET NUMBER (2)
0 5 0 0 0 3 3 4 1 OF 0 2

TITLE (4)

Surveillance Program Deficiency

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)										
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)									
0	5	1	6	8	5	8	5	0	1	2	0	0	6	1	4	8	5	N/A	0 5 0 0 0 0
										N/A	0 5 0 0 0 0								

OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)															
POWER LEVEL (10)	1 0 0	20.402(b)				20.405(c)				50.73(a)(2)(iv)				73.71(b)			
		20.405(a)(1)(i)				50.38(a)(1)				50.73(a)(2)(v)				73.71(c)			
		20.405(a)(1)(ii)				50.38(a)(2)				50.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)			
		20.405(a)(1)(iii)				X 50.73(a)(2)(i)				50.73(a)(2)(viii)(A)							
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)							
		20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(ix)							

NAME		TELEPHONE NUMBER	
Robert J. Druga, Manager of Technical Services		AREA CODE	4 1 2 6 4 3 - 1 5 3 0 1 8

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	
A	X	X	X	X	X	X	X	X	N	

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)	X NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During a review of Technical Specification Requirements, against the Technical Specification Surveillance Program, a deficiency was noted on a Surveillance Verification Log. Item 118 of Surveillance Log L5-8 did not contain a reference to Technical Specification 4.5.3. Technical Specification Surveillance 4.5.3 requires the verification of the valve position of the Low Head Safety Injection to the Reactor Coolant Hot Legs, the Low Head Safety Injection to the Reactor Coolant Cold Legs and the High Head Safety Injection to Reactor Coolant Hot Legs with power to the valve operator control circuits disconnected by removal of the plug in the lock out circuit for each circuit, every 12 hours. While correcting this deficiency, it was noted that Technical Specification Surveillance 4.5.3 is required in Mode 4, while Surveillance Verification Log L5-8 is only performed in Modes 1, 2 and 3. An investigation was made to ascertain if the lock out jacks were checked in Mode 4. Positive verification could not be found. The cause for this deficiency in the Surveillance Verification was attributed to personnel error. This surveillance verification will be deleted from Surveillance Verification Log L5-8 and added to Surveillance Verification Log L5-11. Surveillance Verification Log L5-11 is performed in Modes 1 through 4, which satisfies the surveillance requirement of Technical Specification 4.5.3.

8507030031 850614
PDR ADOCK 05000334
S PDRIE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Beaver Valley Power Station, Unit 1	0 5 0 0 0 3 3 4	8 5	— 0 1 2	— 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

To ensure that all procedures referenced in Technical Specification 6.8 and Regulatory Guide 1.33 receive their required reviews and approvals, a matrix was developed to relate surveillance requirements to the appropriate procedures. During development of this Technical Specification and Procedure Matrix, it was noted that Item 118 of Surveillance Log L5-8 did not contain a reference to Technical Specification 4.5.3. Technical Specification 4.5.3 requires the verification of the valve position of the following valves: the Low Head Safety Injection to the Reactor Coolant Hot Legs [MOV-SI-890A, B], the Low Head Safety Injection to the Reactor Coolant Cold Legs [MOV-SI-890C], and the High Head Safety Injection to the Reactor Coolant Hot Legs [MOV-SI-869A, B], and the verification that power to the valve operator control circuits is disconnected by removal of the plug in the lock out circuit from each circuit every 12 hours. During implementation to correct this deficiency, it was noted that Technical Specification Surveillance 4.5.3 is required in Mode 4 (Hot Shutdown), while Surveillance Verification Log L5-8 is only performed in Modes 1, 2 and 3 (Power Operation, Hot Startup and Hot Standby). An investigation was made to ascertain if the lock out jacks were checked during Mode 4 (Hot Shutdown). Positive verification that this check was performed during Hot Shutdown could not be found; however, it was determined that the valve positions were verified during Hot Shutdown by the performance of a separate surveillance test.

The cause for this deficiency in the Surveillance Verification was attributed to personnel error in the initial preparation and review process of the Surveillance Verification Logs. To correct this deficiency, the lockout plug surveillance verification will be deleted from Surveillance Verification Log L5-8 and will be added to Surveillance Verification Log L5-11. Surveillance Verification Log L5-11 is performed in Modes 1 through 4 (Power Operation through Hot Shutdown), which satisfies the surveillance requirement of Technical Specification 4.5.3. To prevent future recurrences, a review of the present administrative procedures governing the revision and generation of Technical Specifications and corresponding surveillance verifications was performed. It has been determined that the existing controls are adequate to prevent future recurrences.

There were no safety implications to the public as a result of this deficiency in the surveillance verification program because the actual valve positions were checked during the required modes of operation and at no time were any valves found out of their required positions.



Duquesne Light

Nuclear Group
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 393-6000

June 14, 1985
ND1SS1:2470

Beaver Valley Power Station, Unit 1
Docket No. 50-334, License No. DPR-66
LER 85-012-00

Dr. Thomas E. Murley
Regional Administrator
United States Nuclear Regulatory Commission
Region I
Park Avenue
King of Prussia, PA 19046

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications,
the following Licensee Event Report is submitted:

LER 85-012-0, 10 CFR 50.73.a.2.i, "Surveillance Program Deficiency".

Very truly yours,

Wm S Lacey
Wm S. Lacey
Plant Manager

md

Attachment

1E:22
11

T. E. Murley
June 14, 1985
NDISS1:2470
Page two

cc; Director of Management & Program Analysis
United States Nuclear Regulatory Commission
Washington, D.C. 20555

C. A. Roteck, Ohio Edison

Director, Office of Inspection and Enforcement Headquarters
United States Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Peter Tam, BVPS Licensing Project Manager
United States Nuclear Regulatory Commission
Washington, D.C. 20555

W. R. Troskoski, Nuclear Regulatory Commission, BVPS Site Inspector, BV-A

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator, Toledo Edison

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Mr. J. A. Triggiani, Operating Plant Projects Manager
Mid Atlantic Area
Westinghouse Electric Corporation
Nuclear Services Integration Division
Box 2728
Pittsburgh, PA 15230

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange Suite
270 Farmington Avenue
Farmington, CN 06032