



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

November 25, 1992

Docket
File

Docket No. 50-412
Serial No. BV-92-043

Mr. J. D. Sieber, Vice President
Nuclear Group
Duquesne Light Company
Post Office Box 4
Shippingport, Pennsylvania 15077-0004

Dear Mr. Sieber:

SUBJECT: OPERABILITY OF THE ALTERNATE MINIMUM FLOW PATHS FOR THE HIGH-HEAD
SAFETY INJECTION PUMPS (TAC NO. M84935)

On August 20, 1992, the staff issued Information Notice 92-61, and on September 1, 1992, the NRC staff issued special team inspection report No. 50-400/92-201 detailing staff findings and inspection activities pertaining to the effect and circumstances of a reported loss of high-head safety injection (HHSI) at the Shearon Harris Nuclear Power Plant (SHNPP) operated by Carolina Power & Light Company (CP&L). This event was reported to the NRC in Licensee Event Report (LER) 50-400/91-008 on May 3, 1991. The LER was supplemented on May 15, 1991. On November 6, 1992, the NRC issued Supplement 1 to NRC Information Notice 92-61 (Enclosure 1).

This event was examined in an Oak Ridge National Laboratory accident sequence precursor study of 1991 reactor operational events. In that study, the event was assigned a conditional core damage frequency of 6.3×10^{-3} per year. The special team inspection centered around the alternate minimum flow (AMF) system piping and valves. The AMF system was installed after a Westinghouse 10 CFR Part 21 report and NRC Bulletin 80-18 were issued.

On October 13, 1992, CP&L submitted LER 50-400/91-008, Rev. 2, reporting additional system failure during the performance of an integrated functional test on the AMF system. In this LER, CP&L also stated that the as-designed AMF system at SHNPP is being modified to remove the system weaknesses that have been previously identified.

During the course of staff review of the reported loss of HHSI at the SHNPP, the staff identified that a similarly designed AMF system is installed at Beaver Valley Power Station, Unit No. 2.

Because of the high safety significance of this issue, we request that you meet with the staff on December 10, 1992, to provide your justifications for the continued operability of the HHSI at BVPS-2. Please be prepared to describe the AMF system configuration in detail, as well as your surveillance

300130

NRC FILE CENTER COPY

9212070253 921125
PDR ADOCK 05000412
P PDR

DFC

Mr. J. D. Sieber

-2-

testing experience to demonstrate that the AMF system will perform its functions as designed for all reactor pressure conditions. You should also be prepared to discuss any planned modifications to the AMF system.

Sincerely,

Original signed
by

Jose A. Calvo, Assistant Director
for Region I Reactors
Division of Reactor Projects -I/II
Office of Nuclear Reactor Regulation

Enclosure:
As stated

cc w/enclosure:
See next page

Distribution:

Docket File
NRC & Local PDRs
PD 1-4 Plant
SVarga
JCalvo
SNorris
ADeAgazio
OGC
EAdensam
NLe
ACRS (10)
JFRogge, RI

OFFICE	LA:PDI-4	PM:PDI-4 <i>all</i>	D:PDI-4 <i>all</i>	AD:DRPE <i>NAC</i>	
NAME	<i>SNorris</i>	ADeAgazio:cn	JStolz	JCalvo	
DATE	11/24/92	11/24/92	11/24/92	11/25/92	1/1

OFFICIAL RECORD COPY

Document Name: G:\DEAGAZIO\84935LET

Mr. J. D. Sieber
Duquesne Light Company

Beaver Valley Power Station
Units 1 & 2

cc:

Jay E. Silberg, Esquire
Shaw, Pittman, Potts & Trowbridge
2300 N Street, NW.
Washington, DC 20037

Nelson Tonet, Manager
Nuclear Safety
Duquesne Light Company
Post Office Box 4
Shippingport, Pennsylvania 15077

Commissioner Roy M. Smith
West Virginia Department of Labor
Building 3, Room 319
Capitol Complex
Charleston, West Virginia 25305

John D. Borrows
Director, Utilities Department
Public Utilities Commission
180 East Broad Street
Columbus, Ohio 43266-0573

Director, Pennsylvania Emergency
Management Agency
Post Office Box 3321
Harrisburg, Pennsylvania 17105-3321

Ohio EPA-DERR
ATTN: Zack A. Clayton
Post Office Box 1049
Columbus, Ohio 43266-0149

Bureau of Radiation Protection
Pennsylvania Department of
Environmental Resources
ATTN: R. Janati
Post Office Box 2063
Harrisburg, Pennsylvania 17120

Mayor of the Borough of
Shippingport
Post Office Box 3
Shippingport, Pennsylvania 15077

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406

Resident Inspector
U.S. Nuclear Regulatory Commission
Post Office Box 181
Shippingport, Pennsylvania 15077

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR REACTOR REGULATION
WASHINGTON, D.C. 20555

November 6, 1992

NRC INFORMATION NOTICE 92-61, SUPPLEMENT 1: LOSS OF HIGH HEAD
SAFETY INJECTION

Addressees

All holders of operating licenses or construction permits for nuclear power reactors.

Purpose

The U.S. Nuclear Regulatory Commission (NRC) is issuing this information notice to alert addressees to additional developments relating to the loss of high head safety injection (HHSI) function because of anomalies in the associated alternate minimum flow (AMF) system. It is expected that recipients will review the information for applicability to their facilities and consider actions, as appropriate, to avoid similar problems. However, suggestions contained in this information notice are not NRC requirements; therefore, no specific action or written response is required.

Description of Circumstances

On April 3, 1991, Carolina Power & Light Company (the licensee) determined that the HHSI system for the Shearon Harris Nuclear Power Plant had been in a degraded condition during the previous operating cycle. The degraded condition resulted from relief valve and drain line failures in the AMF system for the charging/safety injection pumps (CSIPs) which would have diverted a significant amount of safety injection (SI) flow away from the reactor coolant system (RCS). Additional description of the existing AMF system and additional discussion regarding the specifics of this event are contained in Information Notice 92-61, "Loss of High Head Safety Injection," dated August 20, 1992, and in NRC Special Inspection Report 50-400/92-201, dated September 1, 1992. In addition, Figure 1 provides a schematic of the existing HHSI system at Shearon Harris.

To address NRC staff concerns regarding long-term operability of the existing HHSI system, the licensee committed to implement procedures to minimize the potential for gas or air intrusion into the AMF system and to perform additional testing of the AMF system.

On September 17, 1992, the licensee tested the HHSI AMF system. When the 1CS-746 motor-operated isolation valve was opened to test train "A" of the HHSI AMF system (1CS-746 will stroke fully open in approximately 7 seconds), relief valve 1CS-744 chattered slightly for several seconds and then

9211020211

successfully opened. When the ICS-752 motor-operated isolation valve was opened (also requiring approximately 7 seconds) to test train "B" of the HHSI AMF system, relief valve ICS-755 chattered significantly, the valve bellows failed, and the test was halted. Additional discussion regarding these tests is contained in NRC Inspection Report 50-400/92-17, dated October 1, 1992.

Discussion


The licensee has indicated that the chattering of the ICS-755 relief valve is believed to have been caused by hydraulic effects associated with opening the ICS-752 motor-operated isolation valve. The NRC staff believes that the fluid frictional and dynamic pressure loss characteristics of the long inlet piping upstream of ICS-752 may have also contributed to the chattering. The licensee indicated that the testing, disassembly, and examination of the ICS-755 relief valve identified that the valve lift setpoint (2300 psi) had not changed, and that the bellows failure was caused by cyclic fatigue of an inside weld. Static testing to verify the valve lift setpoint had been routinely performed, during the plant lifetime, whereas testing to simulate flow through the valve to assure proper operation and reseating apparently never was performed.

The Crosby relief valve technical manual states that chattering can affect the life, operation, and performance of a relief valve. The manual recommends that relief valves not have restricted inlets because restricted inlets can cause valve chatter. The opening and closing of the motor-operated isolation valve in the existing HHSI AMF design at Shearon Harris restricts the inlet to the relief valve. In addition, relief valves are generally designed to provide system overpressure protection and are not designed for continuous fluid throttling purposes.

The licensee also indicated that modifications will be made to the HHSI AMF system before restarting the plant from the current refueling outage. Figure 2 provides a schematic of the proposed modifications to the HHSI AMF system at Shearon Harris. The licensee intends to install flow restricting orifices upstream of the motor-operated isolation valves and to remove the relief valves. The motor-operated isolation valve actuation logic will also be modified so that the isolation valves will open when a safety injection signal is present coincident with RCS pressure above approximately 2300 psi.

The NRC staff is aware that other facilities may employ an HHSI AMF design similar to the existing system at Shearon Harris. These include, but may not be limited to, Millstone Unit 3, Comanche Peak Units 1 and 2, Beaver Valley Unit 2, and Vogtle Units 1 and 2. In addition, systems other than the HHSI AMF system may contain relief valves with restricted inlets, thus also making these valves potentially susceptible to chatter.

This information notice requires no specific action or written response. If you have any questions about the information in this notice, please contact the technical contact listed below or the appropriate Office of Nuclear Reactor Regulation (NRR) project manager.



Brian K. Grimes, Director
Division of Operating Reactor Support
Office of Nuclear Reactor Regulation

Technical contact: J. Ramsey, NRR
(301) 504-1167

Attachments:

1. Figure 1, Existing Shearon Harris High Head Safety Injection System
2. Figure 2, Modified Shearon Harris High Head Safety Injection System
3. List of Recently Issued NRC Information Notices




FIGURE 1
EXISTING SHEARON HARRIS HIGH HEAD INJECTION SYSTEM




FIGURE 2
MODIFIED SHEARON HARRIS HIGH HEAD INJECTION SYSTEM

LIST OF RECENTLY ISSUED
NRC INFORMATION NOTICES

Information Notice No.	Subject	Date of Issuance	Issued to
92-73	Removal of A Fuel Element from A Re- search Reactor Core While Critical	11-04/92	All holders of OLs or CPs for nuclear power reactors.
92-59, Rev. 1	Horizontally-Installed Motor-Operated Gate Valves	11/04/92	All holders of OLs or CPs for nuclear power reactors.
92-72	Employee Training and Shipper Registration Requirements for Trans- porting Radioactive Materials	10/28/92	All U.S. Nuclear Regulatory Commission Licensees.
91-64, Supp. 1	Site Area Emergency Resulting from A Loss of Non-Class 1E Uninterruptible Power Supplies	10/07/92	All holders of OLs or CPs for nuclear power reactors.
92-71	Partial Plugging of Suppression Pool Strainers At A Foreign BWR	09/30/92	All holders of OLs or CPs for nuclear power reactors.
92-70	Westinghouse Motor-Operated Valve Performance Data Supplied to Nuclear Power Plant Licensees	09/25/92	All holders of OLs or CPs for nuclear power reactors.
92-69	Water Leakage from Yard Area Through Conduits Into Buildings	09/22/92	All holders of OLs or CPs for nuclear power reactors.
91-29, Supp. 1	Deficiencies Identified During Electrical Dis- tribution System Func- tional Inspections	09/14/92	All holders of OLs or CPs for nuclear power reactors.

OL = Operating License
CP = Construction Permit