NRC For (9-83)	- 344					LIC	ENSE	E EV	ENT RE	PORT		U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMS NO. 3150-0104 EXPIRES 8/31/80								
PACILIT	Y NAME (1	1)	PAL	ISADES P	LANT						-	OCKET NUMBER	255	PAGETS						
TITLE (4	1)					_						15 10 10	10171	1 OF 0						
	CTOT		s Fro	m Nuclea	BATTLE STATE OF THE PARTY.	stru	-	-												
MONTH DAY VEAR VEAR SEQUENTIAL TREVERO								PORT DA	YEAR		FACILITY NAM		DOCKET NUMBER(S)							
	un.	75.80	16411	NUMBER	++	NUMBER	MONTH	UAT	TEAN		NA		0   5   0   0							
0 8	2,3	8 5	8 5	- 0 1	3 _	0 0	0,9	2 3	8,5		NA		0 15 10 10							
OPI	RATING		THIS REP	ORT IS BUSHITT	ED PUR	BUANT 1	TO THE R	EQUIREN	MENTS OF 1	0 CFR & /	Check one or more of	the following) (1								
POWER LEVEL (10)		20.402(b) 20.405(a)(1)(i) 20.405(a)(1)(ii) 20.405(a)(1)(iii) 20.405(a)(1)(iiv) 20.405(a)(1)(iv)				20.466/ 80.36/e 80.73/a 80.73/a 80.73/a	(1) (2) (2)(i) (2)(ii)		X	80.73(a)(2)(iv) 80.73(a)(2)(v) 80.73(a)(2)(vii) 50.73(a)(2)(viii)(A 80.73(a)(2)(viii)(B) 80.73(a)(2)(viii)(B)		72.71(b) 72.71(c) OTHER (Specify in Abstract below and in Text, NRC Form 386A)								
NAME						L	ICENSEE	CONTAC	FOR THIS	LER (12)										
	Fenec	h, To	echni	cal Engi	neer	, Pa	lisad	les				AREA CODE	7 6 4 -	8 9 1 3						
				COMPLETE	ONE LI	NE FOR	EACH CO	MPONEN	T FAILURE	DESCRIBE	D IN THIS REPORT	(13)								
CAUSE	SYSTEM	SYSTEM COMPONENT				PROS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS							
Х	JC	D	ET	G 3 0	5	Y					111	111								
		1 1		1.1.1																

On August 23, 26 and 27, 1985, a noise spike resulted in an inadvertent Reactor Protection System actuation. In each event, the Plant was initially in a shutdown condition. Therefore, no transient resulted from the reactor trip signals. All equipment actuations occurred normally.

SUPPLEMENTAL REPORT EXPECTED (14)

The noise spikes were attributed to an unused circuit feeding into a startup rate bistable card. The circuit has been removed from the system. Other system channels will be evaluated for a similar unused circuit.

8509260467 850923 PDR ADOCK 05000255 S PDR

YES I'I YOU COMPINE EXPECTED SUBMISSION DATE!

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten fines) (16)

IEZZ

YEAR

DAY

MONTH

EXPECTED SUBMISSION DATE (15) NRC Form 366A

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO. 3150-0104
EXPIRES. 8/31/85

FACILITY NAME (1)		DOCKET NUMBER (2)							Г	LER NUMBER (6)										PAGE (3)			
										¥	EAR	T		SEQU	MBE	R		REVISIO NUMBE	2 8		T	T	
PALISADES PLANT	0	15	0	10	1	0	2	5	5	8	3 :	5 -	_	0,	1	3	_	0,0	(	0 2	01	o	12

TEXT IN more space is required, use additional NRC Form 366A's/ (17)

At 0440 on August 23, 1985, with the Plant shutdown (515 degrees, 1400 psi), a noise spike in a nuclear instrument channel [IG] resulted in an inadvertent Reactor Protection System [JC] actuation signal. At 1104 on August 26, 1985, with the Plant in cold shutdown (175 degrees, 260 psi), a nuclear instrument noise spike again resulted in a reactor trip signal. On August 27, 1985, with the Plant in hot shutdown, two additional reactor trip signals occurred from noise spikes. A high start-up rate trip occurred at 0625, and a second high start-up rate trip occurred at 2216. In each event, all plant systems responded normally.

Troubleshooting revealed the source of the electrical noise to be from an unused latching circuit feeding into a start-up rate bistable card. The resultant voltage spikes actuated the Reactor Protection System high start-up rate channels. The unused circuit was disconnected from the system. The circuit was not utilized for any system function. Other nuclear instrument channels will be evaluated for the presence of a similar unused circuit.

A reactor trip is initiated from either of the two wide range, logarithmic nuclear instrument channels if the rate of change exceeds a specific setpoint. The wide range instruments are provided to monitor reactor power from the start-up range to full power. Each wide range channel feeds two protective system channels. The reactor trip occurs from a two-of-four coincidence logic.

In each event, the Reactor Protection System actuations occurred with the Plant in a shutdown condition. No transients resulted from any of the actuations. All equipment responded normally to the reactor trip signals.



General Offices: 1945 West Parnall Road, Jackson, MI 49201 \* (517) 788-0550

September 23, 1985

US Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

DOCKET 50-255 - LICENSE DPR-20 - PALISADES PLANT - LICENSEE EVENT REPORT 85-013- REACTOR TRIP FROM NUCLEAR INSTRUMENT NOISE

Licensee Event Report (LER) 85-013 (Reactor Trip From Nuclear Instrument Noise) is attached. This event is reportable to the NRC per 10 CFR 50.73 (a)(2)(iv).

Brian D Johnson

Staff Licensing Engineer

CC Administrator, Region III, USNRC NRC Resident Inspector - Palisades

Attachment

IE22