

Commonwealth Edison Quad Cities Nuclear Power Station 22710 206 Avenue North Cordova, Illinois 61242 Telephone 309/654-2241

NJK-85-193

July 15, 1985

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Reference: Quad Cities Nuclear Power Station Docket Number 50-265, DPR-30, Unit Two

Enclosed please find Licensee Event Report (LER) 85-007, Revision 01, for Quad Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of the Code of Federal Regulations, Title 10, Part 50.73 (a)(2)(ii), which requires reporting of any event or condition that resulted in the condition of the nuclear power plant, including its principle safety barrier, being seriously degraded.

The original Licensee Event Report (LER) 85-007 stated that the Local Leak Rate Testing (LLRT) program had found leakage in excess of Technical Specification limits, but did not provide a complete summary pending completion of the testing program and corrective actions. This report addresses all valves and penetrations that had repairs performed to reduce the leakage total to within the Technical Specification limit.

Respectfully,

COMMONWEALTH EDISON COMPANY Quad Cities Nuclear Power Station

N. J. Kalivianakis Station Manager

NJK/eem/e

Encl.

cc: J. Wojnarowski A. Madison INPO Records Center NRC Region III

> 8507310084 850715 PDR ADDCK 05000265 S PDR

IE22

11,

EVENT DESCRIPTION

During the Unit Two end of cycle seven refueling outage, the following valves required repairs or adjustments (RA's). Note that some of the RA's were not due to excessive leakage, but were the result of preventative maintenance or modifications. The valve leakage before and after the RA's and an explanation of the work performed is provided in Table 1. For valves where the RA's were initiated due to local leak rate test (LLRT) results, notes are shown in the comment section with details provided in the corrective action section of this report.

TABLE 1

DESCRIPTION	VALVE NO.	COMPONENT DESCRIPTION	AS FOUND	(SCFH) AS LEFT	COMMENTS
Main Steam Line Drain	MO 2-220-1	Crane 3" Gate Valve (783U)	75.50	6.42(c)	Note 1, Table 2 as Left Leakage Is Total for 220-1,2
Main Steam Line Drain	MO 2-220-2	Limitorque Type SMB	40.20		Note 2, Table 2
"A" Reactor Feedwater	CV 220-58A	Crane Tilting Disc CV	1921.66	16.00	Note 3, Table 2
"B" Reactor Feedwater	CV 220-62B	Same as Above	789.50	5.42	Note 4, Table 2
"A" Drywell Spray	MO 2-1001-23A and 26A		0.63(c)	0.84(c)	New EQ Limitorque Operators Installed
"A" RHR Return	MO 2-1001-29A		4.50	9.00	New EQ Limitorque Operators Installed
"B" Drywell Spray	MO 2-1001-23B and 26B		15.12(c)	15.67(c)	New EQ Limitorque Operators Installed
"B" RHR Return	MO 2-1001-29B		4.14	4.14	New EQ Limitorque Operators Installed
RCIC Steam Supply	MO 2-1301-16,17		4.10(c)	2.00(c)	New EQ Limitorque Operators Installed
Drywell/Torus Purge Exhaust	A0 1601-23	Pratt 18" Butterfly (D 1200G)	342.00(c)	0.00(c)	Note 5, A0-1601-23, 24,60,61,62,63 valves Test as one Volume
Drywell/Torus Purge Exhaust	A0 1601-24	Same as Above			Note 5, Table 2
Drywell/Purge Exhaust	A0 1601-60	Same as Above (D 1200G)			Note 5, Table 2
Drywell/Purge Exhaust	AO 1601-63	Pratt 6" Butterfly (D 1200G)			Note 5

TABLE 1 (Continued)			LEAKAGE	(SCFH)	
DESCRIPTION	VALVE NO.	COMPONENT DESCRIPTION	AS FOUND	AS LEFT	COMMENTS
"B" Torus Vent	A0 1601-20B CV 1601-31B	Pratt 20" Butterfly	13.99(c)	13.99(c)	Note 6, Table 2
HPCI Steam Exhaust	CV 2301-45	24" Mission Duo Check	33.80	0.00	Note 7, Table 2
HPCI Drain Pot Exh.	CV 2301-34	2" Kerotest Lift Check	14.20	12.50	Note 8, Table 2
Oxygen Analyzer	A0 8801C	Blaw Knox 3/4" Globe Valve	36.50	13.00	Note 9, Table 2
Oxygen Analyzer	A0 8802C	Same As Above	9.70	6.50	Note 10, Table 2
Oxygen Analyzer	A0 8804	Same as Above	6.50	3.50	Note 11, Table 2
TIP Ball Valve	737-1	General Pneumatics Corp 608 KWJ06-3	0.25	0.80	Retested after Preventative Maintenance
TIP Ball Valve	737-2	Same as Above	0.40	0.80	Retested After Preventative Maintenance
TIP Ball Valve	737-3	Same as Above	0.10	1.30	Retested After Preventative Maintenance
TIP Ball Valve	737-4	Same as Above	0.00	0.30	Retested After Preventative Maintenance
TIP Ball Valve	737-5	Same as Above	1.70	0.50	Note 12, Table 2
ACAD System	AO 2599-2A	1" AO Gate Valve WKM Valve Div., ACF Ind	7.80	2.30	Note 13, Table 2
ACAD System	AO 2599-4B	Same as Above	6.50	0.90	Note 14, Table 2
CAM System	S0 2499-1A	Target Rock 1/2-SMS-S	0.00	0.00	EQ Valve Modification
CAM System	SO 2499-2A	Same as Above	0.00	0.00	EQ Valve Modification
CAM System	S0 2499-1B	Same as Above	0.00	0.00	EQ Valve Modification
CAM System	S0 2499-2B	Same as Above	0.00	0.00	EQ Valve Modification
Core Spray Penetration	X-16B	Metal Bellows	0.00	0.00	Outer Test Bellows Added (Inner Bellows Replaced Last Outage)

CAUSE

The first step to a good corrective action or maintenance program is to determine why the valve in question leaked. The answer to that question is not always obvious when dealing with valves that are sometimes quite large or when the air leakages are small but require repair due to regulatory limitations. At Quad Cities, we believe that we have a good program for diagnosing valve problems and facilitating repairs through the use of Station Procedure QMP 800-18 and the checklist QMP 800-S15. When any safety related and/or primary containment isolation valve is disassembled, a Quality Control inspector performs a thorough inspection of the valve in order to determine the root cause of the valve leakage (or any other problems mandating the repair). An additional inspection is performed during re-assembly of the valve. A copy of the procedure and checklist is included in Appendix A. We believe that this method of diagnostics and control on these types of repairs meet or exceed any prevailing standard within the industry.

In addition, Quad Cities maintains on file the LLRT results for every primary containment isolation valve and penetration dating back to plant startup and trends those results. The station's willingness to repair valves or penetrations that exhibit low, but equipment specific high or increasing leakages over past LLRT results, demonstrates a sincere effort to meet the requirements of 10 CFR 50, Appendix J.

Because of the stringent testing requirements of the above regulation and problems encountered industry-wide in meeting those requirements, the corrective action portion of this report has been prepared to identify "chronic" problems experienced at Quad-Cities. Actions taken in the past and future plans are discussed.

The specific action taken this refuel outage on all valves with RA's due to LLRT leakage is given below in Table 2. The note numbers can be referenced back to Table 1 to identify the valves.

- 4 -

-	-	~		-	-
	<i>a</i> .	-		- · ·	-
	ю.	-			
		~	-	_	

ote No.						DISCUSSIO	N						
1	Work Request No. ping the seat.	Q41003. I	Repairs t	o this	valve	included	cleaning	the	internals of	rust-like	dirt	and	lap-
	Leakage History:												
		07/26	/71		0.00	SCFH(c)							
		01/18	/75		0.00	(c)							
		10/17	/75		1.70	(c)							
		09/11	/76		5.42	(c)							
		01/15	/78		6.55	(c)							
		11/26	/79		1.72								
		01/23	/80		8.45	(c)							
		09/07	/81		66.30								
		12/23	/81		8.63	(c)							
		09/05	/83		39.27	(c)							
		01/12	/84		07.46	(c)							
		03/17	/85		75.50								
		05/21	/85		6.42	(c)							

Note:

(c) = combined leakage of both 220-1 valve and the 220-2 valve.

Conclusion: While this valve performed well for the first 10 years of plant operation, chronic problems with valve leakage have been experienced recently. Reference the corrective action section of this report.

Work Requests No. Q39984 and Q41911. During operation, this valve had a small steam leak from the bonnet seal ring that only leaked when the MO 2-220-1 was open. After the as found LLRT, this valve was disassembled, inspected, and cleaned with no observed defects that would explain the through leakage. Subsequent LLRT showed little improvement in leakage. Subsequent investigation determined that Limitorque operator was not closing the valve completely and that torque switch setting could be increased. This corrective action eliminated most of the valve leakage.

Conclusion: Valve inspection and corrective action required do not indicate that this valve has a chronic problem requiring further corrective action at this time.

0258H

2

-							
	-		~		ut.	~	
- 234	E 1.	т.	-	- 97	se:	c	
	•		u			9	- 10

DISCUSSION

Work Request No. Q41492. No problems were found with seat or seals. Valve was disassembled and put back 3 together with new o-rings on disc/seat assembly and seal ring. One of the hold down clamp set screws had a cracked tack weld but no probable affect on valve leakage.

- 6 -

Leakage History:

07/13/71	4.60 SCFH
12/30/74	97.00
02/08/75	8.80
10/12/76	1.70
10/19/76	0.00
02/03/78	1.56
12/26/79	Could Not Pressurize
01/16/80	7.80
09/21/81	1.03
10/05/83	267.30
01/09/84	0.52
04/10/85	1921.66
05/04/85	16.00

Conclusion:

The feedwater check valves are large, 18" check valves on the feedwater lines and have an erratic test history. The main reason for this is that the valve does not seat when tested with 48 PSIG of air. All feedwater check valves are considered a chronic problem. Reference the corrective action section of this report.

Note No.

4

DISCUSSION

Work Request No. Q41492. This valve was found to have a hinge pin missing even though the set screw, lock nut, and tack weld to hold the hinge pin were still in place. Future valve repairs will include modifications to better secure the hinge pins. This is the first failure of this kind at Quad Cities. Subsequent repairs to the valve to make it leak tight included machining a slight valley out of the valve body where the seat ring is clamped down.

Leakage History:

08/21/71	7.50 SCFH
12/30/74	2647.00
02/18/75	1.36
09/14/76	811.00
10/11/76	6.78
01/17/78	Unable to Pressurize
03/02/78	16.50
11/27/79	406.80
01/28/80	14.90
09/17/81	1018.00
11/13/81	13.60
09/14/83	362.00
12/30/83	28.50
03/22/85	789.50
05/31/85	5.42

- 7 -

Conclusions:

Same as for CV 220-58A

TARIE	2	(Cont	(hauni
1 Male	-	10000	muou/

Note No.		DISCUSSION
5	Work Request No.	041926 Replaced A0 1601-23
	Work Request No.	042341 Replaced A0 1601-24
	Work Request No.	241927 Replaced AO 1601-60
	Work Request No.	142345 Replaced A0 1601-63
	Leakage History:	Volume Boundary - A0 1601-23, 24, 60, 61, 62, 63
		08/24/71 3.20 SCFH
		08/22/72 0.70
		04/16/73 11.25
		10/18/73 4.55
		10/03/76 0.00
		02/25/78 12.52
		12/05/79 27.00
		02/12/80 18.00
		10/18/81 17.99
		09/30/83 9.00
		04/29/85 342.00
		05/24/85 0.00
	Conclusions:	The above values all have vulcanized rubber seats and are Pratt butterfly values. Inspections on disassembly revealed that all of the values were dirty and the seat were hard and non-resilient. These values were original equipment from when the plant was built (1971).
		The 23-valve was disassembled and cleaned in February, 1980. The 24-valve was disassembled and cleaned in April, 1981. This is the only maintenance performed o the internal seating surfaces of these valves since plant startup. While the valv gave little warning of impending failure (excessive leakage), the inspections show that the seating surfaces were at the end of their useful life. The valves were replaced with new valves and the old ones will be decontaminated and sent out for seat replacement (re-vulcanizing).
		The leak rate history shows that these values do not constitute a chronic problem. The fact that so many values (4) failed simultaneously is, however, reason for concern. Reference the corrective action section of this report.

Note No.

DISCUSSION

6 Work Request No. 41665. V 1601-31B was disassembled and cleaned. Was found to be dirty. A0 1601-20B had packing on shaft replaced.

- 9 -

Leakage History:

08/19/71	0.08 SC	FH
04/16/73	1.91	
10/17/73	0.00	
01/28/75	0.00	
09/12/76	2.29	
01/18/78	110.74	
02/15/78	0.73	
12/03/79	0.76	
09/23/81	19.90	
09/30/81	10.70	
09/12/83	07.10	
03/23/85	13.99	
05/30/85	13 99	

Conclusions:

Repairs performed did not reduce leakage from the volume. Probable source of leakage is through AO 1601-20B. This is a rubber seated Pratt butterfly valve. While no chronic problem has been experienced with this valve, reference the corrective action section of this report.

Note No.

DISCUSSION

7 Work Request No. 042118 and Modification M-4-2-85-27.

This value is a TRW Mission Duo Chek on the HPCI turbine exhaust. The inspection on this value showed damage to the rubber seat and a bent stop pin. The value was new in October, 1981. The value was replaced this outage with a nearly identical value.

Leakage History:

07/21/71	2.20 SCF
01/30/75	0.40
09/13/76	57.23
10/13/76	0.00
01/16/78	1.56
11/26/79	16.90
09/08/81	165.00
10/06/81	12.04
09/05/83	0.00
03/18/85	33.80
05/23/85	0.00

Conclusions:

The life expectancy of this valve appears to be approximately 3 cycles. Because of the severe damage found during valve inspections and problems encountered in the industry with these valves used for this application, this is considered a chronic problem. Reference the corrective action section of this report.

Note No.

DISCUSSION

8 Work Request No. Q41548. Modification M-4-2-85-19.

While this value has not had a bad LLRT performance, maintenance records showed that the value did not have much stellite left on its seat from previous seat lapping repairs. Since the value leakage did increase over previous values, the decision was made to replace the value.

4

Leakage History:

12/31/70	0.19 SCF
04/15/74	0.41
01/04/76	0.26
03/22/77	0.00
01/19/79	1.90
08/31/80	4.50
09/09/82	0.00
03/08/84	0.00
03/18/85	14.20
06/02/85	12.50

Conclusions:

The leakage history of this valve does not indicate a chronic problem with leakage. The new valve, a Kerotest lift check valve, exhibited some leakage when installed. The performance of this new valve will be carefully trended.

Note No.

DISCUSSION

9 Work Requests No. Q41308 and Q42167.

The valve was originally found to have very dirty (rusty) internals with a piece of paper or gasket material across the seat. Cleaning the valve and seat surfaces reduced the leakage from 36.5 to 17.0 SCFH. The valve was disassembled again and the seat surface lapped reducing the leakage to its final value.

Leakage History:

01/02/75	1.49 SCFH (c)
09/16/76	1.20
01/18/78	10.50
12/06/79	11.00
09/29/81	4.40
10/03/83	6.00
03/29/85	36.50
05/21/85	11.00

Conclusions:

These oxygen analyzer valves do not represent a serious source of containment leakage because the lines go to a sample rack and are manually isolated at this point. In fact, recent changes to the containment monitoring systems (CAM and HRSS) have made the lines with AO 8801-1, 2A and AO 8801-1, 2B and AO 8801-1,2C, obsolete and no longer used. A modification will be started to remove these valves and cap the lines.

Note No.

11

DISCUSSION

Work Request No. 041309 10

This valve was found to have dirty internals with a rust-like build up. It was cleaned and re-assembled.

Leakage History:

01/02/75	1.49 SCFH (c)
09/16/76	13.00
01/18/78	>30 (limit of flowmeter)
02/09/78	0.05
12/06/79	0.60
09/29/81	0.40
10/03/83	16.00
11/29/83	1.40
03/29/85	9.70
05/03/85	6.50
10/03/83 11/29/83 03/29/85 05/03/85	16.00 1.40 9.70 6.50

Same as for Note 9 above. Conclusions:

Work Requests No. 041307 and 042167.

On the first Work Request, the valve was cleaned of dirty, rust-like material. Subsequent to reassembly, the leakage rate increased slightly. On re-inspection, small scratches on the valve seat were observed. The seat was lapped and the leakage was reduced to its final value.

Leakage History:

01/28/75	3.87 SCFI	H
09/27/76	4.00	
01/30/78	3.90	
12/06/79	2.90	
10/01/81	9.50	
10/14/83	10.00	
03/29/85	6.50	
05/22/85	3.50	

Conclusions:

This valve does not have a chronic problem. No further action is required.

- 13 -

lote No.			DISCUSSION
12	After preventative seals and O-rings, large leakage for	e maintenance, cons the leakage of th these valves, it w	isting of cleaning valve internals and replacing/lubricating valve his valve increased from 1.70 to 4.00 SCFH. Since this is an unusual was replaced with a new valve.
	Leakage History:		
		01/26/78 12/05/79 09/25/81 02/02/83	0.80 SCFH 0.10 0.00 0.00
		11/07/83 03/21/85 06/02/85	4.50 1.70 0.50
	Conclusions:	No chronic prot	olems, no further action required.
13	Work Request No. (041662	
	On disassembly, th leakage. Valves h	ne bonnet to body g nad not been worked	pasket was discovered to be improperly installed allowing some slight d on since their original installation in 1980.
	Leakage History:		
		02/29/80	0.00 SCFH (c)
		09/28/81	0.20 (c) 5.00
		04/01/85	7.80
		05/03/85	2.30
	Conclusions:	This is not a d	chronic problem and no further action is required.
14	Work Request No. (241663	
	Rust and dirt was found to be improp	cleaned from the perly installed (sa	internals of this valve. In addition, the body-to-bonnet gasket was ame as 13 above)
			- 14 -

lote No.			DISCUSSION
	Leakage History:		
		02/29/80	0.00 SCFH (c)
		12/18/81	9.50
		09/23/83	6.50
		04/02/85	6.50
		00/00/00	0.00
	Conclusions:	The leakage from t to be tight now.	this valve had been nearly constant since 1981. Valve would appear No further action would seem required at this time.

CORRECTIVE ACTION

The immediate action taken for many of the RA's is sufficient corrective action because the leakages involved were small and no pattern of chronic failure exists. The items of special concern, however, are valves that have a history of excessive leakage and/or large leakage rates. These problems are identified as follows:

- 1) Main steam line drain vaive 220-1;
- 2) All feedwater check valves 220-58A, B; 220-62A, B;
- 3) Drywell purge butterfly valves 1601-23, 24, 60, 61, 62, 63;
- 4) HPCI Steam exhaust 2301-45.

The above problems will be discussed in detail here concerning future corrective actions required to prevent further re-occurrences.

MAIN STEAM LINE DRAIN VALVE (220-1)

As noted from the leakage history of this valve, the valve performed reasonably well for the first 10 years of plant operation. Since 1981, however, this valve has caused problems requiring repair each refuel outage. During the 1983 refuel outage, fairly extensive repairs were performed by replacing the valve disc and disc guide, as well as lapping the seat. The following additional actions are warranted at this time:

- 1) Replace the valve during the next refuel outage;
- Investigate a better valve for this application (e.g. a globe type valve instead of a gate valve);
- 3) Investigate the possibility of relocating this valve in the drywell (under the steam lines) to a location that would make future repairs easier to perform and possible result in less dirt or rust being deposited on valve internals.

ALL FEEDWATER CHECK VALVES (220-58A, B; 220-62A, B)

The failure of these valves to give good LLRT results is well documented at Quad Cities and at other stations throughout the industry. While modifications have been performed to reduce the potential of valve leakage (e.g. modifications to the disc/seat assembly seals and hold down clamps), the primary problem continues to be that these valves are intended to isolate a high pressure water line and we are testing them with low pressure air. The test method does not include a way to firmly seat the disc prior to testing. The testing does not simulate either normal operating or accident conditions that would act to seat these valves, and normally the feedwater lines would not act as a leakage path because they are water filled. While other stations, with NRC approval, have attempted to use water and/or water/air mixtures to seat the valves prior to testing with air, Quad Cities has not found this technique to be effective. The quantity of water that can be introduced into an 18-inch line through a 1-inch test tap does not seem to affect closure of the valve, and at times can be counter-productive by washing rust and dirt into the seat. The water velocity that can be developed seems inadequate to either move the disc or keep the surface free of crud.

While the station continues in its efforts to develop a better maintenance program and test procedure for this valve, we believe that the problem is to a great extent generic with these particular valves. Unfortunately, recent industry experience with a newly designed dual seat valve offered by Anchor Darling Corp. has not been totally successful as documented in NRC IE Bulletins.

The station has initiated an Action Item Request (AIR NO. $\underline{85-12}$) to Station Nuclear Engineering Department (SNED) to investigate this problem and determine a solution.

DRYWELL PURGE BUTTERFLY VALVES

As stated in the previous section, the valves that developed excessive leakage have a history of good performance. The concern of the station, however, is that these valves, because of their soft rubber seats, might be reaching the end of their useful life in terms of the vulcanized seat material. There are a number of other containment valves with this same valve manufacturer and design. The additional valves are listed below and they will be disassembled during the next refuel outage for seat inspection, maintenance, and/or replacement:

> AO 1601-20A AO 1601-20B AO 1601-21 AO 1601-22 AO 1601-22 AO 1601-56

A similar inspection maintenance/replacement program will be established on Unit One.

HPCI STEAM EXHAUST VALVE

There is an existing AIR to SNED to investigate a replacement for this valve. The station does not feel that the Mission Duo Check valve, while it does give adequate service for more than one cycle, is the best choice for this application. Further engineering will be performed to determine if a more suitable valve is available, or if modifications to the existing valves will make them more reliable.

APPENDIX A

QMP 800-18 Revision 3 July 1984

FOR REFERENCE ONLY

INSPECTION OF SAFETY-RELATED VALVES DURING DISASSEMBLY, REPAIR, AND RE-ASSEMBLY OF VALVES

TD/10

A. PURPOSE

The purpose of this procedure is to outline the requirements for the inspection of safety-related valves, including primary containment isolation valves, during disassembly, repair, and re-assembly for maintenance. This procedure also is intended to verify that foreign materials are not introduced into the valve which may affect future valve performance or testing.

B. REFERENCES

1. ANSI 18.7 (1972 Edition).

C. FREREQUISITES

- When value or value components such as pilots or bonnet, stem, and disc assemblies are to be removed from the system area for repair, obtain a hold tag(s) if needed from Quality Control and place the hold tag(s) on the value and/or parts.
- Refer to manufacturer's repair manual or instructions, etc., if available in system file for recommendation for replacements parts, bolt torque procedure orders and for cleaning solvents and lubricants (CECo approved products). This is to achieve optimum valve operation and performance so that Technical Specification operability and timing requirements are met.
- Primary containment isolation valve disassembly during a refueling outage must not be undertaken until an "as-found" Local Leak Rate Test (LLRT) is performed first by the Technical Staff.

D. PRECAUTIONS

 Use extra precautions when hanging rigging. Some climbing may be required to rig in some areas.

E. LIMITATIONS AND ACTIONS

- 1. This procedure is intended to be used in conjunction with a developed work package for the proposed maintenance on safety-related valves.
- 2. The maintenance foreman responsible for the repair shall discuss with the mechanics the proper techniques for the disassembly, inspection, repair, and reassembly of safety-related valves. This discussion shall include the specific cleaning solvents and lubricants to be utilized during the repair and the application and amounts to be used.

APPROVED

AUG 0 1 1984

Q.C.O.S.R.

- Quality Control shall inspect every safety-related valve upon disassembly and prior to reassembly to verify that foreign materials are not present on valve seating surfaces.
- The checklist QMP 800-S15 shall be reviewed by QC and QA prior to use to include hold points as deemed necessary to verify maintenance performance.

F. PROCEDURE

- Before disassembly of the valve, survey the entire exterior of the valve for corrosion, cracks, wear and pits etc. (Remove valve insulation only if there is evidence of valve leakage.) Record specific data such as loose bolting, fittings, packing, condition of the stem and the above inspection information on QMP 800-S15.
- Contact Quality Control for inspection of valve intervals (seating surfaces, etc.) immediately upon disassembly.
- When disassembly is complete, briefly describe the condition of the valve internal parts (including surfaces, stem, disc, seat, etc.). Also note the valve leakage source on QMP 800-S15.
- 4. Repair and replace parts as identified in the accompanying work package. If changes are required to the approved work package, the package revision must be approved prior to work proceeding. Note all repair and replacement parts on the checklist. Also, list the specific manufacturer's product name for lubricants and cleaning solvents used on valve component surfaces (i.e., o-rings, gaskets, sealing surfaces, stems, etc.). The product used shall be in accordance with the valve manufacturer's recommendations and/or good maintenance practices; for purposes of assuring smooth and resistance-free valve operation. Describe the type application used for cleaning solvents, lubricants and the proper amounts.
- Contact Quality Control immediately prior to valve closure to inspect the internal seating surfaces for cleanliness and to verify that foreign material is not on the seating areas.
- Complete the reassembly of the valve in accordance with manufacturers recommendations and good maintenance practices. Add the bolt torquing requirements and rotational and sequential orders on the checklist.

G. CHECKLISTS

 QMP 800-S15, Safety-Related Valve Inspection Checklist (Includes Primary Containment Isolation Valves).

H. TECHNICAL SPECIFICATION REFERENCES

1. None.

FOR REFERENCE ONLY

AP.PROVED AUG 0 1 1984 Q.C.O.S.R.

-2-(final)

ID/1P	1 E.		
	EPN	WORK REQUEST	NO
VALVE DESCRIPTION	(I.E., MAKE, MODE	L, SIZE, ETC.)	
A. VALVE EXTERNAL	I SPACTION:	QC/QA HOLD POINTS	(X IT REQUIRED)
(NOTE CONDITIO	INS FOUND)	QC QA	
	YES NO	SIGN	DATE
CORROSION			
CRACKS		and a second	
WEAR		rop DEE	FRENCE ONLY
PITS		I FUR NLI	Linente
OTHER		and the state of the	
OTHER			
IF YES, DE	SCRIBE CONDITIONS	FOUND:	
		or reaction of the two states and the two states and the states are stated as	

-1-

DESCRIBE ANY DISCREPANCIES SELOW:

APPROVED ALG 0 5 1983 Q.C.O.S.R.

QMP 800-S15 Revision 1

IDENTIFY VALVE LEAKAGE SOURCE	F	QC/O	QA HO	DLD PO	INTS	(X IF	REQUI	RED)
		QA		SIGN	1		DATE	
	YES	1	NO					
MAIN SEAT/POPPET								
PILOT SEAT/POPPET								
STEM PACKING		[1		limite		
SEAL RING/BODY-BONNET GASKET		Ľ		24	FOR	REFE	RENC	EONLY
OTHER		Г						A
	IDENTIFY VALVE LEAKAGE SOURCE MAIN SEAT/POPPET PILOT SEAT/POPPET STEM PACKING SEAL RING/BODY-BONNET GASKET OTHER	IDENTIFY VALVE LEAKAGE SOURCE YES MAIN SEAT/POPPET PILOT SEAT/POPPET STEM PACKING SEAL RING/BODY-BONNET GASKET OTHER	IDENTIFY VALVE LEAKAGE SOURCE QC/(QC) QC QA MAIN SEAT/POPPET PILOT SEAT/POPPET STEM PACKING SEAL RING/BODY-BONNET GASKET	IDENTIFY VALVE LEAKAGE SOURCE QC/QA HO QC QA QA MAIN SEAT/POPPET	IDENTIFY VALVE LEAKAGE SOURCE QC/QA HOLD PO QC QA SIGN MAIN SEAT/POPPET PILOT SEAT/POPPET STEM PACKING SEAL RING/BODY-BONNET GASKET	IDENTIFY VALVE LEAKAGE SOURCE QC/QA HOLD POINTS QC QA SIGN NAIN SEAT/POPPET PILOT SEAT/POPPET STEM PACKING SEAL RING/BODY-BONNET GASKET OTHER	IDENTIFY VALVE LEAKAGE SOURCE QC/QA HOLD POINTS (X IF QC QA SIGN VES NO MAIN SEAT/POPPET PILOT SEAT/POPPET STEM PACKING SEAL RING/BODY-BONNET GASKET	IDENTIFY VALVE LEARAGE SOURCE QC/QA HOLD POINTS (X IF REQUI

IF YES, DESCRIBE CONDITIONS FOUND:

IF UNKNOWN AFTER INSPECTION INCLUDE OBSERVATIONS AND POSSIBILITIES OF LEAKAGE SOURCE :

D.	VALVE INTERNAL INSPECTION NOTE GENERAL CONDITION OF:	QC/QA HOLD PO	INTS (X IF REQUIRE	ED)
	INTERNAL VALVE BODY SURFACES VALVE SEAT GUIDE			
	GASKET AND SURFACES PACKING/FOLLOWER STEM			
	BOLTING LUBRICATION (I.E., DRY, NORMAL ETC OTHER CONDITIONS NOTED	.)		
E.	REPAIRS, IF NECESSARY, SHALL BE IDE (I.E., MAINTENANCE/MODIFICATION PRONOTE: NO DATA REQUIRED ON THIS FOR	NTIFIED ON A WO DCEDURE AND STA	ORK PACKAGE TION TRAVELER).	APPROV
	-2-			Q.C.O.S

QMP 800-S15 Revision 1

F. REPLACEMENT DATA:	QC/QA HOLD	POINTS (X	IF REQUIRED)
	QA	GN	DATE
PA	RT NO. (IF APPLICABLE)		
VALVE ASSEMBLY	and a state to a state of the		
STEM	•		
MAIN DISC			APPROV
MAIN SEAT			AUG 0 5 1
PILOT SEAT			Q.C.O.S.
GUIDE		FAD	TECheve
OPERATOR		Lioni	CLERENCE ONLY
OTHER			
G. LUBRICANT AND SOLVEN	TS QC/QA HOLD QC QA SI	POINTS (X	IF REQUIRED) DATE
G. LUBRICANT AND SOLVENT	TS QC/QA HOLD QC QA SI TYPE APPLICATION	POINTS (X	IF REQUIRED) DATE
G. LUBRICANT AND SOLVENT	TS QC/QA HOLD QC QA SI TYPE APPLICATION TYPE APPLICATION	POINTS (X	IF REQUIRED) DATE AMOUNT*
G. LUBRICANT AND SOLVENT MFG NAME LUBRICANT	TYPE APPLICATION TYPE APPLICATION TYPE APPLICATION TYPE APPLICATION	POINTS (X	IF REQUIRED) DATE AMOUNT* AMOUNT*
G. LUBRICANT AND SOLVENT MFG NAME LUBRICANT MFG NAME SOLVENT *AMOUNT: DESCRIBE COATIN DESCRIBE ANY ADDITIONAL 1	TYPE APPLICATION TYPE APPLICATION TYPE APPLICATION TYPE APPLICATION SI TYPE APPLICATION TYPE APPLICATION	POINTS (X CN (I.E., L)	IF REQUIRED) DATE DATE AMOUNT* GHT FILM, HEAVY USE
G. LUBRICANT AND SOLVENT MFG NAME LUBRICANT	TYPE APPLICATION TYPE APPLICATION TYPE APPLICATION NG OF LUBRICANT OR SOLVENT USES OR POTENTIAL PROBLEMS	POINTS (X CN (I.E., LI WITH LUBH	IF REQUIRED) DATE DATE AMOUNT* GHT FILM, HEAVY USE RICANT OR SOLVENTS:
G. LUBRICANT AND SOLVENT MFG NAME LUBRICANT	TYPE APPLICATION TYPE APPLICATION TYPE APPLICATION SI SI TYPE APPLICATION SI SI SI SI SI SI SI SI SI SI	POINTS (X GN (I.E., L] WITH LUBH NT (X IF F	IF REQUIRED) DATE DATE AMOUNT* GHT FILM, HEAVY USE RICANT OR SOLVENTS:
G. LUBRICANT AND SOLVENT MFG NAME LUBRICANT MFG NAME SOLVENT *AMOUNT: DESCRIBE COATIN DESCRIBE ANY ADDITIONAL U H. VALVE REASSEMBLY QUALITY CONTROL INSPI VALVE PRIOR TO CLOSUM (VALVE REASSEMBLY)		POINTS (X CN CN (I.E., L) WITH LUBH NT (X IF H GN	IF REQUIRED) DATE DATE AMOUNT* GHT FILM, HEAVY USE RICANT OR SOLVENTS: REQUIRED) DATE
G. LUBRICANT AND SOLVENT MFG NAME LUBRICANT MFG NAME SOLVENT *AMOUNT: DESCRIBE COATIN DESCRIBE ANY ADDITIONAL U H. VALVE REASSEMBLY QUALITY CONTROL INSPI VALVE PRIOR TO CLOSUD (VALVE REASSEMBLY). ANY EXCESSIVE OR UNAU RECLEANING IS REQUIRE FOREIGN MATERIALS ARE		POINTS (X CN CN (I.E., L) WITH LUBH NT (X IF H GN ON SEATIN H THE CLOS	IF REQUIRED) DATE AMOUNT* AMOUNT* GET FILM, HEAVY USE RICANT OR SOLVENTS: REQUIRED) DATE G SURFACES. SURE, IF
G. LUBRICANT AND SOLVENT MFG NAME LUBRICANT MFG NAME SOLVENT *AMOUNT: DESCRIBE COATIN DESCRIBE ANY ADDITIONAL U H. VALVE REASSEMBLY QUALITY CONTROL INSPI VALVE PRIOR TO CLOSUD (VALVE REASSEMBLY). ANY EXCESSIVE OR UNAU RECLEANING IS REQUIRN FOREIGN MATERIALS ARD CONDITION	QC/QA HOLD QC QA QA SI TYPE APPLICATION TYPE APPLICATION TYPE APPLICATION G OF LUBRICANT OR SOLVENT USES OR POTENTIAL PROBLEMS QA HOLD POI QA CO QA SI NOTE JTHORIZED FOREIGN MATERIAL ED PRIOR TO PROCEEDING WIT E NOTED.	POINTS (X CN CN (I.E., L] WITH LUBH NT (X IF H GN ON SEATIN H THE CLOS	IF REQUIRED) DATE DATE AMOUNT* GHT FILM, HEAVY USE RICANT OR SOLVENTS: REQUIRED) DATE G SURFACES. SURE, IF

.

· ·.

QMP 800-S15 Revision 1

	DSURE	QC/QA 1	HOLD POINTS	(X IF REQUIRED)
		QC		
		QA	SIGN	DATE
BOLTING	EQUENTIAL ORDER			
R	ROTATIONAL ORDER			
Т	ORQUE VALUE			
Т	ORQUE WRENCH NUMBER			
c	ALIBRATION DATE			
CYPRON.				
SALICH:	\frown		r	
(0 003	EFEDEMAT AM
			I run n	erenenge uni
-			Long reservice and the	en en la sub-sense a contra en la sub-sense de la sub-
FINAL SIGNATU	RES:			
FINAL SIGNATU	<u>RES</u> :			
FINAL SIGNATU MECHANIC	<u>RES</u> :	SIGNA	TURE	
FINAL SIGNATU MECHANIC	<u>RES</u> :	SIGNA	ATURE	 Date
FINAL SIGNATU MECHANIC FOREMAN	<u>Res</u> : Review	SIGNA	ATURE	_/DATE
FINAL SIGNATU MECHANIC FOREMAN	<u>RES</u> : REVIEW	SIGNA	ATURE	/ DATE / DATE
FINAL SIGNATU MECHANIC FOREMAN MASTER M	REVIEW ECHANIC REVIEW	SIGNA	ATURE	/ DATE / DATE
FINAL SIGNATU MECHANIC FOREMAN MASTER M	REVIEW ECHANIC REVIEW	SIGNA	ATURE	/ DATE / DATE / DATE / DATE
FINAL SIGNATU MECHANIC FOREMAN MASTER M	REVIEW ECHANIC REVIEW	SIGNA	ATURE	/ DATE / DATE / DATE / DATE
FINAL SIGNATU MECHANIC FOREMAN MASTER M QUALITY	REVIEW ECHANIC REVIEW CONTROL REVIEW	SIGNA	ATURE	/ DATE / DATE / DATE / DATE / DATE / DATE

. . .

*

4.2.2

APPROVED AUG 0 5 1983 Q.C.O.S.R.

٠.