

Robert W. Boyce Plant Manager Limerick Generating Station

PECO Energy Company Limerick Generating Station PO Box 2300 Sanatoga, PA 19464-0920 610 718 2000

10CFR50.73

February 3, 1997 Docket No. 50-352 License No. NPF-39

U.S. Nuclear Regulatory Commission

Attn.: Document Control Desk

Washington, C 20555

SUBJECT: __censee Event Report

Limerick Generating Station - Unit 1

This LER reports the unplanned inoperability of the High Pressure Coolant Injection (HPCI) system, a single train safety system due to the loss of the HPCI turbine speed signal caused by a loose speed sensor connector. This condition alone could have prevented the HPCI system from fulfilling its intended safety function to mitigate the consequences of an accident.

Reference:

Docket No. 50-352

Report Number:

1-96-018

Revision Number:

01

Event Date:

September 25, 1996

Report Date:

February 3, 1997

Facility:

Limerick Generating Station PO Box 2300, Sanatoga, PA

19464-2300

This report is being submitted pursuant to the requirements of .0CFR50.73(a)(2)(v)(D). This revision provides an update to the event description, analysis, cause, and corrective actions, based on replacement of the speed sensor connector and further analysis. Changes are indicated by a revision bar in the left hand margin.

Very truly yours.

DBN\TST
cc: H. J. Miller, Administrator Region I, USNRC

N. S. Perry, USNRC Senior Resident Inspector, LGS

IEDO/

9702070092 970203 PDR ADDCK 05000352 S PDR