



GPU Nuclear, Inc.
U.S. Route #9 South
Post Office Box 388
Forked River, NJ 08731-0388
Tel 609-971-4000

November 4, 1996
6730-96-2337

U. S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, DC 20555


Dear Sir:

Subject: Oyster Creek Nuclear Generating Station
Docket No. 50-219
NRC Bulletin 96-003

On May 6, 1996, the USNRC issued Bulletin 96-003 "Potential Plugging of Emergency Core Cooling Suction Strainers by Debris in Boiling Water Reactors". Page 9 of that bulletin requires a response within 180 days of the date of the bulletin. The attachment to this cover letter meets that reporting requirement.

If any additional information or assistance is required, please contact Mr. John Rogers of my staff at 609.971.4893.

Very truly yours,


for 
Michael Roche
Vice President and Director
Oyster Creek

MBR/JJR

Attachment

cc: Oyster Creek NRC Project Manager
Administrator, Region I
Senior Resident Inspector

Sworn and Subscribed to before me this 4th day of November, 1996


A Notary Public of New Jersey

9611130340 961104
PDR ADOCK 05000219
C PDR

130010

IE 73 1/1

Attachment 1
NRC Bulletin 96-003
180 day Response

NRC Required Response

"All addressees are required to submit the following written report(s):...Within 180 days of the date of this bulletin , a report indicating whether the addressee intends to comply with these requested actions, including a description of planned actions and mitigative strategies to be used, the schedule for implementation, and proposed TS, if appropriate;..."

GPU Nuclear Reply

GPU Nuclear intends to comply with the requested actions described in the bulletin. A modification to the torus strainers is presently scheduled to be installed during our next refueling outage (17R). This outage will commence during the third quarter of 1998. The modification will serve to maintain sufficient cooling capacity to meet current licensing requirements.

GPU Nuclear has participated in the development of the Boiling Water Reactor Owners Group (BWROG) Utility Resolution Guidance (URG) document, and will use this guidance in the design of the modification. Consistent with the URG, potential strainer clogging mechanisms for the Oyster Creek Nuclear Generating Station will be included in the design of the resolution of this issue. GPU Nuclear will continue to participate in the ongoing efforts to finalize the URG document.

At the present time, the URG document is not completed, with the test and analytical information being finalized. Resultingly, it is not possible to provide a detailed description of the final modification design package at this time. It is presently our intent to install a large capacity passive strainer to address the clogging concern. The Mark I LOCA induced hydrodynamic loads have been evaluated and the strainer calculation envelope developed. The strainer design will encompass the debris generating potential of the installed insulation at the Oyster Creek Nuclear Generating Station. Additionally, the potential mitigation which could be provided by replacement or encapsulation of the insulation will be included. BWROG experimental results will be utilized to support these evaluations.

During the recently completed 16R refueling outage, Foreign Material Exclusion procedures were implemented in the torus. Each of the three suction strainers were inspected, video taped, and found in perfect condition, with all holes free of debris and fibrous material. All existing foreign material in the torus was removed and the torus was desludged. A sludge accumulation rate was calculated to be 50 lbs per year using the methodology in the URG. Future desludging operations will be scheduled based on the accumulation rate and the assumptions made for the proposed modification.

The existing Oyster Creek Nuclear Generating Station Technical Specifications require a visual inspection of the torus interior at each refueling outage. Existing Preventative Maintenance tasks include inspecting the torus strainers as well as the downcomers, the vent header, and the remainder of the torus components. Therefore, no new Technical Specifications or Preventative Maintenance tasks are required.