

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Browns Ferry - Unit 1 DOCKET NUMBER (2) 0 5 0 0 0 2 1 5 1 9 PAGE (3) 1 OF 0 1 3

TITLE (4) Failures Experienced with Reactor Building Ventilation Radiation Monitor Circuits

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 2	1 5	8 6	8 6	0 0 9	0 0 0	0 3	1 7	8 6	Browns Ferry - Unit 2		0 5 0 0 0 2 1 6 1 0
									Browns Ferry - Unit 3		0 5 0 0 0 2 1 9 1 6

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §. (Check one or more of the following) (11)

OPERATING MODE (8) N	20.402(b)	20.405(c)	X	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 0 1 0 1 0	20.405(a)(1)(i)	50.36(c)(1)		50.73(a)(2)(v)	73.71(e)
	20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)	
	20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)	
	20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME Richard C. Steele, Compliance Engineer TELEPHONE NUMBER 2 0 5 7 2 9 1 - 2 0 7 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS
AY	I	LRL	Y	P 2 9 7	Y				

SUPPLEMENTAL REPORT EXPECTED (14) YES (If yes, complete EXPECTED SUBMISSION DATE) X NO

EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

This report describes recent events that were experienced with reactor building radiation ventilation monitoring system. The events are not specifically related; however, each involves the reactor building ventilation radiation monitors.

1. On February 15, 1986, at 1200 CST, on unit 2 a secondary containment isolation occurred due to a wiring discrepancy on the panel under test. A drawing discrepancy has been initiated to correct the problem.
2. On February 15, 1986, at 2239 CST on unit 3, a secondary containment isolation occurred due to a random relay failure.
3. On February 26, 1986, at 1550 CST on unit 1, a secondary containment isolation occurred due to improper jumper installation on the panel under test. Personnel were cautioned to exercise better judgment in the performance of duties.

8603250012 860317  
PDR ADOCK 05000259  
S PDR

IE 22  
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Browns Ferry - Unit 1	DOCKET NUMBER (2)  0 5   0   0   0   2   5   9   8   6	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		- 0   0   9	- 0   1   0	0   2	OF	0   2

TEXT (If more space is required, use additional NRC Form 365A's) (17)

Units 1 and 3 were in an extended maintenance outage, and unit 2 was in a refueling outage at the time of the events described below. The events are not specifically related; however, each involves the reactor building ventilation radiation monitors.

1. On February 15, 1986, at 1200 CST, the unit 2 instrument mechanics were performing the reactor building ventilation radiation monitors calibration surveillance instruction (SI 4.2.A-10) on channel 'A' detectors. The instrument mechanics placed a jumper across terminal points AA-52 and CC-34 on panel 9-42 to bypass relay 16A-K61A (inboard isolation logic) contacts 1 and 2. Proceeding with the next step of the SI, which deenergized 16A-K61A, an inadvertent secondary containment isolation occurred as follows:
  - a. Standby gas treatment (BH) train 'A' and 'C' initiated.
  - b. Control room emergency ventilation (VI) train 'A' initiated.
  - c. Unit 2 reactor zone (VB) isolated.
  - d. Unit 1, 2, and 3 refuel zone (VA) isolated.
  - e. Primary containment isolation system (JM) group 6 (purging and venting) isolation.

The SI had been revised on February 12, 1986, to simplify and clarify the instruction in accordance with a commitment made in LER BFRO-50-296/86003. During this first performance of the revised SI, it was found that the field wiring did not agree with the electrical connection drawings. The circuit was wired schematically correct; and the field wiring did not affect the normal function of the circuit. The wiring discrepancy did, however, cause the surveillance procedure to be in error and caused the inadvertent actuation described above. The actuations that occurred are consistent with expected actions when the logic trip contacts were not actually bypassed. Similar circuits of units 1, 2, and 3 reactor building ventilation radiation monitors were checked and verified to agree with the electrical connection drawings. A drawing discrepancy has been initiated to correct the problem on the unit 2 'A' channel detectors.

2. On February 15, 1986, at 2239 CST, a unit 3 primary containment isolation occurred. The actuations occurred because relay K2, (Potter & Brumfield, model KH4690) in refueling zone exhaust radiation monitor (IL) (RM-90-141) channel 'B' high radiation exhaust circuit had failed and caused the following:
  - a. Standby gas treatment (BH) trains A, B, and C initiated.
  - b. Control room emergency ventilation (VI) train A and B initiated.
  - c. Unit 1, 2, and 3 refuel zone (VA) isolated.
  - d. Primary containment isolation system (JM) group 6 (purging and venting) isolation.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Browns Ferry - Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 2 5 1 9 8 6	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
			- 0 0 1 9	- 0 1 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The actuations are consistent with action expected due to the K2 relay (upscale trip) failure. The failed relay was replaced, and the listed circuits returned to normal standby readiness.

3. On February 26, 1986, at 1550 CST, the unit 1 instrument mechanics were performing the reactor building ventilation radiation monitors calibration surveillance instruction (SI 4.2.A-10) on channel 'A' detectors. The instrument mechanics placed a jumper across terminal points CC-38 and CC-40 on panel 9-42 to bypass relay 16A-K61A (outboard isolation logic) contacts 3 and 4. Proceeding with the next step of the SI, which deenergized 16A-K61A, an inadvertent secondary containment occurred as follows:
  - a. Standby gas treatment (BH) trains B and C initiated.
  - b. Control room emergency ventilation (VI) train B initiated.
  - c. Unit 1 reactor zone (VB) isolated.
  - d. Units 1, 2, and 3 refuel zone (VA) isolated.
  - e. Primary containment isolation system (JM) group 6 (purging and venting) isolation.

Investigation of the problem indicated that the jumper was not in good contact with the terminal points; thus, the trip logic was not effectively bypassed. When relay 16A-K61A was deenergized the initiating isolation logic was completed. The actuations that occurred are consistent with expected actions when relay 16AK61A contacts were not properly bypassed.

Personnel error is involved because the instrument mechanics did not verify good electrical contact when the jumper was installed. The personnel involved were cautioned to exercise better judgement in the performance of duties.

No significant safety concerns were raised by these events. In each case, the isolations that occurred are in the conservative direction.

Responsible Plant Section - IM

Previous Events - BFRO-50-259/85021; -296/86003; -296/85019; -296/85022

TENNESSEE VALLEY AUTHORITY

Browns Ferry Nuclear Plant  
P.O. Box 2000  
Decatur, Alabama 35602

March 17, 1986

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555


Dear Sir:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-259/86009

The enclosed report provides details concerning failures experienced  
with reactor building ventilation radiation monitor circuits. This  
report is submitted in accordance to 10 CFR 50.73 (a)(2)(iv).

Very truly yours,

TENNESSEE VALLEY AUTHORITY



Robert L. Lewis  
Plant Manager  
Browns Ferry Nuclear Plant

Enclosures

cc (Enclosures):

Regional Administrator  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 2900  
Atlanta, Georgia 30303

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

NRC Resident Inspector, Browns Ferry Nuclear Plant

IE22  
11