

Commonwealth Edison Company
LaSalle Generating Station
2601 North 21st Road
Marseilles, IL 61341-9757
Tel 815-357-6761



April 14, 1997

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Licensee Event Report #97-013-00, Docket #050-373 is being submitted to your office in accordance with 10 CFR 50.73(a)(2)(i).

Respectfully,

Fred Dacimo
Plant General Manager
LaSalle County Station

Enclosure

cc: A. B. Beach, NRC Region III Administrator
M. P. Huber, NRC Senior Resident Inspector - LaSalle
C. H. Mathews, IDNS Resident Inspector - LaSalle
F. Niziolek, IDNS Senior Reactor Analyst
INPO - Records Center

IE22/1

9704220187 970414
PDR ADOCK 05000373
S PDR



LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1): LaSalle County Station Unit One
DOCKET NUMBER (2) 05000373
PAGE (3) 1 of 4

TITLE (4) Misinterpretation of Technical specifications Resulted in Failure to Perform the Isolation Valve Surveillance For All Transversing Incore Probes

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
03	20	97	97	013	00	04	14	97	LaSalle County Station Unit Two	05000374	
									FACILITY NAME	DOCKET NUMBER	

OPERATING MODE (9) 4
POWER LEVEL (10) 000
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)

<input type="checkbox"/>	20.2201(b)	<input type="checkbox"/>	20.2203(a)(3)(i)	<input type="checkbox"/>	50.73(a)(2)(iii)	<input type="checkbox"/>	73.71(b)
<input type="checkbox"/>	20.2203(a)(1)	<input type="checkbox"/>	20.2003(a)(3)(ii)	<input type="checkbox"/>	50.73(a)(2)(iv)	<input type="checkbox"/>	73.71(c)
<input type="checkbox"/>	20.2203(a)(2)(i)	<input type="checkbox"/>	20.2003(a)(4)	<input type="checkbox"/>	50.73(a)(2)(v)	<input type="checkbox"/>	OTHER
<input type="checkbox"/>	20.2203(a)(2)(ii)	<input type="checkbox"/>	50.36(c)(1)	<input type="checkbox"/>	50.73(a)(2)(vii)	(Specify in Abstract below and in Text, NRC Form 366A,	
<input type="checkbox"/>	20.2203(a)(2)(iii)	<input type="checkbox"/>	50.36(c)(2)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)		
<input type="checkbox"/>	20.2203(a)(2)(iv)	<input checked="" type="checkbox"/>	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)		
<input type="checkbox"/>	20.2003(a)(2)(v)	<input type="checkbox"/>	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(x)		

LICENSEE CONTACT FOR THIS LER (12)

NAME: W. Steffes, Staff Assistant
TELEPHONE NUMBER (Include Area Code): (815) 357-6761 Extension 2992

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO
EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines 16)

On March 20, 1997 the Primary Containment Isolation (PCIS) System Functional Performance Review Team (SFPR) identified a concern regarding LaSalle Electrical Surveillance LES-PC-107(207), Unit 1(2) Group 7 Isolation Logic System Functional Test. The concern was whether the testing methodology used in this procedure met the surveillance requirements of Technical Specification 4.3.2.2. Technical Specification 4.3.2.2, Logic System Functional Test, shall be performed at least once per 18 months, this includes the actuated device to verify operability. Contrary to this requirement LES-PC-107, and LES-PC-207, Unit 1/2, Primary Containment Isolation System (PCIS) Functional Test did not check the actuated device on all 5 TIP machines. This condition has existed since initial plant licensing.

This condition appears to have been caused by misinterpretation of Technical Specification surveillance requirement 4.3.2.2.

Corrective actions include revising the procedures to check all five TIP machines and testing the system per the revised surveillance procedures prior to start-up of either unit.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
LaSalle County Station Unit One	05000373	97	013	00	3 of 4

(If more space is required, use additional copies of NRC Form 366A)(17)

D. ASSESSMENT OF SAFETY CONSEQUENCES

The safety consequences of this event are minimal. The TIP system has a design feature which mitigates the consequences of a failure of a TIP to withdraw. Each TIP guide tube ball valve assembly is provided with a manually operated shear valve. The shear valve is equipped with an explosive squib. When manually detonated, the shear valve will cut the TIP cable and close off the guide tube. Upon receipt of a valid isolation signal during TIP system operation, the operator is directed by LOP-NR-06, TIP Operation, to verify TIP withdrawal and ball valve closure. If a TIP detector fails to withdraw, the operator is directed to manually withdraw the detector or actuate the associated shear valve.

E. CORRECTIVE ACTIONS

1. LES-PC-107(207) will be revised to meet the requirements of Technical Specification 4.3.2.2.
2. The revised procedure will be performed prior to entering operational conditions 1, 2, or 3, when the isolation actuation instrumentation is required to be operable. The performance of LES-PC-107 is being tracked by Degraded Equipment Log (DEL) entry #227-96-1-140 for Unit 1, and LES-PC-207 for Unit 2 (DEL) #136-95-2-154, to ensure it is performed prior to each unit restart.

Other activities to improve plant performance with respect to the design and licensing bases are:

System Functional Reviews

These reviews were initiated to establish a level of confidence that selected systems demonstrate performance consistent with the design basis. An element of these reviews is to identify required system functions and sub-functions as described in design bases documents, including the Technical Specifications. Surveillance testing requirements, procedures, and other test documentation are then reviewed to confirm that system functionality is demonstrated. Any inconsistencies identified among the source documents are being documented and tracked to resolution. These reviews are being implemented with applicable corrective actions completed prior to each unit restart.

UFSAR Validation

To ensure the integrity of the UFSAR, a verification and validation of the regulatory design basis information contained in the UFSAR is being performed. This includes a review of the UFSAR, the Technical Specifications, and other applicable documents and plant procedures.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
LaSalle County Station Unit One	05000373	97	013	00	4 of 4

(If more space is required, use additional copies of NRC Form 366A)(17)

F. PREVIOUS OCCURRENCES

LER NUMBER	TITLE
373-96-015	Misinterpretation of Technical Specification Surveillance Results in Inoperable Diesel Driven Fire Suppression Pumps.
373-97-006	Diesel Generator Testing Did Not Meet Surveillance Requirements Due to Misinterpretation of Technical Specification.

The corrective actions discussed in LER 373-96-015 Revision 01 included implementation of the System Functional Review Program. The event being reported in the subject report (373-180-97-013LER) and (373-97-006) both were discovered by implementation of the System Functional Review Program. This is evidence of the effectiveness of the corrective actions being taken as a result of the LER 373-96-015 event. Therefore, this event is not an indication of inadequate corrective action for the previous occurrence.

G. COMPONENT FAILURE DATA

Since no component failure occurred, this section is not applicable.