

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Monticello Nuclear Generating Plant DOCKET NUMBER (2) 0500021613 PAGE (3) 1 OF 02

TITLE (4) SBGTS Initiation Due to Plenum Monitor Spiking

| EVENT DATE (5) | | | LER NUMBER (6) | | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | | | | | | | | | | | |
|----------------|-----|------|----------------|-------------------|-----------------|-----------------|-----|------|-------------------------------|---|---|---|---|---|---|---|---|--|--|--|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAMES | | | | | | | | | | | |
| 1 | 0 | 15 | 8 | 5 | 8 | 5 | 0 | 1 | 8 | 0 | 1 | 0 | 1 | 0 | 2 | 8 | 6 | | | |

OPERATING MODE (9) 1010

POWER LEVEL (10) 1010

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

| | | | |
|--|---|---|---|
| <input type="checkbox"/> 20.402(b) | <input type="checkbox"/> 20.406(c) | <input type="checkbox"/> 50.73(a)(2)(iv) | <input type="checkbox"/> 73.71(b) |
| <input type="checkbox"/> 20.406(a)(1)(i) | <input type="checkbox"/> 50.38(a)(1) | <input type="checkbox"/> 50.73(a)(2)(v) | <input type="checkbox"/> 73.71(c) |
| <input type="checkbox"/> 20.406(a)(1)(ii) | <input type="checkbox"/> 50.38(a)(2) | <input type="checkbox"/> 50.73(a)(2)(vii) | <input type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 386A) |
| <input type="checkbox"/> 20.406(a)(1)(iii) | <input type="checkbox"/> 50.73(a)(2)(i) | <input type="checkbox"/> 50.73(a)(2)(viii)(A) | |
| <input type="checkbox"/> 20.406(a)(1)(iv) | <input type="checkbox"/> 50.73(a)(2)(ii) | <input type="checkbox"/> 50.73(a)(2)(viii)(B) | |
| <input type="checkbox"/> 20.406(a)(1)(v) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input type="checkbox"/> 50.73(a)(2)(x) | |

LICENSEE CONTACT FOR THIS LER (12) Shawn Halbert, Radiation Protection Specialist TELEPHONE NUMBER 612 295-5151

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPROS | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPROS |
|-------|--------|-----------|--------------|---------------------|-------|--------|-----------|--------------|---------------------|
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

SUPPLEMENTAL REPORT EXPECTED (14) YES (if yes, complete EXPECTED SUBMISSION DATE) NO EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On October 15, 1985, A Reactor Building Isolation and Initiation of Standby Gas Treatment occurred during routine performance of Test #1267, Reactor Building Exhaust Plenum Monitor Monthly Functional Test. The isolation was caused by an upscale trip from the monitor when the TRIP CHECK push button was released. The potential for this occurrence had been recognized previously, and changes to Test #1267 had been completed; however, the most recent revision of the test was not used on October 15. The upscale trip was reset and SBGTS was secured.

Fewer copies of the procedures requiring temporary changes will be placed in the file and each will have a hold sheet attached.

8601090056 860102
PDR ADOCK 05000263
S PDR

JE22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | |
|--|--|----------------|------------------------------------|------------------------------|----------|----------|
| FACILITY NAME (1) Monticello Nuclear Generating Plant | DOCKET NUMBER (2) 0 5 0 0 0 2 6 3 | LER NUMBER (6) | | | PAGE (3) | |
| | | YEAR 8 5 | SEQUENTIAL NUMBER - 0 1 8 | REVISION NUMBER - 0 0 | 0 2 | OF 0 2 |

TEXT: (If more space is required, use additional NRC Form 365A's) (17)

During power operation on October 15, 1985 at 1304, a Reactor Building Ventilation (VA) Isolation and Standby Gas Treatment System (BH) initiation occurred. This was caused by an upscale trip from the Reactor Building Exhaust Plenum Monitor Monthly Functional Test.

This event was caused by a problem with Document Control. Procedures with temporary changes requirements are not pulled from the filing location, but a hold sheet, Form #3087, is placed in the front of the procedures for notification. Form #3087 was placed in the file containing Test #1267, but it was not seen because it adhered to the inside front of the file folder and was not attached to a copy of Test #1267. The hold sheet stated "The current revision shall not be used until the individual who applied this form has been contacted to discuss use of the current revision and any required temporary changes".

Upon discovery of the procedural error, the test was terminated and all trips were restored. Reactor Building Vent and Standby Gas Treatment were returned to normal.

This event had no effect on public health or safety.

To prevent recurrence, fewer copies of those procedures requiring temporary changes will be placed in the file and each copy will have a hold sheet attached. Form #3087 will be revised to more clearly address any temporary changes. Additional training on the use of the hold form will be conducted.



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

January 2, 1986

U S Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

SBGTS Initiation Due To Plenum Monitor Spiking

The Revised License Event Report for this occurrence is attached.

This event was reported via Emergency Notification System per 10 CFR Part 72
on October 15, 1985.

for *Monica Vik*
David Musolf
Manager - Nuclear Support Services

DMM/MMV/dab

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
MPCA
Attn: J W Ferman

Attachment

IC22
1/1