

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	G	A	E	I	B	1	2	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

01	1	6	0	5	0	0	0	3	2	1	7	1	2	2	6	7	9	8	0	1	1	7	8	0	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During shutdown and while performing normal surveillance, the HPCI steam line differential pressure switch was found at 241 in. H<sub>2</sub>O. This exceeds the Technical Specification Table 3.2-2 Item 11 of less than or equal to 216 in. H<sub>2</sub>O plus a head correction of 21 in. H<sub>2</sub>O. There were no effects upon public health or safety. This is a repetitive occurrence as last reported on LER 50-321/1978-52.

01	C	E	11	X	12	Z	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	7	9	1	0	2	0	3	L	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

ATTACHMENT SUBMITTED (Y) PRIME COMP. SUPPLIER (N) COMPONENT MANUFACTURER (G O 8 0)

CORRECTIVE ACTIONS (27)

Instrument IAL 1004, HPCI Steam Line Differential Pressure Switch, failed to operate at the required setpoint because of instrument drift. The instrument was recalibrated and the surveillance successfully run.

01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

ACTIVITY CONTENT (Z) AMOUNT OF ACTIVITY (NA) LOCATION OF RELEASE (NA)

01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

PERSONNEL EXPOSURE (Z) DESCRIPTION (NA)

01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

PERSONNEL INJURIES (Z) DESCRIPTION (NA)

01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

LOSS OF OR DAMAGE TO FACILITY (Z) DESCRIPTION (NA)

01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

PUBLICITY (Z) DESCRIPTION (NA)

01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

ISSUED (N) DESCRIPTION (NA)

NAME OF PREPARER R. T. Nix - Supt. of Maint.

PHONE 912-367-7781

8001220 582

# NARRATIVE REPORT

Georgia Power Company  
Plant E. I. Hatch  
Baxley, Georgia 31513

Reportable Occurrence Report NO. 50-321/1979-102.

During cold shutdown and while performing HNP-1-3307, HPCI Steam Line Differential Pressure Instrument Functional Test and Calibration, Instrument 1E41-N004, HPCI Steam Line Differential Pressure Switch, was found to be out of tolerance. The switch was found at 241 in. H<sub>2</sub>O. The expected setpoint is  $226 \pm 6$  in. H<sub>2</sub>O. This exceeds Technical Specifications Table 3.2-2, Item 11, which states that the trip setting should be less than 216 in. H<sub>2</sub>O. This is a repetitive occurrence.

The switch was recalibrated per HNP-1-5202, Barton Model 288A and 289A Differential Indicating Switch, and the surveillance procedure was performed satisfactorily.

This type of instrument is utilized in other systems on both units, but no generic problems have been discovered at this time. Investigations are continuing to try and determine the cause of setpoint drift. A follow-up report will be submitted.

90028058