

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Beaver Valley Power Station, Unit No. 2	DOCKET NUMBER (2) 0 5 0 0 0 4 1 2	PAGE (3) 1 OF 0 3
--	--------------------------------------	----------------------

TITLE (4)
2/4 Refueling Water Storage Tank Level Channels Inoperable

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER (5)
0	2	2	1	8	8	8	8	8	N/A			0 5 0 0 0
0	2	2	1	8	8	8	8	8				0 5 0 0 0

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)											
POWER LEVEL (10) 0 5 8	20.402(b)			20.405(c)			50.73(a)(2)(iv)			73.71(b)		
	20.405(a)(1)(i)			50.36(e)(1)			50.73(a)(2)(v)			73.71(e)		
	20.405(a)(1)(ii)			50.36(e)(2)			50.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 365A)		
	20.405(a)(1)(iii)			X 50.73(a)(2)(i)			50.73(a)(2)(vii)(A)					
	20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)					
20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(ix)						

LICENSEE CONTACT FOR THIS LER (12)									
NAME T. P. Noonan, Plant Manager								TELEPHONE NUMBER	
								AREA CODE	
								4 1 2 6 1 4 1 3 - 1 1 2 1 5 1 8	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	
C	B	E	L	T	R	3	6	9	N	

SUPPLEMENTAL REPORT EXPECTED (14)				EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO								

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 2/21/88, at 0850 hours, operators received Control Room indication that the "C" Refueling Water Storage Tank (RWST) level transmitter was indicating a Low-Low level. Operators immediately verified that the other transmitters were indicating normal level. Investigation determined that the transmitter's sensing lines were frozen, even though its associated heat tracing was energized. Maintenance thawed the frozen line with a portable heater. As a precautionary measure, a tent was erected around the level transmitters and the portable heater was placed in the tent. At 1630, the "A" transmitter again froze, indicating Low-Low level. Investigation determined that the tent/portable heater had raised the local temperature to the point where the thermostat's for the "A" and "C" transmitters had deenergized their heat tracing. At 1720, the setpoints for these thermostats were raised, re-energizing the heat trace. At 1722, before the re-energized heat tracing could be affective, the sensing lines for the "A" transmitter froze, causing the transmitter to fail low. At 1743, the "A" and "C" transmitters thawed. Engineering is investigating improvements in the heat tracing for these sensing lines. There were no safety implications due to this event, as the other two transmitters were fully operable.

8803290165 880322
PDR ADOCK 05000412
S DCD

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Beaver Valley Power Station, Unit No. 2	DOCKET NUMBER (2) 0 5 0 0 0 4 1 2 8 8	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		88	006	00	02	OF	03

TEXT (If more space is required, use additional NRC Form 308A's) (17)

On 2/21/88, at 0850 hours, the Control Room bistable status light for the "C" Refueling Water Storage Tank (RWST) level transmitter illuminated. This meant that level transmitter [QSS-LT104C] was indicating a Low-Low level for the RWST. All other RWST level indicators (status lights, wide range indicators and narrow range indicators) were indicating normal RWST level. Investigation determined that the sensing lines for [QSS-LT104C] had frozen, causing the transmitter to fail low. This occurred even though the temporary heat tracing on this sensing line (installed as part of the immediate corrective actions for LER 88-001-00) was energized. Ambient temperature at this time was 12 degrees Fahrenheit. Using a kerosene heater, Maintenance thawed the frozen sensing lines and returned the transmitter to service by 1120 hours. In order to prevent further freezing, Maintenance erected a tent around the RWST level transmitters and heated the tent with the kerosene heater.

At 1630 hours, the sensing lines of the "C" level transmitter again froze, causing the transmitter to fail low. Investigation found the heat tracing for the "A" and "C" RWST level transmitters to be deenergized. The local ambient temperature inside the tent had increased to the point that the thermostats associated with the heat tracing for these two level transmitters, had deenergized their heat tracing. Electricians were instructed to increase the setpoints of these thermostats, in order to re-energize the heat tracing. At 1720 hours, the electricians reported that the thermostats had been adjusted and all heat tracing was energized. At 1722 hours, before the heat tracing could thaw the "C" level transmitter sensing lines, the sensing lines for the "A" RWST level transmitter, [QSS-LT104A], froze, causing this transmitter to also fail low. With two level transmitters inoperable, the station entered Technical Specification 3.0.3. At 1743 hours the "A" and "C" level transmitters sensing lines thawed. The transmitters returned to normal operation at this time.

Engineering is in the process of designing permanent heat tracing for these sensing lines. This permanent heat tracing will be more reliable than the temporary heat tracing currently in place. Until this permanent heat tracing is in place, the Control Room status lights for these transmitters will provide constant indication of the operability of these transmitters.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Beaver Valley Power Station, Unit No. 2	DOCKET NUMBER (2) 0 5 0 0 0 4 1 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 8	- 0 0 6	- 0 0	0 3	OF 0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

There were no safety implications due to this event. The only safety function associated with the affected transmitters is automatic transfer to the recirculation cooling mode in the event of a RWST Low-Low level subsequent to a Safety Injection signal. The "B" and "D" transmitters were operable throughout this event and fully capable of initiating this action if it had been required.



Duquesne Light

Nuclear Group
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 393-6000

March 22, 1988
ND3SPM:0192

Beaver Valley Power Station, Unit No. 2
Docket No. 50-412, License No. NPF-73
LER 88-006-00

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 88-006-00, 10 CFR 50.73.a.2.i.B, "Two of Four Refueling Water Storage Tank Level Channels Inoperable".

Very truly yours,

T. P. Noonan
Plant Manager

tlu

Attachment

TR22
11

March 22, 1988

ND3SPM:0192

Page two

cc: Mr. William T. Russell
Regional Administrator
United States Nuclear Regulatory Commission
Region 1
King of Prussia, PA 19406

C. A. Roteck, Ohio Edison

Mr. Peter Tam, BVPS Licensing Project Manager
United States Nuclear Regulatory Commission
Washington, DC 20555

J. Beall, Nuclear Regulatory Commission,
BVPS Senior Resident Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator
Toledo Edison

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Mr. J. N. Steinmetz, Operating Plant Projects Manager
Mid Atlantic Area
Westinghouse Electric Corporation
Energy Systems Service Division
Box 355
Pittsburgh, PA 15230

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. Richard Janati
Department of Environmental Resources
P. O. Box 2063
16th Floor, Fulton Building
Harrisburg, PA 17120